


Existing Hardware Machine components



Frank Tecker - AB/OP
for the CTF3 Team


- Review of various hardware
 - gun, RF, ...
- Software / Controls
- Conclusion




Preface



- 2003 Injector + part of linac
- 2004 Linac + 30 GHz test stand
- 2005 Delay Loop
- 2006 TL1 + Combiner Ring
- 2007 - 2009 New photo-injector, TL2 + CLEX



- CTF3 in **steady evolution** since 2003
 - Machine extending every year
 - Work concentrated on commissioning of new components
 - Increased complexity
 - Higher demand for availability of components
- **Full recombination** (DL + CR) to be demonstrated
 - Operation becomes more demanding in terms of stability
 - Review the performance and identify bottlenecks




Gun



- the source of a lot of down-time and problems this year
 - Heater power supply
 - Bias power supply
 - Bad contacts
 - Gun pulser
 - Cathode
 - Dark current
 - 2 vacuum leaks after solenoids on Oct 9 and Nov 20, caused by gun dark current, 6 and 5 days downtime
 - Stability and jitter





Gun – Current stability



- Current stability **crucial** because of full beam-loading in the linac

$$\frac{dV / V}{dI_{beam} / I_{beam}} = - \frac{I_{beam}}{I_{opt}}$$

1% current variation = 1% energy variation

- Also for other effects changing current (SHB phase switch, bunching variations)





Table 1: Parameters for the CTF3 gun for the nominal working point

Parameters	Unit	Initial and Nominal
Voltage (Running)	kV	140
Voltage (Conditioning)	kV	160
Pulse flat-top	ns	200 - 1600
Gun current	A	6
Max mean current	mA	0.5
Rise/ Fall time	ns	≤ 20
Charge flatness on flat top	%	≤ 0.1
Voltage stability $\Delta V/V$ for 200 to 1600 ns (flat-top)	%	≤ 0.1
Repetition rate	Hz	5


- Specification:
For the nominal working point (6 A), the possibility of a $\pm 5\%$ current modulation signal with bandwidth of up to 20 MHz is required.




Gun current variation



- We observed current variations caused by **HV change**
 - Small HV variations not obvious since acquisition is noisy
- Could trace them to the **gun regulation**:
for a high dark current
the gun changes from current to voltage regulation and lowers the HV to limit the current
- Could be fixed by increasing the threshold for switching
- But the problem reappeared ...







Energy variations and jitter



- Correlation between energy (hor position in dispersive region) and SHB02 loaded signal
- Stable SHB phases measured
- Gun current stable
- => other variation from gun, HV? but we **miss proper diagnostics**




- Periods of better or worse jitter, not understood why
- Jitter variations bigger than tuning variations
- Beam **very difficult** to **set up**
- Lower variations without 1.5 GHz SHBs => used 3 GHz beam




Dark current



- 2 Oct: high dark current after cathode change
- 9 Oct: vacuum leak after solenoid exit (CL.0405)
- 15 Oct: restarting, almost 10 mA dark current, try to fix
- 23 Oct: restarting commissioning
- 20 Nov: new leak at same location
- 25 Nov: restart, temperature probe installed
- **Conclusions:** Vacuum activity and local temperature at the leak
 - NOT correlated to
 - beam pulsing or not
 - RF on or off
 - BUT are correlated to
 - gun average current readings
- **Dark current (cw) from gun responsible for leaks**









Gun pulse shape



- Current pulse shape shows variations, ringing needs to be optimized






Gun - improvements



- With the present gun performance
 - It is extremely **difficult** to **set up** combination
 - It will be even more difficult with DL+CR and beam for CLEX!
- We certainly **need** a **consolidation** of the gun !
 - Review different power supplies
 - Add proper measurement signals to allow better diagnostic
 - Review the voltage regulation
 - Implement feedbacks as an upgrade?
 - Activate current modulation feature (in design) to compensate current modulation during SHB phase switch




Sub-harmonic bunchers (SHB)



- three 1.5 GHz SHBs fed by Traveling Wave Tubes (TWT)
- Required for DL operation
- 1 tube broke in May
- We have **1 spare tube** but **no spare amplifier**
- => amplifier has to be send to repair
2-3 month delay
- We were left with 2 SHBs for a large fraction of the run
larger satellite bunches
- Other point: no remote indication of status
we had periods of faults, not immediately obvious to operation







Klystrons + RF



- Need all 11 klystrons available reliably for proper operation
- Klystron trip consequence:
 - Direct down time
 - Recuperation time (for RF pulse compression)
 - temperature change in LIPS/BOC cavities
 - phase adjustment
- Set-up of power level with margin to avoid trips
- Important: proper conditioning at the beginning
- Plan in sufficient time in the schedule
- Remark: small team of specialists, very efficient but limited






Klystron - Spares



- Two klystrons failed due to charging power supply failures
 - MKS15 End Oct
 - MKS11 27 Nov
- **No spares** available
- Could continue operation but needed a completely new setup of the machine
=> several days time lost each time
- We need spares for these power supplies
- We also need spares for klystron tubes
- => Gerry's talk

- Option: install structures on girder 14 to **increase** linac **energy**
we need another modulator for this







Water station for LIPS/BOC



- Temperature control for RF pulse compression cavities
- Tuning very crucial
- Filter for one device got blocked twice
→ flow rate reduced, cavity detuned




- Regular maintenance + cleaning needed
- Regulation for some devices slower than others
=> needs regulation, evtl. change of feedback to include power dependance




RF pulse compression



- We had frequent problems with the waveform generators on one front-end computer
- Finally fixed by CPU card exchange
- Setting up improved by Hamed's software
- **Slow drifts** in compressed pulse shape
- Should invest time into automatic feedback to keep power constant
- A basic version for this exists but needs testing
- Combination for long beam pulse difficult due to energy variation over the pulse
- Need to review phase sag, eventually lower compression ration






1.5 GHz RF deflector (DL)




- Problem with reflected RF limiting power
- Difficult to diagnose
- Leak in the **water load**, no spare, had to wait for 1 month
- Driver amplifier for MKL02 was unstable at some time
- Could be regulated but there was no spare
- Pulse shape of pulse forming network of klystron MKL02 needs to be regulated




Quad scans + spectrometers



- Quad scans **essential for optics studies** and machine setup
- on girder 10 (for linac matching) during 2nd run
 - Al screen was damaged
 - Carbon screen did not give sufficient light
- Got repaired => widely used for linac matching
- **Screen control** + analysis software not optimum
- Spectrometer 10 screen has radiation hard camera => not enough light for energy measurement
- New segmented dump foreseen (=> Thibaut)
- We would profit from measurement software for energy







BPMs and WCMs



- We have different types of current / Beam Position Monitors (different chamber geometry) with different electronics
- **BPE**: electrostatic, in solenoids charge up during pulse, bias test not successful
- **BPM**: circular, **working very well** since the beginning
- **BPR**: RF BPM working well, one phase-shifter needs proper remote control
- **WCM** (Wall Current Monitor): working well, basically unused foreseen beam loss system








BPIs



- **BPI**: racetrack, similar to BPM, different electronics
- First version had a signal droop due to different low frequency cut-off
- CR BPMs overcompensated for droop during 1st run 2007




- Finally, also working very well (see next slide)
- But we had only $\sim 2/3$ of all BPIs in the CR until last period




BPI signal droop corrected



- Adjustment of electronics solved droop for current signal
- Still small droop for position signals left







BPM alignment



- DL and CR vacuum chamber has sparse bellows
- Difficult to align
- BPM **offsets** up to **15mm** measured
- Taken into account in software but still questionable
- Will be realigned during shut-down







BPM calibration



- We had quite some problems/confusion with the different type of BPIs concerning calibration
 - Different calibration windings
 - Different gain
 - Different signal treatment
- Doubts about position calibration
 - BPMs in CR show smaller position variation than BPI
 - Measurement data to be analyzed ..
- BPMs and BPIs used for many important optics studies
 - Dispersion
 - Corrector kick measurements







Slits + Stepping motors



- We use stepping motors for collimating slits and RF equipment
- Most have been upgraded to PLC control
- CK.MKS14-PHAS / -ATTN are not working remotely (still on old system, extremely slow – locally OK new system does not yet support this motor)
- Will be upgraded
- Slit calibration needs to be added






Magnets / Power supplies



- In general OK
- Startup after power cut / lock-out lengthy (1/2 – 1 day)
- Several power supplies without remote reading (after CPU card change – new EPROM version?) need to be verified
- Stability usually not verified (instability from gun dominant)
- We had some problems with polarities / calibration / control
- A complete field verification might be useful



Controls issues



• Operation console

- extremely **slow**, significantly slower than the old one
- often **unreliable**, the values are not updated, inconsistencies
- => we use the old one whenever possible


- Major upgrade improvement foreseen for 2008

• Front-end crates

- Frequent reboots
- Overloaded
- CPU cards will be upgraded
- Some other (little) things to be fixed (too detailed for here)
- Recent meeting with controls group to address this

The screenshot shows a control console window with a menu bar (File, Edit, View, References, Commands, Control, Programs, Help) and a status bar (Dec 06 09:32:58 SCT - SETUP). The main area displays a table with the following data:

RFMKSP	Stop Gun	Status	CCV	AQN	Unit	
CR.PHASBPR0505	Enabled	Standby	190.00	0.00	deg	
PTIM-V	Pulse	CCV	AQN	Start	Train	
CX.SMEAS-UMAR	Didn't ...	Didn't...	Didn't ...	CX.GENERAL-START	Didn't receiv...	
COMPAR	Status	Ref.	Unit	Aqn.	Unit	
CTF.CPSMUMAR	Didn't receiv...	Didn't recei...	CX.TRF	Didn't recei...	CX.TRF	
SAMPAQ	Cursor	Interval	Unit	Aqn at C	Mean C+I	Unit
CR.SVBPI0130S-C	Server 'd...	Server 'd...	...	Server 'dc...	Server 'dc...	A
CR.SVBPM0155S-C	Server 'd...	Server 'd...	...	Server 'dc...	Server 'dc...	A
CR.SVBPM0195S-C	Server 'd...	Server 'd...	...	Server 'dc...	Server 'dc...	A



Conclusion



- Operation becoming more and more complex
- We suffered from a lot of down-time and problems
- For smooth commissioning, we need
 - Higher availability of the components, SPARES are vital !!!
 - Higher reliability of the equipments
- Gun
 - Jitter problem not completely understood
 - Review / consolidation required
- RF
 - Assure availability => sufficient spare parts
 - Proper conditioning
- Then we should manage the combination DL + CR
- We are only now starting to address performance
- Automatic measurement + analysis programs very helpful