



Mechanical problems for a Ni-alloy reinforced Bi-2223/Ag conductor

-Towards a super-high field and compact size NMR magnet-

M. Nawa^{1,3}, Y. Yanagisawa^{1,3}, H. Nakagome¹, K. Kajita^{2,3}, T. Takao², H. Maeda³

¹Chiba University, ²Sophia University, ³RIKEN





How to prevent the buckling?

400

600

Time (s)

The composite conductor was buckled

caused by the release of the internal strains


800

1000


1. Winding tension

200

Prevent the buckling with winding tension in the coils?




Winding tension is




3 : Buckling

Bi-2223/A



i-Cr reinforcement




Transverse stress (kPa)


Bend radius dominates

the reduction of critical current

R=3.1 (mm)



13.0 (kPa)



R=8.6 (mm)

600 [μm]

600 [μm]

Conclusion

- 1. The high strength Bi-2223 conductor is buckled by the release of the internal strain due to temperature rising.
- 2. A low transverse compressive stress can prevent the buckling.
- 3. Methods to prevent the buckling in a coil is being investigating.