

- ➔ Report on MicroFip™ problems
 - Field-bus coupler type DQAMGS (new QPS layer)
 - Using latest MicroFip™ and FIELDRIVE™ (line driver) version
 - Data are still readable but no longer updated
 - Problem could be caused by both components
 - Power cycle (triggered via an old MicroFip™ version!) re-establishes communication correctly

Event	Date and time	Dose [Gy]	Fluence [10^9 ncm ⁻²]
1	2009-06-21 02:29:40.870	0.179	7.7
2	2009-06-22 17:44:48.070	0.017	0.8
3	2009-06-23 23:44:38.470	0.110	4.7
4	2009-06-25 05:29:55.270	0.088	3.8
5	2009-06-28 18:29:57.670	0.329	14.2
6	2009-06-30 07:44:54.070	0.077	3.3
7		0.80	34.5

→ Estimates:

- ~9 events /Gy device → 9 events /year device in LHC arc → 4050 events / year (450 devices in LHC arcs) → 20 events / day (assuming 200 days operation with beam) → not acceptable

→ Possible workarounds:

- Option 1: firmware upgrade to detect loss of communication in the field
 - Re-initialization of chip and hard reset of line driver via MicroFip™
 - No modification of field-bus coupler hardware
- Option 2: hard reset of MicroFip™ via microcontroller
 - Minor modification of field-bus coupler hardware
- Option 3: power cycle of MicroFip™ triggered by microcontroller
 - More complex but still feasible hardware modification
- Option 1 and 2 to be tested in CNGS

→ Future developments:

- Software compatible radiation tolerant replacement of MicroFip™ and FIELDRIIVE™ needed