




Calorimeter ReadOut Card Shielding

Bernard Debennerot, Olivier Duarte, Jacques Lefrançois, Frédéric Machefert, Pascal Rusquart



Noise observed at 1MHz






- During the 1MHz tests performed in June, some extra noise was observed systematically on a single FEB of each crate
- The FEB is located on the left of the CROC board. Two regions of the FEB looked more affected.
- The RMS of the noise of the worst channels reached up to 3 and 4 ADC in the two concerned regions (to be compared to 1.2)



Identifying the origin of the noise (I)



- On the worst channel, a structure appears
- A first test was performed at 1MHz
 - CROC configured to disable half a crate → one of the two noisy regions disappeared
 - Noise was linked to the data transfer between the CROC and the optical emitter
- Optical emitter looked as a good culprit
 - The metallic cover of the emitter is not connected to the ground...
 - The two regions would correspond to the two emitters of the CROC
 - The emitter are not exactly but almost facing the delay line of the FEB (delay line = good antenna?)





Identifying the origin of the noise (II)




- But then, we should be able to "see" the noise with an oscilloscope looking at the signal input of the FEB (one of the two "ends" of the delay line)
- We tried to configure the test bench in a way such that we could reproduce the noise observed at the pit
 - We have never been able to do so
 - We had to work at the pit and launch 1MHz runs
- Finally even by averaging the oscilloscope signal over a large number of samples, nothing relevant appeared
- Optical emitters were too good culprits : we had to look for something else
- Jacques imagined that RC circuits on the FEB could be a good antennas
 - Circuit is outside the ASIC, on the signal path, between the buffer and the integrator
 - We have some lines at the surface of the CROC to feed GOLs facing those RC
 - 2 groups of such lines
- We made a crude shielding with a double sided scotch and a layer of copper
- Noise disappeared on the Calo event display (1MHz runs)



Shielding and intervention





- Shielding designed at LAL
- A PCB layer (P. Rusquart)
 - 0.3mm thickness
 - 35μ Cu on external surf.
 - Thin layer of silver (polishing)
 - Use the optical mezzanine plastic screws (x6)
 - Soldered to the ground of the LEMO connectors of the CROC
- 32 Layers bought
 - Made in a month
 - Received on Sept. 2nd, 09
- First test on Sept. 3rd at the pit
 - Noise disappears
- Shielding of ALL the CROC on Sept. 4th, 09



Conclusions



- The CROC have been shielded
 - No problem after re-installation of the boards
 - Configuration of ECAL/HCAL/SPD-PS crates
 - 1MHz test with ECAL/HCAL → noise has fully disappeared
 - Stéphane / Daniel started to control SPD-PS → looks ok
- The operation took a bit more than one day
- The CROC have been put in their original crates → no effect for the user
- We used this access to correct problems on some FEB
 - 1 board to debug (ADC bit stuck at 128) and replaced → crate 9 / slot 3
 - 1 board fixed (transistor ripped off) straight away → crate 9 / slot 11
 - About ten cables/connectors fixed