



Fracture Failure Analysis for MQXF Magnet Aluminum Shells

H. Pan, E. C. Anderssen, G. Vallone, E. T. Takala, P. Ferracin, D. W. Cheng, S. O. Prestemon, G. Ambrosio



Mon-Mo-Po1.03-02

Abstract: The High-Luminosity LHC Accelerator Upgrade Project (HL-LHC AUP) is approaching the production phase of the US-contributed Q1 and Q3 Interaction Region Quadrupoles (MQXFA). The structures for the MQXFA prototypes were design and inspected by the US-LARP (LHC Accelerator Research Program), AUP developed criteria, which will be used for the pre-series structures. As the first two full-length prototypes with 4.2 m magnetic length, MQXFAP1 and MQXFAP2, were designed and assembled at Lawrence Berkeley National Laboratory (LBNL), and tested at Brookhaven National Laboratory (BNL). The end aluminum short shell of MQXFAP2 was fractured along the shell length during the test, and tests were stopped. Analytical and Finite Element analysis were performed in light of the graded procedure defined in the Structure Design Criteria to investigate the fracture failure for MQXFAP2.

In this paper, we report the fracture analysis of the current shell design, including the elasto-plastic simulations with sub-model technique, and calculations with Linear Elastic Fracture Mechanics (LEFM). Test material properties are also presented. The results of this analysis explain why the end shell of MQXFAP2 failed, and suggest fillets on the end shell notches to meet the margin specified in the Structural **Design Criteria.**


Introduction

The MQXFA magnet is the first prototype that has a 150 mm aperture and uses Nb3Sn superconducting technology in a 4.2 m magnetic length structure.

As same as the previous LARP HQ and MQXFS magnets, MQXFA magnet has the same cross section, and relies on the pre-tension of the aluminum 7075-T6 shell, which is pre-loaded at room temperature with the bladder-and-key technology.


The cold test of MQXFAP2 was stopped by a notable unstable structure behavior, which was identified fracture failure on the end shell. A longitudinal crack was plainly evident in the RE end shell. The shell displaced by approximately 15 mm axially, and rotated also about 0.5°. The fractured surface appears rough, and no "fatigue-induced" cyclic rubbing appears present based on microscope checks.

MQXF Magnet Parameters




Fracture Failure of the MQXFAP2 End-Shell












Fracture Analysis and Shell Redesign



- The size of the plastic zone of the cut-out of the MQXFAP2 end shell is close to the critical flaw size with a real corner radius on the level of 0.02 mm.
- It's apparently that the weld block cut-out of the MQXFAP2 end shell does not meet the load factor requirement.

