

Internal Review of the LHC Machine Protection System: The Beam Dumping System

Jan Uythoven
For the LBDS Team

LBDS Statistics 1 March to end April 2010

(No time to update, but conclusions are still valid)


● **Beam 1:**

- 1689 Dumps
- XPOC false 13 %
 - -/- Tests (10 %)
 - -/- Loss (1.6 %)
- **1.1 % real XPOC faults left**
- **5 Internal Dump requests**
or system faults
 - 0.3 %
- Energy distribution:
 - 1459 at 450 GeV
 - 54 at 3.5 TeV
 - 11 at other energy
 - 165 Test (no energy)

● **Beam 2:**


- 1715 Dumps
- XPOC false 10 %
 - -/- Tests (7.6 %)
 - -/- Loss (1.1 %)
- **1.6 % real XPOC faults left**
- **11 Internal Dump requests**
or system faults
 - 0.6 %
- Energy distribution:
 - 1531 at 450 GeV
 - 55 at 3.5 TeV
 - 10 at other energy
 - 119 Test (no energy)

Total of False XPOCs, B1 + B2: 92



- BLM: Beam in the abort gap or losses at injection
- BCTFR: No data
- BLM data: No data
- Operator: Dumped with BIS loop open
- MKD XPOC: MKD generator 'drifts'
- Vac: No vacuum data
- Soft: Analysis error in MKD module


Relative Change XPOC error April vs. March [%]



Since 'Direct Get' on FBCT: OK
 Only no data when FE is down
 (about once per week).


Total of Internal Faults B1 + B2: 16

LBDS Internal Faults: total 16



- Vacuum: Vacuum glitches MKB interlock, filtered
- IPOC ADC: cards failing, all cards replaced
- PTU PC: problem C, all exchanged
- Main PC: Stability problem
- PC: 5 V or 15 V, replaced
- Switch: surveillance problem, switch was ok

Relative change internal faults April vs. March [%]




Vacuum glitches are now filtered. Only once error, last week, when glitch > filter time constant (some seconds)

Beam Dumps Statistics

- At the moment almost all false XPOC are due to beam in the abort gap giving losses above XPOC BLM thresholds
 - 1.0 – 1.5 % of all dumps
- Internal faults due to hardware was about 0.5 % of dumps
 - MKB vacuum glitches: now filtered
 - IPOC ADC – now all replaced
 - PTU failures – now all replaced
 - PC stability (main and compensation power converter)
 - 5 V power converter – all replaced
 - 1 switch surveillance failure
- (Sub)systems changed BEFORE real failure due to early indication by XPOC:
 - Three MKD generators were exchanged after ‘bad trends’ detected with XPOC. Inspection has shown contact erosion problems

XPOC trend and error leading to generator exchange last technical stop

Low. Limit




Reference generator O R_end : 1.40 +/- 0.5 %

References gen M: 1.25 %, gen C 0.85 %, gen E 0.69 %

Conclusions: All R_end references dropped, but most on the replaced generator O.
On top of this: generator O had this sudden drop given false XPOCs.

Definition of XPOC R_End

R_END	= 100 x (I_END - I_REF100PCT) / I_REF100PCT	%
-------	---	---



XPOC

- New modules: BTVDD, BPMD, BCT, TSU
 - Operational in 'dev' but difficult to get going reliably...
 - Stability of some BI data
 - Optimisation of applied limits and algorithms
 - New modules help the understanding if things go wrong
 - Should we operate this with tight limits and get many faults?
- PM GUI being extended with more detailed information
- XPOC users GUI being overhauled
- Reset by EIC in case of false XPOC due to unbunched beam

MKD generator performance / exchange


- Two generators replaced during winter technical stop
- One generator replaced week 22 (**generator O last slide**)
- Performance degradation detected by XPOC
- Found GENERAL problem with erosion of contacts – degradation
 - Recall program
 - Check all contacts and connections
 - Redefine torque etc. for the different contacts
 - Need to make modifications in laboratory
 - Replace 2 spares at each technical stop 2010
 - With 4 spares available in 2011, can replace up to 4 generators at each technical stop

Full detailed procedures for generator exchange still missing

Contact erosion series diode stack not sufficiently tightened




Contact erosion on Exit Box
Replaced on 18 out of 30 generators installed



MKB

- Generators (2008 – 2009)
 - Damaged multi-contact on the multi-chip diode which is in parallel with the GTO stack. Solution: multi-contact replaced by soldering
- Magnets (2008 – 2009)
 - Breakdown on araldite insulators between forward and return path of MKB magnet. Solution: insulators replaced by ceramic ones (MKI type)
 - Damaged ground connection of MKB coil. Solution: redesign of the contact and stronger contact tightening
 - Cracks of the MKB coil insulation. Solution: coils ends remoulded with different araldite filler (silica rather than dolomite)
- Vacuum pressure false interlock due to noise on signal solved by filtering and voting solution, but still need to find out why noisy signal



MPS related 'exercises'

- **External** review follow-up 15th June 2009
- MPS system checks with and without beams
 - Following procedures edms document 896392
 - Progress filled in on the Web
 - Conclusions fed into **Internal** review:
- **Internal** review 4th May 2010

External LBDS review follow-up 15th June 2009

- 27 out of 47 recommendations of the initial review of January/February 2008 were implemented at that time
- Others under implementation 2009. 'Confident will be followed up'
- Impressed by XPOC/IPOC
- Concerns:
 - Faulty timing transmission RF
 - **Done**: Now check in place in sequencer
 - FPGA code review and FPGA test bench
 - **On-going** for TSU.
 - Depending on experience will do for other systems (BETS)


Issues from LBDS internal review 4th May 2010

- rMPP invited to participate
- In view of LHC intensity progression:
 - Review critically the system and the problems occurring;
 - Identify any potential issues which could compromise machine protection functionality;
 - Define the short- and medium-term actions needed for the system and its commissioning.
- Identified issues with equipment, controls, SW, procedures, commissioning, operation.
 - 38 TOTAL actions generated (15 completed, 9 in progress)
 - **14 items with MP repercussions (8 completed, 3 in progress)**

14 items with MP repercussions





1. F_rev check in sequencer before arming: **DONE**
2. Formal validation procedures of system after technical stop: **TO DO**
3. Damaged re-trigger resistors (see before): replacement **ONGOING**
4. Erosion of contacts: replacement program for next two years **ONGOING will take long time but trends visible on XPOC**
5. BLMs needed to quantify some MP tests already made: **TO DO, RC filters on some BLMs point 6 installed, but need analysis**
6. Protected sequences and unskippable tasks **ONGOING**
7. TCDQ software issues for movement **DONE**
8. TCDQ position settings check can't be done, software precision issue **ONGOING**
9. Debunched dumps at 450 GeV with $1e11 p^+$ & analyse: **DONE**
10. Set-up TCSG/TCDQ at 450 GeV and 3.5 TeV: **TO DO**
11. Aperture measurements in Point 6: **DONE**
12. BLM calibration: **DONE** TCDQ **TO DO** TCT
13. MPS test: system off and RF frequency interlock: **DONE**
14. Understand why 15 x 1 MKD knob did not cleanly extract: **Done**

Beam Dump Performance

- No single beam dump happened which would have lead to any damage with unsafe beam
- No asynchronous dump happened since TSU fix 2009
 - Many dumps with unbunched beam to check performance of protection – see talk Wolfgang
 - Expect about two asynch. dumps per year
- All errors have been seen by surveillance!
- Measurements which give confidence in system 

LSS6 Aperture and Dump Lines


Apertures according to Models



Position of dumped beams on BTVDD (in front TDE) according to calculations


TD68.BTVDD.689339.B1

2010/03/24 03:23:34.600000




TD62.BTVDD.629339.B2

2010/03/24 03:23:34.600000



MSD Septum Calibration

Measured vertical beam positions



Measured position after technical stop. As expected the error at 450 GeV increased. Actions:

- Recalibration MSD hall
- Check hysteresis MSD
- Effect of MKB

Before change MSD calibration curve in LSA during technical stop 27/4/10

Interlocked Beam Instrumentation

- **Interlocked BPMD References**
 - Were set-up once in the beginning of the 2010 run.
 - Ascension weekend 15th May lost 2 ramps on BPMD interlocks
 - Changed `lhcbpmsb.b4l6.b2` from il values $-0.26/+6.94$ mm to $-2.0/4.0$ mm. This seemed to be closer to trajectory around which collimators and TCDQ were set-up at that time
 - Needs now to be revisited – check with dump from positions at limit of interlock position and maximum angle:
 - Take into account BPM sensitivity for different bunch intensities
 - ‘Final’ reference trajectories, squeeze etc.
- **Direct Interlocked BLM** (not via BIS)
 - Not tested

Conclusions

The Positive Side

- No asynchronous dumps since 2009 TSU problem solved. No dumps which would have caused damage with unsafe beam
- All failures detected by XPOC or Internal Interlock, requiring expert acknowledge
- System generally well understood:
 - MPS checks passed
 - Aperture as expected
 - Dump figure as expected

Conclusions

The Negative Side I

**In RED: Required for Stable Beams
with few bunches of $1e11$ at 3.5 TeV**

- Worries about MKD generator contact erosion
 - But so far always slow trend caught by XPOC
 - Replacement program started but will take into 2011
- Outstanding work:
 - **Interlocked BPMD verification** and Direct BLM check
 - Dumped beam vertical offset at 450 GeV: MSD
 - Detailed check of RC filters BLMs point 6
 - New XPOC modules
 - See talk Wolfgang on dump protection:
 - **Set-up of protection with $1e11$ p⁺ plus verification**
 - **Abort gap monitoring and cleaning operational**

Conclusions

The Negative Side II

- **The Human Part = Weakest Link**
 - Sequencer, unskippable tasks etc.
 - This has to guarantee the hardware settings applied to the system, that the previous XPOC was ok etc.
 - Procedures
 - For coming out of access, after intervention
 - For making generator exchange, tests to be made, checking cables
 - For resetting XPOC, for resetting faults of beam dump equipment

Additional Slides

MKD issues above 5 TeV beam energy: Not an issue for present operation

- Corona discharge along side switch
 - Solution to be installed 2010/2011
- Effect of radiation on switches at high voltages
 - Measurements to be made
 - Upgrade of number of GTO will be difficult in 2012 shutdown
- Cooling of MKD generators not sufficient when running for a longer period at 7 TeV beam energy

