Current Status of **Nanometer Beam Size Monitor** for ATF2

TIPP 2011 Chicago, 11 Jun. 2011


Yohei Yamaguchi M. Oroku, J. Yan, Y. Kamiya, S. Komamiya T. Yamanaka, T. Suehara T. Okugi, N. Terunuma, T. Tauchi, S. Araki, J. Urakawa

Shintake Monitor's largest difficulty at present

= Laser crossing angle mode switching

- What's mode switching ?
 Obstacles in mode switching
 Strategies for resolving difficulty

Mode switching




During mode switching, two laser beams must be realigned at the IP using different laser paths

The modulation must be reconstructed from scratch

For good interference fringe contrast, laser pathway requires alignment precision of a few microns

Otherwise, we lose the signal modulation





Interference fringe pitch (d) depends on laser crossing angle θ

$$d = \frac{\pi}{k\sin\frac{\theta}{2}}$$

Measurable beam size range (proportional to fringe pitch) **controlled by mode switching**


2-8, 30 and 174 deg crossing modes





Mode switching causes sudden modulation drop

 \rightarrow Modulation is easily lost during mode switching



For example: In 2010 we could not reconstruct modulation when switching to 30 deg mode

Beam Tuning

Main cause for losing modulation: signal jitter > modulation depth


No signal jitter Large signal jitter 30 signal signal 25 25 20 20 15 15 0 10 10 5 5 0¹ 0¹ 10 12 14 phase [rad] ¹² phase [rad]

2

8

10

10 Jun. 2011 Current Status of Nanometer Beam Size Monitor for ATF2 TIPP2011



Large signal jitter hinders modulation reconstruction

High BG

increased 10 times from early 2010

Low signal

decreased down to 1/5 of early 2010

Laser orbit fluctuation

Beam size jitter

typically 20%

Other jitter sources

High BG

increased 10 times from early 2010

Low signal

decreased down to 1/5 of early 2010

Laser orbit fluctuation

Beam size jitter typically 20%

Other jitter sources

early 2010: tentative large $\beta_{y(x)}^*$ beam optics

optics with design $\beta_{y(x)}^{*}$

High BG

increased 10 times from early 2010

Low signal

decreased down to 1/5 of early 2010

Laser orbit fluctuation


Beam size jitter typically 20%

Other jitter sources

bending magnet


Bremsstrahlung generated at final bending magnet can enter gamma detector

Plan to install additional collimator to cut this radiation



gamma detector

bending magnet Bremsstrahlung



High BG

increased 10 times from early 2010

Low signal

decreased down to 1/5 of early 2010

Laser orbit fluctuation

Beam size jitter typically 20%

Other jitter sources

bad laser profile

design spot size: 10 μm measured spot size: 20 μm affects local laser power density at IP

Total laser pulse power and beam current are satisfactory

High BG

increased 10 times from early 2010

Low signal

decreased down to 1/5 of early 2010

Laser orbit fluctuation

Beam size jitter typically 20%

Other jitter sources

laser orbit fluctuation

- suspected to be a dominant jitter source
- under evaluation with Position Sensitive Detectors
- hardware upgrade for stabilization is going on



High BG

increased 10 times from early 2010

Low signal


decreased down to 1/5 of early 2010

Laser orbit fluctuation

Beam size jitter

typically 20%


Other jitter sources



Beam size fluctuation can cause signal instability

This can be constantly monitored by...
 1. beam profile monitor

2. Q-magnet current monitor



High BG

increased 10 times from early 2010

Low signal

decreased down to 1/5 of early 2010

Laser orbit fluctuation

Beam size jitter typically 20%

Other jitter sources

<Checked>

- 1. relative position jitter < 200 [mrad] (8 deg mode)
- 2. laser power fluctuation
 0.9 % (May 2010)
 2 % (Dec. 2010)
- 3. beam current fluctuation2 5 % (measurement resolution)
- 4. laser timing fluctuation
 600 ps (May 2010)
 900 ps (Dec. 2010)
 (pulse width: 8 ns (FWHM))

These are negligibly small

High BG

increased 10 times from early 2010

Low signal


decreased down to 1/5 of early 2010

Laser orbit fluctuation

Beam size jitter typically 20%

Other jitter sources

<Still Checking> **1. beam trajectory fluctuation** can be measured with BPMs and correctable



High BG

increased 10 times from early 2010

Low signal


decreased down to 1/5 of early 2010

Laser orbit fluctuation


Beam size jitter typically 20%

Other jitter sources

<Still Checking> 2. signal separation from BG using shower development in gamma detector degraded when BG spectrum changes



Example of hardware upgrade: laser orbit stabilization




laser orbit feedback system with PSDs and mirror actuators



stabling and monitoring laser system temperature

vibration removal in laser transport


laser position fluctuation at IP ${\sim}10~\mu m {\rightarrow} {\sim}1~\mu m$



We are commissioning 30 deg mode...


Because mode switching is challenging...

long time is needed to detect modulation when switching to 30 deg mode



Detecting modulation takes time \rightarrow beam and laser become unstable Time taken should be below 1 hour

After hardware upgrades, we can switch modes quicker and easier



Status and plan

Commissioning 30 deg mode then 174 deg mode

Suppressing signal jitter is important

Main candidates for signal jitter at 8 deg mode are...

- 1. high BG from bending magnet
- 2. bad laser profile
- 3. laser orbit fluctuation

To suppress the jitter, we are upgrading our system **The upgrade will finish by this autumn**


Beam trajectory fluctuation is significant for 30 deg mode At 100 nm beam size, beam trajectory jitter must be below 50 nm IP-BPM resolution must be below 30 nm


Recovery from the earthquake

We improved earthquake resistance of our system.

Performance of all devices are being inspected

laser	realigned oscillator working well
DAQ	still being checked
control system	working well
gamma detector	still being checked
optical system	being realigned
monitors for laser	still being checked





Summary

Signal modulation can easily be lost during mode switching


Resolution degradation due to signal jitter hides the modulation


Sources of signal jitter are under investigation

Hardware upgrades for 30 deg mode are undergoing

We will finish upgrading and be ready to measure under 100 nm beam size by this autumn

backup





How to evaluate the **relative position jitter**

This plot shows the interference scan

This plot shows the phase difference between the graph points and the fitting curve

From this plot, We evaluate relative position jitter

How to evaluate the **relative position drift**

