# Radiation protection issues at the PS linked to MTE and CT operation

M. Widorski, DGS/RP

# Summary

- Measurement by induced activity monitors
- Evolution of induced activity in the PS tunnel
- Stray radiation impact

HSE

Occupational Health & Safety and Environmental Protection Unit

### Induced Activity Monitors




• In sections:

9, 16, 31, 37, 39, 42, 63, 75

- Intended measuring range:
  - 0.02 ~ 400 mSv/h
- No beam loss monitors !
- Following slides: Measured values in 2009 and 2010


Radiation protection issues at the PS linked to MTE and CT operation

#### Radiation detectors PS



Radiation protection issues at the PS linked to MTE and CT operation


#### PMIPS16 - 2009



DGS/RP

Radiation protection issues at the PS linked to MTE and CT operation


#### PMIPS16 - 2010



DGS/RP

Radiation protection issues at the PS linked to MTE and CT operation


#### PMIPS16 - 2010



DGS/RP

Radiation protection issues at the PS linked to MTE and CT operation

#### PMIPS09 - 2009




DGS/RP

Radiation protection issues at the PS linked to MTE and CT operation




#### PMIPS09 - 2010



DGS/RP

Radiation protection issues at the PS linked to MTE and CT operation


#### PMIPS31 - 2009



DGS/RP

Radiation protection issues at the PS linked to MTE and CT operation


#### PMIPS31 - 2010



DGS/RP

Radiation protection issues at the PS linked to MTE and CT operation


#### PMIPS37 - 2009



DGS/RP

Radiation protection issues at the PS linked to MTE and CT operation


#### PMIPS37 - 2010



DGS/RP

Radiation protection issues at the PS linked to MTE and CT operation


#### PMIPS39 - 2009



DGS/RP

Radiation protection issues at the PS linked to MTE and CT operation


#### PMIPS39 - 2010



DGS/RP

Radiation protection issues at the PS linked to MTE and CT operation


PMIPS42 - 2009



DGS/RP

Radiation protection issues at the PS linked to MTE and CT operation


#### PMIPS42 - 2010



DGS/RP

Radiation protection issues at the PS linked to MTE and CT operation


#### PMIPS63 - 2009



DGS/RP

Radiation protection issues at the PS linked to MTE and CT operation


#### PMIPS63 - 2010



DGS/RP

Radiation protection issues at the PS linked to MTE and CT operation


#### PMIPS75 - 2009



DGS/RP

Radiation protection issues at the PS linked to MTE and CT operation

#### PMIPS75 - 2010



DGS/RP

Radiation protection issues at the PS linked to MTE and CT operation


#### Evolution of dose rates in 8 PS sectors

Monitor	01/02/10	09/05/10	29/05/10	19/06/10	16/07/10	05/08/10	30/08/10	13/09/10
PMIPS09	0.2	0.3	0.5	0.8	0.6	0.8	0.5	0.7
PMIPS16	0.4	30.8	20.5	15.3	12.7	13.7	13	14.9
PMIPS31	0.4	0.45	10.2	12.1	9.2	11.6	10.1	13.7
PMIPS37	0.9	0.8	5.8	6.6	5.2	6.5	5.6	6.7
PMIPS39	1.3	1.1	7.4	7.3	6.3	8	7.4	6.6
PMIPS42	0.9	5.5	7.8	6.3	4.7	6.1	5.3	7.8
PMIPS63	0.2	0.2	0.5	0.7	0.5	0.4	0.5	0.6
PMIPS75	0.3	0.6	1.8	1.9	1.4	1.8	1.5	2.1

Data taken 1-2 hours after beam stop  $H^*(10)_{PMI}$  [mSv/h]

Radiation protection issues at the PS linked to MTE and CT operation


#### Evolution of dose rates in 8 PS sectors



Radiation protection issues at the PS linked to MTE and CT operation

- MTE: high impact on SS16, other sectors much less affected
- SS42 is mostly depending on injected intensity, not on MTE (CT has a certain impact, but not visible from this data)
- CT has a high impact on a big number of sectors (31 onwards)
- CT has smaller impact on SS16 than MTE


#### Radiation detectors PS



Radiation protection issues at the PS linked to MTE and CT operation



## Linac 3: PAXS14 (2009)



DGS/RP

Radiation protection issues at the PS linked to MTE and CT operation




#### Stray radiation in LINAC 3



Radiation protection issues at the PS linked to MTE and CT operation



# Linac 3: PAXS14 (2010)




DGS/RP

Radiation protection issues at the PS linked to MTE and CT operation



## CT beam losses in SS16




PAXS35

- Red dots = CT + MTE (2009)
- Blue dots = CT (May 2010  $\rightarrow$  )
  - Maximum and average dose rate were reduced compared to 2009
  - Effect of shielding wall visible but less than expected factor (complicated geometry, multisource case)
  - Less problems in CT ejection in 2010 (?)

Radiation protection issues at the PS linked to MTE and CT operation

## CT and MTE beam losses in SS16


Correlation PAXS35 - PAXS14



- Red dots = CT + MTE (2009)
- Blue dots = MTE only (beginning 2010)
  - Higher correlation between PAXS35 and PAXS14: Losses from MTE are much more 'targeted'
  - Same average value for PAXS35, lower value for PAXS14


Radiation protection issues at the PS linked to MTE and CT operation

#### Survey SS16-FT16 (17/12/2009)




Radiation protection issues at the PS linked to MTE and CT operation

#### Survey SS16-FT16 (01/06/2010)



Radiation protection issues at the PS linked to MTE and CT operation


#### Detailed measurements SS16/FT16



Radiation protection issues at the PS linked to MTE and CT operation

HSE Occupational Health & Safety and Environmental Protection Unit

# Shielding on top of SS16




DGS/RP

Radiation protection issues at the PS linked to MTE and CT operation

# Stray radiation from weak top shielding in SS16

#### Measured ambient dose equivalent rate *H*\*(10)



#### Consequences


- At present beam intensities, annual dose to workers in some centre-of-ring offices exceed 100 µSv/year
- Offices close to PS justified only for work in direct relation with PS operation
- Similar issue for CT extraction
- Impact reaching further on a number of office buildings at the PS complex (getting closer to justification level)

HSE

Occupational Health & Safety

and Environmental Protection Unit

#### Stray radiation monitors on site Occupational Health & Safety and Environmental Protection Unit




HSE

Radiation protection issues at the PS linked to MTE and CT operation




# PMS128N (PS ring, SS31)



DGS/RP

Radiation protection issues at the PS linked to MTE and CT operation


### PMS129N (behind Booster)



Radiation protection issues at the PS linked to MTE and CT operation




### PMS123N (close to fence)



Radiation protection issues at the PS linked to MTE and CT operation



### PMS122N (Rest. 2)



DGS/RP

Radiation protection issues at the PS linked to MTE and CT operation

#### Conclusions

- MTE operation much cleaner than CT in all parts of the PS ring, except SS16. As such, MTE is clearly preferred to CT (if SS16 problem solved) !
- Only reason against MTE:
  - High losses in SS16 → leading to too high activation levels and increased stray radiation levels outside tunnel. SS16 is the less shielded location at the PS !
  - Activation is critical in terms of intervention time for septum and magnet replacement → no MTE possible with current losses
- Actions:
  - Reduce losses (minimum factor 2-3) or concentrate losses in uncritical well-shielded sector
  - Increase shielding on top SS16
  - Study and integrate improved shielding at door 122
  - Review usage of Linac 3 area and building 151 (RF workshop)