
## PS Report W28-29



Many thanks to: Fernando, Marc, Patrick, Mike, Antoine, Thierry, Pieter, Alvaro, Didier, Thibaut, Denis, Frank, Raul, Vincent, Fabrice, Abdel, Oliver, Stephane, Jeroen, James, Yves, Fulvio, Quentin, Gilles, Jean-Marc, Todor, Carlo, Heiko, Alexander, Alexandre, Matthew, Ana, Olivier, Dominique, Anthony, Hannes, Ben, Bettina, Klaus, Gil, Benoit, Ewen, Gerd, Tom, Anti, Guillaume, ...

## **Accelerator Fault Tracking (AFT)**





### **Beam stops**

- Need to replace gap relay of the C10-36 (currently running without spare) and C10-76
- Put in place the plexiglass protection box on the W8L
- Few additional minor interventions could be done in parallel
- $\rightarrow$  Done, planned intervention with no beam on Tuesday (20/07), 14h00-16h30
- Beam stopper FTN.STP428 blocked on Wednesday (21/07) evening
- No beam for nTOF for one night
- → Intervention in shadow of SPS stop on Thursday (22/07) with no beam 8h00 to 10h00
- → Pneumatic valve was blocked
- → IGBT in modulator of Linac4, no beam until ~11h30

#### **Activities of last week**

#### Optimisation of operational beams

- Loss reduction by ~50% on AD beam by optimising working point at extraction, and improving longitudinal settings for transition crossing and batch compression
  - ◆ Transmission through FTA worse compared to 2018, being followed up with AD team
- Nominal TOF bunch length achieved by adjusting rotation at extraction, beam loss reduced by optimising working point at extraction
- AWAKE single bunch available at 30x10<sup>10</sup> p and already taken by the SPS


#### TOF DSO tests on Thursday 15/07 and Friday 16/07


- Tests couldn't be completed immediately on Thursday morning (objects left in the area, cabling issue with beam imminent warning)
- Issues resolved during the day on Friday —> beam permit signed
- W8L repair and access in the shadow of the DSO tests
  - ◆ Electronic card (crowbar control) found to be damaged inside the W8L converter
  - Presence of dust might be a reason for the failure —> cleaning campaign of the converters in this room to be envisaged
  - Repair of C66 amplifier, SEH23 calibration, bumper and septum in SS61





#### Beam to nTOF

- First beam sent to the new nTOF target on Monday 10am
  - First shots didn't reach target due to wrong settings on FTN quadrupoles —> settings generation to be put in place
  - New SEM grids upstream the target worked immediately
  - Intensity of 200x10<sup>10</sup> ppb to be used during the early commissioning phase
- Intensity increased to almost nominal (700x10<sup>10</sup> ppb) with fewer cycles
  - Quadrupole scans to optimize beam size on target
  - Compromise between transverse size and losses to be discussed











# **Summary of operational beams**

Fixed target beams	Status	Comment
SFTPRO (core only)	Operational	Delivered to SPS at $^{\sim}67 \cdot 10^{11} \text{ p/p}$
SFTPRO (5 turn extraction)	Operational	<b>2 - 5</b> $\cdot$ 10 <sup>12</sup> ppp delivered to SPS, <b>up to 1.5</b> $\cdot$ 10 <sup>13</sup> ppp
AD	Operational	1.4 · 10 <sup>13</sup> p
TOF	Operational	8 · 10 <sup>12</sup> ppb
EAST	Setup	Basic setup, dedicated studies ongoing to improve extraction control
LHC-type beams	Status	Comment
LHCPROBE, LHCINDIV	Operational	
LHC25 (72b)	Operational	Polished up to $1.3 \cdot 10^{11}$ ppb setup at $2 \cdot 10^{11}$ ppb $e_h$ (C2595 flat-top) $\approx$ 2.1 mm mrad $e_v$ (C2595 flat-top) $\approx$ 1.8 mm mrad
LHC25 (12b or 24b)	Temporary	3 BP cycle delivered to SPS
LHC25 BCMS (48b)	Operational	Polished up to $1.3 \cdot 10^{11}$ ppb
AWAKE	Operational	3 · 10 <sup>11</sup> ppb, adjusted extraction bump compensation





### Questions and Comments

### PS Supervisor of the week 29 – Heiko Damerau



8:45 Daily Zoom meeting during beam commissioning

Web address: <a href="https://cern.zoom.us/j/9372114100?pwd=L29BcmlHUENCdFBRSytXYVcrM1B4Zz09">https://cern.zoom.us/j/9372114100?pwd=L29BcmlHUENCdFBRSytXYVcrM1B4Zz09</a>

Meeting ID: 937 211 4100

Passcode: 525463