Machine Protection during Beam Commissioning

J. Wenninger

See also earlier presentations at LMC by:

- R. Assmann on Collimation
- B. Goddard on Injection and Dump

Acknowledgements:

B. Puccio, B. Todd, M. Zerlauth, B. Goddard, J. Uythoven & LBDS + injection team, M. Meddahi,
R. Assmann & Collimation team, B. Dehning M. Sapiski & BLM team, A. Macpherson, S. Redaelli,
V. Kain, R. Schmidt, R Appleby, the EICs, the Post-Mortem team, and many more.

Special thanks to Brennan & BI for the dump BTV images

Beam Interlock System

□ BIS is running with almost nominal configuration.


- Only a few missing inputs, ~1/2 of them due to the 'absence' of client (ATLAS RP, CMS magnet, transverse damper).
- Behind the ~180 inputs to the BIS there are ~20k-40k individual interlock channels (QPS, PIC, BLM...).

□ BIS operation fault free.

- In the STABLE BEAMS periods all connected interlocks were active.
- Masking facility proved essential for availability in first days and MPS tests (see later).

Safe Machine Parameters

- SMP system responsible for generation of:
 - ✓ SPS Probe Beam Flag
 - ✓ SPS Safe Beam Flag
 - ✓ LHC Beam Presence Flag
 - Safe Energy
 - LHC Setup(Safe) Beam Flag (SBF)
 - Safe Stable Beams Flag
 - Movable Devices Flag




>> OK for present low intensity/energy

Safe Energy

□ Energy information generated by the LBDS BETS system (IR6).

□ Redundant information transmitted @ 1 kHz to SMP system in CCR.



Problems were observed in the energy value distributed in the pre-beam periods:

Energy set to safe value of 7864 GeV a few times per day. Internal comparison of A/B redundancy suspected to be at the origin of the issue.

>> Disable redundancy + crash program on fast internal diagnostics.

No problems observed during beam commissioning (without redundancy).

The internal comparison process has been upgraded and will be back for 2010.

Powering Interlocks

Powering interlocks (PIC) link to BIS were activated in <u>commissioning</u> <u>configuration</u>:

- Main circuits, IPD and IPQ \rightarrow un-maskable beam interlocks.
- Trim quads, sextupoles, > 60 A CODs \rightarrow maskable beam interlocks.
- Other circuits : don't care.

Performance:

- Very reliable.
- Maskable inputs were occasionally masked, or the configuration was adapted when circuits were not available (almost always MCBX !).

>> MCBX also a problem for steering, separation, real-time feedback ... !

• All dump triggers were clean and fast (no effect seen on beam before dump).

Fast Magnet Current Change Monitors (FMCM)

All 12 LHC FMCMs were commissioned in parallel to HWC by generating powering faults on the associated circuits.

- Performance in spec, dump thresholds:
 - ~ few 10⁻⁴ relative current change at 450 GeV
 - ~ 10⁻⁴ relative current change at nominal current
- **G** FMCMs operated reliably. 'Anomalies':
 - FMCM of RD34.LR7 triggered a few times without associated PC fault.
 - All but one event concentrated in the 3-4 hours before 18 kV transformer problem. Precursor? M. Zerlauth is investigating...

18 KV Transformer & FMCMs

- BIS interlock sequence during 18 KV transformer problem on 02.12 at 01:10.
 - FMCMs triggered one after the other within 22 ms.
 - 'Unfortunately' no low intensity beam to witness but encouraging sign that FMCMs may catch the such events before the consequences on beam become a problem.


Input	Delta (ms)
FMCM RD1.LR1	0.00
FMCM RD1.LR5	3.42
FMCM RD34.LR3	4.15
FMCM RD34.LR7	5.74
FMCM RMSD.B1	8.22
FMCM RMSD.B2	10.87
FMCM RQ4.LR7	14.34
FMCM RQ5.LR7	14.42
FMCM RQ4.LR3	16.37
FMCM RQ5.LR3	22.11
WIC IR1	556.89
WIC IR5	594.40
WIC IR7	653.16
PIC IR2 (Mask+Un-Mask)	1522.70
PIC IR3 (Mask+Un-Mask)	1523.12

FMCM Beam Tests for D1 IR1/5

Low intensity beam test.

□ Trajectory evolution after OFF send to RD1.LR1, with FMCM masked.

Beam dumped by BLMs in IR7.




FMCM beam tests

Low intensity beam test.

□ Trajectory evolution after OFF send to RD1.LR1, with <u>FMCM active</u>.

Beam dumped by FMCM.



- Trajectory over 1000 turns at a the same BPM.
- No position change visible within resolution.

>> The redundant protection is working

Beam Loss Monitors

- BLM system is working reliably. It is one of the primary and very powerful observations tools (@ 1 Hz + PM analysis).
- BLM configuration for this period:
 - Arc + triplet BLMs \rightarrow un-maskable interlocks.
 - LSS + warm elements \rightarrow maskable interlocks.
- BLM reliability is excellent.
 - Isolated problems with noise and with connections.
 - >> For 2010 more BLM will be attached to the un-maskable interlocks.
- Overall the thresholds seem OK.
 - Thresholds at TCTs and TCLA were increased by factor 50 after beam tests.
 - Thresholds at TDI were set 'out-of-range' for short integrations windows.
- □ Signal cross-talk (through particle showers):
 - Transfer line collimators \rightarrow ring BLMs.
 - TDI IR8 \rightarrow MQX (Q3).
 - TCP beam $1/2 \rightarrow$ TCLA beam 2/1.

Quenches


- Quench count now at 4.
- □ All quenches were 450 GeV 'Quench-inos'.
- □ All quenches were associated to beam injection ultra-fast loss.
 - Latest event related by injection while trimming bumps for aperture scans.
 - >> Importance of :
 - Low intensity injection into empty ring.
 - Orbit corrector interlocking by SIS !

Injection Protection

□ Transfer line interlocks fully commissioned and active for first injection.

- Only missing item: TL collimators.
- Injection protection (TL collimators TCDI, TDI, TCLI) setup for stable beams with 2e10 p/injection.
 - Abort gap protection (inj kicker) not perfectly timed, but OK for now.
 - BLM cross-talk TL collimators \rightarrow ring.
 - >> H collimators to 6 sigma (instead of 4.5), V collimators to 4.5 sigma

>> Beam scraping in the SPS (H plane).




12

IR8 TDI Losses

Monitor on D1 (for protection of MQX3 from beam1) close to or over threshold when beam 2 is dumped on TDI.

- Not present in IR2 (layout ...?).
- Must understand the 'path' of the showers (inside/outside vac. chamber).
- Prevents over-injection of beam 2 for the moment.



Scraping in the SPS

□ Fast (ISR !!) scraper worked for ~ 3 days before it 'failed'.

- Scraping towards the end of the ramp.
- Reason of failure to be understood apparently HW issue on a motor axis. Access is required for more precise diagnostics.
- Scraping is now done at start of ramp by bumping the beam (orbit correctors) toward the SPS (static) momentum scraper (TIDP).
 - Only for H plane.
 - Must be done at low energy (orbit corr. strength).

>> So far OK, but may not be sufficient for higher intensity.

Collimation and Passive Protection


(see also LMC talk by R. Assmann on collimation)

- The LHC collimation system in the cleaning insertions provides highly efficient beam cleaning and passive protection for the LHC beams.
- □ Validation of the collimation efficiency and protection done by:
 - moving tune over 1/3 order resonance,
 - changing RF frequency (energy error)

>> Proved to be very powerful !

- Passive protection by collimators and absorbers is tested at the same time! Requirement: all primary beam losses at collimators!
- The tests were fully successful in terms of passive protection (cleaning not discussed here):
 - Leakage at the level of 10⁻⁴
 - Losses in cold regions.
 - Losses on tertiary collimator (TCT) in IR5 not aligned to the beam !!

Global Protection Checks with Beam




Global Protection Checks

- □ Loss pattern for beam lost on 1/3 resonance.
- □ With higher intensity, the leakage into the cold parts of the machine becomes visible !


-				LHC BL	M Fix	æd Disp	lay			· 🗆	
<u>F</u> ile	<u>T</u> ools										
2.2		Unit: Gray	/ s 🔻	Scale: Log 🔻	I	ntegration Ti	me:	5.2 s 💌	Display: Acquisiti	on / Refe 💌 🗝	
	Sectors Filter										
	-Filter (3560 / 3										
	Location	Type	Section	Left Right	Octant	_	Beam		Position on Elemen	Observed Element	
∇	🗹 Quad	✓ IC	🗹 LSS	🗹 Left	☑ 1	2 5	🗹 Beam 1	🗹 External	🗹 Entrance		
	🗹 Other	r	DS		2	⊮ 6		🗹 Internal	🗹 Center	%	
	✓ 2 Elements	SEM		Right	2 3	2 7	🗹 Beam 2	✓ Top			
	🗹 Mobile		ARC		☑ 4	⊮ 8		Beta-clea	ining		
	Total I	acces: 0.1205.10	New / cl						–	009 00:03:06	
	TOTAL	osses: 0.1205 [C		old eleme	nte				11.12.2	009 00.03.08	
					1115				Oct	ant 6	
1000 1000 100 100 100 100 100 10											
	ihow Labels				Display C)ptics Elemer	nts			Use DCUM	
	> Start	Stop 🛃 Save	Continuous Saving	/user/pcrops/data/l	HChwc/L	ogging/SDDS	Cour	rtesy Collima	tion & BLM te	eam	
C	onsole Runnir	ig tasks									

Dump of Debunched Beam




Dump of Debunched Beam

Bunched and debunched beam 2 on the dump BTV (pilot + 4x2e10)




IR Aperture Scans

- □ Aperture scans in all IRs together with experiments:
 - Aperture check.
 - Rough BLM calibration aimed to produce measurable loss (μGray to ten's of μGray over 1.3 sec) a factor 10 or more above background.
 - BCM sensitivity check.



BLM & BCMs during Aperture Scans

- \Box Scans Ok for CMS, LHCb, ALICE: BCMs reach ~% of dump level losses of ~10⁸ p.
- Issue for ATLAS: beam dump by ATLAS BCM before we could see any measurable signal on BLMs in H plane (V plane OK) – did not reach the aperture !
 - >> Probably combination of very low dump threshold (100 lower than other exps tbc ?) and loss on incoming side. Offline analysis with ATLAS in progress...




21

BLMs during Aperture Scans

□ Loss of $\sim 10^9$ p in IR8 triplet (Q2 over ~ 1 second):

◦ BLMs signals at ~ 1/20 of dump threshold → threshold ~ few 10^{10} p ~ OK.



Software Interlock System (SIS)


- SIS able to inhibit injection or dump beam.
- □ SIS for injection:
 - Almost fully commissioned (~ 4000 interlocks).
 - Missing : protection against over-injection, RF cryo maintain.

□ SIS for dump:

- Almost fully commissioned.
- Only active interlock (availability): orbit corrector locking for STABLE BEAMS.

SIS Corrector Interlock

- □ Deflections of all CODs reconstructed from currents & energy.
- \Box Dump is >= 2 CODs out of tolerance (bump...).
- □ Note : ignores CODs where PC is OFF.
- □ Used in all STABLE BEAM periods.



Post-mortem System

- Dump diagnostics with Post-mortem system is already a routine check in the CCC. The diagnostics is very good for:
 - BIS who dumped and when
 - o BLMs

- PIC
- FMCM

Online diagnostics will be extended to

• BPMs

2/8/

				Ornine diagnostics will be extended to						
	HEADER		more systems for 2010							
System	BIC	1	pmAnalysisModule		9,010111	0.0		7		
Class	EVENT_SEQ		Analysis result description	First input change detected:	USER PERMIT: Ch 1	4/EMCM RD11R	1): A T - N E on CIB I	IS15 1 P2		
Source	ISA		Triggered BIC inputs	Ch 14(FMCM_RD1.LR1), Ch						
Event stamp			OVERALL	30 BICs triggered valid PM of		o, en ratinent	(D1.6(0), CH 12(H	rem_rebs+rersy		
Version	0.3.15			po bies inggered valia i mie	ala a					
Encoding	BIC/EVENT_SEQ									
Oualifier										
Analysis fla	gs [INTERESTING_EQP, INTERESTIN	IG_BEAM]								
EVENT OVERVIEW SOURCE OVERVIEW										
ex Loc.Per		De		escription	BIC name	Index	Source Name	Data Valid		
	01:10:36.212+212966	2			CIB.US15.L1.B2 🔺	1	CIB.UA83.L8.B2	true		
4	01:10:36.212+212966	2		14(FMCM RD1.LR1): A T	CIB.US15.L1.B1	2	CIB.UJ56.R5.B1	true		
5 100	01:10:36.212+212967	3			CIB.US15.L1.B2	3	CIB.UJ56.R5.B2	true		
5	01:10:36.212+212967	3			CIB.US15.L1.B1	4	CIB.UA83.L8.B1	true		
4	01:10:36.216+216385	3421		14(FMCM_RD1.LR5): A T		5	CIB.US15.L1.B1	true		
	01:10:36.216+216385	3421			CIB.UJ56.R5.B1	6	CIB.US15.L1.B2	true		
5	01:10:36.216+216386	3422		14(FMCM_RD1.LR5): B T		7	CIB.SR7.S7.B1	true		
	01:10:36.216+216387	3423			CIB.UJ56.R5.B2	8	CIB.SR7.S7.B2	true		
2	01:10:36.217+217113	4149		12(FMCM_RD34.LR3): A.T		9	CIB.USC55.L5.B2			
3 9 9 9 9	01:10:36.217+217113	4149		12(FMCM_RD34.LR3): A T		10	CIB.UA87.R8.B1	true		
	01:10:36.217+217114	4150		12(FMCM_RD34.LR3): B T		11	CIB.UA87.R8.B2	true		
5 10 5 10 1 10	01:10:36.217+217114	4150		12(FMCM_RD34.LR3): B T		12	CIB.USC55.L5.B1			
	01:10:36.218+218700	5736		Ch 12(FMCM_RD34.LR7):	CIB.SR7.S7.B2	13	CIB.US15.R1.B1	true		
	01:10:36.218+218700	5736			CIB.SR7.S7.B1	14	CIB.UJ33.U3.B1	true		
	01:10:36.218+218701	5737		Ch 12(FMCM_RD34.LR7):	CIB.SR7.S7.B2	15	CIB.UA63.L6.B2	true		
	01:10:36.218+218701	5737			CIB.SR7.S7.B1	16	CIB.UA63.L6.B1	true		
	01:10:36.221+221183	8219			CIB.UA67.R6.B1	17 18	CIB.SR3.S3.B2	true		
	01:10:36.221+221184	8220		9(FMCM_RMSD-b1): B T			CIB.SR3.S3.B1	true		
	01:10:36.227+227307	14343 14344			CIB.SR7.S7.B1	19	CIB.UA67.R6.B1	true		
	01:10:36.227+227308	14344		13(FMCM_RQ4.LR7): A T		20 21	CIB.UA47.R4.B1	true		
3	01:10:36.227+227309 01:10:36.227+227309	14345			CIB.SR7.S7.B2 CIB.SR7.S7.B1	21	CIB.CCR.LHC.B1 CIB.UA23.L2.B2	true		
	01:10:36.227+227309	14345			CIB.SR7.S7.B1	23	CIB.CCR.LHC.B2	true		
	01:10:36.227+227384	14420			CIB.SR7.S7.B1	23	CIB.UA47.R4.B2	true true		
	01:10:36.227+227385	14421			CIB.SR7.S7.B2 CIB.SR7.S7.B2	24	CIB.UA47.R4.B2 CIB.UA23.L2.B1	true		
	01:10:36.227+227386	14422			CIB.SR7.S7.B2	26	CIB.UA23.L2.B1 CIB.UA43.L4.B2	true		
	01:10:36.229+229332	16368			CIB.SR3.S3.B2	20	CIB.UA43.L4.B2	true		
	01:10:36.229+229332	16368		13(FMCM_RQ4.LR3): A.T 13(FMCM_RQ4.LR3): A.T	CIB.SR3.S3.B2 CIB.SR3.S3.B1	28	CIB.UA43.L4.B1 CIB.TZ76.U7.B2	true		
	001 101 SD 279±779337	TDSDA	I T USER FERMIT I F	CISTEMU WEREIGERSTAT		20	CID. 1 27 0. 07. BZ	uue		

Post-mortem Analysis

□ MPP team is now looking at all dumps.

- Majority is well understood and shows no anomalies
- Few isolated cases are not understood, for example:
 - Beam lost over few turns at injection during MPS setup for 2e10p / bunch.
 - Two consecutive events, but rather different signature.
 - In both cases losses on TCT in IR1, ATLAS dump.

>> highlights the importance of only injecting low intensity into empty ring !!

□ For next year.

- Database of dumps with main characteristics.
- Offline analysis team for un-explained events (starting...).

General Remarks

□ Fast progress in beam commissioning:

- MPS quickly becomes a bottleneck strong pressure to commission as fast as possible.
- Mixing of beam commissioning and STABLE BEAMS at same energy raises protection issues (procedure to switch from one mode to another...). This is made even worse by the fact that sequences are not well established, change rapidly...

>> OK for this year - could be major issue when beams become unsafe !

- If the excellent state of the machine at 1.18 TeV reproduces at 3.5 TeV, MPS setup is likely to dictate progress in 2010.
 - 'Quiet beams' period should not become a standard OP mode!
 - >> Give time for MPS setup to establish low intensity collisions (~ 4 pilot style) in STABLE BEAMS asap to avoid 'Quiet beams'.

Then run at fixed intensity until MPS qualifies for more beam...

Summary

No major problems in the MPS commissioning – some issues to be investigated & fixed for 2010.

<u>The system is already very safe</u> – but the intensity is also very low.

- As expected MPS requires a lion's share of beam time in the early phases, in particular because the machine works well.
- So far we are working with ~1 permill of nominal beam, but things will rapidly change next year when beams will become unsafe. Besides completing the tests we need:
 - Well defined OP sequences for CCC.
 - More post-operational checks for critical systems port-mortem acknowledge, BIS, LBDS, BLM tests... some of this is active or ready to go.
- We will re-evaluate 'quiet beam' preference in MPP to go quickly to a safe low intensity OP rather than 'abusing' of quiet beams.