
Asynchronous dump @ 450GeV 19/11/2010

C.Bracco, E.Carlier, B.Goddard, J.Uythoven

Real Asynchronous dump


- Asynchronous between kickers and relative to abort gap
- Friday evening 19/11/10 @ 21:23, Beam 1
- Single ion bunch of 1e10 charges
- Properly extracted, but not at the correct position ob BTVDD
- XPOC errors on MKD, MKB and BTVDD but BLMs ok




CONTEXT MKD MKB BLM VAC BTVDD BPMD BCT BSRA TSU

XPOC:

IPOC




Relative delays of 15 kickers



Low level diagnostic


TE/ABT Equipment Control 11/ LHC													11/19/	/20		Stage7 - Interlocks						
Beam Dumping Kicker Systems - BEAM1						450 [GeV] REMOTE					ON		S701	S701			PTU1 - Trig IN1	S717	PTU2 - Trig IN1			
					1 -	1									S702				PTU1 - Trig IN2	S718	PTU2 - Trig IN2	
	Control	A	B	C	D REM	REM	F REM	G	H	REM	J	K REM		M	S703	8		PT	U1 - Re-Trig IN1	S719	PTU2 - Re-Trig IN1	
	Mode		AUTO		A CONVERSE		AUTO						AUTO /		S704	P			U1 - Re-Trig IN2	S720	PTU2 - Re-Trig IN2	
Mask															S705	PTU			- PTM A Driver	S721	PTU2 - PTM A Driver	
	AUE														5706				- PTM B Driver	5722	PTU2 - PTM B Driver	
	Mains Earthing Switches													_	5707	1			Voltage divider	5723	RTB2 Voltage divider	
	Power Supplies																					
	On														S708				TB1 Principal A	S724	RTB2 Principal A	
	Tracking														S709	, , , , , , , , , , , , , , , , , , ,		R	TB1 Principal B	S725	RTB2 Principal B	
1.00.0	Triggering Ready			INTL	INTL	· .									S710	RTB1		B1 C	compensation A	S726	RTB2 Compensation A	
			9699	0507	2507	2500	0507	9091	9507	9699	2507	2500	2500	200	S711	RTB1		B1 C	ompensation B	S727	RTB2 Compensation B	
Pulse Counter 2598 2602 2597 2597 2597 2601 2597 2603 2597 2598 260 CLEAR CLEAR </td																						
												2 😫 🕺 🥸										
	Date				Number Point of erro					or		Entity				WinCC Message text						
1	19/11/	A			:39.1	and the second second	1. SAN	6		a state of the sta	DS1				SYS	TEM			IPOC Ready			
2	19/11/	A			:37.:			16	37		DS1	<u> </u>				TEM			Acknowledge rea		d	
3	19/11/	A			:37.:		_	35			DS1						UA63		Trigger / Re-Trig			
4				09:23:37.322 PM 09:23:37.322 PM				29 LBDS1								KDGA.CUA63			Trigger / Re-Trigger			
5	19/11/		_					10			DS1					TEM			MKD / MKB Read	dy		
6	19/11/		_		:37.:			9		-	DS1					TEM			TSU Ready			
7	19/11/				:37.:			5			DS1					TEM		_	BETS Ready			
8	19/11/	St	-	0.000	:55.4		2.000	11		11000	DS1				100000000000000000000000000000000000000	TEM			ARM Command			
9	16/11/	2	_		:19.9			4			DS1					TEM			LASS Ready			
10 11	16/11/				:19.0			3		-	IDS1	· · · · · · · · · · · · · · · · · · ·			LAS				LASS - Loop B LASS - Loop A			
12					:58.4			1		-	IDS1				LAS				LASS - Loop LSS6			
12	1010	10	12	0.00	.00.4	407	1° 191	1		LC	001	-			LAS	0			LY99 - LOOD F98	50		
13			-							-												
14	-						_															

LBDS Trigger Synchronization and Distribution System



Failure Source

Failure of a MAX4429EPA driver (single power driver) in one TFOT module



- Dual secondary transformer used in TFOT in order to guarantee the triggering of both PTUs of one generator (kick rising edge and synchronization issues)
- MAX4429EPA is oversized for its use in this application (voltage & Current)

- MAX driver breaks... probably initially to short-circuit and finally to open-circuit.
- Power pre-loaded in blocking capacitor discharges in the primary winding of the pulse transformer and generates glitches at the secondary outputs.
- PTU1 of generators C & D triggered on reception of the "trigger" glitches
- Generators C & D pulsed asynchronously with beam on reception of the PTU pulses
- Re-trigger signals sent from the pulsed generators to other generators
- Remaining generators pulsed
- Asynchronous pulse recorded by IPOC
- Asynchronous pulse recorded by XPOC
- Bad trigger signals detected by PTU monitoring system because glitches were smaller than nominal trigger pulse length
- Generators in fault status


Actions

- Validation dumps performed after the asynchronous dump where correctly synchronized (no IPOC error)
- Acknowledge still requested due to missing trigger pulses on "PTU1- Trig IN1" for generator C & D (faulty driver circuit)
- 2 options
 - Mask the interlock channels (redundancy exist)
 - Repair the fault (access needed)
- Decided to make an access in UA63 to properly repair the fault
- Trigger signal switched to spare outputs of TFO system (same cabling logic)
- System pulsed in local to validate the intervention
- Faulty TFOT still in the machine
- Procedures for re-commissioning of the system after this type of intervention are missing but the right actions were taken

Why 2 generators pulsed?


- TFOs are located in the "Fault-Tolerant" part of the TSDS
 Signal presence are checked only after each pulse...
- Cabling logic optimized to reduce as much as possible the probability of missing generator
 - Output pulses of one driver circuit is connected to 2 different generators
 - Trigger inputs of one PTU are coming from 2 different TFOT modules
- Initial configuration changed after reliability analysis in order to improve the reliability of the system... in case of missing trigger pulses

Effect on Beam Sweep



TFOT trigger signals distribution


Actual cabling



- 1 out of 4 trigger signal missing in 2 generator in case of failure (missing) of 1 driver circuit
- 2 generators pulsed in case of faulty trigger pulse at driver output

TFOT trigger signals distribution

Initial cabling



- 2 out of 4 trigger signals missing in 1 generator in case of failure (missing) of 1 driver circuit
- 1 single generator pulsed in case of faulty trigger pulse at driver output

Conclusions

- First real asynchronous dump
 - Due to failure of component in fan out of trigger signal leading to two generators triggering erratically followed by asynchronous trigger of the 13 other generators
- Signature different from standard and studied asynchronous dump
 - Erratic in single generator
- Different load on protection elements between the two cases
- To be studied how to start up next year