

The Interlocked BPMs of the LHC in Pt.6

- Issues
- Modification proposals
- Commissioning plan

Eva Calvo (BE-BI)

Introduction - Layout



System Constraints

- Due to integration constraints, these pick-ups have very large diameters (80mm & 130mm) and long cables to reach the front-end electronics.
- The electronics consist on the standard LHC BPM frontends, BUT with a particular FPGA firmware in the digital acquisition part.
 - The analogue part works in 2 sensitivity modes
 - High sensitivity from 2×10⁹ to 5×10¹⁰
 - Low sensitivity from 5×10^{10} to 2×10^{11}
 - The input levels are matched to the electronics by attenuators, taking into account the cable losses.
 - Chamonix decided to lower low sensitivity threshold to give more margin
 - Led to issues with probes visible at injection, triggering system when injection cleaning on.

The attenuators issue



Attenuators are placed in each of the 44 cables, attached on the top of the rack, with very difficult access.

		30 V	Mesure de couplage et de phase																		
AIMANT / Mini Rack		Numero		Cablotheque	Filt	ters		Bear	m1 V	Be	Beam1 H			Beam2 V							
								noir> ja	noir> jaune blanc		jaune> noir r		k/	noir> jaune blan		c je					
WBTN #	17							B/A	φ	B/A	(φ ″	ok	B/A	φ						
BPMSA	.A4L6.B1	B1-H	1618170	1618171		17 20	6-261	1.01	1.4	1.00	-1	.6		1.00	1.6	the second	~				
BPMSB	.A4L6.B2	B1-V	1618172	1618173		18 85	5-78	1.01	0.4	1.00	1.00 2	.8		1.00	0.6		6				
BY02	UA63	B2-H	1618178	1618179	19		3-39	B/A	φ	B/A		φ	ж	B/A	φ		-				
chassis 1	droite	B2-V	1618180	1618181	AIMAN	NT / Mi	ni 🔄				u Fitters					Me	esure de	coup	uplage et de phase		
BPMSA	.B4L6.B1	B1-H	1618174	1618175	Т В	ack		Numero	Labiome ,a	φu				Beam1 V		Beam1H			Beam2 V		
BPMSB	.B4L6.B2	B1-V	1618176	1618177	Ī									noir> jae	une blanc	(aune)	noir rouge I	oki	noir> ja	une blan	
BY02	UA63	B2-H	1618182	1618183		17								B/A	φ	B/A	φ	nok	B/A	φ	
chassis 2	gauche	B2-V	1618184	1618185	BPMSA	.A4L6	5. B1 B1-	H 1618170	161817	1	17	206-26	1	1.01	1.4	1.00	-1.6		1.00	1.6	
BPMSB	.A4R6.B1	B1-H	1618206	1618207	- BPM3B	.A4L6	- BZ BI-	V 1618172	101017	3	18	40.00			0.4	1.00	2.8	οк	I.UU DIA	0.6	
BPMSA	.A4R6.B2	B1-V	1618208	1618209	ВТ02	UAE	8 82	1618180	161818	o 11	20	40-00 216-139	;	1.00	• 05	1 00	• -2.2		1.00	• 05	
BY02	UA67	B2-H	1618198	1618199	BRMSA	B4L6	<u>≌ v</u> ⊾ B1 B1-	H 1618174	161817	5	20	13-222	, 	1.00	2.0	1.01	2.2		1.00	-2.2	
chassis 1	droite	B2-V	1618200	1618201	BPMSB	.B4L6	.B2 B1-	V 1618176	161817	7	22	90-205		1.00	0.0	1.01	0.7		1.01	4.3	
BPMSB	.B4R6.B1	B1-H	1618210	1618211	BY02	BY02 UA63 charsis, gauch		1618182	161818	3	23	56-01	01	B/A	φ	B/A	Α φ ΟΚ	ок	B/A	φ	
BPMSA	.B4R6.B2	B1-V	1618212	1618213	charsis.			1618184	161818	5	24	93-104		1.00	1.0	1.00	0.8	1	1.00	-3.3	
BY02	UA67	B2-H	1618202	1618203	BPMSB	.AAR6	6.B1 B1-H	H 1618202	161820	13	15	110-100		1.01	-2.7	1.01	-1.1		1.01	-2.3	
chassis 2	aauche	B2-V	1618204	1618205	BPMSA	A4R	. B2 B1-	V 1618204	161820	15	467	439-49	9	1.00	3.6	1.01	2.3	пк	1.01	3.8	
	guuene				BY02	UAG		1618206	161820	7	10	79-111		B/A	φ	B/A	φ		B/A	φ	
					chassis 1	dia	Ng - 12	1618208	161820	19	9	83-5		1.01	-3.2	1.00	-1.7		1.00	-3.1	
		127			BPMSB	.B4R	B1 B1-	H 1618210	16182	11	13	58-297		1.01	1.3	1.01	.01 2.3		1.01	4.8	
					BPMSA	.B4R6		V 1618212	161821	3	451	356-39	91	1.00	0.1	1.01	-1.1	ок	1.00	-3.9	
					BY02	UAG	7 B	1618198	161819	9	11	36-157		BIA	Ŷ	B/A	φ		B/A	Ŷ	
					chassis.	gauo	he 🗌 u	1618200	161820	л	12	46-132		1.01	U.6	1.00	1.7		1.01	4.4	

An error in the documentation reporting the cabling numbering was the cause that the attenuator changes during first part of the year produced so strange behaviour.

Additionally, details like the the complicated naming, does not facilitate locating the channels (errorprone)

Observations

Changes in attenuation

- Attenuation increased for BPMSA.B4R8 twice to counter injection issues
- A scrapping on 24/5 showed attenuation had been increased on wrong channel
 - Explained both continued problems at injection & higher intensity limit for B2



Status and changes justification

Today's status

- Attenuation modified on 25/05 for B2 BPMSAs limit now at 4.2e10
- Both beams can be further optimised
- Aim is to align all interlock BPMs to limit around 2e10 3e10



Status and changes justification (cont.)

B1 (status at 24/5/2012)



Suspected there are 4dB instead of the 0dB noted in the traveller in BPMSB.A4R6.B1

Now that the cause of the successive problems is understood, "there is no risk" for optimising the system.

Improving the System...

Current settings (MCS)

- The BPM interlock firmware compares the ADC output of every single bunch measured with a defined threshold.
- Currently if 70 readings out of limits over 100 turns triggers the system (i.e. 1 bunch)
- Second window with 250 out of limits over 10 turns to quickly catch fast orbit change
- Errors currently counted as "out of allowed window"
 - Intentionally implemented in this way to guarantee correct operation of the system
 - It's typically on errors that we trigger the system when bunch intensity drops to threshold levels

• Firmware/Software upgrades:

- The attenuator change and the filling scheme change (no private IR8 collisions) has avoided that we trigger the interlock during the last weeks.
- The new firmware can separate badly acquired bunches from real measurements.
 - This will provide additional post mortem data
 - to distinguish between weak bunches not correctly measured or oscillating bunches.
 - Should make the system more accommodating to specific operational scenarios without compromising protection functionality
 - by allowing different trigger thresholds for the oscillating bunches than for the number of weak bunches.

Commissioning Plan

• Sunday, during BI MD : Test the new firmware functionality

- Deployment of the new firmware and FESA versions.
- Set up one BPM interlocked crate to trigger the interlock if 3-4 bunches are too weak to be correctly acquired. (To prove that protection functionality is not compromised).
- Setup the second crate in order not to trigger the interlock with only 3-4 weak bunches. (To prove flexibility)
- During the TS: Include the temperature correction coefficients and test their efficacy by modulating the crate fan speed.
- During TS: Replace the attenuators of BPMSA.A4R6.B2 , BPMSA.B4R6.B2 and BPMSB.A4R6.B1.
- After TS : Verification of the attenuator change
 - B1 and B2 scrapping (~30 minutes)
 - "Bump test": make trigger all the channels through bumps, and compare the position when triggering with the defined threshold. (~1h?). The comparison between the levels found last time and the new ones should give an indication about any included offset.
- Collimator alignment campaign in IR6 to verify the BPM offsets.





Linearity error vs bunch charge

