

Observations and conclusions
after TDI issue in IP8
Scrubbing Run: TDI, MKI and MKE interlocks

ABT/BTP

Acknowledgments: M. Barnes, M. Di Castro, E. Carlier, R. Losito, A. Masi.

Outline


- ▶ TDI
 - ▶ Heating
 - ▶ Issues encountered with TDI right jaw and resulting deformation
 - ▶ TDI checks
 - ▶ Followup and Improvements

- ▶ Scrubbing run:
 - ▶ TDI position and MKI/MKE interlocks




TDI Position Sensors: LVDT

- One LVDT on each side of the support bar allows to detect deformation




TDI Position Sensors: LVDT

- One LVDT on each side of the support bar allows to detect deformation




TDI Heating

Timeseries Chart between 2012-08-06 00:00:00.000 and 2012-08-07 08:00:00.000 (LOCAL_TIME)




TDI Heating

Physics




TDI Issue 07/08/2012

Timeseries Chart between 2012-08-07 08:00:00.000 and 2012-08-07 10:00:00.000 (LOCAL_TIME)



TDI Issue 08/08/2012



After recovery, a residual offset of ~150 μm persisted between **RD LVDT** and **Resolver** at injection position → deformation!

Cause and Follow-up

Cause:

- ▶ **Not found any mechanical problem** → not clear correlation with TDI heating
- ▶ Most likely candidate: **spurious glitch** on the RU end-switch → switch active → motor stopped


Follow-up:

- ▶ The **control module** (rack in service tunnel) of the switch was **exchanged** (09/08/2012) → the problem did not appear any more
- ▶ New task in the sequencer: **TDI position check before ramp.**




Switch Exchange and Re-initialisation

- ▶ After switch exchange the motor counter had to be re-initialised → LVDT used as reference
 - ▶ Parking position used as reference (09/08/2012), moreover 150 μm offset introduced by the deformation → interlocked LVDT too close to inner dump threshold at injection position



Switch Exchange and Re-initialisation

- ▶ After switch exchange the motor counter had to be re-initialised → LVDT used as reference
 - ▶ Parking position used as reference (09/08/2012), moreover 150 μm offset introduced by the deformation → interlocked LVDT too close to inner dump threshold at injection position
 - ▶ Beam dumped during Q20 injection studies because of thermal drift (12/08/2012)




Switch Exchange and Re-initialisation

- ▶ After switch exchange the motor counter had to be re-initialised → LVDT used as reference
 - ▶ Parking position used as reference (09/08/2012), moreover 150 μm offset introduced by the deformation → interlocked LVDT too close to inner dump threshold at injection position
 - ▶ Beam dumped during Q20 injection studies because of thermal drift (12/08/2012).
 - ▶ New re-initialisation: offset “removed” using as reference an old LVDT reading at injection position (before 07/08/2012) → centered wrt thresholds **BUT 150 μm deformation hidden by the new re-initialisation! Impact on the jaw?**




TDI Setup Checks

- ▶ Angular scan → no measurable change



TDI Setup Checks

- ▶ Retraction wrt vertical primary collimator: beam blowup with MKQ → retract TCP with 0.1 sigma (76 μm) steps → TDI becomes primary when losses decrease at TCP and increase at TDI → number of TCP steps gives retraction



Nominal retraction = 6.8σ

Measured retraction:
Right jaw = $6.8 \pm 0.1 \sigma$
Left jaw = $6.4 \pm 0.1 \sigma$

Old measurements:
Right jaw = $6.6 \pm 0.1 \sigma$
Left jaw = $6.4 \pm 0.1 \sigma$

Difference within the measurement accuracy.

TDI jaws OK!

Future Improvement (TS3)

Modify the low level (PXI) control software to introduce a check on the skew angle of the TDI jaws:

- ▶ **Check the command sent from the operator** (sequencer) to verify that the **requested position is within the admissible angle**. The command will be **refused** in case the angle is too big and a **warning** will be sent back.
- ▶ Add a **control on the position** measured with the **resolvers** to ensure that during a movement a jaw cannot go into a dangerous state. Also in this case **no dump**, but just a **warning** sent back to the operator, and the **two motors of that jaw will be stopped**.
- ▶ **Maximum allowable skew angle: 5 mrad** (11 mm offset between up and downstream LVDT)



Scrubbing Run with 25 ns beam 4/10-8/10

- ▶ Scrubbing run:
 - ▶ Injection and accumulation of trains of 144-288 bunches
 - ▶ Long periods without injections
 - ▶ The TDI has to be retracted to parking position if staying > *15 minutes (?)* without injections to limit heating/deformation

Risk of MKI erratics with TDI retracted ???

MKI interlocks : “NO-TRIGGER PULSE” the PFN gets **discharged** through the **dump switch ~2.5 ms after the injection pre-pulse**

TDI interlocks: injection inhibit if TDI jaws open to parking (BIS) → **no beam permit** → **inhibit the pre-pulse triggers and not possible to charge the MKI PFN** → **no erratics**

Risk of extraction from SPS with TDI retracted ???

MKE interlocks: “NO-TRIGGER PULSE” only in point 4. No dump switch in point 6 but **No beam permit** if **TDI open** (injection permit removes the extraction permit.). Only possible to extract if **TED in**.

Further protection: Dedicated sequence to put MKI into STANBY before moving the TDI out (Injection permit removed when MKI in STANDBY).

Conclusions

- ▶ A problem with TDI right jaw occurred twice at the beginning of August
 - ▶ Spurious glitch at end-switch → upstream corner blocked when moving to parking → big tilt and residual deformation
 - ▶ Task added in the sequencer to check TDI jaw position wrt settings before the energy ramp
 - ▶ Switch control module exchanged → no more problems up to now
 - ▶ TDI jaw checked with beam and no measurable effects on angle and retraction wrt TCP
 - ▶ Further improvements will be applied at the low level control during TS3
- ▶ Sign of heating inducing LVDT drifts observed when moving to high bunch intensity → elastic deformation
- ▶ Scrubbing run:
 - ▶ TDI retracted to parking if > 15 minutes without injections
 - ▶ Dedicated sequence to put MKI in STANDBY before moving TDI
 - ▶ “No-trigger pulse” prevents MKI and MKE4 pulses 2.5 ms after injection pre-pulse (MKE6 relays on no beam permit with TDI open)
 - ▶ TDI open → no beam permit → no erratics
 - ▶ Future upgrade (LS1): add TDI jaw position in to MKI BETS.

