

Science and Technology Facilities Council

# RFD Prototype: Assembly lessons learned

12th HL-LHC Collaboration Meeting

21/09/2022

**Edward Jordan** 


**Mechanical Project Engineer** 



#### **Progress to Date**

#### Auxiliary STEP A, B, C, D: STEP 1: STEP 2: STEP 2:







#### Progress to Date

#### Auxiliary A, B, C, D: STEP 1: STEP 2: ST









String on Trolley (pre-cleanroom aligned)





PIMS + Cavities cavity line Joints made (Cleanroom ISO4)

FPC installed to cavity x2 (Cleanroom ISO4)

Challenge #1

**Complexity of design** 

Challenge #2

**Studs on Cavity String Joints** 

Challenge #3



Challenge #1

# **Complexity of design**

Challenge #2

**Studs on Cavity String Joints** 

Challenge #3




# **Complexity of design**

- Auxiliary Steps ABCD comprises 200+ discrete steps
- Over 400 unique components
- Easy to confuse items with one another













- 6x Plug in Modules (PIMS)
- Each unique position and orientation captured correctly

## **Complexity of design**


• Ensure common nomenclature observed throughout





CAVITY LINE SHORT SIDE SECONDARY LINE SHORT SIDE






# **Complexity of design**

RFD Short CW Transition LHCVBMCC0033 Dent | LHC-ACFVW-QN-0001

- Error during assembly led to a dent on the secondary line CWT,
- Highlighted the need to follow assembly procedures carefully,
- Non-conformance is to be closed once secondary line vacuum

integrity has been demonstrated, (coming weeks)





Challenge #1

**Complexity of design** 


Challenge #2

#### **Studs on Cavity String Joints**

Challenge #3



#### **Studs on Cavity String Joints**



- Studs are longer and 68mm
- Studs are longer than clearance behind flange
  - Studs need to be pre-placed into PIMS before joint is made

• Therefore, studs cannot be replaced once joint operation begins








### **Studs in Cleanroom**

Threads Stripped on String Joints (STEP 1) |LHC-ACF\_A-QN-0001




Cause: combination of poor thread form on fasteners & difficulty of joint arrangement to gauge force/feel feedback during torque setting.

Remedy: blind holes and stud threads re-tapped in-situ in cleanroom, vacuum integrity check passed.

- Joints 4, 6, 7 experience thread failures





- When torque is applied to the Nut on the stud, there is no way to monitor if the stud is rotating/stationary
- Silver coating of nut means thread form is inconsistent
- Therefore, difficult to monitor force feedback and stud position during torque application
- Remedy for the series will to ensure the Studs used have a slot or equivalent to prevent rotation



Challenge #1

**Complexity of design** 

Challenge #2

**Studs on Cavity String Joints** 

Challenge #3



## Scheduling (Covid / Brexit / Global Issues )

- Arrival of long lead items impacting build phases
  - Outer Vacuum Chamber (Valveplates are the first item on string assembly)
  - Cryoline (Main item installed on step 3)
- Also delays to short/medium lead time items and tooling impacting the build & mechanical design
  - Cleanroom tooling delays in the manufacture of these items impacted into other work streams
  - String Lifting equipment –
- Availability of these items makes it difficult to plan visits from CERN personnel
  - FPC Install
  - FSI install
  - Various Instrumentation install
- New trade barriers between EU + UK has drained project resource (Brexit)
  - A logistical issue that has consumed a lot of resource from staff not specialised in customs/ logistics.



# Thank your for your attention,

# **Questions?**



