

# RELIABILITY IN MEDAUSTRON POWER CONVERTERS

A look back at the power converter reliability since 2016

Rui Alen  
Wiener Neustadt, May 31, 2023

# CONTENTS



1. The importance of being reliable
2. Medaustron power converters
3. Power converter incidents
4. Improving power converter reliability

# THE IMPORTANCE OF BEING RELIABLE

## MedAustron is a cancer treatment and research center!

- We provide advanced patient care;
- Thus human lives are our first priority;

## Power converters

- Have a significant role in the therapy accelerator;
- They should be consistently good in performance;
- And able to be trusted;



The importance of reliability in human life!

# MEDAUSTRON POWER CONVERTERS

Family	Quadrants	Cooling	Voltage (V)	Current (A)	Magnet
<b>A2</b>	1	Air	50	200	LEBT-MEBT quadrupoles, solenoid
<b>A3</b>	1	Air	50	300	
<b>B1</b>	4	Air	30	50	LEBT, MEBT, HEBT correctors and quadrupoles, MR correctors, skew, betatron
<b>B2</b>	4	Air	30	150	
<b>B3</b>	4	Air	50	300	
<b>B4</b>	4	Air	90	300	
<b>C1</b>	4	Water	160	650	MR-HEBT quadrupoles and sextupoles
<b>C2</b>	4	Water	300	360	
<b>C3</b>	2	Air	250	1250	IH quadrupoles
<b>C4</b>	4	Water	200	2000	HEBT dipoles, septum
<b>C5</b>	4	Water	70	3300	
<b>D1</b>	4	Water	600	600	Scanning Dipoles
<b>D2</b>	4	Water	600	600	
<b>E1</b>	2	Water	1500	3000	Main Bending Dipoles
<b>E2</b>	2	Water	500	2300	90° Dipole
<b>F1</b>	4	Air	15	170	Quadrupole corrector




Family D1 power converter


# POWER CONVERTER INCIDENTS

## Family A2 & A3 power converters


- No reply from serial link;
- Faulty output power stages;
- Burnt input power stage;



Family A3 PCO output power stages assembly



Family A PCO output power stages repair




Family A2 PCO input power stage explosion

# POWER CONVERTER INCIDENTS

## Family B1 power converters


- Dead time compensation ripple;
- Cabinet fans wrongly assembled;
- CAN BUS alarms;
- Faulty (R16R) current regulation board;
- Broken DC-link and system power supplies;



Family B1 PCO front panel



PULS AC/DC Switch Mode Power Supply




Family B1 wiring diagram


# POWER CONVERTER INCIDENTS

## Family B2, B3 & B4 power converters


- Broken PLC card;
- Loose connections Inside the power converter;
- Faulty (R17C3) IGBT boards;
- Main circuit breaker malfunction;



R17C3 IGBT driver board



Family B2 PCO PLC card




Family B2 PCO PLC cards


# POWER CONVERTER INCIDENTS

## Family C1 & C2 power converters

- High current on PWM filter;



Family C2 PCO wiring diagram





Broken resistors on PWM filter



# POWER CONVERTER INCIDENTS

## Family C1 & C2 power converters

- Weak output filter;
- CAN BUS alarm;
- AFE unbalanced current;
- IGBT driver;
- Dead zone compensation ripple;
- Current transducer board;



Family C1 PCO broken output filter


# POWER CONVERTER INCIDENTS

## Family C3 power converters


- Defective Auxiliary contactor;
- Control card transients immunity;
- Main Circuit Breaker Wrong State;
- IGBT linear mode drive broken transistor;
- Hitek CC1000 Thermal fuse failure;
- Hitek CC1000 Faulty Fan;
- Relay bounce;



Hitek CC100 capacitor charger



IGBT linear mode drive card



MaxiDisCap power crate

# POWER CONVERTER INCIDENTS

## Family C4 & C5 power converters

- Clogged water system;
- Defective Mean Well PS;
- Jammed water pressure sensors;
- PLC software bug (stuck in transition);
- Several CAN BUS alarm;
- Defective IGB module (unbalanced output currents);
- Cabinet temperature overheats;



Family C4 clogged water pipe



Mean Well TDR-960-48




Broken Mean Well TDR-960-48


# POWER CONVERTER INCIDENTS

## Family D1 & D2 power converters


- IGBT gate driver card badly assembled;





Family D IGBT module



A4X30 board loose resistors



Mitsubishi CM600DX-24S1 (Half-bridge)



Broken IGBT detail

# POWER CONVERTER INCIDENTS

## Family D1 & D2 power converters

- PLC software bug (drivers protection);
- Noise sensibility;

Power converter fail as soon its cabinet door is closed!



# POWER CONVERTER INCIDENTS


## Family D1 & D2 power converters

- IGBT gate driver card SMPS burn;



Onsemi MC33063ADG SMPS

IGBT gate driver power supply burning!




# POWER CONVERTER INCIDENTS

## Family E1 power converter

- Water pump;
- Flow sensor;
- Water leaks;
- Software bug;
- Capacitor bank fan;
- Auxiliary contactor;



Water flow sensor



Family E1 cooling unit control software



Family E1 PCO output cooling cabinet


# POWER CONVERTER INCIDENTS

## Family E2 power converter

- Sinus filter burn;
- Control cable routing;
- Water leaks;
- Faulty insulation monitoring device;
- Software bug (stuck in transition);



Socomec ISOM AM475



Sinus filter burnt resistor connections




Family D2 PCO sinus filter resistor installation




# IMPROVING POWER CONVERTER RELIABILITY


- Preventive maintenance;
- Continuous upgrade;
- New power converter design;
- Faulty power converter quick replacement:
  - Extension cables;
  - Output switch to a spare PCO;



Flexible output connections



Replacement of a faulty POC-A/B by a spare power converter diagram



Single-line diagram of the spare-converter

# THANK YOU

*"The unavoidable price of reliability is simplicity."*

- Tony Hoare -