



CERN Computer Centre(s) Network evolution (Part II)



Vincent DUCRET – vincent.ducret@cern.ch
HEPiX Spring 2023 – Taipei

Agenda

Part I:

- Reminder about 2019 status
- Datacentre migration (during COVID19 lockdown - 2020)
- Overview of current Datacentre Network
- Evolution of links between Main datacentre and other CERN sites
- Plans for 2023 and new Prévessin Data Centre (PDC)

Part II:

- New tools and/or features we started to deploy
- Main issues faced with new Datacentre Network setup




New tools and/or features

- Dual router attachment for all switches
 - Based on EVPN/VxLAN ESI on the routers


Servers

ToR Layer2 switches

Distribution routers




Former setup



Current setup


New tools and/or features

- Vlan on the ToR switch
 - Multi domain support on a single switch
- **Before:**
 - All servers on a switch must belong to the same Network/Bcast domain
 - Needs and server allocation may evolve over time.
 - If some servers need to be moved, we must connect them to a different switch




New tools and/or features

- Vlan on the ToR switch
 - Multi domain support on a single switch
- After:
 - Servers on a switch can belong to different Network/Bcast domains
 - ➔ Possible to “move” servers logically, without any additional hardware/cabling required



New tools and/or features


- Vlan on the ToR switch
 - Multi domain support on a single switch
- After:
 - Need to configure 802.1q trunk between routers and switches
 - Migration implies small downtime
 - Adding Vlans afterwards is transparent
- Currently applied on a limited number of switches




New tools and/or features

- Zero Touch Provisioning (ZTP) for Juniper devices
 - ZTP is proposed by default on Juniper devices

```
$ set chassis auto-image-upgrade
```



1. Upgrade
2. Reboot
3. Commit configuration
4. End of Juniper ZTP




New tools and/or features

- Zero Touch Provisioning (ZTP) for Juniper devices
 - Juniper ZTP has some limitations:
 - Single firmware upgrade: not able to follow an upgrade path
 - Supporting switches with different version and/or different configuration file implies specific configuration in dhcpd.conf
- ➔ Need to tune the default ZTP process to have a cleaner process

New tools and/or features

- Zero Touch Provisioning (ZTP) for Juniper devices
 - Juniper ZTP + enhancement via SLAX scripts:

```
$ set chassis auto-image-upgrade
```



1. Load "default-ztp.conf"
2. End of Juniper ZTP
3. Start "ztp-discovery.slax" script (called by the configuration file)

New tools and/or features

- Zero Touch Provisioning (ZTP) for Juniper devices
 - Juniper ZTP + enhancement via SLAX scripts:

`ztp-discovery.slax`

- Check our DB to get the hostname corresponding to the S/N
- Apply hostname to switch and run next script

`ztp-upgrade.slax`

- Based on the hostname or model type, upgrade the devices following a specific upgrade path (multiple upgrades if required)
- Once target version is reached, run next script

`ztp-configure.slax`


- Based on the hostname or model type, apply the configuration
- If required, apply licences
- If required, power-off device (ex: stock device preparation)

Special thanks to Carles Kishimoto (carles.kishimoto@cern.ch) who developed the SLAX scripts

Main issues


- High delivery time
 - Need to order ~1 year in advance (ex: PDC)
 - Rely on spare/lab devices for urgent request (Ex: ALICE O2 QFX chassis)
- Several IPv6 issues:
 - DHCPv6 issues
 - DHCPv6-relay option-79 in a wrong format
 - Packet loss with DHCPv6-relay binding and dual router setup
 - DHCPv6-relay option-79 not inserted for traffic crossing VxLAN tunnel
 - CEPH nodes not handling dual IPv6 default gateway dynamically

DHCPv6 relay issues: What is DHCP relay?



- DHCP client sends broadcast/multicast messages
- The first hop router intercepts the broadcast and transforms it to unicast to relay the message up to the DHCP server

DHCPv6 relay issues: option-79 wrong format




- DHCPv6 option-79 is added by the relaying router
- It contains the client MAC-Address (which may not be part of the DUID)
- Juniper router in version 18.4 adds option-79 is a wrong format

RFC 6939: 8 Bytes = `00:01:<client-mac-address>`

JunOS 18.4: 6 Bytes = `<client-mac-address>`

DHCPv6 relay issues: option-79 wrong format




- We applied a workaround on the DHCP server so it accepts “6 Bytes” option-79 as sent by Juniper router
- This workaround is not supported on the new KEA DHCP servers, so we needed a long-term fix

DHCPv6 relay issues: DHCPv6 binding and dual router setup

- Juniper routers has two modes for DHCP relay:
 - Forward-only: the router simply relays the DHCP packets.
 - DHCP binding: the router relays the DHCP packets and keep a track (binding-table) of the `<mac-address><ip-address>` associations.
- Until version 21.2, adding option-79 for DHCPv6 was only possible with DHCPv6 binding
- When DHCPv6 binding is used, some traffic inspection is done (and cannot be disabled) and will drop packet if the `<mac-address><ip-address>` association is not correct.

DHCPv6 relay issues: DHCPv6 binding and dual router setup




- VM1 created and DHCPv6 relayed by Router 1
- VM1 traffic routed normally by the two routers

DHCPv6 relay issues: DHCPv6 binding and dual router setup

VM1
MAC: aa:aa:aa:aa:aa
IPv6: 2001:1458:1::100:1


Router 1 binding table

aa:aa:aa:aa:aa ↔ 2001:1458:1::100:1




- VM1 destroyed
- Router Binding table entry stays (1 week idle timeout – based on DHCP lease duration)

DHCPv6 relay issues: DHCPv6 binding and dual router setup



- VM2 created:
 - DHCPv6 relayed by Router 2
 - It reuses VM1 IPv6 address
- Router1 will drop packet from VM2 due to DHCPv6 binding old entry

DHCPv6 relay issues: DHCPv6 binding and dual router setup



- VM2 has ~50% IPv6 packet drop
- Workaround: manually clear Router1 old DHCPv6 binding entry


DHCPv6 relay issues

- Version 21.2R1-S2:
 - Fixed the issue with Option-79 “wrong format”
 - Support Option-79 insertion with DHCPv6 “forward only “ (no more binding table)
- However it introduced a new bug...




By Francisco Welter-Schultes - Own work, CC0, <https://commons.wikimedia.org/w/index.php?curid=103292729>

DHCPv6 relay issues: Option 79 not inserted via VxLAN tunnel



- On version 21.2, DHCPv6 Bcast/Mcast packets are replicated to the 2nd router via VxLAN tunnel
- DHCPv6 packets crossing VxLAN are relayed by 2nd router without Option 79
- DHCP server sees two requests coming, one with Option 79, the second without

DHCPv6 relay issues: Option 79 not inserted via VxLAN tunnel




- DHCPv6 server replies twice (with or without IP address allocation)
- It is transparent for most of the DHCP clients
- Depending on the client/OS version, it may lead to clients being unable to get an IPv6 address...
- Version 21.2R3-S2 fixed this issue

CEPH Client and IPv6 default route handling: issue

- By default, servers learn their IPv6 default gateway via RA (Router Advertisement), and use “link-local” IPv6 address
- Servers have two default routes, each pointing to one of the router Link-local address
- Depending on the OS/system, the server may not detect correctly that one router is down.
- Behaviour tested on lab was OK, but production CEPH nodes were not...


```
[10:17][root@cephdata20b-13f09a71b3 (production:ceph/gabe/osd*48) ~]# route -6
Kernel IPv6 routing table
Destination      Next Hop          Flag Met Ref Use If
[::]/0           fe80::46ec:ce00:7ba4:8508 UG   100 65 0  enp59s0f0
[::]/0           fe80::c242:d000:7b87:fa26 UG   100 65 0  enp59s0f0
```





CEPH Client and IPv6 default route handling: fix

- This was fixed by changing the router configuration to use a virtual link-local address shared by both routers
- Servers will have only one default gateway pointing to this virtual link-local address (similar to IPv4)
- Behaviour is no more OS/System dependent
- Virtual addresses shared by routers were already configured for IPv4 and all IPv6 addresses, except link-local...


```
[root@server ~]# route -6
Kernel IPv6 routing table
Destination      Next Hop          Flag Met Ref Use If
[::]/0           fe80::405:0:1    UG    100 65  0  enp59s0f0
```




Router Upgrade path

 LAB
 773(Prévessin)

 513 Main Room
 513 Main Room 100G

 513 Barn (Critical)
 513 Vault



Q&A



