
OPERATION AND RELIABILITY OF THE ALBA KICKER MAGNETS

P. Lengua, J. Casanova, R. Muñoz, M. Sos ALBA Synchrotron, 08290 Cerdanyola del Vallès, Spain

The pulsed magnets of the ALBA Synchrotron consist of 3 Septa, 2 thyratron-driven Kickers and 4 thyristor-driven Kickers. Along the years, efforts to enhance the ALBA pulsed magnets performance and reliability have been devoted, resulting in an improvement of the LINAC-to-Booster and Booster-to-Storage beam transmission efficiency and its Mean Time Between Failures (MTBF). The performance enhancement has been achieved thanks to online feedback and control routines of the pulse signals correlated with the beam position and energy, but also by the incorporation of regular preventive hardware maintenance procedures, most of them created after our own experience with degradation of the components, few of them implemented after replacing obsolete parts requiring different maintenance routines.

Booster and Storage Ring injection schemes —



Pulsed Magnets impact on Storage Ring performance

Since 2019: **12 hours** with no beam stored at Storage Ring due to a pulse magnet incident and **4 incidences** that did not allow reinjecting for long time (>40 min). **Main hardware failures:**

- -At magnet cabinets (inside the tunnel):
 - Driver board inside the SR-Kickers failures due to degraded integrated circuits or burned low voltage power supplies. Radiation shielding has been improved.
- Thyratron degradation of the thyratron-diven Booster Kickers resulting in a degradation of the flat top of the pulse which shows thermal drifts and jitter.
- -At the magnets (inside the tunnel):
- RF-fingers deformation of the SR-Kickers, causing beam block. They have been all removed and no heating problems have been observed.
- <u>At control system (outside the tunnel)</u>: degraded contactors, PLC and safety relais inside the Control Units.

Hardware maintenance and upgrades:

- Preventive hardware electronics renovation: contactors, integrated circuits and small power supplies are replaced every 4 years at the magnet cabinets driver boards and at the Control Units. We observed their live cycle is between 5 and 6 years.
- Thyratron replacement when jitter is too high (> 100ns): performance shows a degradation after 5 years in use.
- Cooling and radiation shielding improvements.
- Implementation of data acquisition and online feedback control routines that help optimizing in real time pulse variations to recover beam injection efficiency.

M. Pont et al., "Septum and Kicker magnets for the ALBA booster and Storage Ring", in Proc. IPAC'11, San Sebastián, Spain, 2011, pp. 2421-2422



ALBA Synchrotron

Carrer de la Llum 2-26 08290 Cerdanyola del Vallès, Barcelona, Spain Tel: +34 93 592 43 00

www.albasynchrotron.es