


X-Box Summary

9.10.2024




X-Box 2 TD31 N3 N4: Structure B


- Many problems during summer
 - Visit Scandinova 6-9th August
 - Several problems with IGBT in HVPS
 - Decided to reduce voltage and wait for next fault
- Restarted 28.09.2024
- 100:1 ratio, all power to Structure B
- Pulse width 100ns
- Setpoint DUT 51MW
- BDR=2E-5 (Monday 7th)
- IGBT Interlock in modulator HVPS2
 - Scandinova visit 14th October




X-Box 2 TD31 N3 N4 Structure B- Pulse













CERN






CERN



Paz Alonso Arias | X-Box Update

CERN





XBox2 – Pulse count


File: EventDataA_20240714 579806759 580300045 File: EventDataA_20240715 0 308033 File: EventDataA_20240716 0 623390 File: EventDataA_20240717 624148 1225387

File: EventDataA_20240829 15548504 16841140 File: EventDataA_20240909 0 147631 File: EventDataA_20240910 147631 154865 File: EventDataA_20240911 154865 752189

- Problems with PXI and Pulse Count reset
 - Has this ever happened before?
- 15th July
 - Emergency stop PXI off
- 2nd September
 - Electrical cut PXI off
- Need to readjust pulse count manually
 - Not possible via Python (not allowed)
 - Maybe possible with LabView code

X-Box 3: HEK measurements

- Operative now! More or less...
- Changed also the solenoid power supply
 - "Fixed problem"
 - The installed SPS may be faulty
- Vacuum is 1.7E-7mbar
 - Leak test



- In the meantime...
 - Plan to calibrate all the lines for the test (Drive, KLYFWD and KLYRFL)
 - Plan to calibrate temperature sensors
 - Installation of bigger flowmeter for collector (in range)
 - Installation of klystron E37123 in modulator B
- Visit from Scandinova 14th October
 - Offer to come and do calorimetry (Kevin)
 - Calibrated calorimeter (custom made).
 Accuracy:
 - flow meter is +-0.8% of reading, +-0.1% full scale
 - temperature sensor is +-(0.1C + 0.17% * T)



home.cern

X-Box 2: Reminder on BD classification

