

Experience with SPS RF and outlook

Sam Pitman, Eric Montesinos, Gino Cipolla, Sebastien Calvo, Flory Matthia Ten Broeke, Fred Killing, Christophe Renaud, Joan Revoltos, Calum Sharp, Christian Schachtner, Francesco Repola, Luciano Ciampo, Odin Ervik, Kim Wagener, Alessandro Cazzaniga, Giulia Papotti, Ivan Karpov, Bartek Bielawski, Rama Calaga 10/12/2024

Introduction and outline

- 6 x 200 MHz cavities in SPS
- 2 x tetrode systems
- 1 x solid state
- Single exceptional failures
- High failure rate
- Siemens update







Introduction

One Transmitter is composed of

16 x 144 kW RF amplifiers

One RF amplifier is composed of

- 1:80 cavity splitter
- 80 x 1.8 kW RF blocs (160 transistors)
- 80:1 cavity combiner

In total

- Two transmitters
- 32 RF amplifiers
- 2560 RF blocs
- <u>5120 transistors</u>

Introduction

One Transmitter is composed of

0


0000

ors)


- 16 x 144
- One RF ar
- 1:80 cav
- 80 x 1.8
- 80:1 cav

In total

- Two tran32 RF at
- 2560 Mc 🔊
- <u>5120 tra</u>









SSPA exceptional failures

Scrubbing

Large vacuum spike on cavity 3, 14 modules broken within 30 minutes, around 30 in total.

Degraded mode for 4 days, scrubbing at flat bottom only.

Reduced number of modules that can break before calling piquet to 3

Half towers unpowered

LLRF signal cable disconnected from half towers, around 100 modules lost (over around 3 months)

2 x high power loads broken

Towers are thought to have been overdriven

Interlocks have since been connected to prevent this happening again

No AM modulation

AM turned off in HIRADMAT cycle - 14 modules lost at once

For 2 batches to be spaced half a ring apart

Peak power only achievable with AM - Mandatory not interlocked

Working on average power interlock

HOM coupler burned


10 modules lost in 30 mins prior to HOM burning Same coupler in Cav 6 to be inspected in YETS

Broken Loads

Loads on isolated port of combiners have been broken

Not clear what impact this had on failure rate

All loads to be replaced in YETS (14/30 replaced during the run)





Measures taken

Improved brazing	Tightened acceptance criteria	Installed additional logging	Commissioned test bench
Cleaned cooling water circuit	Line length analysis	Measurements of whole system	Reduced gain of individual towers
Isolating problem tower	Modules PCB improvements	Module position analysis	Changed high power loads



SSPA Failures

What we know

• Overdrive

- Modules are very sensitive to overdrive. Overdriving a small amount on the test bench resulted in rapid failure.
- Instances of known overdrive have correlated with high rates of module breakage.
- Cavity 3 has higher failure rate than Cavity 6
 - Cavity 3 has poor impedance matching step
 - Higher baseline vacuum level
- Loads need maintenance
- Thermal problems lead to high loss.
 - Brazing to coldplate is essential
 - Integrity of the cooling system

What we don't understand

- Reflected power
 - Installed scopes to monitor reflected power to towers on Cav 3
 - Could not correlate reflected power transients to module breakage (ongoing)

• Different tower breakage rates

- No understanding of why some towers experience next to no loss, and some very high loss.
- Failure rate vs Cycle
 - Difficult to analyse as SFTPRO1 is running all of the time

YETS & Future Operation

YETS

Cavity 3 matching

Reduce reflected power back to modules but also maximise power into cavity.

Inspection of HOM coupler in Cav 6

Replacement of high-power loads

New mechanical passive gain and phase adjustment.

Overdrive protection upgrade

Average power interlock

This should enable us to operate with nominal power values from 2025

Spares

Spares management is what has limited us operating at full power this year.

Worst case 3 modules broken per day we would need to replace 1500 transistors in 25-26 run.

We will have 1430 spares

>1000 need to be brazed to baseplate

Ceramic transistors

More robust

Better for pulsed power operation

plastic case absolute maximum drain-source voltage 133 V

ceramic case absolute maximum drain-source voltage 177 V



C1&2 missing power

- Reduction in gain within pulse for C1 and C2 needs to be addressed
 - See I.Karpov at JAP23
- Filament voltage was reduced to expand the lifetime of the tubes
 - See E. Montesinos at IEFC23
- This means less gain and less peak power
- Can be increased if we are prepared to consume more tubes
 - Would need to be discussed with supplier
 - Would also require more person power
- No filament transformer spares
 - About to launch a tender for delivery in 2025

ttings					7.1 - SPS20
ALL	Display settings:				
LHCION1	✓ legend	0	N		
MD1		Rescale		Vmm	
ZERO	✓ grid			· V	
LHCION4	Manual limits:				
MD2	Axis: W	•			
AWAKE1					
HIRADMT1	Min: 0.000	\$			
HIRADMT2	Max: 0.000	\$			
LHC25NS	Set				
Refresh cycles	A Save	Load			
All devices:	fwdpo				
IcFwdPower.C4				nna All	
lcFwdPower.Mi	n.C4			v v v v v v v	
IcFwdPower.Ma IcFwdPower.C5					
IcFwdPower.Mi				\sim $ $	
IcFwdPower.Ma	ix.C5				
IcFwdPower.C6					
IcFwdPower.Mi IcFwdPower.Ma		-			
+ Add		Remove			
		Remove			
IcFwdPowe	C1 LHCION1 24			~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	
IcFwdPowe	.C2 LHCION1 24		V		
IcFwdPowe	C3 LHCION1 24				
IcFwdPowe	.C4 LHCION1 24				
IcFwdPowe	.C5 LHCION1 24	•			
Devices:	Selected				
Channel setting					
Samples:	65536	\$			
Decimation		÷			
Sync to Fre					
Frigger settings	:				
Base event:	Start Flat Top	-	0.100	0.105	0.110
✓ Enabled	1000.00 ms	\$			
				≢∠ ₿	





- SPS high power RF caused a lot of downtime and degraded operation this run
- Some events were unavoidable, those that were avoidable have informed improvements already actioned or to be done in this YETS
- Ongoing efforts to understand the root causes of the high failure rate
- Nonetheless improvements are being made to reduce the failure rate
- More spares should enable us to run at nominal values next run
- Excluding exceptional events, we have benefitted from the granularity of the system
 - Broken modules changed mostly in shadow
 - Opportunity to benefit even more from this next run by reviewing piquet procedure






home.cern

Technical stop event


- A connection error lead to the LLRF signal being missing on one half of system
- Some towers were full power and some zero
- This was very unbalanced due to the integration
- T26 first lost 13 modules
- Then the load broke
- Next the final load broke
- Finally the signal was re-established to the other towers
- Around 100 modules broken as a result of this event





Thermal Paste


- Thermal paste was introduced to the cooling system
- This blocked the cooling channels of the transistors and caused overheating
- System was flushed of impurities
- Uncertain if there are still blockages causing problem
- We still see burned transistors







Cumulative Failures Over Time





SPS Downtime

- >200h downtime for SPS attributed to RF Power
 - For downtime and fault statistics see G. Papotti at <u>RF internal</u> <u>Operations Review on 21.11</u>
- Significant faults:
 - SSPA module failures
 - See next slides
 - Cavity 1 elbow arcing, exchanged and solved
 - See F. Killing at SPS MPC on 30.07
 - Cavity 3 burned HOM coupler
 - Single event not linked to beam intensity
 - Cavity 6 half towers not powered
 - Human error, covered by interlock now.

