

AMBER --> Feedback from CEDAR operation

Josef Novy

October 2024 Drell-yan run CEDAR performance

- **Measurements done**

- Alignment runs
- Diaphragm scan
 - 190 GeV positive, kaon and pion, 2e6, 20e6, 70e6, 160e6, 280e6, diaphragm 0.10, 0.20, 0.30, 0.35, 0.40, 0.45, 0.50, 0.55, 0.6 mm, (0.65, 0.7, 0.75, 0.80, 0.85, 0.90, 0.95, 1 low intensity).
 - 190 GeV negative, both kaon peak, 20e6, 70e6, 160e6, 300e6, diaphragm 0.10, 0.20, 0.30, 0.35, 0.40, 0.45, 0.50, 0.55, 0.6 mm, (0.65, 0.7, 0.75, 0.80, 0.85, 0.90, 0.95, 1 low intensity).
 - 160 GeV positive, kaon and pion, 70e6, 310e6, diaphragm 0.75, 0.65, 0.55, 0.45, 0.4, (0.35, 0.3, 0.2, 0.1 high intensity).
 - 160 GeV negative, both kaon peak, 20e6, 70e6, 160e6, 350e6, diaphragm 0.75, 0.65, 0.55, 0.45, 0.4.
- 'Periscope' Test (Misalignment Test) (190 GeV negative, 2.9e8)
 - Aligned runs and misaligned runs (diaphragm 0.2mm and 0.4mm)
- Normal Runs with Kaon Settings (190 GeV)
 - Small changes of pressure around peak – problematic control

- **Highlights & Major issues faced**

- Air contamination in CEDAR 2 and later CEDAR 1 – hard to diagnose and recover -> ~3 days lost
- Precise pressure control of CEDARs problematic
- A lot of different beam conditions take time to setup (beam tuning, CEDAR alignments etc.) – more time spend commissioning than measuring

CEDAR operation – air contamination

Initial Issue:

- Peak not found during pressure scan; wider scan revealed it much lower than expected.

Peak Movement:

- Peak position moved towards the expected value with each scan—indicating air contamination.

Verification:

- Issue confirmed by emptying to 3 bar and pressurizing back to 12 bar.

Refilling:



- System pumped to vacuum and refilled on Monday. **CEDAR 2** OK, but **CEDAR 1** showed similar problems.

Solution:



- Issue resolved by **cycling gas volume between 2 and 13 bar** for CEDAR 1.

Recommendation:

- Develop a **precise preparation procedure for CEDAR**.



Very good centering of CEDAR w.r.t beam



2024 - all PMTs less than 10urad from the center,
2023 - discrepancies up to 70urad seen....

Highlights & Major issues faced

- Air contamination in CEDAR 2 and later CEDAR 1 – hard to diagnose and recover -> ~3 days lost
- Precise pressure control of CEDARs problematic
- A lot of different beam conditions take time to setup (beam tuning, CEDAR alignments etc.) – more time spend commissioning than measuring