



**2nd inter-experiment workshop
on pixel operational experience**

CERN, March 8, 2012

FLOW RATE ISSUES IN THE ALICE SPD COOLING

Rosario Turrisi



+ In this talk

- Cooling layout
- Performance history
- Tests
- Main suspect
- Viable solutions
- Results of the interventions

SIDE A

Size: 16x26 meters
Weight: 10,000 tons³

SIDE C




SPD Silicon Pixel Detector

$$R_i = 39.3\text{mm}$$


$$R_o = 73.6\text{mm}$$

$$L = 282\text{mm}$$



+SPD structure


4



SPD




2 half-barrels



Half-barrel




5 sectors



Sector



12 half-staves



Half-stave



1 multilayer bus



1 MCM



2 bump bonded ladders



Ladder



5 read-out chip





1 sensor

Totale: 120 half-staves

1200 ASIC



9.83 M channels

half-stave = basic working unit




+ Detector's (in)side

- 1 sector = 1 cooling line
- 1 cooling line feeds 6 staves
- input: collector box, 6 capillaries 550 mm × 0.5 mm i.d.
- output: collector box, 6 pipes ~10 cm long, 1.1 mm i.d.
- 2 bellows in a row, 1/4" tube diameter, 6" and 12" length




+ The plant



+Critical components - 1


■ Capillaries

- used to enter the coexistence phase
- CuNi, 550 mm long, 0.5 mm i.d.



■ Cooling pipes

- where the heat absorption happens
- Phynox, 40 μm wall
- round 3 mm pipes squeezed to 0.6 mm inner size




■ Both sensitive to pollution!

+Critical components - 2

9

Filter Swagelok SS-4-VCR-2-60M




D = 5.6 mm

T = 11.8 mm

X = 0.7 mm (~1 mm in the filtering area)

S = 4 mm


L = ~5000 mm




Pipe: SS 316L 4-6 mm i-o diameter




Swagelok gland 6LV-4-VCR-3-6MTB7

Swagelok 316 SS VCR Face Seal Fitting, 1/4 in.
Female/Male Nut: SS-4-VCR-1 & SS-4-VCR-1




← SEM picture of the filter






+ Test in the lab


11



- For ~ 3 years the system has been tested in the DSF at CERN
- In the lab, filters were missing ($60\text{ }\mu\text{m}$ in line and the final $2\text{ }\mu\text{m}$ filter on the plant)
- very stable against changes in parameters settings (1-2 sectors at a time)
- **100% efficiency**
 - tested one half barrel at a time
 - full power to the detector ($\sim 150\text{ W/sector}$)




Max: 29.00 °C
Awr: 27.58 °C
Min: 22.66 °C
Temp: 27.28 °C
FstP(x/y): 15/73
LstP(x/y): 246/71
Points: 232



+ Efficiency history

12



DSF status (tests pre-installation): efficiency = 100%




First switch on after installation: efficiency = 87%

Long stop (you know why...) – minor rerouting of return pipes

Restart after long stop: efficiency = 71%

+ Efficiency history

13



+ Looking for the “unsub”

14


- Pressure increase line by line
 - Check if performance can be recovered by increasing the flow
 - **The flow is enhanced by the pressure increase**
- Lines swapping
 - Could be something related to the lines' path/conditions
 - **Some dependence is found – replaced lines with symmetric and shorter path**
- Lines insulation
 - Heating up the fluid can cause early bubbling
 - **Impossible to insulate the lines – too much surface w.r.t. the volume**
- SEM analysis of ‘first-stage’ filters
 - Clogging material in the lines?
 - **Keystone test...see later**
- “Ice age” test
 - Further subcooling to avoid early evaporation: 8 m of pipe in a bucket filled with ice (thanks Restaurant #1) in PP4 (~6 m before the detector)
 - **Two lines tested, flow increased, 6-7 hs/sector recovered, in one line +50% of flow**

+ Pressure correlations

15


- Principle: look at the correlation (slope) between the pressure set at the plant and the pressure close to the detector

Test done in 2009




Observed behaviors:

1. "Good" sectors have a higher pressure drop
2. "Bad" sectors are more "sensitive" to pressure changes ...



bad guys



+SEM analysis

Analysis of a filter taken from PP4, in place for 1 year approx.




Results and conclusions: "In the used filters several exogenous fragments were located clogging the filter. There were several fragments containing different composition elements. In addition to elements from the Stainless steel, the following traces of elements were found: O, Al, K, C, Sn, Cu, P, Ca, Cu, Na, Cl and Zn."

Possible origin of the fragments:

- pumps (graphite)
- hydrofilter (aluminium oxide)
- weldings (TIG weldings remnants)

NB lines: electro-cleaned s.s. pipes (Sandvik), flushed after installation with liquid freon

20 μ m



+ The picture

- Some pollution went into the lines
 - It had to go through molecular sieve/hydrofilter of the plant (2 μm filter was installed after 1 year run)
- and/or
- It had to go through the first 60 μm inline filter and clog (and partly go through) the second inline filter
 - The second clogged filter cannot be replaced (have to disassembly the experiment) and causes:
 - less flow
 - pressure drop
 - The liquid heats up to room temperature along the path to the detector (~40 meters) – this was not a problem, if alone
 - The combination of the last two causes:
 - less flow in the single line → worse performance in the sector
 - bubbling before the capillaries → local and occasional loss of performance

+ “Upgrades”

1. Installation of a $2\mu\text{m}$ at the plant (in 2008)
2. Installation of new liquid-side pipes
 - dedicated path of new lines, more straight (less elbows), shorter;
 - inox SS316L, 6/4 o/i diameter (same as before),
 - no insulation (useless)
3. Additional heat exchangers to cool the fluid close to the detector
 - 10 HX's (one per line), redundant exchange factor (more than 5 times)
 - use leakless system with water cooled down at 7.5°C
4. Flushing each line counter-flow wise
 - drain particles clogging the filters outside the line
 - redundant protection against overpressure: 2 safety valves (mechanical)
 - + pressure switch (electronic)
 - 2 filters, stainless steel, $1\mu\text{m}$ grid, on the “washing machine”
 - 1 to 4 days washing cycle per each sector

+ Optimization of power consumption

19

■ From the lab to ‘real life’:


■ Three main parameters to tune:

- thresholds
- charge-preamplifier current
- reference I-V

> power consumption

- reduced by cutting charge-preamplifier current: efficiency is conserved, a couple of “compromises” at low current

Typical distribution during run






+ Thermal contact

20


Could thermal contact be another issue?

- Performed with AOS 52029 thermal grease
 - real K measured (slightly less than promised)
 - mechanical stress tested
- Long term performance?
- Thermal/mechanical stress?
- It is a minor issue (by now): well cooled sectors do not show a worse performance





+Possible solutions?

- Essential for any intervention of this kind: first, try in the lab!
 - We build a test bench to reproduce the issue and test any possible of solution
 - We have a spare sector for most critical tests and two dummies (same hydraulics but fake detectors) to play with.
- Be open-minded: solution can come from whatever technology, e.g.



+ Test bench: plant + dummy



+Evidences from the test bench

23




- A test bench has been installed in DSF
 - same fluid and pressure/flow conditions as in the system installed in ALICE
 - plant build by EN/CV/DC, test section by INFN-Padova + CERN-ALICE
- Two lines feed a dummy sector (same hydraulics as real detector, dummy heat load) and a test hydraulics
- Thermal bath and real pipe length (~40 m) to reproduce different liquid input conditions
- Many pressure/temperature pick-up points and transparent pipe sections for visual inspection



- Loss of flow-rate due to filter clogging
- Local inefficiencies due to impedance non-perfect equalization
- Bubbling in the pipe section before the detector
 - caused by a combination of pressure drop (due to filter clogging) and heating of the fluid (thermal contact with environment and slow translation)

+ Failed attempts...

- Counterflow flushing with solvents
 - used METKLENE C3 ("SUPERFLUSH") for ~1 h
 - no clear effect – flow changed <10%
- Generate the ultrasounds close to the filter with piezoceramics:
 - tubes with size $6 \times 2.2 \times 1.0$ (LxODxID), transversal oscillation, $\nu_R \sim 3.8$ MHz
Material is PIC 181, a modified lead zirconate-titanate



+ The hard way: drilling

Tools used:


- drilling:
 - tungsten carbide tip welded on twisted ss cable
 - drill to operate the rotation
 - counter-flow at 200 mbar w/manometer to detect the presence of the hole
- cleaning:
 - rilsan pipe connected to a rotary vane vacuum pump
 - magnet tip on twisted ss cable
 - cleaning machine to force counter-flow wise a cleaning fluid



Edwards RV3 rotary vane 2-stage pump




magnet



Ø 2.5 mm ss twisted cable

cleaning machine

tungsten carbide 5-faces tip



Ø 2.5 mm ss twisted cable



+ Procedure



■ Drilling:

- rotation of the tool inside the pipe by the drill
- pressure drop (~20-50 mbar) on a manometer with specific trend when hole done

■ Cleaning:

1. suction of drilling remains with small pipe inside the stainless steel pipe (down to the filter) and vacuum pump
2. “walk” with magnet inside the pipe
 1. the steel of the filter is slightly magnetic
3. counter-flow with C_6F_{14} for 30' @ 1.5 bar
4. pipe drying with Ar flow @ 1.5 bar
5. repeat 1-4 4 more times (5 cycles total)
6. last counter-flow with fluid lasts 12 h

+ A few pictures...



+ First application

- First sector treated: #9
- It never worked properly
- First one to be turned on for some time: 12/12/2007, h 15:13, for 41'
- Pre-cleaning:
 - 4 cycles
 - vacuum cleaning + 3 magnet sweeps + vacuum cleaning + counterflow
 - last counterflow left running overnight
 - flow: from 0.27 to 0.46 g/s
- Cleaning: 5 cycles (overnight counterflow between cycle 3 and 4)
- Results:

Flow= 2.0 g/s @ 4.75 bar ^{Was: 0.27 g/s @ 6 bar}


Modules on= 100% ^{Was: 0%}

+ Materials analyses – Optical images




Residuals collected







before...










...and after the cleaning!



+ Materials analyses – SEM images 1



Materials analyses – SEM images 2



+Current performance



33

Efficiency changed from this...

to this! (and more to come!)

62.5% (75/120 on) - Nov, 30 2011

89.2% (107/120 on) - Mar, 8 2012








Thanks for the attention!





+ Backups


+ Test bench scheme






37





+ Layout of the circuit

- The pipe is in yellow
- The access point (1) is ~4.5 m away from the target point (2).
- The pipe is not fixed but laying in the aluminium box (below the yellow pipe in the exploded view)
- The pipe will be filled with liquid (C_6F_{14}) or flushed at low pressure (0.5 bar) with the same liquid



+ 'Ice age' test

We installed an 'intercooler' on the freon line in PP4 (close to SPD)


- 8 m of plastic pipe in a bucket filled with ice (many thanks to CERN Restaurant #1!)
- freon reached $\sim 8^{\circ} \text{C}$ in PP4
- Test done on 2 sectors (#6 and #5)

■ Observed:


- increase of flow in one case ($\sim 50\%$)
- clear improvement of performance
- in both cases 6/7 half-staves recovered !

+ Measurement of flow

41




Very low flow rate in sectors 7 and 9;



Pipes New routing (Symmetric inlet)

42



+ Flow/power correlation

- Slowly decreasing trend of flow
- The flow doesn't tell the whole story – stable # of modules must depend on local thermodynamical conditions (not monitored)

