



Argonne
NATIONAL
LABORATORY

... for a brighter future



U.S. Department
of Energy



THE UNIVERSITY OF
CHICAGO



**Office of
Science**

U.S. DEPARTMENT OF ENERGY

A U.S. Department of Energy laboratory
managed by The University of Chicago

Performance of the Advanced Photon Source 350-MHz 1MW CW Klystrons

Doug Horan

RF Group

Accelerator Systems Division

CWRF08 Workshop

March 25-28, 2008

PRESENTATION OUTLINE

1. Review of APS 350-MHz RF System Topology
2. APS 350-MHz RF System Operation
3. APS 350-MHz Klystron Inventory
4. APS 350-MHz Klystron Operation 2006-2008
5. Klystron Problems and Corrective Action

APS 350-MHz RF System Topology

- **7GeV Booster-Synchrotron**
- **Electron Storage Ring capable of 300mA**
- **Five 350-MHz/1.1MW CW rf systems:**
 - *four dedicated to Storage-Ring service (RF1, RF2, RF3, RF4)*
 - *one dedicated to Booster-Synchrotron service (RF5)*
- **A waveguide switch system provides 12 different operating modes:**
 - *Parallel-klystron configuration necessary for Storage-Ring currents greater than 150mA*
 - *RF3 redundancy for RF5 (Booster-Synchrotron)*
 - *Ability for RF1 to supply rf power for the 350MHz RF Test Stand*


APS 350-MHz RF System Topology

Mar 17, 2008

WGSDisplay1.adl

07:43:18

- **7GeV BOOSTER**
 - four 5-cell cavities, grouped in pairs
- **STORAGE RING**
 - 16 single-cell rf cavities, grouped in four sectors



APS 350-MHz Klystron Installation

- **Al/Pb/Al “GARAGE”
X-RAY SHIELD**

- Movable half-shell for full access to klystron
- Fixed half-shell fitted with two hinged doors to provide access for cavity tuning
- X-ray levels normally less than 2mr at one foot from garage



APS 350-MHz RF System Operating Levels

- **Normal Storage Ring operation is 103mA in “Top-Up” Mode**

- *Requires two rf stations (RF1-RF4) operating at 600-700kW CW rf output, depending on gap voltage required*
- *Beam voltage set to 80kV (where possible!) to improve operating efficiency*
- *RF drive power as high as possible for highest efficiency (~ 50-52%), limited by klystron stability issues*

- **Normal Booster-Synchrotron operation at 7GeV**

- Requires one rf station (RF3 or RF5) operating at 400-500kW peak rf power, depending on gap voltage required
- 253ms ramp from 5kW to 420kW, at 2Hz rate
- Klystron operating class A, ramped rf drive, 68kV@~12.5A.


APS 350-MHz RF System Operating Levels

- Klystron control screen for RF3 – **EEV s/n 01**
- Efficiency lower than 50% due to low rf power requirement (*reduced storage ring gap voltage*)
- Approximately 330kW rf required with no SR beam
- RF power is controlled by an AGC loop that varies mod-anode voltage in response to storage ring beam loading

Mar 17, 2008

SrfKlystronParallelA.adl

07:38:08



APS 350-MHz RF System “Hot Standby” Mode

- RF stations not providing rf power to the storage ring or 350-MHz RF Test Stand are operated in “diode mode” (no RF) at 70kV/5A
 - *RF stations are routinely switched in/out of standby mode approximately every 30 days*
 - *Maintains gun conditioning and vacuum in klystron*
 - *Maintains HVPS crowbar conditioning and general reliability*
 - *Ok with all klystrons except Thales s/n 089041; a problem with excessive body power dissipation requires 70kV/6.2A diode operation.*

APS 350-MHz Klystron Inventory

- **Total of ten klystrons tuned to APS RF Frequency – *351.93MHz***

- Present Five Operating Klystrons:

- *Three Thales TH2089A, two EEV K3513A*

- Five Spare Klystrons:

- *All Thales TH2089A.....one new, four rebuilt*

- **One Philips YK1350 klystron tuned to *352.21MHz***

- Less than 500 hours of operation

- Recently tested into rf load to full 1MW CW after ten years of storage

- Under consideration for retuning to APS frequency

APS 350-MHz Operating Klystrons

EEV K3513A s/n 02

- Presently in service at **RF1**
- **59,014 hours** as of March 13, 2008
- No operational problems noted; *absolutely trouble free!*

Thales TH2089A s/n 089041

- Presently in service at **RF2**
- **43,976 hours** as of March 13, 2008
- Ongoing unresolved problems with excessive x-ray emissions and high body power
- Sideband instabilities suppressed by careful adjustment of circulator bias; *very sensitive to output match*
- *Reduced efficiency by ~ 2% to achieve stability!*
- *Suspected input cavity electron instability which causes erratic rf output between 300-400kW*

APS 350-MHz Operating Klystrons

EEV K3513A s/n 01

- Presently in service at **RF3**
- **42,478 hours** as of March 13, 2008
- No operational problems noted; *absolutely trouble free!*

Thales TH2089A s/n 089030

- Presently in service at **RF4**
- Refurbished and factory acceptance tested on 10/31/2000
- Installed at RF4 on 11/15/05
- **15,774 hours** as of March 13, 2008
- No serious problems, *but can become unstable.*

Thales TH2089A s/n 089026

- Presently in service at **RF5** (Booster-Synchrotron)
- **33,881 hours** as of March 13, 2008
- No operational problems noted

APS 350-MHz Spare Klystrons

Thales TH2089A s/n 089043

- Last NEW klystron purchased, delivered to APS on 12/5/01
- Presently in spares storage

Thales TH2089A s/n 089036

- Refurbished; *factory acceptance tested on 12/13/02*
- Presently in spares storage

Thales TH2089A s/n 089029

- Refurbished; *factory acceptance tested on 12/8/03*
- Presently in spares storage

APS 350-MHz Klystron Inventory

Thales TH2089A s/n 089024

- Refurbished; *factory acceptance tested on 8/30/04*
- Presently in spares storage

Thales TH2089A s/n 089033

- Removed from service at RF4 on 11/15/05 at 52,720 hours
- Shipped to Thales on 3/30/06
- Thales factory refurbishment and factory acceptance test completed on 2/6/07
- Delivered to APS on 3/20/08, and passed gas test on 3/21/08
- Presently in spares storage

Klystron Operational Record 2006-2008

- ***No klystron-related downtime during this period!***

→ Klystron issues (arcing, instabilities) were originally suspected in some beam losses, but further investigation proved otherwise!

→ 350-Mhz klystron performance contributed to the outstanding overall reliability from the APS rf systems:

	<u>% DOWNTIME</u>	<u>MEAN TIME TO FAULT</u>
• FY 2006	0.84%	195.0hr
• FY 2007	0.39%	339.3hr

But there were some klystron problems.....

Klystron Problems 2006-2008

• Pantak Socket Problems

- *cracked sockets*
 - *over-tightening?*
- *broken or distorted contact springs*
 - *caused several cases of intermittent heater current*
- *oil seepage into socket*
 - *causes swelling of cable plug, loss of cable (~ \$6K!!)*



WHITE PANTAK SOCKETS CAN BREAK!

More attention to proper maintenance has reduced these failures

Klystron Problems 2006-2008

- **Excessive x-ray emissions from RF2 klystron garage** – *Thales s/n 089041*
 - *Routine Health Physics monitoring indicated ~ 7-25mr at mid-point of garage (same region of klystron where drift tube melted in 1999)*
 - *Excessive Body1 power dissipation (~9-15kW!)*
 - *Ongoing problem.....many attempts by Thales to resolve problem*



Supplemental lead shielding added to garage!

Klystron Problems 2006-2008

- **Sideband instabilities**


→ Can cause sudden beam losses and are hard to diagnose

→ Only seen on Thales klystrons


- s/n 089041 particularly bad

→ Best remedy is to adjust circulator bias for additional reflected power on the low-efficiency side of the curve

- sacrifice ~ 1-2% efficiency



Typical klystron sidebands
 $\pm \sim 1.8$ MHz from carrier



Klystron Problems 2006-2008


- Unstable rf output due to suspected electron instabilities

- multipactor in 1st or 2nd cavity suspected
- severe ~ 800kHz sidebands
- kept under control by determining a stable range for rf drive power



- Thales s/n 089041 particularly bad.....only stable between 42-46 watts of rf drive power!

1/2000 Serious loss of efficiency at RF4 & severe sidebands

86.48KV / 13.01A / 13.28KV



86.5KV / 7.77A / 31w drive



Hp Meter Reads drive power at final coupler as 59.4w Fwd 43.3w Rf


← 86.5KV / 7.77A

Klystron Problems 2006-2008

- **Arcing in ion pump connector -- EEV s/n 01**

→ *Dirty connector ????*

→ *Did not result in downtime (auxiliary non-interlocked ion pump)*



Klystron Problems 2006-2008

- **Output window arc detector trip on RF1**

-- *EEV s/n 02*

→ *Only one arc event (appeared to be a real arc)*

→ *Ran klystron into load at ~ 700-800kW for four hours with no problems*

→ *Placed back into SR service with no further problems for over a year*


APS 350-MHz Klystron Maintenance

- Adjust the rf system for best possible stability and performance
.....then leave the klystron alone if it is happy!
- Weekly analysis of operating parameters
 - *Watch for changes in efficiency, body losses, mod-anode current, perveance*
- Monitor and alarm on klystron sideband instabilities
- Thorough visual inspection of klystron every shutdown, including Pantak plugs and sockets
- Check oil quality every shutdown (30kV or greater breakdown)

APS 350-MHz Klystron Maintenance

- Perform emission checks every 7000 hours at nominal operating point.

→ *Running the cathode hotter than necessary can cause many types of chronic problems!*



APS 350-MHz Klystron Maintenance

- “Spotknock” the klystron gun at least once every two years.....*and whenever your crowbar fires excessively!*
 - A very valuable test!
 - Helps find the real cause of crowbar events.....
it may not be the klystron!

13/06

SPOTKNOCKED RFZ KLYSTRON (SN 08904) - in response to numerous unexplained CB firings

13.2kV
w/ Fairchild
close
now
Done!
dry
new
noise
position
and
up!

ANODE - BODY CERAMIC

10kV — 0
20kV — 0
30kV — 0
40kV — 0
50kV — 0
60kV — 10 μ A
70kV — 20 μ A
80kV — 50 μ A
90kV — 90-100 μ A
93kV — 130 μ A - Several Sparks
99kV — 110 μ A - Several Sparks

NO Sparks

Backed Down to 90kV,
and Leakage Current
was now $\sim 30 \mu$ A

An improvement, but
overall, very little
activity

ANODE - CATHODE CERAMIC

10kV — 0
20kV — 0
30kV — 0
40kV — 0
50kV — 30 μ A
60kV — 120 μ A
70kV — 450 μ A Sparks!
80kV — 1.27mA Sparks!
83kV — 1.78mA SPARK!
85kV — 2.4mA - Sparks
faded off
and ended

Backed Down to 60kV,
and Leakage Current is
now 60 μ A

An improvement - but
overall, very little activity
at normal operating voltages

Considering the age of this klystron (and its history) = 32k hrs,
the spotknocking process was remarkably quiet!