# "WHAT YOU GET" INJECTION & DUMP SYSTEM

C. Bracco, M.J. Barnes, W. Bartmann, E. Carlier, L. Drosdal, E. Gianfelice,

B. Goddard, V. Kain, M. Meddahi, V. Mertens, J. Uythoven, G. Vanbavinckhove


Acknowledgments: M. Di Castro, G. Le Godec, A. Lechner, R. Losito, A. Masi


### Outline


- Injection:
  - Performance during 2012 operation
    - Steering
    - Transfer Line stability
    - Injection of 25 ns beam
    - Injection HW (MKI, TDI and TCDI): problems encountered (Operation and Machine Protection), mitigations applied and foreseen actions for LS1
- LHC Beam Dump System (LBDS):
  - Performance during 2012 operation
    - Problems encountered (TCDQ, LBDS logic)
    - Applied mitigations and foreseen actions for LS1

• Golden reference trajectory was established on March 25<sup>th</sup> minimise both

losses and injection oscillations Difference wrt YASP DV LHCB1Transfer / LHC INDIV 2011 V1 golden reference for P 450.730 GeV/c - SC # 2254 LHC1\_TI2 - SPS.USER.LHC4 - CAPTURE - 30/03/12 02-26-06 1 Nominal bunch Beam 1 H Pos [mm] TT60-TED 120 100 Collimators region P 450.730 GeV/c - SC # 2254 LHC1\_TI2 - SPS.USER.LHC4 - 0 \_ 🗆 🗆 X of 🗹 Mean = -0.053 / RMS = 0.215 / RMS-dp = 0.194 / Dp Beam 2 TI8-TED 100 120 Collimators region **□** □ 0.023 / RMS = 0.144 / Dp = 0.0632 TT40-TED TI8-TED 100 120








- Need for steering became more and more frequent:
  - Once, maximum twice per week until end of September
  - Every 1-2 days in October and November (Q20 optics)
- Injection oscillations were the main reason for steering
- More time spent for steering:
  - When injection oscillations ok, still high losses **BUT** mainly **from debunched beam** (independent from transfer line steering). For operation after LS1 we could **improve the IQC to give a clearer indication of when steering is needed** (i.e. highlight region where TL collimators are installed and reference BLMs in the injection region)
  - Not same trajectory for 6 bunches and 144 bunches injection  $\Rightarrow$  corrections have to be calculated with 144 bunches  $\Rightarrow$  6 bunches have to be injected after every correction  $\Rightarrow$  time needed to change beam in the SPS. Still not known why this is more critical than before

# Transfer Lines Stability

Why steering is needed more frequently with Q20 optics?

- L. Dorsdal analysed transfer line uncorrected trajectories for 144 bunches injection since beginning of October (Q20 period) and a similar period in May/June (Q26 period)
- Model Independent Analysis (MIA) used to **define sources of variations** from the different trajectories




# Transfer Lines Stability

- No or only a small worsening of the trajectory variations was observed for the Q20 optics
- Two main sources for trajectory variations were identified:
  - Current ripples in the SPS extraction septum (MSE) are the main source of shot-by-shot variations (already mentioned in Evian 2011). Currents were changed by 5-8% to match Q20, but ripples are not larger than for Q26.
    - During TS4, further checks are foreseen to investigate any eventual deterioration of the system (visual inspection of the septum and a test campaign for the Power Converter units). Possibly a new type of converter (capacitor discharge) will be installed during LS1.
  - Orbit variation in the SPS. These variations were only monitored for the Q20 optics while a reasonable statistic for Q26 is missing → not possible to say if any worsening was introduced when moving to the new optics

### Losses from Unbunched Beam


• Some effect from **satellite enhancement** but **not only contribution** (batch-by-batch blow-up, injection cleaning?)



### Losses from Unbunched Beam

- Some effect from **satellite enhancement** but **not only contribution** (batch-by-batch blow-up, injection cleaning?)
- Beam was dumped twice by LHCb BCM at injection because of two trailing 50ns bunches (11/11 and 12/11)
- Situation was improved by shortening the **PS extraction kicker** pulse length

T. Bohl



# 25 ns Scrubbing Run

- Injection setup 6/12/2012:
  - Straightforward steering of both lines
  - Clean injections with trains of up to **288 bunches** (first injection: Beam 2 max. loss 10.8%, Beam 1 max. loss 15.3%)
- Re-steering of the lines on 9/12/2012
- Injection of several trains of 288 bunches for scrubbing run:
  - Worst injections for both beams losses at  $\sim 50\%$
  - For Beam 1, in average: max. losses at  $\sim 17\%$ , max. losses from TL at  $\sim 10\%$
  - For Beam 2, in average: max. losses at  $\sim 17\%$ , max. losses from TL at  $\sim 3\%$

# 25 ns Scrubbing Run

- Injection setup 6/12/2012:
  - Straightforward steering of both lines
  - Clean injections with trains of up to **288 bunches** (first injection: Beam 2 max. loss 10.8%, Beam 1 max. loss 15.3%)
- Re-steering of the lines on 9/12/2012
- Injection of several trains of 288 bunches for scrubbing run:
  - Worst injections for both beams losses at ~50%
  - For Beam 1, in average: max. losses at  $\sim 17\%$ , max. losses from TL at  $\sim 10\%$
  - For Beam 2, in average: max. losses at  $\sim 17\%$ , max. losses from TL at  $\sim 3\%$

Equivalent to "good" injections of 144 bunches separated by 50 ns

About a factor 2 higher then for injections of 144 bunches separated by 50 ns

# 25 ns Scrubbing Run

- Injection setup 6/12/2012:
  - Straightforward steering of both lines
  - Clean injections with trains of up to **288 bunches** (first injection: Beam 2 max. loss 10.8%, Beam 1 max. loss 15.3%)
- Re-steering of the lines on 9/12/2012
- Injection of several trains of 288 bunches for scrubbing run-
  - Worst injections f
  - For Beam 1, in av
  - For Beam 2, in av
- We are not limited by injection losses but:
- Several BLM monitors with RC filters in the injection region (including @ TDI) → sensitivity reduced by up to a factor 180 and signal delayed
- TCDI @ 5σ instead of nominal 4.5σ (better protection of LHC aperture → more margin for orbit variations)

Need for sunglasses after LS1 is confirmed (LICs under evaluation by the BLM team)

• Two spurious glitches on the RU end-switch when moving to parking (7/8/2012 and 8/8/2012) → switch active → motor stopped → huge tilt of the jaw (22 mrad – 11 mrad) → suspected plastic deformation



- Two spurious glitches on the RU end-switch when moving to parking (7/8/2012 and 8/8/2012) → switch active → motor stopped → huge tilt of the jaw (22 mrad 11 mrad) → suspected plastic deformation
  - Control module of the switch exchanged (9/8/2012)
  - TDI alignment re-checked and validated!
  - Maximum allowed angle of 5 mrad (check of the requested position and warning if bigger than specifications, low level control on position measured by resolvers and motors stopping if angle > 5 mrad)
  - Added a task in the sequencer to check TDI position before the energy ramp
- Left (upper) jaw stuck at parking position during the **25 ns scrubbing run**.

  Hypothesis: **beam induced heating** + frequent **cycling** of the jaw from injection to parking position → **mechanical degradation** of the motorization system
  - Increased current to augment motor torque
  - Exchange of full motorization block for the upstream axis of the upper jaw (during TS4)

- Failure of the LVDT of the upstream corner of upper jaw (14/10/2012)
  - Moved controls to LVDT(2)
  - Position and energy interlock thresholds setup around the new LVDT → introduced an offset of ~200 µm between settings and LVDT readings
- While moving from parking to injection position (without beam) the LU side of **TDI** upper jaw fell across the beam axis onto the lower jaw (3/12/2012).





- Failure of the LVDT of the upstream corner of upper jaw (14/10/2012)
  - Moved controls to LVDT(2)
  - Position and energy interlock thresholds setup around the new LVDT → introduced an offset of ~200 µm between settings and LVDT readings
- While moving from parking to injection position (without beam) the LU side of **TDI** upper jaw fell across the beam axis onto the lower jaw (3/12/2012).
  - Jaw put back into correct position plus hardware consolidation
  - Re-checked TDI alignment (both jaws) → no significant change in settings was measured but a further offset of 100 µm was introduce between LVDT and settings (closer to inner position interlock limit)
- LU LVDT drifted beyond inner dump limit when at injection position  $\rightarrow$  not possible to move the jaw to parking (11/12/2012)
  - Re-checked TDI alignment → defined new settings and thresholds. A total offset of
     530 μm between LVDT readings and settings persists
  - Exchange of full motorization block for the upstream axis of the upper jaw (during TS4)

- Failure of the LVDT of the upstream corner of upper jaw (14/10/2012)
  - Moved controls to LVDT(2)
  - Position and energy interlock thresholds setup around the new LVDT → introduced an offset of ~200 µm between settings and LVDT readings
- While moving from parking to injection position (without beam) the LU side of **TDI** upper jaw fell across the beam axis onto the lower jaw (3/12/2012).
  - Jaw put back into correct position plus hardware consolidation
  - Re-checked TDI alignment (both jaws) → no significant change in settings was measured but a further offset of 100 µm was introduce between LVDT and settings (closer to inner posi
    - In total TDI alignment had to be re-checked 3 times.
    - About 1 shift needed for setup and validation (downtime BUT only protection in case of MKI failures)
    - During LS1:
      - New beam screens
      - Both TDIs fully dismounted and reassembled + 2 spares
      - Possible to reduce heating? (B. Salvant talk)

- LU LVDT possible to 1
  - Re-checke 530 μm b
  - Exchange

# Wrong TCDI Settings for Q20 Optics

- SPS changed to Q20 optics (after TS3)  $\rightarrow$  transfer lines re-matched and change of  $\beta$ -function at TCDIs (end of the lines) was expected to be negligible
- Trajectories could be steered to the golden reference defined with Q26 optics → no need to change the TCDI centring → no explicit verification of TCDI settings was done
- Changes in  $\beta$  at the TCDIs were quantified in preparation of an LMC (1.5 months after moving to Q20)  $\rightarrow$  differences in settings up to +1.3 $\sigma$  at 1 collimator per line  $\rightarrow$  loose protection
- TCDIs immediately moved to corrected settings and validated with beam (~14 hours)
- Defined procedures to avoid repeating such mistakes
- Discussions on-going to find a way to improve the **detection of wrong** settings/thresholds (topic for 2013 MPS workshop)
- An automatic tool for TCDI setup was tested during an MD and is working **> safer** (new beam centers automatically in TRIM) but **not** necessarily **faster**
- Present **validation is very lengthy procedure \rightarrow** try to define a better procedure for after LS1

### MKI Erratics and Flashovers

Date	Problem	Magnet	Beam
26-Mar-12	MS erratic during PFN charging	MKI8 C	1 nominal bunch on TDI
9-April-12	Flashover, 4.4 µs pulse length (instead of 8 µs)	MKI8 D	12 bunches injected and correctly kicked
15-April-12	Flashover, 3 µs pulse length (instead of 8 µs)	MKI8 D	108 bunches on TDI, quenches, vac valves closed, cryo cond. lost
22-June-12	Flashover during UFO MD (anti- ecloud solenoids off)	MKI8 C	MKI pulsed in empty gaps; dump due to vac interlock
24-Sept-12	Flashover during Q20 injection tests, 1.3 µs pulse length	MKI8 D*	No beam extracted from SPS
13-Oct-12	Flashover, 6 µs pulse length	MKI8 D*	6 bunches injected and correctly kicked
31-Oct-12	Flashover, 4 µs pulse length	MKI8 D*	No beam extracted from SPS

Timing issues during  $H=9 \rightarrow 48$  bunches dumped on the TDI (D. Wollmann's talk)


### No flashover during 25 ns scrubbing run!

(Time for conditioning and complete set of anti-e-clouds coils. Vacuum interlock thresholds in the MKI tanks at 4E-9 and at the interconnects at up to 4.5E-8)

<sup>\*</sup> New Hardware

# Injection kicker MKI heating

MKI injection kicker measured ferrite yoke temperatures (relative to SIS threshold)



- On about **10 occasions** required to wait > 1 hour for an injection kicker (normally **MKI8D)** to cool down
  - Happened after a series of long fills with efficient turn around to refill
- In **TS 3 replaced the hottest kicker** (MKI8D) with version with more screening wires: now amongst lowest measured temperatures.
- All MKIs to be upgraded during LS1 with more screen conductors
  - Don't expect any waiting time for kicker cool-down after LS1
  - See presentation B. Salvant

# LHC Beam Dumping System

- No big operational problems or long downtime induced by the TCDQs (only a minor issue for the Beam 1 TCDQ but no impact on operation). New hardware (2×3 m C jaw → 3×3 m CFC jaw) will be installed during LS1 for operation at 6.5 TeV.
- No asynchronous beam dump with beam
- Two Asynchronous dumps without beam due to failures of WIENER power supplies (February-April).
  - Re-defined logic for cabling and powering of the LBDS
  - During LS1: modify the UPS electrical distribution and upgrade the circuit breaker technology + replace WIENER crates with crates with internal protection.
- Operation at **6.5 TeV →** "real" risk of switch erratics
  - Complete overhaul of all MKD and MKB switches to increase reliability (less sensitive to radiation) during LS1

# LHC Beam Dumping System

- A common mode failure in 12-V DC power feed line, which would not allow to dump (if that failure occurs) the beam when requested, was discovered
  - Implemented an external monitoring of the 12 V line with asynchronous dump request (**no further async. Dumps since April 2012** )
  - LBDS review on 20/06/2012 → several recommendations for additional actions to be taken during LS1, i.e. BIS for triggering a delayed asynchronous dump as ultimate protection → increased risk of asynchronous beam dump...
- Failure of a compensation power supply (13/10/2012) → replaced → offset in energy tracking system **BETS (0.9%)** → few empirical runs in order to validate the adjusted set point over the 450Gev-4Tev range (tolerance window: 0.1-0.5%)
  - test ramps (1 without and 1 with beam) and system ok!

# LHC Beam Dumping System

- A common mode failure in 12-V DC power feed line, which would not allow to dump (if that failure occurs) the beam when requested, was discovered
  - Implemented an extern request (**no further asy**
- Details on the modifications of the logic and architecture of the LBDS will be discussed at the 2013 MPS workshop
- LBDS review on 20/00 be taken during LS1, i.e protection → increased
  - After the LBDS problems were discovered ABT asked to stop high intensity operation to allow implementing mitigation solutions
  - Back to operation after ~6 hours + validation
- Failure of a compensation power supply (13/10/2012) → replaced → offset in energy tracking system **BETS** (0.9%) → few empirical runs in order to validate the adjusted set point over the 450Gev-4Tev range (tolerance window: 0.1-0.5%)
  - → test ramps (1 withou
    - Downtime for power supply replacement and system validation: ~8 hours

# Conclusions 1/2

- Operation with **50 ns**:
  - Reference golden trajectory for TI 2 and TI 8 defined in March 2012 and still valid but steering became more frequent and lengthier after moving to Q20 optics.
  - No evident explanation found for this worsening (SPS orbit, MSE ripples, losses from debunched beam, enhanced satellites, injection cleaning, etc.)
- Scrubbing run with **25 ns**:
  - Steering of the TL to 50 ns golden reference and clean injections of trains of up to 288 bunches
  - No MKI flashovers (continuous monitoring of vacuum)
  - Enhanced TDI heating (also effect of frequent cycling)
  - Need for Sunglasses/LICs after LS1 confirmed
- TDI:
  - several problems (mainly induced by heating and frequent cycling) but interlocks always worked as by design.
  - Mitigations applied and further consolidations foreseen for LS1 + completely new design for LS2

# Conclusions 2/2

- MKI:
  - 6 flashovers and 1 erratic  $\rightarrow$  up to 108 bunches mis-kicked (quenches, valves closed, cryo..)
  - Heating: ~10 times >1 hour waiting before injecting for cooling down of MKIs (normally MKI-8D) → all MKIs will be upgraded during LS1 → no more waiting time
- TCDI:
  - Wrong settings after Q20
  - Safer procedure and additional checks
- LBDS: **2 major events** causing **downtime** (12 V and offset in BETS after replacement of a compensation power supply failure)
  - New more robust TCDQ hardware for operation at 6.5 TeV installed during LS1
  - Weaknesses identified in the powering logic of the TSU  $\rightarrow$  important improvements foreseen for LS1
  - Additional safety net: link BIS → re-triggering → increased risk of async. dumps
  - More reliable MKD and MKB switches



# Cotter pin problem on the TDI.4L2 LU

- > On the 3.12.2012, during a motion, the Left Upstream axis cotter pin "jumped out" from its position
- The LU first changed the moving speed and, at the end of the movement, fell down of approx. 30 mm
- > Signs of a suspected impact between the jaws at the upstream
  - ✓ LVDTs readings on the right jaw, "jumping" on the downstream, deformation on the upstream (200 μm for RU1 and 50 μm for RU2)
  - ✓ The vacuum level at the TDI raised up from 1.1E-8 to 4.2E-7 mbar

