




Update on Beam Failure Scenarios

Jan Uythoven


Thanks to:

T.Baer, R.Schmidt, J.Wenninger, D.Wollmann,
M.Zerlauth, other MPP members and authors of
publications I used



Introduction

- Standard failure scenarios at time of design of LHC Machine Protection System
 - Did they actually occur?
 - Did the protection work as we expected?
 - Do we need to change our protection for these failure scenarios?
- Some other failure modes we were afraid of
- Did failures occur which were not foreseen
 - Were we correctly protected against them or do we need to make changes to the MPS?
- Things which went differently
- Conclusions



Failure scenarios


- Failure from 2008, splice quench, was not included in the failure scenarios
 - People were aware of this failure mode but classified it as extremely unlikely
 - As a result no 'Splice QPS system'
- Non-beam related failure mode
 - Not treated here
- However, it **shows the importance of getting the failure scenarios right**

Slide from presentation \approx 2004




R.Schmidt and J.Uythoven, June 2008, LHC Point 6.
Discussion on how the Beam Dump System reliability could be improved

This failure scenario did not happen







The different failure scenarios

- The Big Three (*New J. Physics 8 (2008), R. Schmidt et al.*)
 - Single turn failure – Injection kicker flashover
 - Single turn failure – asynchronous beam dump
 - Multi-turn failure – normal conducting D1 magnets
- Some other failure modes we were afraid of
 - Other fast kickers/systems: MKQ / MKA / AC-dipole / Transverse Feedback
 - Beam hitting the cold aperture
 - The beam dumping system does not dump
 - Power cuts
 - Magnet quenches
 - Instabilities
- Some failures we were not afraid of but which happened



Classification





Single turn failure – Injection kicker flashover

■ Description

- Injection kicker flash-over, affecting injected OR stored beam
- Beam to be absorbed by the injection absorber TDI
- Can expect quench

■ Did this failure mode actually occur?


- Yes, several times
- In case of grazing incidence (sweep) downstream magnets quenched
 - As quench at injection energy, not a big issue for sc magnets
 - However, ALICE detector affected and short in some sc circuits related in time...


■ Did the protection work as expected

- Yes, beam absorbed by the TDI

■ Do we need to change our protection for these failure scenario's


- Not really, but it showed the importance of the correct positioning of the TDI
- Additional difficulties because of heating / deformation of the TDI
 - Jaws move, position readings change
 - TDI got 'stuck' on some occasions
- Actions
 - TDI out at injection, check temperature during operation
 - LS1: replace all present TDI with similar version – general service and rigid beam screen
 - LS2: complete overhaul, upgrade for LIU and HL-LHC






Single turn failure – asynchronous beam dump

- Description
 - One beam dump extraction kicker, MKD, firing asynchronously relative to the other 14 MKD kickers. Beam gets swept over the aperture and absorber elements
- Did this failure mode actually occur?
 - NOT in the way it was foreseen
 - No switch break-down
 - Trigger Fan Out problem – different recognised failure mode (see talk N.Magnin)
- Did the protection work as expected
 - Yes, TCDQ was in the right place
- Do we need to change our protection for these failure scenario's
 - Yes, TSU will be modified including powering
 - Showed dependency on TSU: add a redundant triggering of the BIS to the re-triggering (see talk N.Magnin)







Multi-turn failure – normal conducting D1 magnets

- Most critical of all powering failures
- D1 has large beta and beam can touch the collimators a few turns after the magnet power converter has tripped
 - Reaching 10^9 protons (detection) after about 15 turns
 - Reaching 10^{12} protons at collimators (damage) could be reached after 25 turns
 - Between 15 – 25 turns the beam should be dumped via the BLMs

V.Kain LHC Project Note 322

- Did this failure mode occur
 - As part of general power perturbation and power converter trips
- Did the protection work as expected
 - Beam dumped by FMCM before significant change in current of the D1 or the orbit were measured.
 - This additional protection always worked, never needed to dump by BLMs
 - Sometimes worked too well: FMCM tripped but not power converter afterwards
- Do we need to change our protection for these failure scenario's
 - We might be dumping too early with the FMCMs and plan to relax
 - Presentation by Ivan Romera







Some other failure modes we were afraid of


■ Other fast kickers/systems:

- MKQ / MKA / AC-dipole / Transverse Feedback
- Limited their strength and interlock operation of MKA / AC-dipole with safe beam only and extra keys 'in the back (CCCR)'
 - As 'Safe Beam Flag' not SIL3, need special procedures in place to kick 'stronger'. Put in place for MD with MKA

■ Beam hitting the cold aperture




- Never really happened
- No beam induced quenches
- Limits on collimation imposed by cleaning efficiency not an issue






Some other failure modes we were afraid of

- The beam dumping system does not dump
 - List of **procedures edms 1166480**, based on three different stages:
 - Force open the BIS loops using a number of client inputs and one of the BICs itself
 - Generate an internal fault of the LBDS
 - Last resort: scrape away the beam on the collimators in IR7, using ADT (parameters not finalised and could be very dangerous)
 - Tested without beam
 - Never needed
- Power Cuts
 - FMCM
 - Do we need to test calculate the SIL level of the FMCM if we like it so much?
 - Hardware AND acquisition chain
- Magnet quenches
 - No quenches at top energy
 - Only quenches due to injection failures.
 - Circulating beam always correctly dump







Some other failure modes we were afraid of

- Beam instabilities


- When beams were unstable beams always safely dumped by
 - BLMs in collimation region
 - BPMS in point 6






Some failures we were not afraid of but happened


- Injection errors
 - Injecting the wrong beam from the SPS after changing some injection timing settings SPS
 - Issues with the timing system
- Orbit feedback putting bumps in the orbit
 - Kind of protected by Jorg's SIS / Kajetans software but this is very specialist and information to be spread
- Beam heating
 - TDI getting stuck or deformed
 - BSRT mirror possibly falling through the beam
 - MKI getting close to Curie temperature
- Other stuff falling through the beam
 - UFO's, Roman Pots UFO's






Some failures we were not afraid of but happened


- Filling of the abort gap due to RF 'failures'
 - These 'failures' often only discovered by filling of abort gap
 - Abort gap cleaning not fully automatic
 - Abort gap monitoring not working over several weeks
- Dumping one beam, absence of LR beam-beam kick dumping the other beam
 - MD 13/12/2012, did in fact not dump the other beam but measure 0.6σ effect when other beam dumped
 - This is a one turn kick and is very fast...
 - Simulations for post LS1 ongoing (TB)
- Radiation leading to many false dumps (QPS)
 - Did they bring us into dangerous situation due to missing redundancy or surveillance?
- During last powering tests discovered some circuits unprotected by the QPS.
 - Reset procedures combined with (known) fault






Things which went differently


- Never needed to mask BLMs because they're not working
 - Much better than expected reliability of the 4000 BLMs
 - General safety against all failures which are not too fast. Performed incredibly well
- Connect direct BLM to the beam dump
 - Only did this later during operation (for 2012)
 - However it never needed to trigger (as it should)
- Not done as such
 - Beam Position Change Monitor
 - Dump the beam if position changes faster than 1 mm/ms
 - No absolute reference
 - Not done. However, present BPMS with absolute measure against reference of *individual* bunches provide the required interlock in case of beam instabilities
 - Beam Current Change Monitor
 - Alternative to measurement of beam losses (at collimators)
 - Direct measurement of any problems; to be **operational** for 2015
- Many BIS channels never triggered. Do they (still) work?






Conclusions

- The LHC Machine Protection System worked properly
 - No major damage after 2008.
- The Big Three failure scenarios
 - They all occurred, with some modifications !
 - However, *equipment weaknesses detected with equipment related to 2 oo 3 of the Big Three failure modes:*
 - TDI
 - LBDS – TSU and powering
 - Changes to FMCM related to the third failure scenario
- Unexpected failure scenarios occurred (as expected)
 - Timing system, beam heating, orbit bumps, UFOs, abort gap, QPS
 - We need to further improve our protection against these due to improvement of the equipment involved and surveillance
- Continue to understand each beam dump (post mortem) before continuing operation





In other words

- On first glance, we might think that all is
- However, there was a lot of
 - This requires actions during LS1
 - Most of them treated at other talks in this workshop
 - A lot of work !
- Unexpected failures scenarios have been identified during operation over the last year. This will continue in 2015. If we don't stay vigilant we might end up

