

Safety in the Data Center

HEPIX – University of Michigan

Tony Wong—Brookhaven National Lab

Background

- BNL is a multi-disciplinary lab with projects at various stages
 - RHIC – operational since 1999
 - NSLS-II – currently building (ETA is 2015)
 - Several new buildings supporting research efforts since ~2008
- Diverse workforce
 - White collar (engineers, scientists, clerical workers)
 - Blue collar (technicians, tradesmen, unskilled labor)
- Aging infrastructure
 - Some BNL buildings date back to ~1950's. Many built in 1970's and 1980's – out of compliance with current building codes, but grandfathered in
 - New research facilities are significantly dependent on old systems (chilled water plant, power substations, outdated safety features, etc)

Safety @ BNL

- A few, isolated high profile accidents recently
 - Arc-flash incident at RHIC (Apr. 2006)
 - Building explosion (Oct. 2008) – propane leak
 - Worker fall 16 ft. from scissor lift (Nov. 2011)
- Safety culture at BNL has been changing
 - Minimize downtime and productivity losses due to accidents
 - Developing processes to record, analyze past accidents (and near-misses) and decrease occurrence of future ones
 - Emphasis on work-planning and accountability

Arc Flash Accident

Damaged Switch



Undamaged switch



Scissor Lift




Rack Tip-Over Accident

- Rack fell on its front face during installation procedure on Sept. 30, 2013
- **No one injured**
- Safety officers notified within 2 hours of accident (BNL internal requirement)
- Since servers are loaded from the front, we could not even remove servers one by one and then attempt to lift up the empty rack – **full rack weighs over 1000 lbs (454 kg)**
- Severed power cables underneath raised floor and damaged nearby CRAC unit
 - No water leak in damaged CRAC unit
 - Power cables not energized – no electrical hazards

Racks Before Accident



Fallen Rack



Adjustable Leg

Wheel




Opening for power and signal cables

Fallen Rack



Damaged Power Cable



Damaged CRAC Unit



Contributing Factors

- Typical of how accidents normally occur—a sequence of conditions that culminated with the incident
 - Tile in front of rack removed to access power and network cables
 - Rack wheels not immobilized
 - Tile in front not replaced after cables are fetched or adjusted
 - Two staff maneuver rack forward and falls into open hole

Aftermath

- Rack raised up with specialized equipment
 - Hydraulic jacks
 - Crane
- Detailed physical inspection ensued
 - Rack front door damaged beyond repair – discarded
 - One hot-plug disk was re-seated
- Extensive tests so far find **NO DAMAGE** to any of the servers
 - Fully loaded rack worth ~US\$100k
 - Warranty still valid
 - Mitigating factors
 - Rack slid down slowly due to open hole and CRAC unit took some of the momentum away
 - Raised floor only 12 in (30 cm) high, not deep enough for impact to cause significant damage

Hydraulic Jacks



Undamaged Servers



Effect on Data Center Operations

- Three power cables replaced on Oct. 14 – delayed energizing of PDU
- All rack installation interrupted ~3 weeks until investigating was completed and remediation procedures were approved on Oct. 21
- Remediation must be auditable – increase in paperwork and more time-consuming (see next slide)
- Internal discussion on hiring external, qualified helpers
- Procedures still in the process of being formalized and implemented
- A review of safety procedures will occur in 3 years (part of remediation)

(In)adequate Training?

Currently in our data center training course:


Close open tiles as soon as possible, no later than the end of each day. Make sure that the floor is flat and there are no raised edges to trip on when the tiles are replaced. Use safety cones, barricades, caution tape, or other safety equipment or devices to direct people away from hazardous areas, especially when a floor tile is removed and the under floor area is open with the potential for someone to fall.

Consider using Masonite or plywood to protect the surface and physical strength of the raised floor when moving heavy equipment like loaded computer racks.

Reinforcement must be used when moving very heavy objects like PDUs and air conditioners.

Remediation Procedures

- Administrative and engineering measures
 - A 3rd person assisting
 - Modified training for data center operations
 - Work plan (permit) in advance
 - Immobilize rack wheels when nearby tiles are removed
- Understand best practices in the field
 - Contacted rack manufacturers
 - Discuss with peer institutions
 - Further measures possible to mitigate contributing factors or conditions that cause accidents



Wheel Chocks

- Successfully used to immobilize wheels after operations were resumed
- Have a limited number of sets – need to purchase or manufacture more

Follow-Up

- What do other data centers do to prevent these kinds of accidents?
 - Risk of equipment damage
 - Risk of serious injury
- Are there more effective administrative or engineering procedures?
- The damaged rack was filled with 14 2-U servers and weighed ~1000 lbs. Racks filled with 1-U or blades would weigh ~1500 lbs. The risk of damage/injury is even higher

Summary

- First serious accident at the RACF in ~15 years of operation
- Bad timing – against backdrop of enhanced safety accountability
- Minor equipment damage but increased scrutiny and oversight by upper management
- Delays to facility operations – increased operational complexity as end result

Questions?



Ofer Rind (c. 2004) – University of Michigan alumnus