

# Vacuum incident on MKB - Implication on HV performance and tests foreseen

MPP meeting

Viliam Senaj, 25/10/2013


# MKB tank view

- Common tank for 2 magnets (MKBH or MKBV)
- Pumping by 2 sputtering pumps in the middle plus turbo pump
- Up to 29 kV and 24 kA per magnet




# MKB coil construction


- Copper coil in short circuit. Coil insulated and surface painted by a conductive painting and grounded
- Parts with risk – coil contact (HV side), connecting plates spacer and tank feedthrough



# MKBV magnet view with coil HV contact



# Coil contact



# Tank feedthrough and connecting plates spacer



# LV side of the coil and its spacer



# Conditioning and electrical tests

- Potentially risky places in case of Al pollution:
  - Tank HV feedthrough
  - Coil contact (HV side)
  - HV conductor spacer
- All risky places visually inspected (with some access limitations)
- Coil in short circuit mode and hence no possibility for DC conditioning
- Careful pulse conditioning with slowly increasing voltage and vacuum activity surveillance (~several weeks).
- As good vacuum as possible ( $< 10^{-6}$  mbar for full voltage) = lower risk of sparking and higher sensibility to a vacuum activity. Presently  $\sim 3.5 \times 10^{-6}$  mbar; sputtering pumps off (?)
- Vacuum gage reading on recently installed tank not included into VAC application yet; Interlocking? Request submitted.