




IBL Project Overview

9th Trento Workshop

Genova, February 26-28, 2014

D. Ferrère on behalf of the ATLAS Pixel community



Overview


- **IBL project** - Introduction and layout & original challenges
- **Detector & FE design features**
- **The module and stave production**
- **The module loading & stave QA overview**
- **Summary of issues met**
- **Overview of the produced staves**
- **IBL package and engineering work**
- **The integration & tests**
- **Feedback from the tests - FBK noise features**
- **The IBL insertion tests & CO₂ cooling system**
- **Towards completion and timelines**
- **Conclusions**

Introduction and Layout



IBL is an additional inner most Pixel layer that will improve our tracking performance

Features:

- ✓ 4th Pixel layer (instead of b-layer replacement)
- ✓ Closer interaction point (5.05 → 3.27cm)
- ✓ Smaller pixels (50 x 250 μm²)
- ✓ Better sensors, better R/O chip
- ✓ More robust tracking
- ✓ Better performance



Pixel with old beam pipe



Rendering view with IBL and smaller beam pipe


Sensor designs

3D and planar technology are used in combination on the same stave

Features	Planar	3D
Thickness (nominal) [μm]	200	230
Depletion voltage [V]	~ 50	10 - 25
Working voltage after LHC fluence ($5 \times 10^{15} \text{ 1MeV } n_{\text{eq}}/\text{cm}^2$) [V]	~ 1000	~ 160
Pixel [FE x Row x Column]	2x336x80	1x336x80
Active size WxL [mm^2]	16.8 x 40.9	16.8 x 20.0


Planar features:

- n-in-n technology
- **Lower thickness** than Pixel
- **Inactive edge** minimized to 200 microns



3D features:


- Double-side Double Type Columns (DDTC) process
- **Guard ring fence:** 200 microns inactive area
- **CNM:** No full 3D columns (210 μm)
- **FBK:** Full 3D columns (230 μm)



Front-end readout – FEI4

FEI4 main features:




- IBM (130 nm)
- 70 Million transistors
- 26880 pixels (50 x 250 μm^2)
- Lower noise than FE-I3 (~150e- with sensor)
- Lower threshold operation
- Higher rate capability
- Radiation hard to >250Mrad
- In use for pixel R&D and towards Upgrade phase2



Through the FEI4 history:

- First version FEI4a for validation and IBL prototypes (32 FE-I4A wafers received in 2010/11)
- FEI4b features: minor fixes + r/o functionalities + uniform pixel matrix + Power functionality
- First FEI4b delivery in Dec. 2011
- FEI4b production (30 wafers) and wafer probing is completed for IBL needs (yield ~60%)




FEI4b noise before and after irradiation (250 Mrad):
114e → 124e (both tuned)



Stave Layout

IBL description:

- 14 staves overlapping in Phi and mounted around the beam pipe on the IPT (Inner Positioning Tube)
- All the staves and services will be integrated inside 12mm envelope in radius along ~7m long
- Small clearances between beam pipe – IPT- staves - IST
- Stave to stave gap is only 0.8mm → Integration for the last stave delicate
- An instrumented stave (32 FE chips) consists of **12 planar** and **8 3D** sensor modules along 664mm)




Module Production

Thin module process steps:

- ① FE-I4 wafers thinned (150 μ m thick FE)
- ② Glued on glass support wafer
- ③ Bump deposition
- ④ Dicing wafer & substrate
- ⑤ Flip-chip & reflow
- ⑥ Substrate wafer removal by power laser.



Final module assembly and QA (at Bonn & Genova)

- Module dressing: DC module with flex
- Wire bonding
- Electrical QA and TC (including debug)






Production completed end of 2013

Two types of modules



Module Production – Failure along batches

Module



Amount per batch

28 52 51 11 42 42 24 41 58 36 5 34

Bump Bonding (BB) failures were monitored all along the production since this was the major concern during the 1st 3 batches

Module Production – Issues with 1st batches

1st batches started in June 2012

It was observed high failure rate mainly because of two types of defects:

- Open: large fraction of the pixel are not properly connected to the FE pads (seen in the noise map without HV and confirm with the source scan)
- “Shorts”: On some region of the FE it was observed coupling between surrounding pixels like shorted pixels or merge bumps (seen on the crosstalk scan)




→ Stopped production in September 2012

→ Investigations made:

- Open bumps traced back to be excessive flux in Flip Chip process.
- Still lack a convincing explanation of the origin of shorts but problem got vanished with flux-free flip chip.

→ Restarted production with flux free Flip Chip after PRR in February 2013

→ The original issue was not observed in later batches (from batch 4ff)





Stave Flex overview

Stave production and features:

- Production was done at Wuppertal - IVW
- Stave QA and preparation on handling frame followed at CPPM
- Ti pipe of 1.5mm ID and 0.1mm wall thickness
- Face plate (module side) is coated with Parylen for safer electrical break to detector HV
- Tight planarity and envelope tolerance: +/- 0.15mm
- Stave fixations on 3 points: 2 end-blocks + central support

Flex features (made in Rui's workshop at CERN and QA at Genova):

- Mix of 4 Cu-layers and 2 Al-layers for the LV lines. Total thickness ~450 μ m
- The 2 Al-layers are processed with CVD for Chrome and Copper (vias)
- The wings supply through 1 layer the connectivity for every FE. Wing thickness 70 μ m
- Wings are folded and glued at 180° for very precise envelope required for the integration








Production is complete

Module Loading

The module loading and QA consisted of 12 working steps

Key features of the loading procedure:

- Modules are mounted with a **thermal grease interface + epoxy glue drops**
- Thermal grease was **qualified for its good thermal performance and for its radiation hardness**
- **Rework and module replacement is possible** but not straight forward → few additional damages observed after this operations
- **11 out of 20 staves were thermal cycled** with loaded modules for QA – Electrical tests and metrology survey were made before and after this operation → 2 FE died after this operation (not explained)
- **Electrical insulation** between HV groups are finally inserted → Thin polyimide layer in module gaps




Module Loading - Rework


Out of 20 production staves made 14 got 1 and up to 4 module replacements

- 54% is due to damage during one of the loading or rework step
- 21% are identified after corrosion rework at DSF
- 18% are linked to FE issues not identified at an early stage
- 7% are seen at the very last step of the QA

Module replacement



Level of exposure to damage risk is height → To be investigated





Modules are thermally and mechanically bonded to a stave thanks to:

- Thermal grease pad
- 2 glue drops per FE (size of 2mm diameter)

Removing a module is always destructive

Module Loading - Overview

- **273 DC Modules Received**
 - 240 Modules Loaded on production staves
 - 23 used for reworking
- **103 CNM Modules Received**
 - 88 Loaded on staves
 - 4 used for reworking
- **79 FBK Modules Received**
 - 72 Loaded on staves



Almost 1 year of production for 20 staves
 → **Considered as a big success** with a lot of lessons learned



- Work parallelization could allow having 1 stave production rate per week
- Average time spent on a stave is 16 wd while it is 10 wd if there is no rework

Stave Quality Assurance

Target: Final test and inspections which will define the acceptance for integration

Working steps:


- **Visual inspection** + high resolution pictures
- **Power test and IV scans**
- **Basic digital and analog functionalities**
- Tuning 1st at warm temperature
- **Tuning at cold temperature at -15°C to -20°C**
- **3 thermal cycles** from warm to cold in operation
- **Source scan Sr90** (for disconnected pixels)






Typical results from stave QA

Stave QA

Threshold @ -15°C



Noise @ -15°C



IBL issues


History of big crisis:

- 1st one in September 2012: **Bump bonding defects** (short and open) after FC - **Resolved**
- 2nd one in September 2013: **Corrosion issue** found accidentally after stave07 and 08 got frozen – **Rework completed**

→ **Both impacted the schedule by several months**

Origin:


1. **Bump bonding defects:** Likely to be due to the FC machine together with the tacking method for reflow. When both were changed the problem disappeared!
2. **Corrosion issue:** DI water tests allowed to observe an extreme sensitivity of wet flex surface which with the galvanic coupling and the presence halogen explained the chemical attack of the Al-wire.
 - White persistent residue $\text{Al}(\text{OH})_3$
 - Detected halogen in samples taken from production staves after corrosion spotted




Corrosion study

Understanding and questions:


- The corrosion can be reproduced even on bare cleaned flex with the drop of DI water
 - Also seen on most of the flex producers while not systematically not on all pads
 - The most aggressive cleaning seems to help but also weaken the gold metallization
 - Coating the surface like with Urethan compounds show very good protection
 - EDS/XPS/FBI analysis showed:
 - Halogen (Cl or F) associated with the corrosion product (residue)
 - No surface halogen contamination measured on cleaned samples
 - One over two techniques showed significant Fluorine into the gold layer (~7nm)
- Where the Cl and F could come from? Surface migration, Coverlay, gold metallization?



Element	Weight%	Atomic%
Sp1		
CK	14.37	20.70
OK	53.17	57.48
FK	4.05	3.69
AlK	26.91	17.25
SiK	0.98	0.60
PK	0.51	0.28



Spectrum	C	O	F	Al	Si	P	S	Cl
Spectrum 1	6.2	2.3		90.8	0.7			
Spectrum 2	9.2	4.1		86.0	0.8			
Spectrum 3	16.0	34.6		48.5	0.6			0.3
Spectrum 4	17.3	47.7	1.1	32.0	0.4	0.8	0.4	0.4
Spectrum 5	25.6	54.0	1.7	17.4	0.3	0.5	0.2	0.2



Stave Rework


Corrosion issue: Right after the observed problem on 11 of the 12 produced staves a TF was set-up to investigate the cleaning, the understanding of the origin of the pollution, the stave rework and, the potential risk wrt the B-field and the LV current fluctuations

What is known:


- The origin of the pollution is on the flex (same issue on many manufacturers) but it is not clear where the Cl/F is located (metal layer/kapton)?
- No efficient cleaning works without degrading the metallization layer
- Potting was qualified on real module wrt to electrical functionalities before/after TC and Irradiations. → Not adopted change due to long term operation uncertainties

Rework consists of: Cleaning after wire removal, and re-bonding all the FE and wing pads

Corroded wing region
Before wire removal and
cleaning



After wet cleaning
Cleaned in term of corrosion
residue but not free of halogen



Overview of the produced staves

Target is to get the best 14 staves out of the 20 produced

Stave #	Corroded and reworked?	Passed QA	# defective channels ‰
1	Yes	Yes	1.18
2	Yes	Yes	0.67
3	Yes	Not yet	-
4	Yes	Yes	0.93
5	Yes	Yes	0.70
6	Yes	Yes	0.85
7	Yes	No	1.08
8	Yes	No	3.30
9	Yes	Yes	1.29
10	Yes	Yes	0.75



Stave #	Corroded and reworked?	Passed QA	# defective channels ‰
11	No	Yes	0.68
12	Yes	Yes	0.63
13	No	Yes	0.83
14	No	Yes	2.18
15	No	Yes	1.00
16	No	Yes	1.02
17	No	Yes	1.22
18	No	Yes	1.47
19	No	Yes	1.13
20	No	Not yet	-

- Stave 7 and 8 were classified as failing after the condensation incident (used for practicing for the next integration steps)
- FE module criteria was based on ranking less than 1% defects per FE (including additional penalties identified during the production) but stave defects is at ‰ level


IBL Package overview

IBL is certainly one of the most challenging integration:

- 14 staves of 7 m long to be integrated with small clearance such as < 1mm between them
- All staves and services are packed inside 12mm envelope along 7m long structure
- The beam pipe is integrated inside IBL package and free to be extracted





2 half shells (IPT connection to BP)



IPT is integrated on the MPC (Multi Purpose Container)




Beam pipe integration into the IPT structure




IBL integration

Next step before integration is the cooling pipe extension for each stave to 7m long by brazing

Operation made in vacuum and with an induction head



Integration is done on the MPC with the integration tool allowing fine tuning



Stave integration



1st 2 real staves (rejected at QA) were integrated with success for practicing


IBL service integration

Practice of service assembly and integration with all the strain relief along the IPT structure

- CTE mismatch of the copper type-1 bundles will be absorbed by the controlled waves
- Intermediate flex joining the stave to the Type-1 is corrugated and allows to compensate for small inaccuracy and CTE



Z-stopper locked into the service rings




Corrugated intermediate flex

Qualification of the stave and service integration thanks to the connectivity set-up

Features:

- Can test that all the FE functionalities is working
- No cooling required & test is performed in less than 5s
- Interlock is always active based on temperature survey
- Setup is mobile and can be also used in the pit
- Two set-ups built to work in // on the two sides






System was extremely useful for the stave rework and for the validation of the stave07 and 08 integration practicing

Tests of staves on the IPT


After integration of stave07, 08 and service for practicing the two staves could be characterized with CO2 cooling and using the final hardware components including services.

- Operating conditions +15°C on the cooling line
- Very stable condition in term of cooling and operation
- Dryness of the volume was about 2-3% RH
- Readout system based on RCE
- DAQ with the production ROD/BOC was also tested successfully (limited tests)
- Efficient team for work preparation and tests




"Commissioning" on the IPT



Excellent results were obtained & compatible with QA results or slightly better



Stave 7



Stave 8



“Commissioning” on the IPT – Con’t


Surface commissioning happened with two staves with the full off-detector chain

All the tests performed were completed with success:


- Connectivity finally understood and corrected on many levels
- Excellent performance with noise performance and tuning level
- Low noise occupancies and no increased occupancy with synchronous external triggering at 5kHz of the two stave
- No increased noise occupancy on one stave/half-stave when threshold scans are running on the neighbor stave/half-stave
- Beautiful cosmic tracks along the entire FE
- Nice source data with Am241 and Sr90 source

Tests performed in Jan 14

Occupancy run with source- Stave 7



Cosmic track on the entire FE





Feedback - Noise on FBK modules

Higher noise on FBK modules are regularly observed:



- During Threshold scan \rightarrow 1st four FEs on A-side are often FBK module
- Noise sensitivity seen when HitBus is enable and wire bond connected on the flex
- Noise sensitivity seen underneath the NTC when they are powered
- Double trigger noise tests exhibit some noise on FBK module into some BC ID

NB:

- It seems that the sensor backplane has a sensitive coupling to the module flex design features
- All of this should have only little impact during operation (Threshold can be adjusted, and HB is not used)





Feedback - Noise on FBK modules (Con't)




HitBus wire bonds:

- Connected on all modules between FE and flex
- Connected on reworked staves on wing side
- Register that can be disabled and not needed in operation

Stave10 and 'HitBus' enable – A8-2 (FBK)




'HitBus' disable – A8-2 (FBK)




HitBus: FE feature that allows self-triggered operation mode
 This line is active when the chip have digital activities and the 'HitBus' register is enable

Feedback - Noise on FBK modules (Con't)


- Observed noise spot which fit with the NTC location
- Measurement from UniGe with NTC power at 5V but also seen at CERN when supplying at 2.5V
- Modules are always FBK when NTC is powered. Not seen on planar and CNM modules





Stave 6 A8-2
Noise from Threshold scan



Stave#3 A8-2- Noise scan



M Stave#5 A8-2 /E SIGMA







Stave#5 A8-2
Noise scan

Feedback - Noise on FBK modules (Con't)

Latency 210
8 slices read

Stave08 Double trigger noise tests

Noise found on FBK modules



IBL insertion tests on the mock-up

Extremely delicate part for the IBL installation is the insertion

A mock-up exists in bldg 180 to practice (originally to minimize the time of intervention in the cavern and review the procedures)

- Tests made first by insertion by hands ✓
- Second stage of test with linear motor and torque limit ✓
- Repeat the above operations with services loaded into the sealing rings and test also the leak rate
- Practice the Z positioning pin insertion (IPT wrt IST)
- Practice the insertion with wrapped services at IPT extremities
- Practice the service unwrapping → procedure

Successful insertion tries



ID Mockup for installation tries






Spare IPT + dummy BP



CO₂ cooling system

IBL cooling features:

- CO₂ cooling is new for ATLAS
- Cooling capacity is for 3kW
- Two cooling plants running in parallel
- Increase the safety during bake-out in addition to the blow-off system
- Plant & 100m vacuum transfer lines already installed with distribution system close the detector
- Commissioning and 1st circulation of liquid CO₂ started last week success fully
- Electrical break at the junction of the Ti and SS pipe was a technological challenge



IBL towards the completion

Work steps	Time line
Completion of the last staves which required module replacement	mid of February
Completion of stave rework	Beginning of February
Completion of stave QA	mid-end of February
Completion of readout of stave 07 & 08 around IPT	Beginning of February
IPT engineering work – Ti-extremity to IPT electrical connection + sealing ring installation	Mid of February
Start of brazing of the 1 st 3 staves and integration of the 1 st stave	Mid of February (started)
Completion of stave and service integration (including functional electrical tests)	Mid of April
Completion of service wrapping and IBL packing for pit	End of April
IBL transport to cavern and installation/alignment inside the Pixel	From May 5 th to 14 th
Electrical and cooling service connection and final tests	Mid May to end of June

Conclusions



IBL is a detector with many interesting challenges such as:

- **New detector technology:** 1st time 3D detector produced for a detector
- **Thinner sensor and FE:** impact on the flip-chipping
- **New FE in 130nm:** after FEI4A, the B version is working as expected with set of improvement
- **Stave Al-Cu flex** to save material budget: 1st time ever tried this technology
- **Light stave structure:** Light, long and stiff object including the thin Ti-pipe
- **Stave extension to 7m long** for cooling: Brazing technique required a lot of investigations
- **Integration with tight clearances:** thanks to very precise and very well engineered tools
- **Overall engineering structures** with new composite material

Two major crisis allowed to gain more experience about what we are building but also good to remind us that building even a small scale Pixel detector is not a straight forward project

The integration and commissioning tests results are extremely positive
→ Allowing to complete the IBL with a higher level of confidence

1st stave integrated last week



BACK-UP SLIDES


Quality and yield of received wafers (depletion voltage)

latest numbers

- we received measurement results performed at CiS
- these include IV measurements and depletion voltage
- distribution of 150 depletion voltages

Depletion voltage 46 ± 6 V mpv

IBL production, batch 1-9, depletion voltage, CiS measurements, accepted wafers




CiS measurements of some wafers show higher values

still to be re-checked with independent measurements

Expect to see lower values

SC-CNM yields smoothed



electrical failure rate dominated by sensor failures

from here on only re-tested CNM sensors

BB failure rate better than for FBK ~10% on average

- 45 modules
- Tamarack laser
- Flux FC method


- 25 modules
- Tamarack laser
- Flux-free FC

- 32 modules
- Gö. laser
- Flux-free FC

- 52 modules
- Ta. laser
- Flux-free FC
- retested sens.

- 14 modules
- Gö. laser
- Flux-free FC
- retested sensors

SC-FBK yields smoothed



reduced electrical failure rate
~10%
→ single chips

higher BB failure rate
~20% for all batches

- 45 modules
- Tamarack laser
- Flux FC method

- 20 modules
- Tamarack laser
- Flux-free FC


- 20 modules
- Gött. laser
- Flux-free FC

- 33 modules
- Tamarack laser
- Flux-free FC

Note: reworked modules not included here

DC yields smoothed

Failure Total



first 3 batches BB issues

first batches done at Gö

constant electrical failure rate of 15 – 20%

BB failure rate of ~5% if not counting batch 1-3 and first Gö

- 131 modules
- Tamarack laser
- Flux FC method


- 77 modules
- Tamarack laser
- Flux-free FC

- 83 modules
- Gött. laser
- Flux-free FC


- 93 modules
- Ta. & Gö. laser
- Flux-free FC

- 39 modules
- Gött. laser
- Flux-free FC

Feedback - Noise on FBK modules – Con't



- were able to make **noise disappear** by **disabling hitbus output** of each pixel
- only seen on FBK so far (but not always)



Stave Score

Stave	#BadPix	BadPix Ratio (%)	▼ Score
ST02	579	0.67	0.44
ST13	718	0.83	0.56
ST11	585	0.68	0.58
ST12	542	0.63	0.62
ST10	646	0.75	0.62
ST05	601	0.70	0.68
ST04	799	0.93	0.69
ST06	734	0.85	0.79
ST16	879	1.02	0.83
ST15	864	1.00	0.84
ST18	1266	1.47	0.94
ST09	1110	1.29	1.00
ST17	1052	1.22	1.01
ST01	1011	1.18	1.04
ST14	1877	2.18	1.11

Better score ↙

↘ Worse score

$$\text{score} \equiv \left(\frac{\sum_{i \in \text{BadPixel}} w_i}{\sum_{i \in \text{AllPixel}} w_i} \right) \times 10^3$$


weight on each pixel

Mapping algorithm – Two points correlation function



It is commonly used in cosmology to describe distribution of observables in the sky using two-point correlation function for studying the structure of the space.

$$P(r) = \int d^3x \int d^3x' A(x)A(x')\delta^3(|x - x'| - r)$$

$A(x)$: some amplitude as a fund of position



We don't like IBL stave bad pixels localized to some area which creates holes, therefore bad pixels are better to be distributed as uniform as possible.



$$X^2 = \int dr |P(r) - P_{\text{base}}(r)|^2$$

The basic concept:
 Compare the correlation function with uniform distribution (“baseline”), and the deviation of the data from the baseline can be a measure of anisotropy.

Layout summary table – Stave integration order

Stave	DSF Rework	#Bad	Score	Planarity	Map	BadPix Distribution
ST01	YES	1011	1.04	224		
ST02	YES	579	0.44	205	#2	
ST04	YES	799	0.69	235		
ST05	YES	601	0.68	189	#14	
ST06	YES	734	0.79	290	#12	
ST09	YES	1110	1.00	229		
ST10	NO	646	0.62	243		
ST11	NO	585	0.58	298		
ST12	YES	542	0.62	314		
ST13	NO	718	0.56	224		
ST14	NO	1877	1.11	218		
ST15	NO	864	0.84	325	#13	
ST16	NO	879	0.83	329		
ST17	NO	1052	1.01	114	#1	
ST18	NO	1266	0.94	336		

