






#### Wir schaffen Wissen – heute für morgen

Paul Scherrer Institut Markus Schneider

Status of the rf-system for the high intensity proton accelerator facility at PSI








## 40 Years since first beam extracted from Ring cyclotron




Ring cyclotron in 1974











### Statistic 2013

Beam time statistics	2012	2013
Beam time Target-M/E Delivered charge	<b>4936 h</b> 10.4 Ah	4436 h 8.9 Ah
To SINQ Delivered charge	4885 h 7.1 Ah	4147 h 6.0 Ah
UCN delivered charge	0.06 Ah	0.05 Ah
Outages		
Short interruptions < 5 min	205 h (180/week)	305 h (260/week)
Overall outage (I < 1 mA)	276 h	690 h
Availability	93.5%	82.2%



## **Injector 2 cyclotron**

Resonate 150 MHz						Local shielding at extraction
Resonate 50 MHz	or 3					sector magnet
Resonator	type	material	frequency	gap voltage	Wall losses in cavity	incident power @ 2.4 mA Beam
1&3	Double gap cavity	aluminum	50 MHz	~ 420 kVp	~ 150 kW	~ 225 kW
2 & 4	Flattop cavity	aluminum	150 MHz	~ 31 kVp	~ 5 kW	~ 14 kW

~ 400 kVp @

extraction

 $\sim 50 \text{ kW}$ 


50 MHz

aluminum

Single gap cavity


2 & 4 new





#### **Specification**

Resonance frequency: Accelerating voltage: Dissipated power: Tuning range: Cavity RF-wall: Structure: Vacuum pressure: Cooling water flow: Dimension: Weight: 50.6328 MHz 400 keV 45 kW@400kV 200 kHz EN AW 1050 EN AW 5083 1e-6 mbar 15 m3/h 5.6x3.3x3.0 m 7'000 kg





#### **Status resonators**



50 MHz Resonators manufactured by SDMS in France.

Resonator 2:

Delivered in 2009 Power test in 2010 + 2011

Resonator 4:


Delivered in April 2012 Power test summer 2012 + 2013

Tests stopped due to tests of new amplifier and moving of test bunker.


Open tasks: Calibration of gap voltage Problems with bridge between lips



### **Bridge between lips of Resonator**



Inside Resonator 2 towards center of cyclotron



Bridges with thermocouples


Arcing during power tests  $\Rightarrow$  bad contact



Bridges are getting to hot redesign



#### **Status tuners**




Plunger for tuning presented at CWRF2012

Gold plated tuner was tested under power. Final tuner design in production. Assembly summer 2014

Finger contacts from: Sumitomo Heavy Industries, Ltd, Japan (Material: silver and graphite)

Contact area: copper with 4 µm hard gold plating




#### Gold plated tuner after power tests






# Moving of test stand



Resonator in old test bunker







### **Status final stages**



Assembly of circuits in machine shop




plate-capacitor

Teflon capacitor, new supplier?

First amplifier assembled in  $2013 \Rightarrow$  tests summer till end 2013 Parts for 4 more amplifiers machined. Soldering and silver plating until August 2014 Start of assembly of part two amplifiers parallel in August 2014

Start of assembly of next two amplifiers parallel in August 2014 Last 2 amplifiers assembly starts close to the end of 2014





### **Status final stages**



Transport of first amplifier to test stand


Power tests on  $50\Omega$  - load: up to 600kW.

Performance as known from existing final stages for Ring cyclotron. Continuing of production





### **Coaxial transmission line**



Coaxial transmission lines (RL 100-230, 6 1/8" EIA) from final stages to cavities. Manufactured by Spinner Munich, Germany.



## **Coaxial transmission line delivery in 2012**



Boxes in first floor WHFA

Boxes in ground floor WHFA




### **Coaxial transmission line installation**



#### Installation in WHFA and Injector 2 bunker



#### Amplifier platform for final stages in WHFA



Support of amplifier (power, air, control)



# **Outlook Injector 2 rf upgrade**



Installation in WHFA 9. Mai 2014

Next tasks for 2014:

- Installation of transmission line and support for amplifiers in WHFA
- Assembly and test of final stages
- Design driver stage
- Finish moving of test stand
- Assembly of tuners
- Continuing tests of new resonators




# The Ring cyclotron

flattop cavity sector magnet copper cavity

numbers	type	material	frequency	gap voltage	incident power no beam	incident power @ 2.4 mA beam
4	Main cavity	copper	50 MHz	~ 850 kVp	~ 250 kW	~ 600 kW
1	Flattop cavity	aluminum	150 MHz	555 kVp	~ 90 kW	~ - 30 kW








# **Problem on Flattop cavity**

25. September 2013 Called in: Problems to get flattop cavity on nominal voltage

Many events on probe at coupling loop  $\Rightarrow$  Status of ceramic at coupling loop ??

Venting the machine for change of coupling loop, but.....



Burned finger contacts at cavity opening for coupling loop



Coupling loop




# **Problem on Flattop cavity**

- 27. September 2013 Finger contacts and coupling loop replaced Conditioning of cavity at about 480 kVp gap voltage start of getting events on probe at coupling loop Over night run at 300 kVp
- 28. September 2013 450 kVp for short time, event on probe at coupling loop after that only 200 kVp achievable.  $\Rightarrow$  venting the machine and inspection of coupling loop




2nd time burned finger contacts



Coupling loop



Cross-section of coupling loop on flattop cavity



Last set of finger contacts installed. New coupling loop installed. Cooling channels checked for sufficient cooling.


Installation of two Thermocouple close to finger contacts.

Very careful start to feed cavity with rf

Temperature rises on right side faster than on left side of coupling loop. This matches to the arrangement of the molten finger contacts.


Change of main magnetic field of cyclotron has an impact on temperature on the right side of the coupling loop !





#### Molten ring of finger contacts






#### Spot on cavity wall

Painting of spot with "Aquadag 18" from Acheson (Colloidal graphite in water)









# 3rd time taking out the coupling loop

11. November 2013 temperature rise on coupling loop  $\Rightarrow$  take out coupling loop

Oil found under cavity  $\Rightarrow$  oil leak on hydraulic tuning system ?




Finger contacts intact, but hanging down



Shadows on coupling loop



## Inspection of flattop cavity



Again spot on cavity wall close to coupling loop



# **Generous painting of cavity**

#### Cavity walls painted with «Aquadag», new contacts and new coupling loop installed





## Service on tuning system



Comfortable workplace underneath the cavity

#### Clamp with hydraulic system for tuning



Hydraulic bellows replaced on oily clamps Old bellows are bent and stretched

But no oil leak found



Removed hydraulic bellows










# Activities on flattop cavity during Shutdown 2014





Replacement of Hydraulic bellows. 12 of 16 replaced

To order more bellows exact specification neededWay+/- 5 mmMax Pressure120 Bar

Tuning system:	way of below	~ 5mm	
	pressure	0 120 Bar	
	frequency range	460 kHz	


#### Beam loss (~ 300 per week), swing from 103 to 87 Bar





# Lift of expandable vacuum seal in shutdown 2014

## View through sector magnet 6 toward flattop cavity



Upper lip not visible

Trim coils in sector magnet

Lips (electrode) of flattop cavity

Lifted position of expandable vacuum seal after shutdown 2014




# Activities on flattop cavity during shutdown 2014



Cavity surface for vacuum seal

Vacuum leak on lifted expandable vacuum seal.


Viton O-ring on cavity side replaced by glued square – ring from chloroprene elastomer  $\Rightarrow$  lifetime in this area unknown (radiation)



Expandable vacuum seal (0.7 Bar compressed air)



# **Outlook flattop cavity**



Measurement on ionization chamber on flattop cavity during 2013

Still same behavior in 2014 since shutdown

- Have a closed look on temperatures on cavity (new interlock system already installed)
- Further measurements with ionization chamber
- Planing or polishing of cavity surface for vacuum seal to get ride of scratches. For this action cavity has be take out of cyclotron and bunker. ⇒ task for shutdown
- Improvements on expandable vacuum seal to avoid scratches on surface of cavity (rf-shielding ?)



Thanks to my colleagues from the RF group. Especially to: Hansruedi Fitze, Markus Bopp, Wolfgang Tron, Lukas Stingelin, Erich Wuethrich, Arthur Schmidheiny, Sebastian Jetzer, Oliver Brun, Andreas Stadler, Harald Siebold



Job description to work in the rf-group:

#### Advanced painting skills

