

Lecture 2: Magnetization, cables and ac losses

Magnetization



- superconductors in changing fields
- magnetization of wires & filaments
- coupling between filaments

Cables



- why cables?
- coupling in cables
- effect on field error in magnets

AC losses

- general expression
- losses within filaments
- losses from coupling



Superconductors in changing magnetic fields



Faraday's Law of EM Induction

$$\oint \mathbf{E} d\mathbf{l} = \int \dot{\mathbf{B}} d\mathbf{A} = \dot{\Phi}$$

- changing field
 - changing flux linked by loop
 - electric field \mathbf{E} in superconductor
 - current I_r flows around the loop
- change stops
 - electric field goes to zero
 - superconductor current falls back to I_c (not zero)
 - current circulates for ever **persistent current**


changing magnetic fields
on superconductors

- electric field
- resistance
- power dissipation

Persistent screening currents

- **screening currents** are in addition to the **transport current**, which comes from the power supply
- like eddy currents but, because no resistance, they don't decay

simplified slab model
infinite in y and z




- $\frac{dB}{dt}$ induces an electric field \mathbf{E} which drives the screening current up to current density \mathbf{J}_r
- $\frac{dB}{dt}$ stops and current falls back to \mathbf{J}_c
- so in the steady state we have persistent $\mathbf{J} = +\mathbf{J}_c$ or $\mathbf{J} = -\mathbf{J}_c$ or $\mathbf{J} = 0$ nothing else
- known as the **critical state model** or **Bean London model**
- in the 1 dim infinite slab geometry, Maxwell's equation says

$$\frac{\partial B_y}{\partial x} = -\mu_o J_z = \mu_o J_c$$

- so a uniform \mathbf{J}_c means a constant field gradient inside the superconductor

The flux penetration process


plot field profile across the slab



field increasing from zero

Bean London critical state model

- current density everywhere is $\pm J_c$ or zero
- change comes in from the outer surface



field decreasing through zero

Magnetization of the Superconductor

When viewed from outside the sample, the persistent currents produce a magnetic moment.


Problem for accelerators because it spoils the precise field shape

We can define a magnetization (magnetic moment per unit volume)

$$M = \sum_v \frac{I \cdot A}{V}$$


NB units of H

for a fully penetrated **slab**



$$M_s = \frac{1}{a} \int_0^a J_c x dx = \frac{J_c a}{2}$$

for **cylindrical** filaments the inner current boundary is roughly elliptical (controversial)



when fully penetrated, the magnetization is


$$M_s = \frac{4}{3\pi} J_c a = \frac{2}{3\pi} J_c d_f$$

where a , d_f = filament radius, diameter

Note: M is here defined per unit volume of NbTi filament

to reduce M need small d - fine filaments



Magnetization of NbTi



Coupling between filaments

recap
$$M_s = \frac{2}{3\pi} J_c d_f$$

- reduce M by making fine filaments
- for ease of handling, filaments are embedded in a copper matrix




- coupling currents flow along the filaments and across the matrix
- reduce them by twisting the wire
- they behave like eddy currents and produce an additional magnetization

$$M_e = \frac{dB}{dt} \frac{1}{\rho_t} \left[\frac{p_w}{2\pi} \right]^2$$

$$M_e = \frac{2}{\mu_o} \frac{dB}{dt} \tau \quad \text{where} \quad \tau = \frac{\mu_o}{2\rho_t} \left[\frac{p_w}{2\pi} \right]^2$$

per unit volume of wire


ρ_t = resistivity across matrix, p_w = wire twist pitch



- but in changing fields, the filaments are magnetically coupled
- screening currents go up the left filaments and return down the right

Transverse resistivity across the matrix



Poor contact to filaments



$$\rho_t = \rho_{Cu} \frac{1 + \lambda_{sw}}{1 - \lambda_{sw}}$$

where λ_{sw} is the fraction of superconductor in the wire cross section (after J Carr)

Good contact to filaments




$$\rho_t = \rho_{Cu} \frac{1 - \lambda_{sw}}{1 + \lambda_{sw}}$$

Some complications


Thick copper jacket

include the copper jacket as a resistance in parallel




Copper core

resistance in series for part of current path




Computation of current flow across matrix



*calculated using
the COMSOL
code by
P.Fabbricatore et
al JAP, 106,
083905 (2009)*

Two components of magnetization

Magnetization ↑



M_f depends on B

External field →

M_e depends on dB/dt

1) persistent current within the filaments

$$M_s = \lambda_{su} \frac{2}{3\pi} J_c(B) d_f$$

where λ_{su} = fraction of superconductor in the unit cell

2) eddy current coupling between the filaments

$$M_e = \lambda_{wu} \frac{dB}{dt} \frac{1}{\rho_t} \left[\frac{p_w}{2\pi} \right]^2$$



or $M_e = \lambda_{wu} \frac{2}{\mu_o} \frac{dB}{dt} \tau$ where $\tau = \frac{\mu_o}{2\rho_t} \left[\frac{p_w}{2\pi} \right]^2$

Magnetization is averaged over the unit cell


where λ_{wu} = fraction of wire in the section

Measurement of magnetization

In field, the superconductor behaves just like a magnetic material. We can plot the magnetization curve using a magnetometer. It shows hysteresis - just like iron only in this case the magnetization is both diamagnetic and paramagnetic.




Note the minor loops, where field and therefore screening currents are reversing



Two balanced search coils connected in series opposition, are placed within the bore of a superconducting solenoid. With a superconducting sample in one coil, the integrator measures ΔM when the solenoid field is swept up and down




Magnetization measurements

flux jumping at low field caused by large filaments and high J_c






RRP Nb_3Sn wire with 50 μm filaments

NbTi wire for RHIC with 6 μm filaments



Fine filaments for low magnetization

Accelerator magnets need the finest filaments - to minimize field errors and ac losses



Typical diameters are in the range 5 - 10µm. Even smaller diameters would give lower magnetization, but at the cost of lower J_c and more difficult production.

Cables - why do we need them?

- for accurate tracking we connect synchrotron magnets in series
- for a given field and volume, stored energy of a magnet is fixed, regardless of current or inductance

- for rise time t and operating current I , charging voltage is

$$V = \frac{LI}{t} = \frac{2E}{It}$$

$$E = \frac{1}{2} LI^2 = \frac{B^2}{2\mu_0} vol$$

RHIC $E = 40\text{kJ/m}$, $t = 75\text{s}$, 30 strand cable

cable $I = 5\text{kA}$, charge voltage per km = **213V**

wire $I = 167\text{A}$, charge voltage per km = **6400V**

FAIR at GSI $E = 74\text{kJ/m}$, $t = 4\text{s}$, 30 strand cable

cable $I = 6.8\text{kA}$, charge voltage per km = **5.4kV**

wire $I = 227\text{A}$, charge voltage per km = **163kV**




- so we need high currents!
- a single $5\mu\text{m}$ filament of NbTi in 6T carries 50mA
- a composite wire of fine filaments typically has 5,000 to 10,000 filaments, so it carries 250A to 500A
- for 5 to 10kA, we need 20 to 40 wires in parallel - **a cable**




the RHIC tunnel


Cable transposition

- many wires in parallel - want them all to carry same current
zero resistance - so current divides according to inductance
- in a simple twisted cable, wires in the centre have a higher self inductance than those at the outside
- current fed in from the power supply therefore takes the low inductance path and stays on the outside
- outer wires reach J_c while inner are still empty
- so the wires must be fully **transposed**, ie every wire must change places with every other wire along the length
inner wires \Rightarrow outside outer wire \Rightarrow inside
- three types of fully transposed cable have been tried in accelerators
 - rope
 - braid
 - Rutherford







Rutherford cable



- Rutherford cable succeeded where others failed because it could be compacted to a high density (88 - 94%) without damaging the wires, and rolled to a good dimensional accuracy ($\sim 10\mu\text{m}$).
- Note the 'keystone angle', which enables the cables to be stacked closely round a circular aperture






Manufacture of Rutherford cable




Coupling in Rutherford cables

- Field transverse coupling via crossover resistance R_c





- Field transverse coupling via adjacent resistance R_a

- Field parallel coupling via adjacent resistance R_a usually negligible




crossover resistance R_c
adjacent resistance R_a



Magnetization from coupling in cables

- Field transverse
coupling via
crossover
resistance R_c

$$M_{tc} = \frac{1}{120} \frac{\dot{B}_t}{R_c} \frac{c}{b} p N(N-1) = \frac{1}{60} \frac{\dot{B}_t}{\rho_c} p^2 \frac{c^2}{b^2}$$



where M = magnetization *per unit volume of cable*, p = twist pitch, N = number of strands
 R_c R_a = resistance per crossover ρ_c ρ_a = effective resistivity between wire centres

- Field transverse

coupling via adjacent resistance R_a

where θ = slope angle of wires $\cos \theta \sim 1$

$$M_{ta} = \frac{1}{6} \frac{\dot{B}_t}{R_a} p \frac{c}{b} = \frac{1}{48} \frac{\dot{B}_t}{\rho_a} \frac{p^2}{\cos^2 \theta}$$

- Field parallel

coupling via adjacent resistance R_a

$$M_{pa} = \frac{1}{8} \frac{\dot{B}_p}{R_a} p \frac{b}{c} = \frac{1}{64} \frac{\dot{B}_p}{\rho_a} \frac{p^2}{\cos^2 \theta} \frac{b^2}{c^2}$$

(usually negligible)

- Field transverse
ratio crossover/adjacent

$$\frac{M_{tc}}{M_{ta}} = \frac{R_a}{R_c} \frac{N(N-1)}{20} \approx 45 \frac{R_a}{R_c}$$

So without increasing loss too much can make R_a 50 times less than R_c - anisotropy

Cable coupling adds more magnetization

filament magnetization M_f depends on B

$$M_s = \lambda_{su} \frac{2}{3\pi} J_c(B) d_f$$

coupling between filaments M_e
depends on dB/dt

$$M_e = \lambda_{wu} \frac{dB}{dt} \frac{1}{\rho_t} \left[\frac{p_w}{2\pi} \right]^2$$

coupling
between wires
in cable depends on dB/dt


$$M_{tc} = \lambda_{cu} \frac{1}{120} \frac{\dot{B}_t}{R_c} p \frac{c}{b} N(N-1)$$

$$M_{ta} = \lambda_{cu} \frac{1}{6} \frac{\dot{B}_t}{R_a} p \frac{c}{b}$$

where λ_{cu} = fraction of cable in the section


Magnetization ↑

External field →




Controlling R_a and R_c

- surface coatings on the wires are used to adjust the contact resistance
- the values obtained are very sensitive to pressure and heat treatments used in coil manufacture (to cure the adhesive between turns)
- *data from David Richter CERN*



Cored Cables

- using a resistive core allows us to increase R_c while keeping R_a the same
- thus we reduce losses but still maintain good current transfer between wires
- not affected by heat treatment




Magnetization and field errors – an extreme case

Magnetization is important in accelerators because it produces field error. The effect is worst


at injection because

- $\Delta B/B$ is greatest
- magnetization, ie ΔB is greatest at low field




*skew
quadrupole
error in
Nb₃Sn dipole
which has
exceptionally
large
coupling
magnetization
(University of
Twente)*

AC loss power



Faraday's law of induction

$$\oint E dl = \frac{d}{dt} \int_A B dA$$



loss power / unit length in slice of width dx

$$p(x) = E J_c dx = \frac{dB}{dt} J_c dx$$

total loss in slab per unit volume

$$P = \dot{B} M$$



$$P = \frac{1}{a} \int_0^a p(x) dx = \frac{1}{a} \frac{dB}{dt} J_c \int_0^a x dx = \dot{B} J_c \frac{a}{2} = \dot{B} M$$

for round wires (not proved here)


$$P = \dot{B} M = \frac{4}{3\pi} \dot{B} J_c a = \frac{2}{3\pi} \dot{B} J_c d_f$$

also for coupling magnetization

$$P_e = \dot{B} M_e = \dot{B}^2 \frac{l}{\rho_t} \left[\frac{p_w}{2\pi} \right]^2 = \frac{\dot{B}^2}{\mu_o} 2\tau$$



Hysteresis loss



loss over a field ramp



$$Q = \int_{T_1}^{T_2} M \frac{dB}{dt} dt = \int_{B_1}^{B_2} M dB$$

loss per ramp
independent of \dot{B}

- in general, when the field changes by δB the magnetic field energy changes by $\delta E = H \delta B$ (see textbooks on electromagnetism)
- so work done by the field on the material $W = \int \mu_o H dM$
- around a **closed loop**, this integral must be the energy dissipated in the material

$$Q = \int \mu_o H dM = \int \mu_o M dH$$

hysteresis loss
per cycle
(not per ramp)



Integrated loss over a ramp

1) Screening currents within filaments


$$Q = \int_{B_l}^{B_2} M(B) dB$$

J_c and M vary
with field

Kim Anderson
approximation

$$J_c(B) = \frac{J_o B_o}{(B + B_o)}$$

good at low field, less so at high field



round
wire

$$M_s(B) = \frac{2}{3\pi} J_c(B) d_f$$


$$Q = \frac{2}{3\pi} \int_{B_l}^{B_2} \frac{J_o B_o}{(B + B_o)} d_f dB = \frac{2}{3\pi} d_f J_o B_o \ln \left\{ \frac{B_2 + B_o}{B_l + B_o} \right\}$$

2) Coupling currents between filaments

loss per ramp, independent of \dot{B}

$$M_e = \dot{B} \frac{1}{\rho_t} \left[\frac{p_w}{2\pi} \right]^2$$

$$Q = \int_{B_l}^{B_2} M(\dot{B}) dB = \frac{(B_2 - B_l)^2}{(T_2 - T_1)} \frac{1}{\rho_t} \left[\frac{p_w}{2\pi} \right]^2$$



3) Coupling currents between wires in cable


loss per ramp $\sim 1/\Delta T$

$$M_{tc} = \frac{1}{60} \frac{\dot{B}_t}{\rho_c} p_c^2 \frac{c^2}{b^2}$$

$$Q = \int_{B_l}^{B_2} M_{tc}(\dot{B}) dB = \frac{(B_2 - B_l)^2}{(T_2 - T_1)} \frac{1}{\rho_c} \frac{p_c^2}{60} \frac{c^2}{b^2}$$

all per unit volume
- volume of what?

The effect of transport current



plot field profile across the slab


- in magnets there is a transport current, coming from the power supply, in addition to magnetization currents.
- because the transport current 'uses up' some of the available J_c the magnetization is reduced.
- but the loss is increased because the power supply does work and this adds to the work done by external field

total loss is increased by factor $(1+i^2)$ where $i = I_{max} / I_c$

$$E = \frac{2}{3\pi} d_f J_o B_o \ln \left\{ \frac{B_2 + B_o}{B_1 + B_o} \right\} (1+i^2)$$

usually not such a big factor because


- *design for a margin in J_c*
- *most of magnet is in a field much lower than the peak*



AC losses from coupling

1) Persistent currents within filaments

$$P_s = \frac{2}{3\pi} \lambda_{su} \dot{B} J_c d_f$$



2) Coupling between filaments within the wire

$$P_e = \lambda_{wu} \dot{B}^2 \frac{l}{\rho_t} \left[\frac{p_w}{2\pi} \right]^2$$

3) Coupling between wires in the cable

$$P_{tc} = \lambda_{cu} \frac{1}{120} \frac{\dot{B}_t^2}{R_c} \frac{c}{b} p_c N(N-1)$$

$$P_{ta} = \lambda_{cu} \frac{1}{6} \frac{\dot{B}_t^2}{R_a} p_c \frac{c}{b} \quad P_{pa} = \lambda_{cu} \frac{1}{8} \frac{\dot{B}_p^2}{R_a} p_c \frac{b}{c}$$

Summary of losses - per unit volume of winding

1) Persistent currents in filaments

power W.m^{-3}

$$P_s = \lambda_{su} M_f \dot{B} = \lambda_{su} \frac{2}{3\pi} J_c(B) d_f \dot{B}$$

loss per per ramp J.m^{-3}

$$Q_s = \lambda_{su} \frac{2}{3\pi} d_f J_o B_o \ln \left\{ \frac{B_2 + B_o}{B_1 + B_o} \right\}$$

where λ_{su} , λ_{wu} , λ_{cu} = fractions of superconductor, wire and cable in the winding cross section

2) Coupling currents between filaments in the wire

power
 W.m^{-3}

$$P_e = \lambda_{wu} M_e \dot{B} = \lambda_{wu} \frac{\dot{B}^2}{\rho_t} \left(\frac{p}{2\pi} \right)^2$$

3) Coupling currents between wires in the cable

transverse field crossover
resistance power W.m^{-3}

$$P_{tc} = \lambda_{cu} \frac{1}{120} \frac{\dot{B}_t^2}{R_c} p \frac{c}{b} N(N-1)$$

transverse field adjacent
resistance power W.m^{-3}

$$P_{ta} = \lambda_{cu} \frac{1}{6} \frac{\dot{B}_t^2}{R_a} p \frac{c}{b}$$

*don't forget the
filling factors*

parallel field adjacent
resistance power W.m^{-3}

$$P_{pa} = \lambda_{cu} \frac{1}{8} \frac{\dot{B}_p^2}{R_a} p \frac{b}{c}$$

Concluding remarks

- changing magnetic fields drive superconductor into resistive state \Rightarrow losses – leave persistent currents
- screening currents produce magnetization (magnetic moment per unit volume)
 \Rightarrow lots of problems - field errors and ac losses
- in a synchrotron, the field errors from magnetization are worst at injection
- we reduce magnetization by making fine filaments - for practical use embed them in a matrix
- in changing fields, filaments are coupled through the matrix \Rightarrow increased magnetization
 - reduce it by twisting and by increasing the transverse resistivity of the matrix
- accelerator magnets must run at high current because they are all connected in series
 - combine wires in a cable, it must be fully transposed to ensure equal currents in each wire
- wires in cable must have some resistive contact to allow current sharing
 - in changing fields the wires are coupled via the contact resistance
 - different coupling when the field is parallel and perpendicular to face of cable
 - coupling produces more magnetization \Rightarrow more field errors
- irreversible magnetization \Rightarrow ac losses in changing fields
 - coupling between filaments in the wire adds to the loss
 - coupling between wire in the cable adds more

never forget that magnetization and ac loss are defined per unit volume - filling factors