


# CDF silicon cooling: problems and recovery

- I will not talk..
- The CDF silicon detector cooling system
  - The leak
    - Investigation
    - Repair
- Status




*Ignacio Redondo*





# Operations

- Rocky commissioning: blocked cooling lines, fried chips due to bad beam aborts, connector cards that tend to disconnect, broken wire bonds due to Lorentz force resonances, PS switching off by themselves... See *Ricardo Eusebi* INSTR 2008, *Marcel Stanitzki*, VERTEX 2006...
- Aggressive maintenance. Huge amount of work in **automation** as the operations group shrink.
- 2 ISL circuits lost due low flow. Both were opened with the laser. One with a stuck prism.
- East ISL+L00 off due to **cooling leak**
- **Radiation damage monitoring program**, particularly of L00 and SVX L0. I. Redondo CMS Pixel Workshop 2006, S. Worm Vertex 2003..
- Radiation monitoring with diamonds





# Silicon detectors inside CDF



- It is (was?) the largest operating silicon detector in HEP:
  - 7 m<sup>2</sup> of silicon covers  $1.2 \text{ cm} < r < 32 \text{ cm}$
  - 722,432 channels/ 704 modules/ 5644 chips
- 8-bit readout, on-chip pedestal subtraction
- Silicon Vertex Trigger (SVT) capable of measuring (and triggering on) impact parameter at Level 2








## CDF Silicon in Run II

- Three sub-detectors:
  - L00 – Single sided CMS-type sensors
  - SVX II – 5 double sided layers
  - ISL – Links inner silicon to outer tracker, extend forward coverage
- Extends 1.2 to 32 cm in  $r$ , up to 1.8 in  $\eta$



**SVX portcards**  
(optical convertors)






# Cooling

- Everything sealed in a Nitrogen Volume
- Direct cooling of the L00 sensors to slow radiation damage
- Evacuate 3.5 kW of heat from electronics within the detector:
  - Readout Chips on top of the sensors (ISL and SVX) sensors
  - Portcards: Optical convertor and power modules.



ISL/L00 portcards







## Cooling System

- System is subatmospheric inside the detector. Leaks suck air into system rather than pushing coolant onto detector or electronics
- DI resin + UV to keep coolant inert
- Two separated subsystems:
  - SVX and L00 sensors coolant is **30 % glycol at -10 C**. Broken into 8 *cooling circuits* on face of central detector with separate *electronic control valves*.
  - ISL sensors and optical convertor modules. Coolant (**6 C**) changed from distilled water to **10% glycol** in 2005 to avoid a rare freeze condition. Can isolate ISL Sensors, ISL Porcards and SVX Porcards (of each half).







## ISL prehistory: A difficult commissioning

- Problem: cooling insufficient to switch on parts of ISL
- Reason: 12 ISL cooling lines (~1/3) blocked by glue (discovered after installation)
- 2002: 11 lines successfully opened by strong laser (not trivial: work with borescopes, shoot laser around corner with prisms)
- Reprise in 2006:
  - Cause (2002): 2 prisms got stuck in cooling lines during retraction
  - Effect (2006): Insufficient cooling to these compromised lines due to air leak in the system

### Blocked ISL Cooling Lines





## Developing symptoms

- Since March 2006: the conductivity of the ISL system went out of scale during a shutdown.
  - This behaviour had been observed before as the detector warms up. It was considered normal.
  - Several attempts to bring it down after the shutdown were not successful.
  - Problem was investigated but no effect on the system was observed
- Beginning of 2007: ISL Cooling System degrades
  - The ISL cooling system became more *unstable*. After a trip or a power outage the flows used to operate the detector were not easily recovered.
  - At the beginning of 2007 some of the *electronic valves started to fail*. This problem got worse with time.
  - pH was only measured on March 07: ~ 2 (*between gastric acid and lemon juice!*).







## Source of Acidity?

- No significant concentration of inorganic ions
- Glycol can oxydate into carboxylic acids, similar process to wine turning to viniger.
- Ion chromatography analysis shows carboxylic acids, mostly


formic acid as source of the low



- Al vulnerable to corrosion below pH 2 because Alumina becomes soluble
- Corrosion resistance is alloy-dependent:
  - Heat affected zone in 6061-Al welds (ISL portcard rings) most sensitive
  - 1100-Al test sample (pipes cooling the sensors) shows no corrosion or mass loss



## Conductivity history




- March 2006 ISL conductivity went out of range of the inline conductivity meter
  - Dashed line shows the estimated behavior of the conductivity
  - Numbers show measurements performed by external labs
- e-valves failures in February – March 2007.
- pH was only measured on March 07: ~ 2 (between gastric acid and lemon juice!).
- **Problem was aggressively attacked!!!**



## System drain

- In March 2007, pH of the ISL cooling system was **1.9** and the conductivity **3300  $\mu\text{S}/\text{cm}$** .
- Treating the coolant with **chemicals** was **discarded** without a complete risk assessment.
- Diluting and/or draining the system was the desired coolant quality. This option would drain the system.
- 16 h access was requested to perform the work contained in the system and replace damaged components.
- The piping system was divided operationally and each section was drained.
- Around 3 – 4 barrels (55 gallons per barrel) of coolant were removed from the system. Glycol was almost completely removed from the system.



**Conductivity = 700  $\mu\text{S}/\text{cm}$**

**pH = 2.8**


- But the operation had to be repeated several times (~5) to reach pH > 4





## Infrastructure: ISL Cooling

- We used a setup with 1/100 of coolant in the system to emulate the effect of the dionizing resin on the ISL system.



- Our tests in the lab showed that at pH ~ 2, the resin worked perfectly.  
**But samples not only had a decrease in conductivity, pH also increased.**
- Obtained a prediction of the quantity of resin needed to get the desired pH and Conductivity.
- We used a larger resin bed to decrease conductivity and increase pH.  
Values obtained were:


**Conductivity = 8 μS/cm**

**pH = 4.5**



## Infrastructure: ISL Cooling


- Coolant was successfully neutralized by draining (to 700  $\mu\text{Si}/\text{cm}$ , pH 2.8) and de-ionizing with resin (to 8  $\mu\text{Si}/\text{cm}$ , pH 4.5).
- Degradation on West portcard flows stopped after pH was increased.
- No additional flow problems observed in ladder lines.
- But...
- **Welds of the aluminium rings which cool the optical transmitters (portcards) had already corroded.**
- Since the system is sub-atmospheric, leaks result in lower flows. In May flow was too low to operate the portcards.



**Since May and up to the shutdown in August we were not able to operate East ISL/L00 (affected 300 pb<sup>-1</sup>)**





# ISL Portcard rings



Portcard ring


- Manifold - AL 6061-T6, 0.7 mm wall, 127 mm long tube 6 mm ID
- Cooling Rings - AL 5052, 5 mm wall, oval tubes (21 sided)
- Welded - either 5356 or 4043 filler
- Inner surface area: 0.12m<sup>2</sup>
- Fed by Cilran (Silicon) tubing from COT face
- Impossible to access from outside, isolated by volume full of cables, ~60cm in z.








Repair







## Leak location





## ISL Cooling Repair


- **Keep the silicon cold and dry:**
  - Plastic barrier encloses wire chamber bore, 600cft volume.
  - Desicant based air drier will provide 300cft/min to the volume.
  - Dewpoint always below –10 C.
- **Cover holes with epoxy DP-190 from the inside of the pipe using borescopes and catheters.**
- Repairs performed over a month with 4 people shifts lead by FNAL specialist (“*head surgeon*”) Ken Schultz.
  - Vacuum tests show that the Al lines are as tight as the stainless steel ones (SVX portcards)
  - **Cooling running stable for a year**







# Repair





## *Current Status*

- System running reasonably stable for a year
- New inline conductivity meters with larger range installed
- Samples are taken to measure pH and conductivity on a weekly basis
- Oxygen and Nitrogen levels coming out from the system are monitored

## *Conclusion*

- The 2007 summer shutdown allowed us to patch the cooling system.
- 1(2) more years to go!






## *ISL repair task force*

•Del Allspach, Mary Convery\*, Jose Enrique Garcia, Doug Glenzinski , Ignacio Redondo Fernandez\*, Ulrich Husemann, C.M. Lei, Mike Lindgren, Aseet Mukherjee\*, Bill Noe, Robert Roser\*, Ken Schultz, David Stuart\*, Bob Wagner, Peter Wilson

\*not shown in the photo











# Tevatron

- Proton-Antiproton Collider
- 1.96 TeV Center of Mass Energy
- 36 x 36 bunches,  $\Delta t = 396$  ns
- Current Instantaneous Peak Luminosity:  $\sim 3 \times 10^{32} \text{ cm}^{-2} \text{ s}^{-1}$
- Integrated Luminosity:
  - Current:  $3.8 \text{ fb}^{-1}$
  - Expectation for **2009**:  **$5.8\text{--}6.8 \text{ fb}^{-1}$**
  - Running in 2010 under discussion
- Two Experiments Collecting Data: CDF & D0



Integrated Luminosity 3084.46 (1/pb)



■ Fiscal Year 07    ■ Fiscal Year 06    ▲ Fiscal Year 05    ◆ Fiscal Year 04    ■ Fiscal Year 03  
▼ Fiscal Year 02