



Focus Coil Update

Oversight Committee meeting

Roy Preece

24th April 2014

Content

- Status at last meeting
- Focus Coil 2 – findings
- Focus Coil 1 back in position
- Absorber fit check
- De-rating of the current
- Future plans




- FC Team
 - Oxford University – J Cobb, W Lau and V Blackmore
 - RAL – T Bradshaw, M Courthold, V Bayliss, S Watson and M Tucker
 - DL – S Griffiths, T Hartnett, C White, I Mullacrane and P Owens




Status at last meeting

- October 2013
 - Full solenoid mode training complete – 114A
 - 240 MeV/C momentum
 - Held for the 2 hours stability test
 - Reached a maximum current of 188A in Flip mode
 - No stability test was carried out
 - Decision for operating at a de-rated current to be made.
 - During this testing period it was known that -
 - The Cold Mass Supports had insufficient tension
 - Cooling at 4K not as anticipated due to insulation being omitted
 - The testing stopped at this point to bring in Focus Coil #2



Focus Coil 2 - Findings

- Arrived at the end of October 13 and was pumped on while FC#1 was removed from the test setup.
- Cooling with the cryo-coolers started a few weeks after.
- During the cool down the cold mass bore temp sensor developed a fault.
 - 4 wire sensor, one leg connected to earth
 - Resistances could be used to ascertain a temperature but the lakeshore unit would not read
- Leak in the He system was found
 - Leak rate increased as the temperature dropped
 - The hypothesis is that the leak in on the cold mass, a weld perhaps.
- The temperature of the radiation shield stalled at ~120K
 - Target temp ~60K
 - Condensation on the warm bore was seen in one specific spot
 - Obvious a thermal short – around 90W excess heat load on the 1st stage




Focus Coil 2 - Findings

- Focus Coil #2 shipped back to Tesla for investigation work
- Warm bore removed - some damage to the MLI found but not enough to cause such a large heat leak.
- Warm bore / Cold mass bore not concentric – around 3mm off of centre – Still only a portion of the hot load
- Reason found to be the waste material from a pop rivet pressing the MLI to a thermal short.
- No evidence of why the sensor stopped working below a certain temperature.




Focus Coil 1 – Back in test position

- Insulation around cooler installed
- Cold Mass support tightened
- Magnet cooled and prepared for re-training
- With the insulation added it was noted that the cooldown phase was a little better.
- Turn around time after quench to ready for power was decreased.
- Training re-started and the first run quenched at 185A, just 3A from where the magnet testing had been left. *Remember it's training??*
- Subsequent runs did increase to a maximum of 189A
- Magnet held stable for 4 hours at 185A



FC 1 Training Flip Mode




Absorber fit check

- Insertion tooling manufactured
- Some adjustment of the Turret / Absorber lines



De-rating of the current for Step IV

- Running with Focus Coil #1 (with current operational boundary conditions) operation would required a de-rating for Step IV running.
- 200 MeV/c operational current 188A
- Stable at 185A but this would not give any tuning during lattice operation.
- De-rating factor of 0.85 to allow for the Stick-shift quenching of the coils
- Equates to ~ 160A for operations
- There are a range of momentum and Beta values that can be used for running of the experiment in Step IV



Future Plans

- Receive Focus Coil #2 as soon as possible – current schedule is mid May
- Map Focus Coil #1 in Flip mode, while pumping on Focus Coil #2
- Swap Focus Coil #1 for Focus Coil #2
- *Take Focus Coil #1 to hall and use for fit checks – to be confirmed*
- Cool and power Focus Coil #2 (this magnet has not seen power as yet)
- Dependant on the results from Focus Coil #2 the decision to use Focus Coil #1 at a de-rated operation value or use Focus Coil #2 can be made.
- Decision point for which magnet to use will be - end July 14
- Latest Focus Coil arrival in the hall – November 14

