

Tracker Commissioning

Edward Overton

On Behalf of the tracker team..

... Alan Bross, Paul Rubinov, Geoff Barber, Mellissa Uchida, Chris Heit, Paul Kyberd, Craig McWatrers, Ken Long, Ray Gamet, (plus others I have forgotten)

- With many thanks to the Software & DAQ Guys..
... Adam, Durga, Yordan, Rhys


Contents

1. Status at CM41
2. System Overview
3. Issue Resolution
4. Calibration, Waveguides and Beam.
5. First look at Beam data (C. Heit).
6. Status now
7. Where next

Status at CM41

- 4 Cold Cryostat's
- Faulty PSU on Downstream Tracker.
- **Noise on all channels, above what was expected.**
- Triggered and read out noise.
- Displayed plots on Online Monitoring.
- Unpacking with MAUS was problematic.
- Internal LED was tested with a single waveguide
- New trigger interface started but incomplete.
- Controls and Monitoring was overly complex, slow & prone to crashing.

System Overview



Issue Resolution I

- Faulty PSU on Downstream Tracker:
 - Turned out to be caused by a loose fuse in the PSU to backplane connections.
- Noise on all channels, above what was expected:
 - Experimented with a number of grounding schemes.
 - Most noticeable change was caused by a overly optimistic integration gate, we reduced this from 200ns to 180ns. (its now 190ns at the board).
- Number of boards were diagnosed with faults and swapped:
 - Invalidated Calibrations from Lab 7 Cosmics.
 - We would have needed to redo these anyway.
- Controls and Monitoring:
 - Improved original codes exception safety to prevent common crashes.
 - Extended functionality with a new derrived class, which wrapped and used the original code base.
 - Wrapped Hardware Interface code with a new EPICS IOC.

Issue Resolution II

- Trigger Integration:
 - Yordan reviewed the modifications and implemented in the firmware.
 - This was tested during Mock Data Run 3.
 - More issues were found in MDR3 with the data quantity.
 - These were fixed post MDR3, in a two day post MDR3 debugging period.
- Unpacking issues:
 - A push on this was part of the MDR3 unpacking and good progress was made.
 - Some data quality issues caused unpacking exceptions which ultimately hindered the effort.
 - Following getting good data from the upstream tracker, data was read correctly into MAUS.

Calibration, Waveguides and Beam

Week 1 (1 June):

- Complete bias calibrations on the upstream tracker (using the external pulser).
- Tuesday/Wednesday Connect the Waveguides.
- Thursday: Begin Bias Calibrations on downstream tracker.
- Saturday/Sunday: Begin first pass timing using upstream tracker and TOF0.
- ? Timed in upstream internal LED system.

• Week 2 (8 June):

- Monday replace boards with readout issues on Cryo4, update firmware, and run calibration scripts.
- Monday/Tuesday: Move external LED pulser around to complete calibrations.
- Wednesday/Thursday: Begin attaching downstream waveguides.
- Friday: Begin looking at internal LED on downstream.

• Week 3 (15 June):

- Monday: Started using TOF1 for trigger, retimed to a pion beam @ TOF1.
- Tuesday: Connected the upstream tracker and saw digits!
- Thursday: Connected the downstream tracker..
 - GeOLD's were wrong, fixed.
 - Saw Digits!

Preliminary Characterisation

- See Chris Heidts Talk (also attached to this slot)

Status Now

Tracker is in ***Alpha***:

...Its mostly working, but not all there.

- Upstream is in pretty good shape.
- Downstream has some known issues.
 - Two banks (256 channels) have readout problems.
 - Station 4 looks interesting... probably related to mapping / readout issues.
- Timing is not perfect (a good estimate at this point). Do not expect ultra high space point finding efficiency.
 - Recommend placing cuts to require hits in tracker if looking for data.

Plans

... Getting to V1.0 ...

- Fix Readout issues on the two bad banks.
- Understand/Fix issues with station 4
- Re-check calibration
- Careful timing studies...
- Efficiency studies along the way...