

**TE-MPE-EP: REVIEW** 



## LS1: "Yellow racks" activities.



Protection of 1232 dipoles and 392 quadrupoles





## Scope and duties concerning the "yellow racks"

- Ensure the protection of the 1232 dipole magnets and 392 quadrupoles of the LHC machine by deploying a new upgrade of the quench protection.
- Studied and produced electronics and mechanics for new DQLPU type A
- Conducted and performed complete tests of new equipment and new functionalities, such as:
  - ✓ enhanced quench heater supervision
  - ✓ new fully redundant linear power supplies (DYPB)
  - ✓ new fuse in DQHDS.
  - ✓ Remote commands,...
  - Refurbished fip connection of 392 quadrupoles + updated firm










#### Connections between «Yellow racks»










#### Connections with DQLPU type A (main development)







#### **CRATE ENCLOSURES**

| New                           | RESSOURCES                            |  |   |   |
|-------------------------------|---------------------------------------|--|---|---|
| DQLPU<br>type A               | IN (MPE)<br>USED/ <mark>NEEDED</mark> | OUT  | +   | -   |
| Mechanics<br>(kits delivered) | x1 / x2:<br>study,<br>design          | Design: x1<br>EM<br>Protos: Atos<br>Contract:<br>purchase<br>services<br>Other<br>company→<br>production | <ul> <li>+: Price</li> <li>-: No real choice: agreement with an unbalanced countrent New product: no experience</li> <li>Had to follow-up every step the company since the beginning, in the end a sample was just copied.</li> <li>Failure: Surface treatment not as required, quality, precision, dimensions (thickness, depth ±6mm, poor quale plastic hinges, very late delivery of the last spares.</li> <li>Only after acceptance, we had to provide a plan detailed explain everything.</li> </ul> |   |
| Assembly                      |                                       | 2 people<br>AGH  | OK, <b>very good</b> progress, efficient and clever work  | No time to assemble all of the crates                             |
| Burndy<br>connectors          | x1: geometry,<br>orders               |  | Directly soldered on pcb  | Delay for huge quantities<br>→asked for equivalent, but<br>price! |
| Harting connectors            | x1: new<br>design                     | Harting<br>x1 EE   | Good collaboration<br>/interaction: <b>top quality</b><br>Directly soldered on pcb  | New product→longer delay  |





#### **ELECTRONIC BOARDS**

| New<br>DQLPU                           | RESSOURCES                              |                       |   |   |  |  |  |
|--|---|-----------------------|---|---|--|--|--|
| type A                                 | IN (MPE)<br>USED/ <mark>NEEDED</mark>   | OUT                   | +   | -   |  |  |  |
| Motherboard                            | x1.2 / <b>x1.5</b>                      | EM:<br>fin.+<br>prod. | New design, direct connectors             | Finalisation: <b>clearance rules changed</b><br>from MPE to EM: HV withstands<br>problems                           |  |  |  |
| DQQDL<br>(Local detector)              | x1: tests / x1.3<br>repair              |                       | Re-used from initial crates. New firmware | Missing 50 : had to repair old ones.  |  |  |  |
| New DQQDL                              | x1: tests<br>x1: rework                 | EM:<br>rework         | 50 tested                                 | 200 boards <b>reworked</b> due to a missing wire and wrong resistor values. New version <b>not compatible</b> .     |  |  |  |
| DQHSU<br>(heaters supervision<br>unit) | x1: design<br>x1 /+x1 for<br>components | EM:<br>fin.+<br>prod. |   | Relays from «Arrowtronic» not able<br>to be soldered: a mess! (broker?)<br>Had to find new supplier in<br>emergency |  |  |  |
| DQCSU<br>(monitoring unit)             | x1 / <mark>x2</mark>                    | EM:fin+<br>prod.      |   | Launched under <b>pressure</b> $\rightarrow$ HV test forgotten $\rightarrow$ 1 bad lot of pcb.                      |  |  |  |
| DQAMC<br>(communication)               | x1 / x2 for repair<br>or new design     |                       | Re-used from old crates                   | Missing 20→<br>Had to be taken from new crates<br>(No time for new production)                                      |  |  |  |
| DQIPF<br>(WorldFip interface)          | x1: design / x2 for<br>details          | EM:fin+<br>prod.      | Programming from outside (gain of time)   | Space between board and front<br>panel had to be adapted.<br>Connectors, screws, etc.                               |  |  |  |



TE-MPE-EP, VF, 02-June-2015

#### **TE-MPE-EP**



|  |  | т   |  |  |  |  |
|--|--|---|--|--|--|--|
|  | New DYPB   | RESSOURCES  |  |  |  |  |
|  | DQLPU<br>type A rack   | IN (=MPE)<br>USED/ <mark>NEEDED</mark>  | OUT                                      | +  |  |  |
|  | Connections tester   | x1 / x2 : study, programming,<br>design<br>x1 / x1.5 : use                                    |  | ок   |  |  |
|  | Crate functional tester  | 1p-4 months : study,<br>programming, design<br>1p-3 months : design, building<br>x1 : use     | x1p-3<br>months :<br>design,<br>building | OK<br>On time<br>Faster                            | Study: <b>more specifications</b> and<br>more feedback needed.<br><b>Synchronisation</b> with worldfip<br>Eliminated data from DQAMC   |  |
|  | Yellow racks<br>functional tester<br>See report:<br>234 errors | x1 : building<br>x1.5 <b>/ x2 : use</b><br>x1: patches for DYPQ                               | x1 EE :<br>building                      | AVG per shift:<br>at least 11,<br>usually 12<br>OK | Few problems with <b>gateway</b> .<br>Starting tests delayed due to<br>humidity (HV): heating switched<br>off. UPS <b>cables too rigid → fragile</b> .<br>+6 days due to DYPQ back from<br>tunnel. |  |
|  | Cscm crate tester  | x1 : making run, teaching<br>x1 / x2 : use, developing<br>interface, preparation of<br>crates | 2 p. no<br>tech.<br>knowled<br>ge        |  | Under <b>pressure</b> , timing too tight.<br><b>New tester</b> to be tuned.<br><b>New interface</b> needed.  |  |
|  | DQQDL tester:<br>interlocks and<br>threshold                   | x1: development<br>x1: use  |  | ОК   | Wire wrap → bad contacts,<br>repaired several times<br>→New pcb  |  |





#### Report about the 1232 yellow rack functional tester

#### 234 problems:

- Divers:128:
  - Offsets values
  - X37 DQQDL
  - X4 DQCSU
  - X5 DQHSU
  - X3 DQAMC
  - X30 power cycles (repeated 2 or 3 times and ok)
  - X15 post mortem data
  - X50 interlocks
- Cables:28 (not connected, wires swapped, pin default, bad connections)
- DQHDS: 28 changed, 30 other problems with cables
- DQLIM: 20 problems





#### QUADRUPOLES

|  | QUADRUPOLES  |   |   |  |  |  |
|--|--|---|---|--|--|--|
| DQLPU<br>type B<br>Yellow<br>rack                  | RESSOURCES   |   |   |  |  |  |
|  | IN (MPE)<br>USED/ <mark>NEEDED</mark>  | OUT   | +   | -  |  |  |
| Taking DYPQ crates from tunnel and returning them. | x2 / <mark>x3</mark>   |   |   | <b>Cables disconnected</b> from the<br>Crawford box: had to be connected<br>back afterwards (not planned)  |  |  |
| Change Fip<br>connectors on DYPQ<br>(new patches)  | x1: design   | 2 people<br>AGH   | OK. <b>Clever work</b> .<br>(Reliability of<br>connections<br>Right screws UNC or<br>Metric)  | Modification on patches:<br>holes had to be en   |  |  |
| Programming and test of DQQDL                      | x1: new pcb for<br>tester<br>x1: use   | x1: use<br>(intern)   | <b>OK</b> . (New firmware,<br>test of interlocks,<br>threshold and<br>discrimination time)  |  |  |  |
| DQAMC<br>programming,<br>preparation               | x1.5 <b>/ x2</b>   |   | OK. <b>Programmed in</b><br><b>advance</b> in 281:<br>saved time.   | Errors due to <b>shifting of addresses</b><br>(difference between position and<br>magnet protected but <b>not</b><br><b>systematically</b> )<br><b>3 missing crates</b><br>Yellow DYPQ racks very dusty  |  |  |
|  | type BYellow<br>Yellow<br>rackTaking DYPQ crates<br>from tunnel and<br>returning them.Change Fip<br>connectors on DYPQ<br>(new patches)Programming and<br>test of DQQDLDQAMC<br>programming, | Vype BVellow<br>Yellow<br>rackIN (MPE)<br>USED/NEEDEDTaking DYPQ crates<br>from tunnel and<br>returning them.x2 / x3Change Fip<br>connectors on DYPQ<br>(new patches)x1: designProgramming and<br>test of DQQDLx1: new pcb for<br>tester<br>x1: useDQAMC<br>programming,x1.5 / x2 | DOLPD<br>Type BDYPO<br>TorlingRESSOURCESIN (MPE)<br>USED/NEEDEDOUTTaking DYPQ crates<br>from tunnel and<br>returning them.x2 / x3Change Fip<br>connectors on DYPQ<br>(new patches)x1: designZ people<br>AGHProgramming and<br>test of DQQDLx1: new pcb for<br>tester<br>x1: useDQAMC<br>programming,x1.5 / x2 | RESSOURCESIN (MPE)<br>USED/NEEDEDOUT+Taking DYPQ crates<br>from tunnel and<br>returning them.x2 / x3J+Change Fip<br>connectors on DYPQ<br>(new patches)x1: design2 people<br>AGHOK. Clever work.<br>(Reliability of<br>connections<br>Right screws UNC or<br>Metric)Programming and<br>test of DQQDLx1: new pcb for<br>tester<br>x1: usex1: useOK. (New firmware,<br>test of interlocks,<br>threshold and<br>discrimination time)DQAMC<br>programming,x1.5 / x2SOK. Programmed in<br>advance in 281: |  |  |





#### COMMISSIONING

|                                   | RESSOURCES                            |     |  |  |  |
|-----------------------------------|---------------------------------------|-----|--|--|--|
| DYPB+DYPQ<br>QPS protection       | IN (MPE)<br>USED/ <mark>NEEDED</mark> | OUT | +  | -  |  |
| Interlock tests                   | x1 / <mark>x2</mark>                  |     | Last sector: fully<br>automated  | Constant <b>manual supervision needed</b> :<br><b>schedule too tight</b><br>Timing requested per sector: <b>8 to 9 hours</b><br>DYPQ:4x49 interlocks<br>DYPB: 2x154 boards<br>nQPS: 14x52 interlocks |  |
| Close current loops in tunnel     | x1 / <mark>x2</mark>                  |     | Only few DQQDL to<br>be replaced.<br>Quick check thanks to<br>monitoring | Many cables not connected, difficult to reach, remain behind magnet or on the wall behind them.  |  |
| UPS1/UPS2 tests                   | x1/ <b>x2</b>                         |     |  | Many cables not properly connected on DQLPUS: many pins bent on Harting Q12, bad insertion of UPS connectors .   |  |
| Interventions after<br>ELQA tests | x1 / <b>x1.5</b>                      |     |  | Some nQPS patches missing. Not properly marked and placed.   |  |
| DYPQ                              | x1/ <b>x2</b>                         |     |  | New interlock cables still in plastic<br>packaging with tie wraps and <b>not</b><br>connected after previous team.<br>A few ripped cables or connectors not<br>seen or <b>not reported</b> .         |  |







#### COMMISSIONING (continued)

| WHAT?                           | RESSOU                                | RCES |  |   |
|---------------------------------|---------------------------------------|------|--|---|
|                                 | IN (MPE)<br>USED/ <mark>NEEDED</mark> | OUT  | +  | -   |
| Picking up DQCSU and returning  | x2 / <b>x3</b>                        |      |  | <b>Tracking</b> : two sectors forgotten   |
| Rework DQCSU                    | x1 / <b>x2</b>                        |      | ОК   |   |
| Programming DQAMGS              | x2 / <b>x3</b>                        |      |  |   |
| Change DQQBS with mDQQBS (cscm) | X3 / <mark>x5</mark>                  |      |  | <b>Pressure</b> to change<br>boards from one sector<br>to another due to lack<br>of boards. |
| Programming DQAMC               | x2                                    |      | <b>External programming</b><br>but difficult to download<br>when on (must be<br>switched off two times<br>due to big capacitors) | Programming station<br>misplaced (not<br>returned) and then<br>found.                       |

#### **TE-MPE-EP**



**FIRIN** 

#### A few illustrations of unexpected events

Programming station misplaced and then found after LS1

Patch missing



Lift/mad/pad
























Concrete lessons learned and recommendation from LS1 to increase probability of getting a reliable machine.

- Better to choose a company that masters a requested product and has demonstrated experience (mechanical enclosures, components suppliers).
   If not possible, more ressource must be found in advance.
  - Ex: I visited racks made by this company in Cern: looked good, even proposed in EDH.
- More advanced preparation, more information, clearer specifications must be dispatched (why were all DYPQ cables disconnected?)
- More **motivated**, **experienced** and **«well cared for» people needed** in the tunnel (Ex: should not lose a good person with two years experience).
- Real slots of time have to be found to **teach external ressources**.
- Not meetings necessarily, but at least a person dedicated to taking note of what has been done is needed (impossible to memorise and remember everything).
  - Ex: forgot two sectors of DQCSU: people were sure that other people already did it before...





Concrete lessons learned and recommendation from LS1 to increase probability of getting a reliable machine (continued).

- Use knowledge and **expertise of people more efficiently**.
  - Ex: **Too many wrong connections** (many pins bent, cables) remained and had to be identify by experts.
    - With more time or more ressources, we could have had time to **investigate more fundamental issues** or to do more tests (ex. nqps remote power cycle).
- Too many cables left without connection, because it was too difficult, too long or due to timing! Should have been reported. Don't underestimate that. It leads to wasting of time afterwards! = Quality insurance missing.
- In order to minimize the number of problems, one sector should have been fully tested and declared as "good" before the deployment to the rest of the machine, preferably not s 6-7.

Ex: keep only the latest version of firmware in boards.

• Before disconnecting any cable, systematically **put a label** on it.





## Conclusions

- Generally for LS1, too many tasks were requested to comply with a good organization and to have a fully tested working reliable equipment.
- Nevertheless, the challenge was overcome.
- Would have been **better to visit**, **discuss**, **and give clear instructions** to the outsourced company beforehand, by a expert.
- Take into account our well-noted ressources in order to define and discuss with the whole team the workload, not overestimate these capabilities, we are not supermen.
- As already started, we have to continue to think about LS2, and **prepare** right now everything we can in advance.
- Decisions must be made asap.





### Conclusions (continued)

- Really take care of the level of knowledge of the teams involved in our equipment: investing time in teaching would ultimately save time. Too many wrong connections (many pins bent, cables) could have been avoided this way. Especially if one sector was fully commissionned at first and report all the problems encountered would be a real advantage.
- Priorities: security, quality, work in a hurry cannot be a solution.
- More time to thoroughly test one device.
   Ex: Proposal: develop in collaboration a specific «acid tester» to test the limits of a new device (EMC Testing Transient Immunity, RF Immunity).
- For LS2 (or sooner), is there really no way to **leave wifi ON in the tunnel** and turn it off during exploitation? (even G4 is far from optimum).
- Having **another person other than the developer**\_could be an advantage to test a new device.
- Keep testers operational (maintenance).
- Having a **tracking** system for defective boards would be helpful.







# Thank you !