

Software Interlock System

-

Real Time Feedbacks

L. Ponce




- **SIS:**
 - 2015 tree structure
 - Status of interlocks and masks
 - Dumps in 2015

- **Tune and Orbit Feedbacks:**
 - Usage in the cycle
 - Status of OFB
 - Status of QFB




Mixed forest: new species introduced for 2015


- **3 INJECTION PERMITS:** exported to injection BICs for T12 and/or T18.
- **3 RING PERMITS:** exported to ring BICs (SR3 B1/2 and CCR) to abort the beam
- **RCBX PERMIT:** exported to BIC and PIC
- **2 POWERING_PERMIT:** exported to the PIC PVSS system to lock PCs.
- **RP PERMIT** taken out from RING PERMIT, only announcer
- **ABORT GAP CLEANING:** exported to abort gap cleaning
- **2 BUILDERS** exported to Telegram





- Interlocks combined by an OR logic with the safe beam flag = true conditions
- No new interlocks since end of 2012
- All branches logic tested.
- Tolerances for critical parameters back to initial values:
 - MKI temp and vac interlocks...







- Several interlocks are still masked, but OK:
 - PM_MACH_PROT_OK (injection permit)
 - COD settings in physics
 - TCDQ_BEAM masked for first collisions
 - BSRA dump level
- PC interlock not yet fully commissioned -> masked and COD settings still used (also masked)



- Complex interlocking logic to limit global orbit excursion and catch undetected bumps (COD settings)
- Tolerances depend on beam modes and ring positions
 - For non-IR region:
 - ± 2 mm for injection (2 BPMs trigger)
 - 1 mm for dump in all modes (15 BPMs trigger)
 - 0.6 mm for dump in stable beams (15 BPMs trigger)
 - In the IR (1+2+5+8): more complex because of specific conditions (VdM, low beta...)
- CODs settings checks is redundant with the PC interlock, will be replaced as soon as PC interlock is validated
 - For injection, tolerance is 15 urad
 - For dump logic, between 12 ad 20 urad, but have to exclude Xing, sep and lumi CODs due to large change during cycle
 - Still masked to get more experience



- QPS_OK signal is not reliable for the main circuits (signal flickering)
- As it is blocking injection, masked to be efficient for injection
- Risk to let it masked after injection and then interlock became useless



LHC SIS GUI File Operation Unlatch all channels Help

RBA: no token

SIS GUI


Permits Tree

- P [AND] ABORT_GAP_CLEANING
- X P [AND] INJ_B1_PERMIT
- X P [AND] INJ_B2_PERMIT
- X P [AND] INJ_PERMIT
- L [AND] BIC_PREOP_CHECKS
- L [AND] BLM_THRESHOLD_TABLE_STATUS
- X L [AND] DP_TRIM_RT
- I INJECTION_BUCKET
- X I INJECTION_ENERGY
- X L [AND] PC-CURRENTS
- L [AND] PC-STATES
- L [AND] POST_MORTEM
- L [AND] QPS-STATE
- L [AND] IPQ-QPS-STATE
- L [AND] RB-QPS-STATE
 - RB_A12_QPS_OK
 - RB_A23_QPS_OK
 - RB_A34_QPS_OK
 - RB_A45_QPS_OK
 - RB_A56_QPS_OK
 - RB_A67_QPS_OK
 - RB_A78_QPS_OK
 - RB_A81_QPS_OK
- L [AND] RCBX-QPS-STATE
- L [AND] RCS0D-RO-QPS-STATE
- L [AND] RD-QPS-STATE
- L [AND] RQ-QPS-STATE
- L [AND] RQT-QPS-STATE
- L [AND] RS-QPS-STATE
- L [AND] RU-QPS-STATE
- L [OR] RF_INJ
- I SMP_PREOPS_CHECK
- L [AND] VENTILATION_DOORS_OK
- L [AND] WPS_IT
- P [AND] POWERING_FPA_PERMITS
- P [AND] POWERING_PERMITS


Depth: 1 Show Font size: +1 -1 Reset

Expand All Collapse all

Combined




- New interlock introduced to cope with possible failure of the quench loop.
- Logic implemented and tested
- No exporter yet (= no action): to be deployed and tested during TS1





- Based on Abort Gap monitor, request to activate the cleaning sent by SIS.
- not commissioned yet:
 - no signal received,
 - no device to act on.





- 15 dumps caused by SIS in 2015:
 - 7 caused by TGM timeout problem
 - 4 caused by communication problem with BLM crate
 - 3 due to subscription problems: Safe Beam Flag “blocked” to false without beam in the machine, IT motors surveillance
 - 1 due to real interlock
 - IR6 BPM faulty channel triggered the TCS-beam offset interlock

=> Nothing related to intensity




➤ TGM timeout problem:


- Telegram signal is lost for long period (up to 25s) on SIS machine,
- Logic programmed such that after a programmed timeout, default energy value is 450GeV -> beam dump at 6.5 TeV by COD settings...
- CO experts working on finding a solution, In the meantime, timeout has been increased and default energy value is set to 6.5 TeV .

➤ BLM-SIS communication problem:

- Some BLM crates (in pt 6 and 7) are becoming unstable, when additional readout are coming (UFO buster, XPOC, IQC..) 1 Hz readout data is blocked and SIS triggered
- BI experts investigating, in the meantime, UFO buster disabled.



Real Time Feedbacks




- Major refactoring of BFSU/OFC during LS1:
 - new machines, migration to FESA3, new developers
 - But functionalities not changed for the restart
 - Diagnostics improved

- Functionalities used/needed by operation:
 - On/Off of the FBs via sequencer or application
 - Loading of references and optics (= set to BFSU)
 - Dynamic change of the references (ramp/Qchange/squeeze)


- “Expert” settings becoming operational (set via YASP and stored in LSA):
 - Eigen values, bandwidth, gains
 - BPM status

- Both tune and orbit references set in 2 different properties of the BFSU class
 - Critical dependence on BFSU when timing is needed



★ Settings loading

🕒 Triggered by timing event
 🖐️ Triggered by hand/sequencer





- QFB:
 - Loosing the peak, coupling too large (automatic off), fake noise peaks...
 - **Interference with transverse damper**: time is needed to optimize the settings
- OFB:
 - Missed timing events to change references: critical in the ramp
- Dependence on FBs can be reduced with feed-forward of the real-time trims into the PC functions (for next fills).
 - High(er) survival probability when FBs switch off.



- The SVD matrix should in principle be recomputed for each optics:
 - Quite long process: Take between 1 and 2 minutes
- Dynamic change of the optics during the squeeze is implemented, never used in nominal operation:
 - Reduced list of optics to avoid crash of BFSU
 - Never tried the re-computation with feedback ON
 - Re-computation time versus squeeze segment length?
- Only used for squeeze in a discrete mode:
 - FB stopped, optics recomputed and sleep time before switching ON again

- ▼ **LOAD REF ORBIT AND OPTICS FOR OFB**
- ▷ **SWITCH ORBIT AND ENERGY FB OFF**
- **calc ALL optics for the squeeze**
- set active optic 2734 (2.5m)
- ARM REF ORBITS FOR THE SQUEEZE
- SET ACTIVE ORBIT INDEX 0
- SLEEP 5S
- ▷ **SWITCH ON ORBIT AND ENERGY FEEDBACKS**



- Needed during ramp and squeeze, following PC functions
- Settings stored in LSA and tasks executed by sequencer
- Linear interpolation between actual settings and requested settings over a time set by the task (*timeConstant*)
 - *BFSU is not playing a function*
- Changes triggered by **timing events send to BFSU.**
- Mechanics for tune feedback:
 - All timing events for given BP are generated in the dynamic timing table which is played at the same time as the:
 - 11 events sent for the squeeze to 80 cm

OFB Control

Device : LHC.BFSU

Control Reference Orbit BandWidth

Arm / Dis-arm OFB	Trigger / abort ref. change
Time since last update	1 seconds
Last orbit upload @	11/06/2015 17:24:15
Is using measured orbit	false
Last event sent @	11/06/2015 04:36:26
Last event payload	9999
Time since last event (s)	46074
Current time constant (s)	1

Orbit List

Ind	T	Time	Scaling	Info
0	1633	0	1.000	0 - R2015-flat-top
1	1633	85	0.000	85 - R2015-lowbeta-900cm
2	1634	91	0.000	176 - R2015-lowbeta-700cm
3	1637	122	0.000	298 - R2015-lowbeta-400cm
4	1637	54	0.000	352 - R2015-lowbeta-300cm
5	1637	67	0.000	419 - R2015-lowbeta-250cm
6	1638	78	0.000	497 - R2015-lowbeta-200cm
7	1639	74	0.000	571 - R2015-lowbeta-150cm
8	1643	38	0.000	609 - R2015-lowbeta-120cm
9	1640	49	0.000	658 - R2015-lowbeta-100cm
10	1641	37	0.000	695 - R2015-lowbeta-90cm
11	1614	54	0.000	749 - R2015-lowbeta-80cm
12		0	0.000	




- Traced back to a configuration problem of the O/S in the processing of interrupts: 2 timing events were sen too close
- Several mitigation methods put in place after the events:
 - Configuration of the BFSU machine corrected
 - Introduced a delay between the timing event to changed the optics and the one to trigger the change of reference
- **No more missing event observed since few weeks.**

MTG tables	SELECTED MTG TABLE DETAILS			
rampdown injection BLM_capture_test optics_orbit_changes precycle Injection_BI	TABLE NAME (no space)	optics_orbit_changes		
	START EVENT	HX.START-TBL-CT (33) - Start table(s)	Set start Event	
	RUN COUNT	-1		
	EVENT NAME	PAYLOAD	OFFSET (ms)	EVENT DESCRIPTION
	HX.FBOREF-CT	1	0	Start Orbit Feedback reference change
	HX.SIS-SSQU-CT	283	0	Start SQUEEZE for PC intick
	HX.OPTID-CT	2727	500	Optics Identifier
	HX.FBOREF-CT	2	65000	Start Orbit Feedback reference change
	HX.OPTID-CT	2770	65500	Optics Identifier
	HX.FBOREF-CT	3	108000	Start Orbit Feedback reference change
	HX.OPTID-CT	2768	108500	Optics Identifier



- Not a feedback issue, but efficient tune feedback need good tune measurement quality
- 2 different problems: Saturation and S/N ratio
 - Saturation = peak disappearing
 - Fixed in 2012: Device sensitivity adapted for high bunch intensity (2 different devices for pilot and nominal bunches)
 - Saturation observed during LHCf physics, to be checked during TS
 - Bad S/N ratio: multiple peaks
 - BBQ vs ADT settings
 - + co-existence with abort gap cleaning?

=> In 2012, after feed-forward during commissioning phase, Tune Feedback left OFF during squeeze and if stopping in the ramp.





- SIS logic ready for intensity ramp-up, but still controls problem to be consolidated.

- Feedbacks are crucial for operation
- Worked very well most of the time with some exceptions when dynamic change of references is needed:
 - Gymnastics with the sequencer tasks
 - Consolidated during commissioning, working well now

- Need a bit of beam time to optimize settings

