


**Bernd Dehning**

CERN BE-BI

for the BLM team

- BLM incident at IP6
- BLM nonconformities
- Signal filter
- Threshold update schedule
- Threshold checks

- Incident with the damage of 18 BLM signal channels and componets
- Date 03.05.2015
  - Three periods of 20 to 30 minutes observed with high voltage disturbance
  - First period:
    - beam dumped by monitor BLMQI.21R6.B1E10.MQ, 13.24.50
    - higher signal already observed in the whole octant, 13.24.31
    - change in HV current observed at 13.23.52




# Point 6L

# BLM signal (color code) vs time vs DCUM (II zoom)

Time [s]

Dose rate [Gy/s]



Dump lines

DCUM [m]

Midd ARC 6-7

Midd ARC 5-6

13.05.2015

LMC, B. Dehning

# Three Periods of 20 to 30 Minutes

2015-05-03 IP6 HV flash event

RS01 (40us) and RS09 (1.2s) From CFV-SR6-BLML crate

1 normal channel:


**BLMQI.19L6.B2I30\_MQ (card 7, ch 9)**

2 reported broken channels:

**BLMQI.19L6.B2I10\_MQ (card 7, ch 13)**

**BLMQI.21L6.B1E10\_MQ (card 8, ch 10)**

The 40us RS of the 2 broken channels go in saturation, I would suppose this is where they broke



# Summary and foreseen actions

- Observations
  - Damage of several tunnel digitizer cards input circuits
  - Damage of filter components
  - Damage could not come from BLM equipment, because of power needed for the damages, several tenth of ampere in 100 us
  - On BLM HV network > 1900 V measured and not supplied by BLM power converters
- Comparison with LS1 event
  - 30th September at around 00:50 UTC and lasted about 15 minutes
  - Very similar damages and signals on BLM channels
- Investigation
  - Try of determination of entry location of high voltage pulse by data analysis: **no entry location found**
    - From the Sunday event postmortem data are stored
    - Ongoing; delayed increase of the BLM signal of dump line monitors (likely pulse entry location not on BLM HV cables of dump line)
- Action
  - Installation of a overvoltage protection on the tunnel cables
    - In preparation: **will be done in TS1**
  - Preventive exchange of HV cables in IP6 during TS1, **will be done in TS1**
    - Inspection of HV cables in SR6 done, BLM HV cables and 18 kV cables in same cable try
  - Insulation measurements foreseen of BLM HV cable shielding against ground: **will be done in TS1**
    - Condemnation of LBDS system and SR6 power converters needed

# LHC BLM Issues Since Startup 2015

- Beam dump due to BLM-SIS communication (x4)
  - More info: [BIBML-1027](#) [2015/06/02], [BIBML-1039](#) [2015/06/06], [BIBML-1040](#) [2015/06/07], [BIBML-1042](#) [2015/06/09]
  - New version of the FESA server deployed 10/06 PM that prioritises differently data readout and transmission.
  - No errors have been observed, but UFO Buster triggers were disabled
- Logging data perturbed/missing when MCS Online check execution
  - Issue prevents the correct execution of the daily threshold check
  - Fixed with FESA server release of 10/06 PM
- Sanity checks don't get registered correctly in the BLECS
  - More info: [BIBML-937](#)
  - Sequencer correctly shows all checks as passed, but the combiner has not received the result. Thus, no release of beam permit happens
  - Confusing for OP; we have been called to investigate several times.
  - We hope to be fixed in TS#1 release.
- CISV shown crates falsely in error after crate reboot
  - More info: [BIBML-1032](#)
  - DIAMON shows the crate in red (error); very confusing for OP, they called to know if action needs to be taken
  - Don't know the reason but a consecutive reboot fixed it.
  - Under investigation with TE and DIAMON team.



# BLM Signal Filter to Extend Upper Limit of Dynamic Range

- **Status filter checking 11.6.2015 (Barbara)**
- injection region **beam 1: IP2**
  - all filters on IC checked by Matti,
  - he found one small filter missing
  - no IC where a filter was installed by mistake (checked all readout cards where at least one filter was installed)
- injection region **beam 2: IP8**
- same as above, but the presence of 6 filters he could not verify (not enough losses)
- Barbara checked (but cannot distinguish between small and big filter!):
  - Losses close to noise level, nevertheless:
    - 5 of the 6 locations do have some filter installed
    - The 6<sup>th</sup> one has possibly a filter installed (BLMQI.04R8.B2E10\_MQY)
    - One of the filters looks strange (BLMTI.04R8.B1I10\_TDI.4R8.B1):
      - Should be small, but has a rather long decay time and a very long rise time

# Filter Channel List IP8

Card	Monitor	DCUM	Card Channel	Filter	test	event
BJBAP.A6R8	BLMEI.06R8.B2E10_MSIB	2352878	14	small		
BJBAP.A6R8	BLMEI.06R8.B2E20_MSIB	2352433	13	small		
BJBAP.A6R8	BLMEI.06R8.B2E30_MSIB	2351988	12	small		
BJBAP.A6R8	<b>BLMEI.06R8.B2E10_MSIA</b>	2351543	11	small	some filter	
BJBAP.A6R8	<b>BLMEI.06R8.B2E20_MSIA</b>	2351098	10	small	some filter	
	BLMEI.06R8.B2E30_MSIA			small	some filter	
BJBAP.D4R8	BLMQI.04R8.B1I30_MQY	2346082	6	no		
BJBAP.D4R8	<b>BLMQI.04R8.B2E10_MQY</b>	2345768	5	small	probably some filter	
BJBAP.D4R8	BLMQI.04R8.B2E20_MQY	2345432	4	no		
BJBAP.D4R8	BLMQI.04R8.B1I20_MQY	2345375	3	no		
BJBAP.D4R8	BLMQI.04R8.B1I10_MQY	2344841	2	no		
BJBAP.D4R8	BLMQI.04R8.B2E30_MQY	2344591	1	no		
BJBAP.D4R8	BLM2I.04R8.B1I10_MBRC_MBRC_S	2344236	108	no		
BJBAP.D4R8	BLM2I.04R8.B1I10_MBRC_MBRC	2343728	8	no		
BJBAP.D4R8	<b>BLMTI.04R8.B2E10_TCTPH.4R8.B2</b>	2343179	7	small	some filter	
BJBAP.A4R8	<b>BLMTI.04R8.B1I10_TDI.4R8.B1</b>	2340023	7	small	looks strange - big filter??	IQC on TDI 10/06/15 20:11:41.485+238525
BJBAP.A4R8	BLMTI.04R8.B2E10_TDI.4R8.B2	2339664	6	small		
BJBAP.A4R8	BLMTI.04R8.B2E20_TDI.4R8.B2	2339294	5	BIG		
BJBAP.A4R8	<b>BLMEI.04R8.B2E10_MBxB</b>	2338280	3	small	filter	IQC on TDI 10/06/15 20:11:41.485+238525
BJBAP.A4R8	BLMQI.03R8.B1I30_MQXA	2337431	1	small		

## Prioritized List of Threshold Updates (Barbara, Bernhard)

1. Arc and DS thresholds (UFO-induced quenches, new BLM locations).
2. Injection regions (New monitors/monitor configurations).
3. Inner triplets, IPQs, IPDs (updated beam-loss scenarios, quench levels).
4. Remaining injection-region monitors (beam-loss scenarios, quench levels)
5. MQWs (improved beam-loss scenarios, new damage-level analysis).
6. Collimators near experiments (FLUKA models, updated damage levels)
7. Remaining collimators (FLUKA models, updated damage levels)
8. DS-region horizontal BLMs on MBs at aperture bottlenecks (dispersion) and for ion runs
9. Roman pots, kickers, septa, MBWs, new scenario for Q1.  
In absence of updates, pre-LS1 thresholds apply.





**Green:** Deployed since Run 1.

**Blue:** Analysis complete. To be implemented in TS1.

**Violet:** Analysis approaching completion. To be implemented “en-bloc” in TS 2 or earlier.





**Orange:** Analysis not yet started.

# Check of Beam Abort Thresholds (logging data base) (I)



Chen Xu

# Check of Beam Abort Thresholds (logging data base) (II)



Plots are available for all elements

Chen Xu

- XPOC/PM buffers update & Injection Interlock Inhibit for the two crates looking at injections
  - Not sure yet if they will be deployed though. We will finish tests middle of the TS and we will take the decision then.
  - Note, if we go ahead, we will need the MPS tests with beam (~4 h).
- Earth measurements at several places to investigate low signal variation in IP4 an IP5
- Installation of filters and check of filters
- Update of settings, channel names, ...
- Update of thresholds

# Summary

- The incident on the BLM system is mitigated by hardware changes and continued investigation
  - The reason causing the event has not been found
  - HV changes are surveyed every 10 seconds, which ensures that the system availability is checked
- Low signal variation are investigated during TS1
- Other occurred nonconformities effected the uptime of the system
  - Mitigations are employed or will be employed during TS1
- Filter have been checked (few are missing), no critical nonconformities have been found
  - Filter checks and installations will be continued during TS1
- Applied BLM thresholds have been checked globally, no nonconformity has been found
- A threshold update table has been given
- Automatic disabling protection is not activated yet