


The APS RF Systems


- 450MeV Linac: FIVE 2856MHz/45MW peak pulsed rf systems
- PAR (Particle Accumulator Ring): ONE 9.77MHz/4kW CW rf system and ONE 117.3MHz/3kW peak pulsed rf system
- 7GeV Booster-Synchrotron: ONE 352MHz/1.1MW CW ramped rf system
- Storage Ring: FOUR 352MHz/1.1MW CW rf systems

APS LLRF Hardware

- VXI packaging
- Separate interface chassis for passive devices such as splitters, directional couplers, etc.
- SMA-Phoenix interconnect cabling between the two sub-assemblies



VXI RF Board Layout:



- Two or four channels of rf measurement/control per board
- RF components housed inside rf-tight enclosures – the remainder of the board is dedicated to EPICS acquisition hardware
- RF connections on VXI front panel using blind-mate Phoenix connectors

Recent LLRF Hardware Upgrades


- ~ 1998, new-design envelope and phase detector boards to replace the obsolete 1992-version Bruel & Kjaer 3154 VXI User Module – design of rf sub-assemblies was not changed
- In 2004, new-design feedback PID amplifier boards to replace the obsolete 1992-version Bruel & Kjaer 3154 VXI User Module, and also to improve analog electronics – completely new design
- 2005 – Upgraded phase detectors to replace the original 1992-version double-balanced mixer phase detector used in rf subassemblies – using the Analog Devices 8302 rf amplitude and phase measurement IC




The APS Low-Level RF Systems

APS LLRF Systems are **entirely analog**, with some use of EPICS-based software scripts to provide simple automation

- Direct amplitude and phase measurement/control at the operating frequency (351.93MHz, 117.3 MHz, 9.77MHz)
- Linearized envelope detectors
- Double-balanced mixers with leveling amplifiers used for phase measurement
- Varactor-diode phase shifters used for phase control




Incidental AM and PM Suppression



RF Cavity Field Probe Signal


- LLRF phase and amplitude control reduces incidental Nx60Hz AM and PM on cavity gap voltage
- Typical sideband level is ~50dBc, indicating ~1° p-p phase jitter and less than 1% amplitude variation

Storage Ring Gap Voltage AGC System



Klystron mod-anode voltage is modulated to regulate cavity gap voltage

FY 2005 Downtime by System
 Data through Run 2005-2



- RF downtime allotment is 0.9%, and 200 hours mean time to beam loss

This includes all rf systems, from Linac to Storage Ring


- Typical rf downtime for an 1600 hour run is >0.5%
- Lowest rf downtime on record was 0.05%

Future Low-Level RF Plans

Proposals have been submitted for the following projects **which will require state-of-the-art LLRF performance and capabilities:**


- DSP/FPGA Upgrade to the PAR 117.3MHz Pulsed LLRF Systems
- APS Short X-Ray Pulse Upgrade:
 - Storage Ring upgrade intended to provide a transverse kick to the beam bunches and thereby generate ultra-short (picosecond) x-ray pulses
 - Will utilize SC crab cavities and CW rf system to provide transverse kick to bunch
- Will require a sophisticated state-of-the-art low-level rf system to achieve 0.05° and 0.05% amplitude control requirements

- FY2006 LDRD proposal to design a LLRF system utilizing Software Defined Radio and DSP techniques:



- Digitize baseband rf signal directly
- Use data manipulation to perform all modulation, demodulation, and processing functions required to meet specifications: 0.5° phase and 0.5% amplitude control
- Possibly achieve extremely wideband programmable frequency agility?

Parallel-Klystron Control



Analog loops maintain correct amplitude and phase relationships between two rf stations operating in parallel

Most Common LLRF Failures

- Intermittent rf connections -- ~ 3 per year
- LLRF board failures -- ~ 1-2 per year
- VXI crate power supply failure – once rare but becoming more common
- Software induced faults – most common problem – approximately 10-15 faults per year:

- Network communication problems with rf hardware

- Incompatibility with GPIB-controlled equipment
- Network-level upgrades that are incompatible with rf hardware

- Reboot-related system configuration errors
- Installation of incorrect system settings (loss factors, setpoints, etc) upon an IOC reboot

- The use of automated control scripts that are not compatible with rf system hardware