

University  
of Glasgow

# Instrumentation Status (but not tracker)

**MICE CM43**


**RAL, 29 October 2014**

**Paul Soler**

# Readiness TOF





- TOF system (TOF0, TOF1, TOF2) working smoothly
- One PMT found broken after TOF1 shielding operation
- During installation of PRY and installation of tracker, some cables were damaged and had to be fixed
- Some mapping problems between software and hardware (flip of vertical/horizontal + 1 bar flipped)



MICE CM43, October 2015



- HV channels moved to EMR high voltage crate
- Calibration muon/pion distributions as function momentum (MICE Note 473)



- Photoelectron modelling shows
  - CKOVA muon threshold: 272 MeV/c,  $n_A=1.073$
  - CKOVB muon threshold: 213 MeV/c,  $n_B=1.116$

## Remaining hardware:

- Final Step IV position after PRY installation during shutdown week in July
- Detector has been working well and was used in pion contamination paper
- New calibrations and surveys carried out



- October 2014:
  - EMR hardware extensively upgraded: new Hamamatsu R6427 PMTs, new rack, AC fan system, remote controlled AC power supply, HV PSU (PMTs), LV PSU, new VME and NIM crates
- Other issues fixed since October 2014:
  - 1 VHDC fails to configure FEBs, HV PSU did not start, LED not working (LV PSU changed), cosmic DAQ code bugs, two noisy FE boards, one single-anode PMT faulty and fixed





- Other issues fixed since October 2014:
  - HV PSU: 48 channels for SAPMTs (1500 V) and 48 channels for MAPMTs (700 V) remotely controlled

/home/epics/epicsDEV/Config/opi/edl/EMRmon.edl

EMR Monitor					
SAPMT			MAPMT		
1500.5 V	314.0 uA	South	PLANE 47 - Y North	700.0 V	323.0 uA
1500.5 V	317.0 uA	Bottom	PLANE 46 - X Top	700.0 V	322.0 uA
1501.0 V	315.0 uA	South	PLANE 45 - Y North	700.5 V	322.5 uA
1500.0 V	314.0 uA	Bottom	PLANE 44 - X Top	701.5 V	325.0 uA
1501.0 V	314.0 uA	South	PLANE 43 - Y North	700.5 V	320.5 uA
1501.0 V	317.0 uA	Bottom	PLANE 42 - X Top	700.5 V	324.0 uA
1500.5 V	314.5 uA	South	PLANE 41 - Y North	700.0 V	323.5 uA
0.0 V	0.0 uA	Bottom	PLANE 40 - X Top	700.5 V	326.0 uA
1501.5 V	314.0 uA	South	PLANE 39 - Y North	700.0 V	323.5 uA
1500.0 V	316.5 uA	Bottom	PLANE 38 - X Top	700.5 V	323.0 uA
1500.5 V	315.0 uA	South	PLANE 37 - Y North	700.5 V	321.5 uA
1500.5 V	316.5 uA	Bottom	PLANE 36 - X Top	700.5 V	322.0 uA
1500.5 V	314.0 uA	South	PLANE 35 - Y North	700.0 V	321.0 uA
1501.0 V	317.5 uA	Bottom	PLANE 34 - X Top	700.5 V	323.5 uA
1500.5 V	315.0 uA	South	PLANE 33 - Y North	701.0 V	321.0 uA
1500.5 V	315.5 uA	Bottom	PLANE 32 - X Top	700.5 V	322.5 uA
1500.5 V	314.5 uA	South	PLANE 31 - Y North	700.0 V	322.0 uA
1500.5 V	316.0 uA	Bottom	PLANE 30 - X Top	700.0 V	323.0 uA
1501.5 V	314.5 uA	South	PLANE 29 - Y North	700.5 V	320.0 uA
1500.5 V	315.5 uA	Bottom	PLANE 28 - X Top	700.0 V	323.0 uA
1501.0 V	314.5 uA	South	PLANE 27 - Y North	700.0 V	321.0 uA
1500.5 V	315.0 uA	Bottom	PLANE 26 - X Top	700.0 V	322.0 uA
1501.5 V	317.0 uA	South	PLANE 25 - Y North	699.5 V	321.0 uA
1500.5 V	316.5 uA	Bottom	PLANE 24 - X Top	701.0 V	324.5 uA
1500.5 V	314.5 uA	South	PLANE 23 - Y North	700.5 V	323.0 uA
1500.5 V	318.0 uA	Bottom	PLANE 22 - X Top	700.5 V	322.5 uA
1501.0 V	314.5 uA	South	PLANE 21 - Y North	700.0 V	323.5 uA
1500.5 V	315.0 uA	Bottom	PLANE 20 - X Top	701.0 V	323.5 uA
1501.0 V	313.0 uA	South	PLANE 19 - Y North	699.5 V	322.5 uA
1500.0 V	316.0 uA	Bottom	PLANE 18 - X Top	700.5 V	322.0 uA
1500.5 V	316.5 uA	South	PLANE 17 - Y North	700.0 V	323.0 uA
1500.5 V	316.0 uA	Bottom	PLANE 16 - X Top	699.5 V	323.5 uA
1501.5 V	314.0 uA	South	PLANE 15 - Y North	700.0 V	320.5 uA
1500.5 V	316.0 uA	Bottom	PLANE 14 - X Top	700.5 V	321.5 uA
1501.0 V	314.5 uA	South	PLANE 13 - Y North	700.5 V	323.0 uA
1500.0 V	317.0 uA	Bottom	PLANE 12 - X Top	700.0 V	323.5 uA
1501.0 V	314.5 uA	South	PLANE 11 - Y North	700.5 V	323.5 uA
1500.5 V	317.0 uA	Bottom	PLANE 10 - X Top	679.5 V	314.0 uA
1501.0 V	314.0 uA	South	PLANE 09 - Y North	671.0 V	308.0 uA
1500.0 V	316.0 uA	Bottom	PLANE 08 - X Top	700.0 V	323.5 uA
1501.0 V	315.0 uA	South	PLANE 07 - Y North	700.0 V	321.5 uA
1500.0 V	316.0 uA	Bottom	PLANE 06 - X Top	701.0 V	322.0 uA
1501.0 V	315.0 uA	South	PLANE 05 - Y North	700.5 V	324.5 uA
1500.0 V	308.5 uA	Bottom	PLANE 04 - X Top	700.5 V	323.0 uA
1500.0 V	313.5 uA	South	PLANE 03 - Y North	700.5 V	322.0 uA
1500.0 V	317.5 uA	Bottom	PLANE 02 - X Top	700.5 V	322.0 uA
1501.0 V	315.0 uA	South	PLANE 01 - Y North	700.5 V	321.5 uA
1500.5 V	317.0 uA	Bottom	PLANE 00 - X Top	700.0 V	322.0 uA

## □ Noise in SAPMTs:

- 39 planes with very little noise ( $< 1 \text{ ms}^{-1}$ )
- 7 somewhat noisy planes ( $< 100 \text{ ms}^{-1}$ )
- 2 very noisy planes ( $> 100 \text{ ms}^{-1}$ )






## □ Noise in SAPMTs:


- Reduce gain of noisy MAROC channels  $\sim 0.75$  ( $< 50 \text{ ms}^{-1}$ )
- Increase discriminator threshold from 0.9 to 1 ( $< 50 \text{ ms}^{-1}$ )

Secondary hits



**Reduction gain**

Secondary hits



**Increase threshold**

- Origin noise unclear (FEB, MAPMT?): noise does not overflow DBB buffer at the moment by reducing gain






# EMR



## EMR charge calibration:

- Require ~300k cosmics (~2-3 days)
- Measure mean charge  $\overline{Q}_{ij}$  and correction factor:  $e_{ij} = \frac{\overline{Q}_{ij}}{\overline{Q}}$
- Will require new calibrations after EMR movement in July



## □ Final status:

- Over the reporting period the remote-controlled switch, the low-voltage power supplies and the high-voltage power supplies have been stable in operation.
- A short manual has been written describing the remote operation of the different pieces of hardware in the EMR rack.
- The NIM crate PSU failed and was replaced by a spare Wiener crate. A study of the noise in the 48 frontend boards was performed. Some boards were identified as “noisy” and will be replaced with spare front-end boards.