



DANISH
TECHNOLOGICAL
INSTITUTE

HTS tape insulation


Nikolaj Zangenberg, Danish Technological Institute
Dec 1st, 2015

HTS tape insulation

- outline

- Evaluation of new HTS insulation techniques:
 - Epoxy-based
 - Liquid polyimide
 - Sol-Gel
- Study of defects in HTS coil from Danfysik

HTS insulation



Insulation	Pros	Cons
Kapton/polyimide tape wrapping	Commercially well-established	Not compatible with impregnation
Fiber glass and kapton wrapping	Well-known from LTS accelerators	Thick (poor Je)
Fiber glass sock with epoxy impregnation	Simple handling	Thick; problems with epoxy impregnation penetration
Black varnish (Innost)	Thin; compatible with impregnation	Health and safety issues
Epoxy (Danfysik, Florida State U)	Compatible with impregnation	Not established commercially?
Sol-Gel (DTI, FSU)	Thin (good Je)	Not developed
Liquid polyimide (SuperOx)	Good insulation	Not established commercially?




Liquid based – good candidates for “up-scaling”. Not well-suited for Roebel.

SuperOx

- Polyimide layer insulation

SuperOx

SUPERCONDUCTOR TO THE FUTURE



SuperOx



DANISH
TECHNOLOGICAL
INSTITUTE

- Insulation and tape from SuperOx (2015)
- Thickness ca. 20 μm
- Very good uniformity of insulation




Danfysik

- Epoxy + heat conductive filler


HTS tape pulled through
liquid epoxy bath and cured.

(also performed at Florida State
University).



Danfysik

- Insulation and tape from SuperPower (2012)
- Cu dog-bone at edges (old tape)
- Insulation thickness ca. 25 μm



Sol-Gel coatings at DTI




DANISH
TECHNOLOGICAL
INSTITUTE


- Inorganic organic hybrid coatings (organosilane based coatings, sol-gel systems)
- Applied by spraying / dip-coating / paint brush
- Curing between room temperature and 200 °C
- Also performed at Florida State University
- Applied to SuperPower 12 mm wide tape (2014)




crystalline SiO₂
(quartz)



amorph SiO₂
(glass)



**Inorganic siloxane network
+ organic groups and/or NPs**



Sol-Gel application process



DANISH
TECHNOLOGICAL
INSTITUTE

Step 1


The substrate undergoes a cleaning and activation procedure



Step 2

The coating is applied by means of


- spraying
- dipping
- rolling



Step 3

The coating is cured by


- Heating (RT to 200 C)
- UV or IR light
- air drying



Breakthrough voltage

Gold masking used to prevent edge effect.

On 4 mm tape
(SuperOx, Danfysik) or
12 mm tape (Sol-Gel)



Insulation	Insulation thickness	600 V	1000 V
Polyimide (SuperOx)	25 μm	OK	OK
Epoxy (Danfysik)	20 μm	OK	OK
Sol-Gel (DTI)	6 μm	OK	Fail



Study of defective coil from Danfysik HTS magnet

Danfysik demonstration stand-alone HTS dipole magnet


Coil layout: 18 coils in block/ellipse design

A few of the coils were not able to carry the designated current


Defective top coil made available for DTI in EuCARD2 project



Mapping of defects in coil



Metallographic sections (cut, grind, fine polish)
Light Optical Microscopy and SEM/EDX




Tape/coil delamination



DANISH
TECHNOLOGICAL
INSTITUTE

Example of delamination (electron microscopy)




Tape/coil delamination



DANISH
TECHNOLOGICAL
INSTITUTE

EDS Layered Image 8




Please note: The investigated tapes/coil are from 2011-2012.
Present day performance is not evaluated.

Coil defect registration



DANISH
TECHNOLOGICAL
INSTITUTE

- A) defect (partial delamination)
- B) complete delamination



Complete delaminations





DANISH
TECHNOLOGICAL
INSTITUTE

Coil section #1



Coil section #2 (inverted)




Sec. 1	Sec. 2
1	1
	2
10	
	13
	30
	35
36	36
37	37
67	67
68	68
	77
	84
	85
	86
	98
109	109

Defect studies - conclusions

Complete delaminations occur with some correlation between 1-2 and 3-4 (to a smaller extent). Serious conductor damage.

Damage may have been caused by outwards pressure on YBCO layer without mechanical backing from Hastelloy.



No correlation between partial delaminations in coil sections 1-2 and 3-4. Defect origin from section preparation cannot be excluded.



DANISH
TECHNOLOGICAL
INSTITUTE

Thank You!