

---

# LHC Risk Review: Kicker Magnet Reliability

Jan Uythoven

Thanks to Brennan Goddard, Etienne Carlier,  
Wolfgang Höfle, Verena Kain and Volker Mertens

# Scope

---


- Different kicker systems
  - Beam Dumping System
    - Extraction Kickers
    - Dilution Kickers
  - Injection Kickers
  - Kickers for Tune and Aperture measurement
  - AC-Dipole
  - Feedback Kickers (Transverse Damper)
- Discussing
  - Expected failure behavior and likelihood
    - From theory and from experience
  - Measures taken
- Conclusions

# Studies / Reviews of Kickers and especially the Beam Dumping System

---

- LHC review on Machine Protection and Interlocks
  - External, April 2005
- PhD thesis on Beam Dumping System Dependability
  - CERN-THESIS-2006-054
- Beam Dumping System Review
  - Internal, January 2008
  - Mainly on controls aspects – not HV aspects
- Planned review on Beam Dumping System Trigger Synchronisation Unit (TSU)
  - External company: wk 17 – wk 33

# LHC Beam Dumping System



MKD:  
2 x 15 Systems

MKBH: 2 x 4 (2)  
MKBV: 2 x 6 (2)

Magnet operates in  
air with coated  
ceramic chambers

Magnet operates  
under vacuum




# Beam Dumping System

---

- Extraction kickers MKD and dilution kickers MKB
- Critical because:
  - Important damage could occur as these system have the potential to deflect the full intensity beam up to 'any angle'
  - MKD failure: can damage the arc / LHC
    - Most critical for the LHC
  - MKB failure: damage the extraction channel and beam dump block
    - [Talk B.Goddard Friday on consequence of dilution failure](#)

# Beam Dumping System

- System safety is based on:
  - Built in redundancy
  - Continuous surveillance
  - Post Operational Checks (IPOC/XPOC)




# MKD System NOT firing

- One kicker not firing is covered by
  - System redundancy: **can dump correctly with 14/15 MKD systems**
- It is very unlikely that one, or even more unlikely more than one, kicker will not fire because of:
  - Choice of switch type:
    - The **GTO Thyristor** switch stack consists of 10 discs
    - Adjusted manufacturer failure rate for 1 disc →  **$2.4 \cdot 10^{-6}$  failures per hour for 1 switch**
  - Redundancy within each kicker generator
    - Each generator has two solid state switches in parallel, which can each take the full current
  - Redundancy in triggering system
- Complete system not firing due to no trigger from Beam Interlock System not treated here
  - Fault external to beam dumping system
  - But studied elsewhere: SIL3

Experience from **Reliability**  
**Run**: No missings occurred!  
Details later

# Functional Architecture of 1 MKD Generator





# MKD system Kicking with Wrong Strength

---

- Probably one of the worst scenario's
- Covered by comprehensive **Energy Tracking System (BETS)**
  - Energy is calculated from the main dipole currents in the **four 'adjacent' octants**
  - Large **redundancy** in generation of energy reference and in verification of kicker strength while being ready for the next dump
  - Kicker settings and Energy Interlock values both hardcoded in the Front Ends, using separate tables
    - No remote access to these tables

# Erratic firing of MKD kicker

---

- **Re-triggering system** which detects any ‘spontaneous’ firing of an MKD or MKB kicker magnet
- Within **700 ns** all switches will be fired asynchronously
  - During this delay and the 3  $\mu$ s rise time of the MKD kickers, the bunches swept over the aperture will be intercepted by the **TCDQ and TCDS absorbers**.
- Again redundant signal paths

Experience from **Reliability Run**: No erratics occurred!  
Details later

# Power Cut

---

- In this case the beam will clearly need to be dumped because most other equipment will stop working
- Beam dumping system kickers are on **2 parallel, redundant Uninterruptable Power Supplies (UPS)**
- UPS required:
  - Trigger Synchronisation Unit needs power from UPS to start the trigger of the beam dump
  - All other power is stored in capacitors, ready to be 'released' at the moment of trigger
- Already tested in 2008 – generates dump – more extensive diagnostics on synchronisation for further tests planned in 2009

# Safety Study

- Ph.D. thesis Roberto Filippini ([CERN-THESIS-2006-054](#))
  - FMECA analysis
    - More than 2100 failure modes at component levels
      - Components failure rates from standard literature (Military Handbook)
    - Arranged into 21 System Failure modes
  - Operational Scenarios with State Transition Diagram for each Mission = 1 LHC fill
  - State Transition Diagram for Sequence of Missions and checks

Likelihood for any unacceptable failure

Case studied	Unsafety/year	False dumps/year
Default scenario	$2.41 \times 10^{-7}$ (> SIL4)	4.06
No redundant power triggers	$2.31 \times 10^{-6}$ (SIL4)	3.02
No redundant triggering sys.	$4.68 \times 10^{-4}$ (SIL2)	4.02
14 MKD	0.011 (SIL1)	3.89
No BETS	0.059 (< SIL1)	3.40
No RTS	0.32 (< SIL1)	4.06

All these systems are obligatory !

# Source of failures (from study)

Case studied	Unsafety/year	False dumps/year
Default scenario	$2.41 \times 10^{-7}$ (> SIL4)	4.06

Apportionment of unsafety (=unacceptable failure) to the different components:


System	Total%
MKD	74.8
MSD	18.6
MKB	6.1
BEMS	0.27
Triggering	0.23

MKD is the most complicated system and contributes most to the unsafety.


The MKB dilution failures contribute 6 % to the unacceptable failures  
(presentation B.Goddard Friday)

# Operational Experience

## Reliability Run of the Beam Dumping System



Operation only below 5.5 TeV, due to MKB break down




Operation 'with beam' at injection energy


System pulses = 19 magnets

	Beam 1	Beam 2
# Pulses	23'534	15'469
Time considered	10.5 months	9.1 months
Continuous running (p < 13 h)	2.7 months	1.7 months

Data from 8/11/07 to 19/09/08



# Reliability Run: Internal and External Post Operational Checks (IPOC / XPOC)



- **741'057** Magnet Pulses Analysed with IPOC and XPOC Systems
  - > 10 years of operation
- Some hardware problems discovered →
- **No critical failures** on the **MKD system** which would have resulted in a non-acceptable beam dump even if redundancy would not be there
- No 'asynchronous' beam dumps were recorded (erratics). No missings.
- However, unexpected MKB breakdown → →

# MKD Issues Discovered

---

- Four switch failures due to short circuit on one of the GTO discs
  - Within limits of reliability calculation assumptions
  - Would not have given an unacceptable beam dump but internal dump request resulting in synchronous dump
- Problem with voltage distribution of GTO stacks: internal dump request
  - All checked and redistributed for 2009
  - Only affected availability, not safety
- Re-soldering of trigger contacts on GTO stack

All failures were detected by diagnostics, IPOC/XPOC !




# MKB failures


- Unexpected common mode failure on the **MKB system**. **Flashovers** in 3 out of 4 magnets simultaneously after **operation under bad vacuum**: stopped operation above 5 TeV. Measures taken:
  - Additional vacuum interlock
  - HV insulators, identified as weak point, being changed for 2009
  - Reduced conductance between adjacent MKB tanks by smaller aperture interconnects

MKB generator design similar to MKD, but with less redundancy within generator

Measured MKB wave form




# Injection System Kickers MKI

- Travelling Wave Structure, with PFNs and 'classical' thyatron switches
  - Per system experienced / expect about **1 missing kick per year**
  - Expect / experienced **a few erratics per year**
    - Limited charging time of 2 – 3 ms before triggering
    - System switched off after injection
- Operation is stopped after any missing or erratic
- No redundancy in number of kickers
- Machine aperture protected by two sided injection absorber TDI 




# Injection Absorber TDI

LEFT OF IP2 (H plane)



## TDI:

- ~ 4m long, ~ 10 m upstream of D1, additional mask in front of D1 (TCDD)
- Protects machine against MKI failures
- Required setting:  $6.8 \sigma$  (Assuming  $7.5 \sigma$  machine aperture)



# Experience 2008

- Some MKI **magnet breakdowns** occurred (nominally: 1/operational year)
  - One magnet had shown a breakdown, probably by over-voltage during lab conditioning due to a calibration error
  - Indications of MKI flashovers triggered by beam loss during aperture studies
  - Results in larger kick (short circuit) or smaller kick (emptied PFN): **system** kick strength can vary between 75 % and 125 % of nominal for a part of the pulse: beam onto TDI / TCDD
    - For small errors beam can graze the TDI: additional collimators TCLI and normal collimators in point 3 and 7.
- Measures
  - **SoftStart** of the injection kickers if not pulsed for more than 1 hour. Automatic ramp up to nominal operational voltage before beam
  - Installation of additional **Beam Loss Monitors** at the MKI to monitor beam losses: improve understanding and later possibly interlock
  - For 2009: injection quality check which includes an automatic analysis all MKI pulses and compare to references (similar as for beam dumping system)
- **Main protection is the TDI / TCDD**

# Transverse Damper



BE/RF

- Also used for abort gap cleaning
- Worst possible failure scenario:
  - Full strength, at **injection energy** at wrong phase resulting in coherent excitation
  - Results in **1  $\sigma$  growth after 4 turns**
- With collimators set-up correctly will loose the beam on the collimators
  - Beam Loss Monitors at collimators should see this as soon as losses are significant and trigger beam dump request
  - **Reaction time of beam dump < 3 turns**: beam should be dumped before any losses which can damage equipment
- If collimators not set-up correctly: BLMs are positioned to have a machine wide coverage and will dump before damage

See also W. Höfle, [review on Machine Protection and Interlocks, April 2005](#)

# MKQA kicker and AC-Dipole


- Four Systems: 2 planes x 2 beams
- Three generators working on each magnet
- **Tune kicker MKQ**: Kick strength limited by system power converter:
  - 0.41  $\sigma$  at 7 TeV
  - 1.6  $\sigma$  at 450 GeV
  - Should not imply any risk
- **Aperture kicker MKA**: also kick strength limited by system power converter:
  - 1.6  $\sigma$  at 7 TeV
  - 6.1  $\sigma$  at 450 GeV
  - Operation potentially dangerous
    - Can only be operated with 'safe beam' – MKA has a maskable interlock on the BIC which is always active
    - Physical key required to switch between MKQ –MKA – AC-dipole



# AC-dipole operating **on tune**: beam loss in about 45 turns: ok

BE/CO

Operation on tune, injection energy, nominal strength (normally gives  $7\sigma$  for  $\delta = 0.025$ ), ramp up of kick strength over 200 ms = 2000 turns



- If excitation too important: beams lost on collimators and detected by Beam Loss Monitors
- If BLMS trigger beam dump, beam dump within  $< 3$  turns
- Only to be used with safe beam. See also LTC meeting 6 June 2007

# Conclusions

---

- By their nature **kickers** are a good candidate for possibly causing important damage to the LHC
- Great care has been taken to avoid this
  - **Redundancy** and **surveillance** of the beam dumping system
  - **Absorbers** on both beam dumping and injection system
  - **Limitation of power** on tune and aperture kicker MKQA
  - AC dipole and Transverse damper (*not really kickers*)
    - Also limited power
    - Slow enough as to trigger beam dump via **Beam Loss Monitors**
- **Requires thorough commissioning of the fully connected system for Machine Protection**
  - Systematic and rigorous tests with formal approval before beam current or beam energy can significantly be increased
  - Awareness is present: keep time for it on the schedule !