

The real "life" of operation

V. Baglin CERN TE-VSC, Geneva







Vacuum, Surfaces & Coatings Group Technology Department

Introduction

• Your beautiful and expensive vacuum system was well designed and prototypes deeply tested ...

... so what can happen?



Vacuum, Surfaces & Coatings Group Technology Department

First turns of LHC: 10 Sept 2008





Vacuum, Surfaces & Coatings Group Technology Department

The real life of operation ...





Vacuum, Surfaces & Coatings Group Technology Department


The real life of operation ...





Vacuum, Surfaces & Coatings Group Technology Department

What about the real life through the looking glass?





Vacuum, Surfaces & Coatings Group Technology Department

The Sector 3-4 incident (just before the 1st ramp)

19th September 2008 at 11:18.36 last test of the last sector: 7kA (4TeV) towards 9.3 kA (5TeV) Electrical arc at 8.7 kA in the interconnection Rupture of bellows, expansion of liquid Helium with superinsulation debris










Vacuum, Surfaces & Coatings Group Technology Department

2009 - overall repair and consolidation






Vacuum, Surfaces & Coatings Group Technology Department

Impact on beam tube ...

• 2x 2.8 km damaged




 \approx 60% of the chambers

$\approx 20\%$ of the chambers



Vacuum, Surfaces & Coatings Group Technology Department

TE-VSC Vacuum Cleaner



Credits: E. Mahner, B. Jenninger, B. Henrist



Vacuum, Surfaces & Coatings Group Technology Department

Beams back: 20 Nov 2009





Vacuum, Surfaces & Coatings Group Technology Department

1. What can happen?



Vacuum, Surfaces & Coatings Group Technology Department

Disclaimer

• What I will show is not an exhaustive list of the events which can happen ...

• I really trust the creativity of nature and humanity to complete the list!



Vacuum, Surfaces & Coatings Group Technology Department


1.1 Vacuum loss



Vacuum, Surfaces & Coatings Group Technology Department

Leaks

- This is the first demon faced by the vacuum expert
- · Leaks can be due to:
 - installations non conformity
 - bad design / material
 - mechanical or thermal fatigue of a component
 - corrosion
 - • •
- One great thing, if you don't look for them, you might not find them yourself
 - ... but something else might find it for you!



See tutorial P. Cruikshank, G. Bregliozzi





Vacuum, Surfaces & Coatings Group Technology Department

Leak at welds: mechanical analysis

• The stress at the level of the weld increases under vacuum and weight (and thermal stress)

- Example of SuperKEKB:
 - Supporting of below before evacuation
 - Rewelding if too thin thickness





Y. Suetsugu et al. J. Vac. Sci. Technol. A 34, 021605 (2016)



Vacuum, Surfaces & Coatings Group Technology Department


LHC: 1st Leak triggering a beam dump


• During operation, the bellow of a wire scanner broke, creating a leak

• The total amount of bellow's cycle was not recorded since the start of LHC and overpassed by far the acceptable limit ;-)

Varnished was applied without success

• The emergency procedure which consist in Ne venting allowed to replace the faulty component and resume beam operation after 2 days








Vacuum, Surfaces & Coatings Group Technology Department Vacuum for Particle Accelerators, Glumslov, Sweden 6 - 16 June, 2017 Sweden, V. Baglin, 6 - 16 June, 2017

Fast Repair: Ne venting

- 5 days intervention
- Ne flow to reduce air back streaming
- This method avoids the NEG saturation (remember Ne is an inert gas)
- Avoid major NEG saturation but possible local saturation close to the exchanged piece
- Zone that can stand **over pressurization** +100mbar





Neon trolley




Vacuum, Surfaces & Coatings Group Technology Department


Corrosion

- Originates from chlorine pitting
- ISR: Brazing flux ! (ZnCl₂)

 SPS: fire detection PVC pipes subjected to radiation in a wet environment and located above the vacuum system

• LEP: PVC based tape wrapped around photomultipliers










Vacuum, Surfaces & Coatings Group Technology Department

Corrosion

Brazing flux containing chlorine leads to corrosion.
Example, ESRF








Vacuum, Surfaces & Coatings Group Technology Department Vacuum for Particle Accelerators, Glumslov, Sweden, V. Baglin, 6 - 16 June, 2017 Water cooling tube

Water leak in cooled devices

- The crotch is a photon absorber (~ kw), used in SR machines. It need to be water cooled ...
- Example ESRF crotch, March 2005
- Water leak:
 - 50 m vented
 - water inside the vacuum system!
 - 5 days lost







L. Hardy, ARW 2009

Origin: de-ionised water+ Copper + radiations



Vacuum, Surfaces & Coatings Group Technology Department

Water – cooled devices: another example

pressure (Pa)

Example Spring 8 photon absorber, June 2001
 New design with cooling tube out of the SR fan





Fig. 5. Photographs of the cross section of the photon absorber removed from the RF cavity (a) and the cross section of the eroded part (b). Corrosion was found only inside the water pipe where the synchrotron radiation hits.

M. Shoji *et al.* Vacuum 84 (2010) 738–742






Vacuum, Surfaces & Coatings Group Technology Department


1.2 Non conformities



Vacuum, Surfaces & Coatings Group Technology Department

LHC Dipole-Dipole Interconnection








Vacuum, Surfaces & Coatings Group Technology Department

Plug-in Modules with RF Fingers

- Last installed component to interconnect superconducting magnets (~ 1 700 PIM)
- RF bridge made of sliding RF fingers (Au coated to avoid cold welding)
- < 0.1 mOhm contact resistance, Rh coating (i.e. 3 mOhm/RF finger)




Room temperature position



Vacuum, Surfaces & Coatings Group Technology Department

August 2007

- After warm-up of sector 7-8
 - A buckled PIM was discovered in interconnect QQBI.26.R7
 - Was really found by chance!






Vacuum, Surfaces & Coatings Group Technology Department

Why buckling ?

- Non conformity during manufacturing
- Not properly documented => Lesson: respect of Quality Assurance is a MUST






Vacuum, Surfaces & Coatings Group Technology Department


The consequence: RF ball emitter

- Identification of critical PIM :
 - Repair / consolidation when possible
 - ~ 1 mm longitudinal shift of quadrupole to gain margin
- Maintain arc below 130 K during stand-by period
- Recurrent observation after each warm up of arc with:
 - RF ball
 - Tomography
 - Endoscopes





RF ball



RF ball inside PIM





Vacuum, Surfaces & Coatings Group Technology Department

Deformation of bellow

Production of bellows for the LHC QRL:

- design: convolution height "at the limit"
- non-conform production
- not traced !
- Cured by mechanical consolidation
- Production follow-up shall be appropriate !





See C. Garion lecture and tutorial




Vacuum, Surfaces & Coatings Group Technology Department

It can always be worse ..

• CERN ISR vacuum chamber located at the interaction point

Imploded Thin Walled Vacuum Chamber





Vacuum, Surfaces & Coatings Group Technology Department

1.3 Aperture losses




Vacuum, Surfaces & Coatings Group Technology Department

Warm Modules for Interconnection



- Modular system
- ~ 1 800 in the LHC ring
- Bellow shielding to optimise beam impedance
- RF bridge with several shapes (circular/elliptical)
- Ag coated CuBe fingers
- Rh coated insert
- Allow thermal expansion during bakeout (+/- 20 mm stroke)
- Can accommodate instrumentation ports






See R. Wanzenberg, B. Salvant, S. Calatroni lecture and tutorial



Summer 2011 : Vacuum Modules - VMTSA

- Design extrapolated and not mechanically validated before installation in the ring
- Pressure spikes located beside inner triplets generated interlocks and background



Observed Pressure spikes during a physics fill



Vacuum, Surfaces & Coatings Group Technology Department

Vacuum Modules : VMTSA - 2011

- X-rays done in May showed a conform module, in November the module was broken
- The RF bridge was destroyed by the beam !
- 8 out of a total of 20 in LHC were damaged i.e. 40 %

Typical default, DCUM 3259.3524

Left side

Side view (xray from corridor to QRL)


 b) Metallic noise due to loose spring when hitting vacuum chamber

c) RF fingers falling due to broken spring

d) aperture reduced ?

Non Conform

Spring was broken between May and November 2011





Vacuum, Surfaces & Coatings Group Technology Department

Heating due to Re[Z]





• Origin of the systematic default was identified to be due to a poor contact between the RF finger and the transition tube.

• Lesson : always validate the design of your components (even under schedule pressure)

See R. Wanzenberg, B. Salvant and S. Calatroni lecture and tutorial





Vacuum, Surfaces & Coatings Group Technology Department

2011: Pressure spikes in right side of CMS

• In 2011, frequent pressure spikes, some up to 10⁻⁶ mbar, were observed at CMS, 18 m, right side.

• When the local pressure was above 10⁻⁸ mbar, CMS background was larger than 100 % thereby reducing the detector capability





Courtesy J-M. Dalin EN-MME

Typical Observation



Vacuum, Surfaces & Coatings Group Technology Department Vacuum for Particle Accelerators, Glumslov, 6 - 16 June, 2017 Sweden, V. Baglin, 6 - 16 June, 2017

37

Ne venting to save the 2012 CMS Run !

Vacuum system performance recovered even following the dismounting of 2 m long

vacuum chambers









Ne



CMS

Forward chamber

3rd Vacuum Symposium UK



January 2012




October 18th, 2012

Vacuum, Surfaces & Coatings Group **Technology Department**

4th July 2012: SM BEH Boson Discovery

ATLAS and CMS discovered a new boson in the mass region ~ 125-126 GeV/c²










Vacuum, Surfaces & Coatings Group Technology Department

RF bridge: PETRA III

- PETRA III RF contact are placed inside the transition tube when the bellow are overextended
 - => beam intensity limited in 40 bunch modes to 80 mA till 2012 (design 100 mA)
- Define specification
- Check at surface mechanical and electrical specification



Courtesy L. Lilje





Vacuum, Surfaces & Coatings Group Technology Department

RF bridge: ESRF

• Vacuum levels and gamma-graphy are great tools to avoid disaster.

• X-rays before machine closure and pressure follow up helps!







Vacuum, Surfaces & Coatings Group Technology Department

RF Contact: SOLEIL

Misplaced RF contact are producing arcing



N. Bechu, OLOAV 2014



Vacuum, Surfaces & Coatings Group Technology Department

RF bridge: RHIC



P. Sampson, ARW2009



Vacuum, Surfaces & Coatings Group Technology Department

RF bridge: BEPC II



J, Cao, ARW2013



Vacuum, Surfaces & Coatings Group Technology Department

RF Bridge: KEKB



M. Mazuzawa, 2004




Vacuum, Surfaces & Coatings Group Technology Department

Beam induced outgassing

- A movable mask to protect ALICE during injection (Boron nitride jaw)
- Deformed beam screen observed during winter technical stop 2011-12
 - Suspected origin is a bad sliding point
 - Cu beam screen was deformed during bakeout at 300 deg



Beam induced, via impedance, thermal outgassing







Vacuum, Surfaces & Coatings Group Technology Department

Benefit of a large aperture

• Allows many optics to be deployed, in particular new ones not foreseen at the stage of the design *e.g.*

- CERN Achromatic Telescope Squeeze to be used for HL-LHC
- PETRA III
- Solving ULO (unidentified lying object) issue by applying a bump










Vacuum, Surfaces & Coatings Group Technology Department

Unexpected beam aperture restriction in LEP around IP1 22 June 1996

Could not get the beam to circulate more than 15 turns even with large bumps all around the ring. Use single turn orbit system and normalised the measurement.




S. Myers





Vacuum, Surfaces & Coatings Group Technology Department

Unexpected beam aperture restriction in LEP around IP1 22 June 1996



Zoom in on Quadrupole





• Qualified by of the CERN accelerator director, S. Myers, of:

Unsociable sabotage: both bottles were empty!!




Vacuum, Surfaces & Coatings Group Technology Department

1.4 Energy losses



Vacuum, Surfaces & Coatings Group Technology Department

Tunnel environment and cleanliness ...






Vacuum, Surfaces & Coatings Group Technology Department

UFO Particulates

- They originate from the construction / installation and may latter interact with the beams
- Most of the particulates have a positive charge (shall be less sensitive to positive beams)
 HERA
 - pumping system upgraded to NEG strip and positron operation preferred
- LHC
 - Most of them are very small, a few leads to beam dump triggered by BLM system
 - Rate reduce with time thanks to gravity and vibrations.




See lecture L. Lilje



Vacuum, Surfaces & Coatings Group Technology Department

Stored Energy

• Modern machines have a few MJ of energy ... what can you do with that apart from collision ?



See F. Cerutti, M. Brugger lectures




Vacuum, Surfaces & Coatings Group Technology Department


Beam extraction from SPS: 10/2004

• 450 GeV beam, 3.4 10¹³ p on stainless steel (3 MJ) miskicked, result:
 → A 1 m long groove along a SPS vacuum chamber after the impact of ~1% of a nominal LHC beam during an 'incident': ~ 3 days repair

• In a superconducting machine, it would cost several months of work!









Vacuum, Surfaces & Coatings Group Technology Department

TEVATRON Accident: 5 December 2003

A roman pot moved into the beam

→ the particle showers quenched 16 superconducting magnets


 \bullet The beam moved by 0.005 mm/turn and touched a collimator jaw surface after \sim 300 turns

→ the entire beam was lost, mostly at the collimator

- · Beam loss monitor where switched off!
- 10 days repair



5 mm hole in a vertical W jaw



25 cm groove in stainless steel



Vacuum, Surfaces & Coatings Group Technology Department

Also with electrons machine

• Example of an air leak in SPRING 8:

• 8 GeV electron beam with 15 micron vertical beam size on a 0.7 mm thick stainless steel wall




Fig. 6. Cross section of the injection chamber wall at the broken part. It seems that the electron beam hits the thin wall several times, since many traces of electron beam bombardment were found.

M. Shoji *et al.* Vacuum 84 (2010) 738–742



Vacuum, Surfaces & Coatings Group Technology Department

Also with photons from SR machine

• Example of melted gate valve at SSRF, Shangai:

• The photon shutter was opened while the gate valve was closed, the synchrotron radiation produced by 3.5 GeV electron beam at 200 mA melted the stainless steel.



L. Yin, ARW2013



Vacuum, Surfaces & Coatings Group Technology Department

Also with photons from SR machine

• Example of SOLEIL, france

Metal melted by SR

heat load

.3

Courtesy N. Bechu




Vacuum, Surfaces & Coatings Group Technology Department

SR induced fluorescence


• Observed at SOLEIL, france

• The X-ray fluorescence of Zr at 16 and 18 keV can destroy the Kapton bakeout foil if the Al or Cu vacuum chamber is thick enough



Primary photons





C. Herbeaux, OLAV 2014




Vacuum, Surfaces & Coatings Group Technology Department

The read pressure is not always a true pressure

 Photons produce photoelectrons, stray particles can ionised the cable or magnetic field can modified significantly the reading of pressure

The apparent absence of beam conditioning is due to scattered particles on the gauge collector and cable








Fig. 2. Normalized pressure rise and beam lifetime as a function of beam dose. Pressure rise is the difference between beam-on and beam-off pressure.

M. Shoji *et al.* Vacuum 84 (2010) 738–742

L. Hardy, ARW 2009 See F. Cerutti and M. Brugger lectures



Vacuum, Surfaces & Coatings Group Technology Department

1.5 Summary



Vacuum, Surfaces & Coatings Group Technology Department

Summary


• The vacuum group people have always the impression of being firemen !!!!!



• Can we do better?



Vacuum, Surfaces & Coatings Group Technology Department



Those who cannot remember the past are condemned to repeat it.

George Santayana



Vacuum, Surfaces & Coatings Group Technology Department

2. Quest towards availability



Vacuum, Surfaces & Coatings Group Technology Department


Availability: Vad fan är det här? (what the hell is this?)


Availability: The percentage of time an equipment is in operable state



Vacuum, Surfaces & Coatings Group Technology Department

Accelerator schedule: objective beam time!

















Vacuum, Surfaces & Coatings Group Technology Department

2.1 Study, Design, Procurement & Installation



Vacuum, Surfaces & Coatings Group Technology Department


Design reports

• Communication & release of Official documents and books is mandatory to share pertinent information across the project

MAX IV design report **Detailed Design Report MAX IV Facility**

2010





2004

HL-LHC Preliminary design





Vacuum, Surfaces & Coatings Group Technology Department

LHC Project

• Defining and understanding the machine parameters impacting the vacuum system was a crucial part of the project

erland		up or Supplier/Contractor Document No. AC/TCP	
the Large Hadron Collider	10	EDMS Document No. 0513.00 rev. 1.1	
project		Date: April 8, 1999	
En	gineering Specificati	on	
	RAMETERS FOR TALLED IN THE	•	
(Project Notes, Project Re directly, or for calculatin components. The presen reference to a document	Abstract neters and operational scenarios a ports, Market Surveys, Technical go safety margins or defining te it document is a compilation of or other sources where more of d in the experimental areas has no	I Specifications, etc.) either est procedures for machine these parameters with a detailed information can be	
	Checked by :	Approved by :	
Prepared by :	-		

	Design		
	Nomina	I Ultimate	
Energy [TeV]	7		
Luminosity [x10 ³⁴ cm ⁻² .s ⁻¹]	1.0	2.3	
Current [mA]	584	860	
Proton per bunch [x10 ¹¹]	1.15	1.7	
Number of bunches	2808		
Bunch spacing [ns]	25		
Normalised emittance [µm.rad]	3.75		
β * [m]	0.55		
Total crossing angle [µrad]	285		
Critical energy [eV]	44.1		
Photon flux [ph/m/s]	1 10 ¹⁷	1.5 10 ¹⁷	
SR power [W/m]	0.22	0.33	
Photon dose [ph/m/year]	1 10 ²⁴	1.5 10 ²⁴	




Vacuum, Surfaces & Coatings Group **Technology Department**

Allow provisions for upgrades!

• There might be always good reasons to upgrade the performance of the machine that you ignore at the time of the design of your project ...

ISR Luminosity Evolution



	Parameter	Design (55 / 95 GeV)	Achieved (46 / 98 GeV)	
	Bunch current	0.75 mA	1.00 mA	
	Total beam current	6.0 mA	8.4 / 6.2 mA	_
	Vertical beam-beam parameter	0.03	0.045 / 0.083	
	Emittance ratio	4.0 %	0.4 %	x 10
	Maximum luminosity	16 / 27 10 ³⁰ cm ⁻² s ⁻¹	23 / 100 10 ³⁰ cm ⁻² s ⁻¹	x 1.4 / 3.7
sity	IP beta function b_x	1.75 m	1.25 m	_
	IP beta function b_y	7.0 cm	4.0 cm	

LEP: Design and Reality

Reality better than design (result of many years work)!

S. Myers

- LEP becomes LEP2
- LHC becomes HL-LHC
- ESRF upgrades
- KEKB becomes SuperKEKB






Vacuum, Surfaces & Coatings Group Technology Department


Base Line Validation

 Many studies conducted over ~ a decade with experts all around the world, some examples:

Material performance qualification




R. Cimino, I.R. Collins, App. Surf. Sci. 235, 231-235, (2004)






System performance qualification



V. Anashin et al., J. Vac. Sci. Technol. A 14(4) (1996) 2618





Vacuum, Surfaces & Coatings Group Technology Department

Design of components / assemblies

• Design review (conceptual, detailed, production readiness ...)

• During LHC procurement, the LHC-VAC group internally reviewed all technical specifications and drawings :

- ensure compatibility across the vacuum system
- allows optimisation across components and performance (standardisation)
- use quality class (class A, approval circuit after control 1&2)

 <u>GOLDEN Rule</u>: reject components, including in-kind, which do not meet VACUUM DESIGN APPROVAL

- Do's and don'ts (just a few important ones from LHC design and experience)
 - No halogenated fluxes
 - No cold demountable joints
 - Helium envelopes are all-metal
 - Joining techniques need to be validated (materials, welding, DT)
 - No dye penetrant testing
 - Minimise thin wall components.
 - Combine RT leak and pressure test of components
 - Decide a policy for cold testing of critical components
 - Keep non-vacuum group manufacturing under control assign a vac link person
 - Don't allow deliveries until tightness certification is approved
 - Minimise number of welds to be tested in the tunnel
 - Many, many more
 - ...

Technical specification & drawing validation
 State of the art material, cleaning methods, procedures



Vacuum, Surfaces & Coatings Group Technology Department



- a spare policy / strategy shall be defined based on:
 - cost
 - time to recover including building of components
 - failure rate
 - failure probability
 - complexity of the component
 - long term storage of spare
 - In case of accident, does the repair can be done in the shadow of another faulty component ?

• ...

Driven by major items and possible events (rupture, beam loss ...)







Vacuum, Surfaces & Coatings Group Technology Department

Long Shutdown 1 (LS1)

• Main aim : consolidate the splice interconnection between superconducting magnets to allow operation at 7 TeV/beam

• Started Feb 2013, Physics resumed April 2015






Vacuum, Surfaces & Coatings Group Technology Department

Overview of LSS Beam Vacuum Activities

• 148 vacuum sector to re-commission *i.e.* 5.1 km of vacuum system (80 % of the LSS)





Vacuum, Surfaces & Coatings Group Technology Department

Quality Assurance Plan

Allows to share information in a global way producing the right component

4 10 LSS L1 4 🕥 7L1 🖻 🗐 LQNFJ.7 SIMA 711 CBWJA.7 RJBHT.7L FTAAL.G

Date: 2013-11-04

ENGINEERING CHANGE REQUEST


Vacuum Pilot Sectors in the LSS8

BRIEF DESCRIPTION OF THE PROPOSED CHANGE(S):

The vacuum pilot sectors provide detailed information for the understanding of the vacuum dynamics stimulated by synchrotron radiation and electron cloud. It opens the possibility, on a day by day basis, to carefully monitor and analyse pertinent beam vacuum parameters for the LHC operation. With this ECR the VSC group requests to allocate the space between Q5L8 and Q4L8 from -163.51 m to -145.18 m on the left of IP8 to dedicated vacuum instrumentation as described below.

PREPARED BY:	TO BE CHECKED BY:	TO BE APPROVED BY:
Name Dept/Grp	Name Dept/Grp	Name Dept/Grp
G. Bregliozzi TE-VSC	G. Bregliozzi TE-VSC	
V. Baglin TE-VSC	V. Baglin TE-VSC	
B. Henrist TE-VSC	B. Henrist TE-VSC	

Engineering Change Request



ssembly Tree	· //	Ea	uipment Folder	· · Mair	Info	22 C	111	
ssembly free		-4	upment router	0.000	11110			
HCVC1TB002.CR000001 . VT Aluminium (harden Assembly	<u> </u>			Faulpment	Identifier: HCVC	1TB002-CR000	001
		_			Other Iden	tifier: VT1		
					Description	VT Aluminium	Chamber - Asse	mbly
Main Made of Equipment data Ma	nufacturing 🕻 Operation 🗎 Doc	uments \ History \	Map					
Actions : Edit History					Nats Made of Equips	ert fate (Handaturing) Op	eration (Documents) His	tary Hap
					Actions : Edit View ex			
External Links				200	Physical			
r				0	Resp. Technique	CERN		
					Status	Manufacturing		
Property Values					Other Identifier Parent Equipment	VT1		
Property	INominal Value	Walse	[Unit		Parent Equipment			
Length	Internative Verse	14404	mm		Location			
				- 11 · · ·	State	Good		MRC V01
Leak Check Accept no bake			mbar I/s		Safety			
Leak Check Ac. after bake			mbar I/s		RP Classification			
Degas Accept after bake			mbar I/s		Comments			
			°C		Comments			
				- 20				
Bake-out Temperature Ac.								
Bake-out Temperature Ac. NEG coating (Y/N)				11	Design How in ADS	NVT Aluminium	Chamber - Assembly (ver. 01
Bake-out Temperature Ac. NEG coating (Y/N) Leak Check Ac. after NEG			mbar I/s	1	Design Item in ABS	UVT Aluminium	Chamber - Assembly (ver.0}
Bake-out Temperature Ac. NEG coating (Y/N)			mbar I/s °C		Item in ABS	,		
Bake-out Temperature Ac. NEG coating (Y/N) Leak Check Ac. after NEG					Item in ABS	UVT Aluminium 2011-08-17 2015-01-14	Chamber - Assembly (ACAIO EDHSINFORT

Standard components Libraries

Equipment Management Folder

Equipment Codes - System: V		Accelerators Entities an NAMING PORTAL	d Signals
Vacuum (110)			
VA Vacuum - Assembly			
WMA Vecaum - Assembly			
P <u>YAB</u> Vacuum - Assembly			
PYAC Vacuum - Assembly			
ID VAD Vacuum - Assembly			
P <u>WAE</u> Vacuum - Assembly	ALL H	C Systems	
P <u>VAE</u> Vecuum-Assembly	ALL STO	o of stems	
Prats Vacuum - Assembly			
PAH Vacuum - Assembly			
P201 Vecum-Assembly			
9 YAL Vecum-Assembly - 212.7	Sector valve		
♦ YAH Vector Assembly Module			
QVANA Vacuum Assembly 3	Adule		
WANAD Vacaum - Assemb	ty - Module - MISAE w	th - VAZAK VAZAF, VAZBD	
WANAU Vectors - Assents	r N- Module - VIUAE vi	In VAZAC /VAZAC _VAZON	

Naming Convention

DUT DATABASE													
ositions Interfaces Systems Electrical Classification	ins Machines Civil Works	More Navigators	✓ Reports			~							
RC 81	Version: STUDY												
L1	^						IDENTIFICATI	DN					
5u	ID					272538							
7L1	Machine					LHC Ring							
DONE1.7L1	Type Description						e ID : 571137, naming		- DFBA - Instrumentatio	- 0			
	Layout Name					VABBG.7L1		Tes, for copulation					
SIMA.7L1.1LM13S	Expert Name					VABBG.235							
CBWJA.7L1	Vacuum Name					VABBG.235							
BJBHT.7L1	Beam Function						n both beams (B1, Blue slot is for both beams						
FTAALG7L1	Links to other databases					This vacuum	slot is for both beams	101					
ETHAL C7L1	Classification												
EVI AZI 1	Log						DIMENSION	e					
EVJ.B7L1	Lengt	1	Width			Height	DIRECTOR	,					
DFBAA.7L1	0.655 m	1	0 m			0 m	LOCALISATIO	ON					
	Vacuum Sector					VACSEC AR							
	Vacuum Sector					VACSEC.AR Positions (S/U/						Rotations	
VRJDP.C7L1	Location From	S Start	S Mid	Idle		S End	V) U S	tart UE	nd V Start	V End	В	A C	Magnetic Leng
VABBG.7L1.C	7L1 IP1 7L1 IP1	26402.2742 m	26403	2.6017 m		26402.9292 m	0 m	1 0 m	0 m	0 m	8:	0: 0:	
10 VFCDO.238.7L1.B	Location: RR13	-200.000 m	-2.99.	2010 11		-200.004 0			0 111				
TFCD0.238.7L1.R							ACHANICAL APE						
ES VIESA.235.7L1.C	Aperture	Function B2	\$ 26402.2742	U -0.097	V	Offset S	Shape	Inr	er Diameter u / v 0.063 / 0.063				se Parameters a/b/ 5/0.0315/0.0315/0.0
© VMDBA.237.7L1.8	Ē	82	26402.9292	-0.097	0	0.6550	CIRCLE		0.08/0.08				0.031570.031570.0
	1	B1 B1	26402.2742 26402.9292	0.097	0	0.6550	CIRCLE		0.063 / 0.063 0.08 / 0.08				5/0.0315/0.0315/0.0 04/0.04/0.04/0.04
1 VMDBA.237.7L1.R		81	26402.9292	0.097	0	0.6550	OTHER PROPER	TIES	0.0870.08				0470.0470.0470.04
10 VMZAP.236.7L1.8	Radiation Zoning Tag						omentionen	THEO					
1 VMZAQ.238.7L1.R	Status					An equipmen	t is installed in this slo						
@ VGP8.236.7L1.8	Responsible						(SHANK (TE-VSC)						
VGPB.236.7L1.R	Comment Downstream flange					VGR, VGP :: DN100	VPIA, VGP						
© VGRB.236.7L1.B	Upstream flange					DN63							
© VGRB.236.7L1.8	SMARTEAM References					Detail		TRSF	Doc number - E				
VGK5.235.7L1.R						MODELE S VACUUM T		IDENTITY IDENTITY	ST0029104_03 - ST0029104_02 -				
Wush.235.7L1.8 Wush.235.7L1.8	Pins & Pinouts												
WVGS1.235.7L1.R													


LHC layout database




Vacuum, Surfaces & Coatings Group **Technology Department**

Vacuum Layout

• Define components, produce data based drawings and SCADA systems, ease installation and optimise future intervention (e.g. in radioactive areas)




Integration studies




Installation drawings

В	С	D	E	F	G	н		J	K	L	M
		LBV component's order f	or LS1								
		Updated	14/07/2014	VB							
Det	Ref EP			LSS	Sector	Deres		Lenght			
V J	Par EP	Theme 🖵	Component	,7		Beam	DCUM(🖕	(mn *	Designation 🖵	Description	Comment J
208	313	NEG upgrade	Assembly module	5	B4L5.R		13180.812	279.5	VAMVE.4L5.R	VPIAN/VPNCA_,-,VVFMF	check
209	103	TCL4	Vacuum module	5	B4L5.B		13180.902	300	VAMWF	VMJAF with -, VGRB, VPIAN/VPNCA, VVFMF	module in the machine, instrumentation changing
210	276	NEG upgrade	Assembly module	5	B4L5.B		13180.902	280	VAMWF.4L5.B	VMJAF with -, VGRB, VPIAN/VPNCA, VVFMF	na
211	161	TCL4	Vacuum chamber	5	B4L5.R		13180.972	1747	VCDRU	Chambre ID80 DN100-QCF100	remplace VCDQN+VMDNA



New components Production & follow up





Vacuum, Surfaces & Coatings Group Technology Department

Infrastructure and Material

• Adapted stores, components, tools and storage management are mandatory






Vacuum, Surfaces & Coatings Group Technology Department

Vacuum Acceptance Tests


• Prior installation all (several thousands) equipment have been baked and validated at the surface before installation in the tunnel:

- functional test
- leak detection
- residual gas composition
- total outgassing rate





2 ALFA Roman pot stations (XRPA) connected to TB1 in B113



→ Logistics, scheduling, coordinating & official reporting


See G. Bregliozzi lecture



Vacuum, Surfaces & Coatings Group Technology Department Vacuum for Particle Accelerators, Glumslov, Sweden, V. Baglin, 6 - 16 June, 2017

G. Cattenoz et al., IPAC 2014

The LHC beam Vacuum Laboratory in 2012





Vacuum, Surfaces & Coatings Group Technology Department

Examples of tested parts





























Vacuum, Surfaces & Coatings Group Technology Department

Installation and Quality Control

Expert teams dedicated to specific tasks, logistic included
Industrial support coordinated by CERN staff






Vacuum, Surfaces & Coatings Group Technology Department Vacuum for Particle Accelerators, Glumslov, Sweden, V. Baglin, 6 - 16 June, 2017

.HC Beam Vacuum Non Conformity tracking system

Work Orders

• Allows, scheduling, coordination, identification of tunnel activities, control of equipment and fulfil safety aspects: electrical lock-out, radiation

European Laboratory for Pa	rticle Physics				
🇊 ІМРАСТ		VINCE	IT BAGLIN 🗿 Help Insident Request Fulfilment 🥳	AR 91831: LSS1 (
Menu 🤞 Search A	ctivities By - TE-VSC-BVO LHC machine		🔨 Advanced 🔚 Save Filter 🔀 Reset 💽 Search	Responsible: PABLO SANTO (786617/TE-VS	S DIAZ
Create Activity Creator:	Title:	Description:	Activity Type:	Description: Instrumentation straight section	
Facility:	LHC Machine v Interv. Period	✓ Interv. Period:	System:	su agni sector	
Activity List Status:	Type:	Meeting Type:	✓ Approval Status: ✓	When	
Activity Cluster List 🔷 Responsib	le: Resp. Group: TE-VSC-BVO	Participant:	Contract: Company / Contract Number 🔎	Proposed Date: Dur	ation: 3 Day(s)s
Radiation Dose Reports Location: Access Control	Access Points:	Priority:	✓ Change Request: ✓	Earliest Start: Lates	
Favourite Activities Dates:	✓ Start Date:	End Date:	Working Time:	Working Time: Normal: Mor	/- Ffl, 07:30 - 18:00
DIMR Search Duration :	: d/h/m Activity Cluster:	Cluster Resp.:	Tags: 🗸 🗸	Scheduled: 13-M	Mar-2017 to 16-Mar-20
94866 - Closed			Created by DIDIER CALEGARI on 06-Apr-2017 10		Mar-2017 to 17-Mar-20
Save 🕄 Refresh	Clone Split CE	RN		Intervention Period: EYE (05- Granted Working Time: Non	Dec-2016 to 14-Apr-20
Approvals		Requests	flow 🔗 Attachments (0) 🕑 View History 📮 Download		
Title*: Pompage ATL	AS Facility:	LHC Machine			
Responsible: DIDIER CALE	GARI 279472 , 165495 Activity Type	: Operation		Who	
Activity Cluster: Link	Priority:	ASAP 🗸			ontact Phone: 164287
				Ma: Presence of Short-term radi	x Participants: 4 ation workers: No
What	- What			Participants:	
<u> </u>	Description: Modification controleur pompe pour pom	npage ATLAS			
Where				<i>?</i> ∂TRIUMF	
When	System: V - Vacuum				
Who	Work Order Request System - Subn	nit APS APS	D APS AV		
How		~ 5		-	
	Badge No: 46942	Group:	•	°	
Safety	1 fe chin c				
RP Assessment	Machine Clinac Cleut CPar CBooster Affected:	r 🌣 Sr Ring 🔍 Other 🕤 Exp Floor	 Mis Test 		JMF
Tests	Rancettu.				
1000	Estimated p			TRIUMF Home Work Me	anagement Maintenance
	Duration: Days Hours				-
				Create New Request	The Request has been saved
	Priority: ^C Urgent ^C As Time Permits ^C N Maintenance	otify for Access 🔿 Next Shutdown 🤇	Next Access C Scheduled	My Requests	Edit Work Request: Add M/q to th
	Work		Ξ		Mass Scan - #1578
	Description:		-		Save Save And Con
				T Attention Required	
				Arrennon Kedoireo	Basic Information *
			Z	Find Work Requests	People
	Safety		E	C	1.00,00
	Concerns:			Notifications (50)	Fields marked with a * are rea
				N Legend	Help for Deliverables
			-	Error Message	
			X	Data error: must be	Deliverables * Add Deliv
		Next Clear		resolved before saving. (Save not allowed)	Title Quantity R
		Main Menu			see request 1 2
	APS	Query Request		Warning Message Submission error: must be	
		Modify Request		resolved before submitting.	
				(Save allowed)	Previous tab Next
				🕲 Update Message	
	02/04/2002 ARW, Grenoble		Operations Group	Success: an indication of compliance	
	Chihyuan Yao		Advanced Photon Source		





Vacuum, Surfaces & Coatings Group Technology Department

Commissioning of a vacuum sector

Usually a **3 weeks** intervention (typical of any baked vacuum system) depending on the sector complexity:

- Venting the sector to air
- Mechanical intervention
- Pumping and leak detection
- Bakeout installation
- Bakeout and NEG activation
- Bakeout removal







Vacuum, Surfaces & Coatings Group Technology Department

Commissioning of the NEG coated vacuum system

Bake out of stainless steel part firstFollowed by NEG activation




Heating Time [h]



Specific procedure for NEG activation
 Activity reports
 Description

Progress & performance charts





Vacuum, Surfaces & Coatings Group Technology Department

Human error

- Controls are necessary because of human fallibility, not incompetence
- Would you take this plane if there were no check list?



Airbus A380 cockpit




Vacuum, Surfaces & Coatings Group Technology Department

Some examples

• A classic: venting or commissioning the wrong vacuum sector!

• Exchanging the of a turbomolecular pump without closing the sector valves while the pump is connected to the beam vacuum venting several vacuum sectors!

- Activating / baking a vacuum sector under atmospheric pressure!
- Pumping down a vacuum sector with aluminium foils used at blank flange!





Vacuum, Surfaces & Coatings Group Technology Department

Check lists

Select name from list OR enter forena Select Name:	ame.surname		r			
Select Name:		E-mail to elog	J			
Due Date	Checkpoint		Status		Notes	
Machine Changes Log -5 the machine operat	gged : ALL modificat ion are logged in e- nutdown changes".	log as "Sumary of	Complete Adrian Johnson	Al modification affect operati	ns and works that may on have been logged in elog	
	lacaowin changes .					<u> </u>
	11			E mail sent w	ith a reminder that Start up	
-5 diamond	-2	All MPS signals vis	sually checked in Cont	rol Room, any faults	Pending	FE19 ABSB-02 Air Pressure switc SO/HS/MSmall investigating.
-5	-	reported and	d repared (excluding \	acuum Valves).		
Open Checksheet	-2	Correctors Powers	ed up and left ON (du	ation determined by	Complete Wayne Perkins	email sent CA /BR11/04 -SR06/ PC-HSTR-05 Unstable.
-5 2013		sche	edule) log any unstabl	e PSUS	Wayne Perkins	
	-2	STORAGE RING : '	Vault Searched and PS	S Permit confirmed.	Pending	
-3 View/Edit Templates						
-3	-2		relevent to Machine O Ind All Operations Key		Complete Wayne Perkins	
Help (Wiki Page)	-2	Insertion Devices Motion confirmed	(ind. Wigglers) Check J, Soft limits checked, Y	ed out : Powered up, /alid BURTs applied.	Pending	Not Done so far: 051, 106A, 106P Phasing unit 10I-A, 10IB, 112, 115
	-1	Cryoplant and O2	Alarm handlers : Che are live and functionir	k with AR that these	Complete Wayne Perkins	
-2						email sent SL/ND/PA 10/4
	-1	Vacuum Va	alve Test Boxes : All A	counted for.	Pending	
	-1	BPM MPS Override B	Boxes (x3) and BPM O : All Accounted for.	verride Red Plugs (x3)	Complete Wayne Perkins	
	-1	LI 8	& BR tested and Opera	tional	Complete Dave Preest	Tested by Chris Christou 03/11/1 New BURT file created.
						Started, see Walkround Checksh
	-1	Wolk round Chock	s Done : Start Up Wal	round Chookshoot 1	Complete	08/04/2013

V. Kempson, ARW 2013



Vacuum, Surfaces & Coatings Group Technology Department

Visual inspection

Documented inspection tours are needed and avoids potential failures





Someone forgot a tool on an undulator: The imprint of it is visible on the Al vacuum chamber!



Vacuum, Surfaces & Coatings Group Technology Department

2.2 Operation



Vacuum, Surfaces & Coatings Group Technology Department

Vacuum Monitoring – Stand-By

General monitoring : check status of components, record of machine status
Stand-by with specific duties: answer to control room request, act on simple intervention, assist expert teams during complicate / delicate interventions
Stand-by must be trained !


CERN CH-1211 Geneva 23 Switzerland Vecum Sofrees,	CERN Div./Group	Project Document No. or Supplier/Contractor Document No. TE/VSC 1503404	And Control of Control			Monitoring	g report										
		Date: 11-12-2014	Francois	Author	V			26/09/201	Date								
<u>+</u>				S		of observation	s and interv										
			Francois	Piquet 1 Bellorini	Y	Pique Esa Paju	t 2	None	VC	≃ uum hres. tings							
т	E-VSC Procedure			Report type		Duratio			SI			Pic	quet rep	ort			
	ne Operation Follow-up of or Complex Vacuum Syste		Monitori	ng report (Daily)		1.5 h Action required	⊻ I on machine	Closed	Jose	Author Antonio Somoza	V				28/08/2	Date	
			Beam V.LHC	Ins V.LHC	SPS	PS Booster		AD	150		Summary	y of obse	ervations	and inte	rvention	s	
	Abstract		×	×	×	Detailed des		Ø		Piquet 1	~		Piquet 2	×	None	VCR Staff	Y
This document describes the tools a vacuum systems, which are required use in the new Vacuum Monitoring R step procedure is given to survey the and heavy ion injector chain. The ma acronyms can be found in the Annex.	to guarantee an optimum efficiency loom (VMR). Based on the present vi e status of all machines comprising th	of all systems. It is dedicated for acuum control system, a step-to- he LHC and the complete proton	1.LHC Insuli 1.2.1. LHC cryogenic LS1 no monitori 1.2.2. LHC operation LS1 no monitori	ng required	1		chption			Report type	×	0 h	Duration	×	Closed	Status	×
				nping groups and valv	<u>e:</u>				Beam	V.LHC Ins V.LHC	SPS	PS	cerned ma Booster		AD	ISOLDE	Other
Author:	Checked by:	Approved by:										Deta	ailed descr	iption			
Eric PAGE, TE-VSC Edgar MAHNER, TE-VSC Ludovic MOURIER, TE-VSC Jose De La GAMA, TE-VSC Germana RIDDONE, TE-VSC	Paul Cruikshank SLs	Paolo Chiggiato							merci de préciser la 1. Date d'intre 2. Heure d'ap 3. Machine, z 4. Equipement 5. Présence d 6. Type d'intr	opel de la CCC	rvention dans la mesure du p blème distance)	eessible :	Important	below for each 1. Date of 2. Time of 3. Machine 4. Affects 5. Interioci 6. Interven	intervention if it is possi f intervention f CCC call e, zone ad equipment, prob	oleme source or remote)	tics please specify the detaile
P	rocedure	es				Daily	/ and	d we	RAS.	y Rej	-						



Vacuum, Surfaces & Coatings Group Technology Department

SCADA & Alarms

- Software tools are available to help & alert the vacuum expert
- Next generation will integrate predictive behaviour of pressure levels!






Vacuum, Surfaces & Coatings Group Technology Department

Pressure Follow-Up

 Expert monitoring: check general trends and track / resolve specific issues, follow daily and detailed machine operation 💮 History: Arc extremity - Unbaked Cu - 🗆 × E+3




Interlocks records

New		•			
Туре	Name	Date	VACSEC	Equipment	Sector valve
P)	Interlock VVGSW.122.4L2.C 30th of November 2012	30/11/2012 14:05	A4L2.X	TDI.4L2.C	WG5W.122.4L2.X
	Interlock VVGSW.819.5R4.B 10th of September 2012	10/09/2012 21:51	E5R4.B	BWS.5R4.B	VVGSW.819.5R4.B
•	2nd Interlock WGST.232.7R7.B 26th of August 2012	26/08/2012 22:30	A7R7.B	VGPB.231 & 233.7R8.B	WGST.232.7R7.B
	Interlock VVGST.232.7R7.B 26th of August 2012	26/08/2012 02:30	A7R7.B	VGPB.231 & 233.7R8.B	WGST.232.7R7.B
	Interlock VVGST.232.7R7.B 16th of August 2012	16/08/2012 16:20	A7R7.B	VGPB.231 & 233.7R8.B	WGST.232.7R7.B
•	Interlock VVGSF.221.1R8.X 20th of July 2012	20/07/2012 02:00	Both VAX in IP8	VGPB.222 & 219.1R8.X	WGSF.221.1R8.X

Descri Calenda Beamdump of fill 3348 triggered by ALICE The b which Beamdump of fill 3053 triggered due to air The b leak on BWS trigge Beamdump of fill 3006 triggered due to Pressi sparking on RF fingers Beamdump of fill 3003 triggered due to Pressi sparking on RF fingers Beamdump triggered by VGPB Possib Beamdump triggered by VGPB Possib

Tracking interlocks



LHC fills + Fill 2012 + All Documents

Fill history 2012 Interlocks 2012

Issue follow up

Team Discussio

People and G

Recycle Bin Al Site Cont

confir

	Rll number	Filling scheme	ppb(xlell)	Туре	Date	Name	Short
s	3359	50ns_1374_1368_0_1262_144bpi12inj	1.64	۲	02/12/2012	Fill 3359	1374 b - Prese observ - Dum IP1/S seen o
es	3348	50ns_1374_1368_0_1262_144bpi12mj	1.42	B	30/11/2012	Fill 3348	6+24 I - bad i TDI2L
	3114	50ns_1374_1368_0_1262_144bpi12inj	1.49	B	30/09/2012	Fill 3114	1374 b DeltaP VGI = Inter_C Composition
	3087	50ns_78b_72_0_48_36bpi3inj	1.47	2	26/09/2012	Fill 3087	Restar Demo
	3045	50ns_1374b_1368_0_1262_144bpi12inj	1.64	2	08/09/2012	Fill 3045	Pressu ramp. MK18 /
1	3044	50ns_1374b_1368_0_1262_144bpi12inj	1.67	(6)	08/09/2012	Fill 3044	Pressu ramp. MK18D up to 2
oups	3006	50ns_1374b_1368_0_1262_144bpi12inj	1.66	8	16/08/2012	Fill 3006	Beam at 2e-i mbar Issue
	2976	50ns_1374b_1368_0_1262_144bpi12inj	1.49	(8)	16/08/2012	Fill 2976	No pre ALICE TD12L
ent	2965	inject and dump	leI0	•	14/06/2012	Fill 2965	450 Ge T012L functio Delta_ Slope - TD1
	2964	TDI 2L angular alignment	1e10	1	14/06/2012	Fill 2964	450 Gi angula Delta_ Slope - TDI
	2957	50ns_1374_1368_0_1262_144bpi12inj	1.55	E	13/08/2012	Fill 2957	CMS s

	Search this site	٩	1
Short description	Modified	Modified By	
1.374 b. - Pressure rises at Q6R5 during ramp (as regularly observed) - Dump on Q6R5 BLH while collapsing separation bump IP1/5. Issue with X6PF area inducing pressure rise as seen on VG1177.6R5.B together with Q5R5 and Q6R5.	03/12/2012 03:33 PM	Vincent Baglin	
6+24 b. - bad injection leading to ALICE triggering dump. 24b hi TDI2L	03/12/2012 05:31 PM t	Vincent Baglin	
1374 b. Defab at MKD_BR VGI = 3.74-9 mbar Inter_Cu = 6e-9 mbar Comparison with fill 2544 of 26/10/2011 Iner_Ceram = 5e-9 mbar	02/10/2012 01:32 PM	Vincent Baglin	
Restart after TS3 and MKID8R exchange. Demonstration that EC is visible at MKI8R	26/09/2012.05:45 PM	Vincent Baglin	
Pressure excursion up to 3e-8 mbar at MKI2D during ramp. The origin is probably the tank itself. MKI8 had no pressure excursion during ramp.	10/09/2012 11:48 AM	Vincent Baglin	
Pressure excursion up to 3e-8 mbar at MKI2D during ramp. The origin is probably the tank itself. MKIBD behaved perfectly with only pressure excursion up to 2e-10 mbar at the same time.	10/09/2012 12:13 PM	Vincent Baglin	
Beam dump at VVGST.232.7R7.8 with interlock level se at 2e-6 mbar while pressure reading on PVSS are 1e-7 mbar 1 Issue with PVSS sampling	t 27/08/2012 04:27 PM	Vincent Baglin	
No pressure rise observed inside OD600 right side of AUCE I TD12L delta_P = 1.7 e-8 mbar.	16/08/2012 09:17 AM	Vincent Baglin	
450 GeV only. TDI 2L was aligned following previous fill. TDI 2L validation with probe beams (1e10 p) as a function of injection oscillations Delta_P ~ 1e-8 Slope on R509: - TDI 2L =5 MGy/8 per mbar	15/08/2012 11:23 AM	Vincent Baglin	
450 GeV only. angular alignment at TD12L with probe beams (1e10 p) Delta_P = 3e-9 Slope on R509: - TD12L = 1.5 MGy/s per mbar	15/08/2012 10:01 AM	Vincent Baglin	
CMS solenoid OFF	13/08/2012 08:06 PM	Giulia Lanza	


Fill by fill monitoring



Vacuum, Surfaces & Coatings Group **Technology Department**

Operation Follow-Up: Checking Design

• Checking that the system behave as expected: example synchrotron radiation induced gas desorption







Vacuum, Surfaces & Coatings Group Technology Department

Beam conditioning

- This is not a myth and it is observed in many machines across the world!
- Your machine shall behave the same way





C. Herbeaux, Journée thématiques RTVide, décembre 2014



Vacuum, Surfaces & Coatings Group Technology Department

Beam scrubbing

Graphitization is clearly visible!

LANL



dipole chamber (SRBM11, 6/20/07)

quadrupole chamber (SRQF11)


Courtesy R. Macek



Vacuum, Surfaces & Coatings Group Technology Department

Accelerator Fault Tracker


- Big brother is watching you ... for your system health!
- it Pays:
 - Machine availability > 96%
 - X-ray availability > 91 %





Vacuum, Surfaces & Coatings Group Technology Department

Fault allocation



Fault Allocations 2000-2001

 _ Annu	al trer	nd, Pl	_S	etc
				MISPS Interlock
	cuum			 Photon Stop Beamline
Val	Juum			OperatorTiming
				LCW
				 Unknown Electric Power
				 Linac Vacuum
				Control MPS
				RF System

	PS	RF	CONT ROLS	VAC	Cooling	other	BL	refill
APS	>15%	>15%	>10%	>35%	<5%	>10%	>5%	
ELET TRA	>15%	>5%	>10%	<5%	>10%	> 5%	>5%	>10%
ESRF	> 5%	>20%	> 5%	>25%	>15%	<5%	>5%	

E. Karantzoulis, 2002

The vacuum system is always a good candidate for fault generator, in particular at the beginning of a project


E. Park, ARW2013



Vacuum, Surfaces & Coatings Group Technology Department

LHC Vacuum: Lost Physics and Fault Time


• A thorough consolidation of the vacuum system during LS1 paid!





Vacuum, Surfaces & Coatings Group Technology Department

LHC Design Luminosity: 26th June 2016 We reached design luminosity!





Vacuum, Surfaces & Coatings Group Technology Department

Celebration at the CCC!





Vacuum, Surfaces & Coatings Group Technology Department

Summary

- The real life of operation relies on availability.
- Availability is a constant concern during the life of a system.
- Availability of vacuum system relies on :
 - Group Expertise (which must be maintained and continued to be developed)
 - New concepts
 - Studies
 - Design
 - Production & installation follow up: Quality Assurance Plan is a must
 - General monitoring / support by stand-by
 - Fill by fill and daily monitoring / support by experts
 - Repair, consolidation and upgrade of the system
- All these activities are based on many technical, engineering and scientific skills which must be <u>available</u> for the project to ensure availability!



Some References

- Cern Accelerator School, Vacuum technology, CERN 99-05
- Cern Accelerator School, Vacuum in accelerators, CERN 2007-03
- This school !

Workshops & conference

- PAC, EPAC, IPAC series available on JACOW web site
- OLAV: Operation of Large Vacuum Systems Workshops
- ARW: Accelerator Reliability Workshops
- WAO: Workshops on Accelerator Operation



Thank you for your attention !!!




Vacuum, Surfaces & Coatings Group Technology Department



QQBI.26R7 line V2









QBQI 8L4.V














Beam screens with soot in tunnel : C19R3

C19R3.V2 before cleanning



Typical default, DCUM 3259.3524 Left side







Using AI foil as a blank flange to check "vacuum force"

QBQI 14L4.V2

A13L4.V1

QBQI 12L4.V1

entrance







Vacuum, Surfaces & Coatings Group **Technology Department**

