# Installation of ELENA Beam Lines to existing experimental zone



## C. Carli on behalf of the AD and ELENA teams



- Present Situation in the AD Hall
- Status of electron cooler, injection kicker, magnetic pick-ups, profile monitors and corrector magnets
- ELENA Project Phases
- Two Scenarios for the Installation of the new Lines to the existing Experiments
- Recap, Summary, Discussion ..

# Present situation in the AD Hall



Transfer line: installation completed, except four profile monitors (in-kind), source installed and tested Injection kicker: issue with pressure (internal leak) Magnetic pick-ups: two for the ring o.k. (open electric connection for the two PUs for lines)

Electron cooler late replaced by simple chamber

Picture taken on 19<sup>th</sup> September

### General situation:

- Vacuum envelope of ring and lines needed for commissioning closed yesterday
- Most of the ring baked

#### ADUC, 20th September 2016

#### **ELENA Status**

# Status of electron cooler



## • Construction coordinated by CERN with

- Magnetic System manufactured by industry
  - Field lines have to be perfectly straight in region where pbars interact with electrons
  - Magnetic field measurements delicate – reproducibility to be improved further
  - Minor problem with mounting of position pick-up (successful tests of mounting of assembly)
  - Delivery expected in November



One single straight solenoid with equipment for magnetic field measurements

- □ Vacuum system designed and manufactured at CERN
  - Issues with colorings (NEG not adhering) and projections from weldings
  - Method(s) to remove projections found, construction on-going
  - Expected to be completed in November
- □ Installation early 2017
  - Tests to be done at CERN (transverse field measurement)?

# **Injection Kicker**



- Vacuum issue likely due to an "internal leak"
  - In total five acceptance tests made all resulted in higher than expected pressures
  - NEG coated plates removed (cannot be activated in case of excessive gas load) and changed pumping configuration
  - In August, decision to vacuum fire and re-machine cover of tank
  - => external leak removed successfully
  - □ Kicker installed now as no "short-term" solution available
    - Expect pressures in low 10<sup>-9</sup> mbar range after bake-out and decrease with time (time constant of 8-10 days seen in 4<sup>th</sup> test)
    - Long term solution to remove this non-conformity to be discussed



# **Magnetic Pick-ups and Profile Monitors**



- Magnetic Pick-ups
  - Electrical issue on two pick-ups for extraction lines outside part needed for ring commissioning
  - Solution for line to be discussed probably lengthy repair with opening of e-beam welded "cavities"
  - □ Pick-ups for ring found o.k. (good surprise) and installed
- Profile Monitors (SEM) for Lines
  - □ SEM Prototype installed in LNS (source) line
  - Waiting for four more monitors under preparation for LNI-LNE would delay start of commissioning
  - □ Bake-out of LNE-LNI without (all) SEMs installed to start ring commissioning as soon as possible?
    - Would have two monitor (SEM in LNS line and MTV after injection septum) out of three for injection via nominal injection channel
    - 2<sup>nd</sup> bake-out of sector once SEMs are available





- H/V Corrector Magnets
  - Delay due to various technical problems, mitigated by installation around chamber after bakeout, no impact on start of commissioning expected

#### **ELENA Status**

# **ELENA Project "Phases"**





**ELENA Status** 

# Installation of the new Lines to the existing experiments over EYETS 2016/17 or in LS2



Decision point agreed with CERN groups via discussion at IEFC: Two moths before start of intervention (mid-September at time of discussion)



Third scenario with installation starting later until end of YETS 2017/18?

**ELENA Status** 

# Recap, Summary, Discussion ...



- ELENA is a small machine, but has challenges due to the low energy and size
  - □ Modeling of small (bending with small curvature radius) magnets
  - $\Box$  Electron cooling at very low energies (with 55 eV electrons)
  - $\hfill\square$  Perturbations of circulating beam due to electron cooler
  - □ Magnetic field quality at very low field, Instrumentation with very low intensities and energies ...
- Status and present issues
  - $\hfill\square$  Most of the ring ready with bake-out of last sector under preparation
  - □ Lines not yet baked
  - □ Issues with injection kicker (vacuum) and profile monitors (availability)
- Position of ELENA team on the scheduling of the installation of the new lines to existing experimental zone
  - □ With ELENA ring commissioning not yet started, not in favor of starting installations at the end of this year unless this would be clearly and strongly supported by users
    - What would be the risks we are ready to take?
  - □ Installation of lines to existing experiments during LS2 the likely option
  - □ Third scenario installation over YETS 17/18 in case of fast progress ELENA commissioning
  - □ Make sure that resources for installation of lines are available (PLAN tool)
    - Some additional cost for installation in LS2
- ELENA will be ready for GBAR in new experimental area from 2017 on ELENA Status
  ADUC, 20th September 2016