

# Report from EATM

Experimental Areas Technical Meeting

Tuesday, 7.11.2017

COMPASS TB meeting

Annika Vauth



### Dates & other news:

- ▶ distilled and raw water stop: 20.12.2017 to 12.03.2018
- ▶ chilled water stop: 19.12.2017 to 9.03.2018
  
- ▶ new cooling in power converter building now operational, temporary cooling units removed
- ▶ SM2 tests: 27.11.2017 to 1.12.2017
  
- ▶ North area consolidation: gas detection to be upgraded during LS2 - no flammable gas in 2019?



# SM2 power converter.

Issues related to the new SM2 magnet power converter

- ▶ polarity switch problem:  
due to cabling in the main circuit breaker, fixed now
- ▶ errors in September:  
water pressure sensor alarm caused by vibrations, was preliminary fixed by short-circuiting the interlock, long-term fix this winter: installation of a silent block
- ▶ replacement of the electronics card to allow up to 4800A:  
will be tested end of the month



# Extra slides


- ▶ SM2 power converter slides



# 1. Polarity switch problem

**The polarity switch was not moving without a FGC local Reset by First Line team.**

Sequence of the polarity changing:



The 18kV Circuit Breaker was not opening when the power converter was sending the OFF command

2 ways to put the 18kV MCB OFF:

OFF cde



PC Fault



This fault occurred after updating the Analog interlock card of the RegFGC3 crate.

Before the update, a PC fault was sent to the MCB at each polarity change.

After the update no PC fault was sent to the MCB and the OFF command didn't work.

After investigation with EN-EL, we found a bad cabling of the OFF command within the MCB cubicle. Everything was repaired and tested.

## 2. Internal interlock problem (1/2)

### The power converter tripped randomly with MCB Wrong Status Fault

26/09 05H05 First trip: MCB Wrong Status Fault

#### Strange behaviour founded:

The safe chain was opening during 500 $\mu$ s without any fault memorized

26/09: Investigations all the day.


A lot of things were changed: 18kV circuit breaker, electronic cards,...

29/09 01H00:

The problem came back, but this time with a COOLING FAULT fault recorded

This glitch was due to an transient opening of the water pressure sensor of the filter chokes.

This contact opening was caused by the strong vibrations of the chokes.



2017/09/29 01:03:48.500000	STATUS WARNINGS	REF_RATE_LIM	CLR_BIT
2017/09/29 01:03:48.520011	DIM DGINTRC_FLT51	TRIGGER	SET
2017/09/29 01:03:48.520011	DIM DGINTRC_FLT51	FLTCOOLING_FAULT	FAULT
2017/09/29 01:03:48.520000	STATE PC	FLT_STOPPING	SET
2017/09/29 01:03:48.520000	VS STATE	FAST_STOP	SET
2017/09/29 01:03:48.520000	DKG STATUS	VS_READY	CLR_BIT
2017/09/29 01:03:48.520000	DKG STATUS	VS_FAULT	SET_BIT
2017/09/29 01:03:48.520000	DKG STATUS	PWR_FAILURE	SET_BIT
2017/09/29 01:03:48.520000	DKG STATUS	VS_IRUN	CLR_BIT
2017/09/29 01:03:48.520000	STATUS FAILURE	VS_FAULT	SET_BIT
2017/09/29 01:03:48.520000	STATUS ST_UNLATCHED	PWR_FAILURE	SET_BIT
2017/09/29 01:03:48.520000	STATUS ST_UNLATCHED	POST_ACRTEAM	SET_BIT
2017/09/29 01:03:48.520000	DKG COMMANDS	VS_IRUN	CLR_BIT
2017/09/29 01:03:48.527000	LOG PM TRIG	PM_SELF_TRIG	SET_BIT
2017/09/29 01:03:48.537000	DKG COMMANDS	UNLOCK	CLR_BIT
2017/09/29 01:03:48.547000	STATE PC	PRG_OK	CLR_BIT
2017/09/29 01:03:48.547000	STATE PC	FLT_OKF	SET
2017/09/29 01:03:48.547000	VS STATE	FLT_OKF	SET
2017/09/29 01:03:48.547000	DKG STATUS	VS_POWER_ON	CLR_BIT
2017/09/29 01:03:48.547000	STATUS ST_UNLATCHED	VS_POWER_ON	CLR_BIT
2017/09/29 01:03:55.002000	LOG PM TRIG	PM_SELF_TRIG	CLR_BIT

## 2. Internal interlock problem (2/2)


### Temporary solution:

Short circuit of the water pressure contact on the chokes

In case of demineralized water missing, the thermocontact installed on the choke protect it against over temperature.

### Solutions that will be implemented this YETS:

1. Installation of specific Silent Bloc underneath the two coils to decrease the vibrations of the power converter.



2. Improvement of the glitch detection by the Analog card of the Reg FGC3 crate.