


Validation of redundant UPS power distribution during HWC'17: Test results

I. Romera (TE-MPE), V. Chareyre (EN-EL)

Acknowledgements: J. Albertone, R. Denz, G. Ferlin, S. Gabourin, J. Lendaro, R. Mompo, N. Magnin, C. Martin, J. Palluel, G. Pigny, J. Steckert, C. Zamantzas and many more

Recall

- Third campaign to validate the redundant UPS power distribution during the EYETS 2016-17 following a new commissioning procedure (EDMS 1773693)
- New procedure consists in **provoking power cuts on General Services and UPS F4 networks** to minimize the impact on sensitive equipment (UPS F3 validated by exclusion)
- Validation tests successfully carried out during the powering test campaign:
 - 5th April => \$78, \$81
 - 10th April => S34, S45
 - 11th April => S56, S67
 - 19th April => \$12, \$23




Recall on power distribution networks

- (Simplified) electrical distribution in LHC tunnel
 - General services, no backup
 - For all users
 - Including non-critical cryogenics and vacuum equipment
 - F3 UPS network for all critical equipment
 - Redundant machine protection (QPS, BIS, LBDS)
 - Non-redundant machine protection (PIC, WIC, BLM/BPM, Collimators, etc.)
 - Cryogenics/Vacuum controls, Power Converters controls,

EE, World-FIP, etc.

- IT star-points, GSM, etc.
- F4 UPS network for redundant machine protection
 - QPS, BIS, LBDS



UPS layout in RE alcoves and LHC odd points



Test results: LBDS

- Fully redundant system powered by two redundant power distribution paths (i.e. F3 and F4)
- Non-conformities found in HWC'15 and HWC'16 were fixed immediately after the tests
- During HWC'17 => Everything ok for all sub-systems with an impact on machine protection (MKD, MKB, TSU, CIBUs, IPOC....)

Sector	UPS area	Position	HWC'15	HWC'16	HWC'17
56	UA63/US65	LBDS1	System not armed. Test not conclusive	OK	OK
56	US65	LBDS1	OK	FEC "cfc-ua63-mkdtspm" used for monitoring with the two redundant power supplies on the same UPS	OK
67	UA67/US65	LBDS2	2 re-trigger crates connected to the same UPS	OK	OK
67	UA67/US65	LBDS2	TSU-IPOC system only connected to one UPS	OK	OK

- Dedicated tests were done for the LBDS by provoking power cuts of UPS F3 and F4, as new procedure only foresees validation of UPS F3 by exclusion
- Collateral effects => Some power supplies did not survive the power outage and had to be replaced



Test results: QPS (1/2)

- Fully redundant equipment powered by two redundant UPS networks (F3 and F4)
- Issues revealed during the two first campaigns were fixed after the tests
- During this campaign 4 new non-conformities were revealed
- 3 types of issues were discovered:
 - REAL: Non-conformity related to UPS power distribution (EN-EL or system internal)
 - COLLATERAL: Non-conformity originated as a consequence of the test itself
 - NONE: Non-conformity revealed by the test but not related to UPS distribution (i.e. typically a system that was switched off before the test)

Sector	Position	Description	Fault type	Crosscheck	HWC'17
S12	B10R1	nQPS - Lost communication during F4 cut, both power packs powered from F4	REAL	Three pins bent in power connector	Cleared
S45	B19L5	Lost power during F4 cut	REAL	Faulty cable between power pack and DQLPU-S	Cleared
S67	MQ.31R6	Powered from F3 instead of F4	REAL	Reconnected to F4	Cleared
S81	B16R8	nQPS – Lost power during F4 cut	REAL	Reconnected to F4	Cleared



Test results: QPS (2/2)


Sector	Position	Description	Fault type	Crosscheck	HWC'17
S23	B11R2	nQPS – DS board partially lost during F4 cut	COLLATERAL	Power pack damaged	Cleared
	MQ.13R2	Heater fired during F4 cut, DQQDL board damaged	COLLATERAL	DQQDL changed	Cleared
	RQ5.R2	Heaters latched, probably not reset after IST	NONE	Not related to UPS powering	Cleared
	B31L3	nQPS – DS kept loop open after repowering	COLLATERAL	Power pack damaged	Cleared
S34	MQ.25L4	Syco - Switch mode power supply damaged during test	COLLATERAL	Confirmed	Cleared
	B9R4	HDS not charged	NONE	Not related to UPS	Cleared
S45	MQ.25R4	Heater fired during F4 cut	NONE	DQQDL not correctly plugged	Cleared
S56	RQ4.R5 RQ5.R5	Communication lost during F4 cut	COLLATERAL	TRACO power supply damaged	Cleared
	MQ.20R5	Syco – Switch mode power supply damaged during test	COLLATERAL	Confirmed	Cleared
	MQ.22R5	Syco - Switch mode power supply damaged during test	COLLATERAL	Confirmed	Cleared
S81	RQX.L1	Heaters discharged during F4 cut	COLLATERAL	TRACO power supply damaged	Cleared



Test results: Beam instrumentation (1/2)

BLM

- BLM acquisition systems are **powered by a single UPS power distribution network** (i.e. UPS F3)
- None of the BLM acquisition cards has switched off during the UPS validation, i.e. no non-conformity observed
- Despite not all cards were fully operational and few cards had still issues, BLM team could reliably extract the needed information (i.e. by checking HV, 2.5V and ±5 V power supplies)
- To be noted that BLM team highly appreciate the new procedure as reduces significantly the validation time, avoids having to restore the boards and increases the life-time of electronics



IP1 P2V5 OK

Report showing the status of one of the 2.5V power supplies in the BLM-R crate in IP1



Test results: Beam instrumentation (2/2)

BPM

- Front-end electronics powered by a single UPS distribution network (F3)
- Located in the tunnel under the dipole and quadrupole magnets and in UA, UJ and RRs alcoves
- Tests were not closely followed due to other task with higher priority...

Sector	UPS	Position	HWC'15	HWC'16	HWC'17
	area				
23	UA27	BYPMDs	Test not conclusive, data missing	Ok : cut 7/03 11h43	Ok?
23	UJ33	BYPM.B10L3	Remained powered during all the test	Ok : cut 7/03 18h00	Ok?
34	UJ33	BYPM.B10R3	Remained powered during all the test	Ok : cut 7/03 18h00	Ok?
34	0000	BY01=UJ33	Remained powered during all the test	Ok : cut 7/03 18h00	Ok?
67	US65	BYPM.10R6	Remained powered upon UPS F3 power cut	Ok : cut 8/03 11h28	Ok?
78	RE78	BYPLMs	Test not conclusive, data missing from 12 to 34R7	Data missing Fesa token lost	Ok?
/ 0	UA83	BY03=UA83	Remained powered during all the test	Ok : cut 03/03 11h30	Ok?
	US85	BYPM.8R8	Powered from UPS F4 network, Reconnected to F3 by EN-EL	Ok	Ok?
81	RE88	BYPM.12R8	Remained powered during all the test. New UPS F3 socket installed by EN-EL	Ok	Ok?
	RE12	BYPLM.20L1	Remained powered during all the test	Ok : cut 03/03 16h37	Ok?



Test results: Collimation

- Collimator controls are powered by single UPS F3 power distribution network, except in point 7 where there is a UPS in TZ76 exclusively dedicated to the collimation
- During this campaign => All collimator control systems remained power during the tests
- TZ76 and USC55 areas were not concerned by the power cuts during the test campaign

Location	Racks	UPS test	HWC'16	HWC'17
US15	TYCFL01 to 03	03/03/2016	All systems switched off at 17H20	Ok, remained powered
0315	TTCFLUT IU US	07/03/2016	All systems switched off at 16H56	Ok, remained powered
UA23	TYCFL01 to 03, TYTDI01, TYCDD01	07/03/2016	All systems switched off at 11H25	Ok, remained powered
UA27	TYCFL01	07/03/2016	All systems switched off at 11H46	Ok, remained powered
	TYCOL01 to 10	02/03/2016	All systems switched off at 15H37	Ok, remained powered
UJ33	I YCOLOT IO TO	07/03/2016	All systems switched off at 17H56	Ok, remained powered
USC55	TYCFL01 to 03	Area not concerned		
US65	TYCFL01	08/03/2016	All systems switched off at 11H39	Ok, remained powered
TZ76	TYCHL14 to 48	Not concerned (dedicated UPS)		
UA83	TYCFL01	03/03/2016	All systems switched off at 11H47	Ok, remained powered
UA87	TYCFL01 to 03, TYTDI01	03/03/2016	All systems switched off at 11H00	Ok, remained powered



Test results: Machine Interlocks

Beam Interlock System - BIS

- Fully redundant equipment powered by two redundant UPS distribution networks
- Non-conformities revealed during the first campaign were fixed in 2015
- No non-conformities revealed this year

Sector	UPS area	Position	HWC'15	HWC'16	HWC'17
34	UA43	CYCIB01	Faulty WIENER power supply powered by UPS F3	OK	OK
67	TZ76	CYCIB01	Both WIENER power supplies powered by UPS F4	OK	OK

To be noted that some CIBUs are not redundantly powered (i.e. installed in users' rack)
 and lost power during the test

Magnet Interlock Systems – PIC and WIC

- Magnet interlocks are powered by a single UPS (i.e. F3)
- Two non-critical non-conformities revealed during the first campaign
- Systems relocated in the TZ76 and UL557 during LS1 were powered by UPS F4

Sector	UPS	Position	HWC'15	HWC'16	HWC'17
	area				
56	UL557	CYCIP01	Rack powered by UPS F4 instead of UPS F3	NON CRITICAL	NON CRITICAL
67	TZ76	CYCIP01	Rack powered by UPS F4 instead of UPS F3	NON CRITICAL	NON CRITICAL



Test results: WorldFIP and Timing

- FIP and Timing infrastructure is powered by single UPS line (i.e. UPS F3) and used for controls and diagnostics of some main clients: Power Converters, QPS and Cryogenics
- A non-conformity persists during this test campaign which can impact diagnostics in case of losing redundant UPS power path (F4)

UPS Area	Clients affected	HWC'16	HWC'17
TZ76 / RR73 / RR77	EPC/QPS/ Cryo	Agents lost communication with F4 power cuts Repeaters in CYFRE01 in TZ76 powered by F4	OK, fixed during EYETS before test
UJ56	EPC	FipDiag powered by F4	NON CRITICAL, just diagnostics
UL557 / RR53 / RR77	Cryo	Agents lost communication with F4 power cuts Repeaters in CYFRE01 in UL557 powered by F4	OK, fixed during EYETS before test

Installation of redundant **WorldFIP powering was not considered as mandatory** by user clients and not endorsed by the LMC due to considerable cost (see <u>J. Palluel at LMC 216th</u>)



Singularities in UL55 and TZ76

Before LS1

UPS F3

EOD F3

QPS

VSC

UPS F4

EOD F4

 UPSs and users racks moved during LS1 due to radiation issues (R2E project)

UPS backup

UPS F4

EOD F4


Distribution F4 in tunnel

- F3 switchboard left in UJ56 and UJ76 because tunnel distribution remained unchanged
- Racks in UL55 and TZ76 connected to F4 switchboard installed in the same zone while they should be connected to F3 network

UPS F3

UL55

UJ56





QPS

Conclusions

- New procedure was highly appreciated by most of UPS users as simplifies the validation of Machine Protection Systems and reduces collateral effects
- Impact on cryogenics is reduced compared to the old procedure (e.g. redundant 24V DC power supplies only partly switched off) and recovery time estimated to 3-4 hours for powering tests / 1.5 days for final physics configuration (2nd option chosen this year).
- Less and less non-conformities revealed during the 3rd campaign
- Non-negligible effort to prepare the new test campaign and impact on powering tests
 - => MPP to review the necessity of repeating these tests on a yearly basis
 - => MPP to decide what to do with singularities affecting powering of MPS in UL55 and TZ76



Thanks for your attention

