

MPP Meeting

# ***FMCM Commissioning and first operational experience with new converters***

A. Antoine  
I. Romera Ramirez


# Outline

---

- Introduction
- EYETS 2017 Work
- RD34.LR3 Issue
- Lessons
- First operational experience
- Conclusions

# Introduction

## Measurement principle




$$\begin{cases} V_1 = V_1' \\ R_2 = R_2' \\ R_2 = R_2' \end{cases}$$

$$U_{mag} = 2 \times V_1 \times \frac{R_2}{R_1 + R_2}$$

# EYETS 2017 Work

## Summary of changes


- In 2016, **22 beam dumps in stable beams provoked by electrical disturbances and followed by FMCM trips.**  
(40% could have been avoided with SATURN)
- **No changes** at the level of the FMCM firmware but two **HV-box interfaces (RD34.LR3/7) relocated** following PC replacement + related changes on the FMCM IPOC.
- RPTG power converters on **RD1.LR1/5 and RD34.LR3/7 replaced by new SATURN power converters** aiming at reducing the sensitivity of FMCMs against electrical network perturbations.




# RD34.LR3 Issue

## Intervention

- FMCM of RD34.LR3 **tripped 4 times** on 29/04/2017 after the successful commissioning (in appearance) of the FMCMs.
- FMCM was **masked** during the weekend.
- The intervention on 01/05/2017 pointed out a **badly crimped connector of one HV cable**.
- After exchange of the HV cable, the HV divider had to be **multiplied by 2** in order to remove the saturation of the isolation amplifier !



FMCM  $U_{mag}$  &  $I_{diffsim}$



Power converter U & I

# RD34.LR3 Issue

## Bad crimping

---




HV cable to connect  
the output of the Power  
converter to the FMCM  
HV box



Bad crimping = cable core retracted

# RD34.LR3 Issue

## Analysis of the divider value change



$$\begin{cases} V_1 = V_1' \\ R_2 = R_2' \\ R_2 = R_2' \end{cases}$$

$U_{mag}$  originally calculated as  $U_{mag} = \cancel{2} \times V_1 \times \frac{R_2}{R_1 + R_2}$

# Lessons

## Analysis of all FMCM data's

- The RD34.LR3 experience triggered a deeper analysis of **all FMCM data's**.

23 October 2016											
FMCM		Operational Measurements				HV Divider Configuration					Meas. Vs. Calc.
Nr	Device	$U_{mag}$ [V] (FMCM)	$U_{nom}$ [V] (FGC)	$I_{nom}$ [A] (FGC)	$U_{mag}/U_{nom}$	R1 [Kohm]	R2 [Kohm]	R3 [Kohm]	R4 [Kohm]	Ratio	
1	CIF.SR3.RD34	7.7803	487.0872	593.5738	0.016	56	56	27	5	0.035	<b>2.188</b>
2	CIF.SR3.RQ4	7.979	268.2587	518.3544	0.03	56	0	39	5	0.05	<b>1.667</b>
3	CIF.SR3.RQ5	8.1124	288.0615	546.1754	0.028	56	56	39	5	0.032	1.143
4	CIF.SR7.RD34	7.1814	295.0717	593.6323	0.024	27	56	0	5	0.057	<b>2.375</b>
5	CIF.SR7.RQ4	8.4332	236.7124	552.9301	0.036	56	15	56	5	0.038	1.056
6	CIF.SR7.RQ5	8.084	247.5349	562.5544	0.033	56	27	56	5	0.035	1.061
7	CIF.UA27.RBXWTVL	9.197	29.2283	578.9254	0.315	3.3	0	0	5	0.301	0.956
8	CIF.UA27.RBXWTVR	8.2611	22.5967	497.0412	0.366	2	0	0	5	0.357	0.975
9	CIF.UA67.RMSDB1	7.9165	410.7927	753.7723	0.019	100	100	33	5	0.021	1.105
10	CIF.UA67.RMSDB2	7.9676	415.091	753.7723	0.019	100	100	33	5	0.021	1.105
11	CIF.US152.RD1	8.6091	490.0038	628.5567	0.018	110	100	51	5	0.019	1.056
12	CIF.USC55.RD1	7.8257	499.24	628.2944	0.016	180	56	56	5	0.017	1.063



# Lessons

## *RD34.LR7 Intervention*

---

- Triggered by the analysis.
- Nearly same issue as for RD34.LR3 with variant:
  - Bad **positive** HV cable.
  - **No** electrical contact **suddenly restored**
  - Much faster intervention.
- Successful intervention done on 15/05/2017.

# Lessons

## Analysis of all FMCM data's after HWC

- RQ4 still identified as potentially having a measurement issue.

11/15 May 2017											
FMCM		Operational Measurements				HV Divider Configuration					Meas. Vs. Calcul.
Nr	Device	$U_{mag}$ [V] (FMCM)	$U_{nom}$ [V] (FGC)	$I_{nom}$ [A] (FGC)	$U_{mag}/U_{nom}$	R1 [Kohm]	R2 [Kohm]	R3 [Kohm]	R4 [Kohm]	Ratio	
1	CIF.SR3.RD34	8.2004	487.1878	593.574	0.017	110	110	56	5	0.018	1.059
2	CIF.SR3.RQ4	7.9875	268.0284	518.3553	0.03	56	0	39	5	0.05	<b>1.667</b>
3	CIF.SR3.RQ5	8.0982	287.8312	546.1752	0.028	56	56	39	5	0.032	1.143
4	CIF.SR7.RD34	8.8674	292.4898	593.6322	0.03	56	47	47	5	0.032	1.067
5	CIF.SR7.RQ4	8.4132	235.561	550.4762	0.036	56	15	56	5	0.038	1.056
6	CIF.SR7.RQ5	8.0669	246.6137	560.5725	0.033	56	27	56	5	0.035	1.061
7	CIF.UA27.RBXWTVL	-9.5911	29.2283	578.9249	-0.328	3.3	0	0	5	0.301	-0.918
8	CIF.UA27.RBXWTVR	-8.9212	22.5148	497.0406	-0.396	2	0	0	5	0.357	-0.902
9	CIF.UA67.RMSDB1	7.8824	411.2915	753.772	0.019	100	100	33	5	0.021	1.105
10	CIF.UA67.RMSDB2	7.9506	414.4769	753.7714	0.019	100	100	33	5	0.021	1.105
11	CIF.US152.RD1	8.6063	489.994	628.5571	0.018	110	100	51	5	0.019	1.056
12	CIF.USC55.RD1	7.8144	505.3038	628.2942	0.015	180	56	56	5	0.017	1.133

# *First operational experience*


---

- 4 beam dump triggered by FMCMs
- All of them because of electrical perturbations affecting all facilities.
- The new 4 SATURN converters have never tripped the FMCMs !

# First operational experience


## Exemple of RD1.LR5: 2016 Vs. 2017 (1)

- On 12th October 2016, RD1.LR5 triggered a beam dump because of an electrical perturbation of  $\sim 8.5\%$  with a duration of 100 ms.



### Power Converter

- V Meas.
- I Meas.




### FMCM

- Umag
- Idiffsim
- Threshold
- BEAM\_PERMIT

# First operational experience

## Exemple of RD1.LR5: 2016 Vs. 2017 (2)

- On 31th May 2017, a comparable perturbation of 2016 triggered a beam dump by the FMCM RMSDB1.
- RD1.LR5 converter rejected successfully the electrical perturbation.



### Power Converter

- V Meas.
- I Meas.

### FMCM

- U<sub>mag</sub>
- I<sub>diffsim</sub>
- Threshold
- BEAM\_PERMIT

# Conclusions

---

- Very successful RD1/RD34 power converters replacement by EPC as there was no interlock from FMCM on these power converters in 2017.
- Commissioning and initial operation revealed problem on the HV boxes of the FMCM
  - Bad crimping on HV connectors leading to missing half the measurement circuit and causes 4 beam dump.
  - Analysis of all circuits made.
  - Two circuits have been corrected (RD34.LR3 & RD34.LR7)
  - One remaining circuit foreseen to be corrected in TS1.

***Thank you for your attention***



[www.cern.ch](http://www.cern.ch)