

CT-PPS Experience during Intensity Ramp-Up; Recent Auto-Retraction



Mario Deile


**MPP Meeting
22 September 2017**

Intensity Ramp-Up




- Up to the highest LHC luminosity: $L = 1.6 \times 10^{34} \text{ cm}^{-2} \text{ s}^{-1}$
- 2 ramp-up periods: before and after TS1
- without any problems (except 1 interlock problem \rightarrow later)
 - BLM signals in line with 2016 (at least factor 3 below thresholds)
 - very good vacuum levels
 - benign temperatures
 - no impedance problems

BLMs



Vacuum





Vacuum dominated by other systematics, not primarily by beam current.

Intensity Ramp-Up (2)




Temperature vs. Beam Current:

on XRP flange (not directly cooled)




on detector hybrid (cooled)



Interlock Problem and FPGA Firmware Modifications during TS1



24 June: spurious dump by movement interlock,
TIMBER logging time resolution not fine enough → no malfunction found
→ Implementation of an LVDT filter and a post-mortem diagnostic system
(see MPP 07.07.2017)



PXI for motor control :


- RS485 communication with motor encoder,
- DIM communication to DCS and CCC,
- Resolver measurement and calculation,
- Motor control.

➤ No modification for this part during TS1



OPCUA Data
exchange :

- Limits for interlocks
- LVDT Positions



PXI for RP position:

- LVDT measurement and calculation,
- Interlock generation according to Warning, Critical or Inner limits.

Modifications implemented during TS1:

- Real time part (1):
- Generation of a post mortem file after an interlock generation (1s before and 1s after).
- FPGA part (2):
- **Interlock Generation if conditions are valid during three consecutive loop iterations of 10 ms each** (same as AFP and ALFA)

i.e. only if the dump threshold was crossed!
Crossing the warning threshold does not trigger a post-mortem file. **To be improved.**

Observations after the FPGA Modifications



No post-mortem file was ever generated.

Dump threshold was never crossed since TS1.

But:

11 Sept., 17:51 h: Spring extraction of all XRP's during Stable Beams without apparent reason,

- no interlock
- no suspicious LVDT activity in TIMBER
- no post-mortem file generated (i.e. dump threshold was not crossed)
- also: crossing the warning limit extracts ONLY the violating pot

→ last conceivable option: signal glitch somewhere (e.g. STABLE_BEAM flag to interlock box)

Future improvement (Christmas shutdown):


- generate a post-mortem file already at a crossing of the warning limit
- think about additional loggings (e.g. SMP flags received)



Restart after TS2



- Alignment of all operational XRPCs due to optics change and TS2 interventions: **done**
- Calibration data at 3 crossing-angles: 150, 130, 110 μ rad: **ongoing**
- New physics settings: TCT + 3 σ + 0.3 mm = 11.5 σ + 0.3 mm



Horizontal:

- C units: empty, unused for the full year
- D units: used in all fills
- A units: empty, unused for the full year
- E units: used in all fills
- B units: used in all fills

Vertical:

- D and B units inserted in calibration runs,
- A and C units empty, unused.

Hardware groups (since TS1, unchanged):


- 1 global group and sequence with all pots used in normal fills (horizontal D, E, B)
- 3 subgroups with related sequences for flexibility (detector problems / limit irradiation):
COLLIMATORS_XRPC_TOTEM_LOWBETA_B / D / E



Additional Material



Movement System Architecture (strongly simplified)




Interlock Logic 2015

IN MOTOR CONTROL RACK

TOTEM INTERLOCK BOX

CMS S1E08



Interlock Logic 2015

(Zoom on the motor control)

