


# Experience with FC7 Failures



*J. Troska*



*on behalf of the CMS TCDS team*

# Overview




- Context: CMS TCDS system
- FC7 board overview
- Operational experience & failures
- Failure analysis
- Solution validation
- Summary

# Context: CMS TCDS System



- Replaced existing TTC/TCS system during LS1
  - Based on  $\mu$ TCA
  - Increased number of sub-detector partitions
  - Increased flexibility in Trigger Control & Monitoring
- 2 racks, 6 shelves, ~50 AMC13s





AMC13 – CMS  $\mu$ TCA readout board

FMM – Fast Merging Module



TTC – Timing, Trigger & Control  
TTCrx – TTC Receiver ASIC  
TTS – Trigger Throttling System

# Heart of the system: the FC7 AMC



*Joint  
development  
by:*



Imperial College  
London




- Xilinx Kintex XC7K420T
  - 10 Gb/s transceivers
- Jitter Cleaner & ref. Xtals
- 2x FMC connectors (LPC+)

- 4Gb DDR3 RAM (128M x 32b)
- Atmel  $\mu$ C MMC &  $\mu$ SD
  - AMC control & FPGA configuration
- 16-layer PCB


# Development & Installation Timeline




# Operational experience & failures





- The CMS TCDS system sustained a very high failure rate of AMCs after ~3 months of operation
- Full system failure was in sight within ~1 year!




# Operational experience & failures




- The CMS TCDS system sustained a very high failure rate of AMCs after ~3 months of operation
- Full system failure was in sight within ~1 year!



# FC7 failure monitoring




- AMC sensors provided diagnostics
  - Board failure accompanied with increased current drawn on FPGA core voltage
- Increased current an abrupt failure
  - within one monitoring interval (1 minute)






# Failure Analysis & Mitigation




- Lengthy investigations & continued monitoring did not reveal problem
- Eventually Xilinx agreed to do Failure Analysis on failed FPGAs
  - Xilinx FA: de-lidding & testing including High-resolution IR imaging for thermal emission analysis
  - Schematic error identified - incorrect XADC supply voltage caused EOS failure of config. memory

*Hot-spot*




*Thermal Emission*




*Die backside laser imaging of EOS-induced diffusion damage*

# Failure Analysis & Mitigation




- Lengthy investigations & continued monitoring did not reveal problem
- Eventually Xilinx agreed to do Failure Analysis on failed FPGAs
  - Xilinx FA: de-lidding & testing including High-resolution IR imaging for thermal emission analysis
  - Schematic error identified - incorrect XADC supply voltage caused EOS failure of config. memory


Hot-spot



*Thermal Emission*




*Die backside laser imaging of EOS-induced diffusion damage*




- Simple fix possible with “white wire”
  - Applied to all boards in April 2015

# Medium/Long-term mitigation strategy




- All installed FC7s at P5 were replaced with boards that had not been powered at incorrect voltage
  - No guarantee that devices previously operated with EOS would continue to survive
  - Relied on existing spares available within TCDS and made available by other projects
  - Ordered 30 new boards with existing design and immediately applied white wire fix
- Prepared to replace full population with stable production version of FC7 when available
  - FC7 R2 included required voltage fix
  - Need to validate FC7 R2 design very carefully to validate success of the fix!
  - R2 first batch delivered Dec. 2015


# FC7 R2 Validation





- QA programme carried out on 5 R2 boards and 1 unmodified R1 board:
  - Temperature Cycling: -40 to +85 °C, 500 cycles
    - Measurements at 100, 200, & 500 cycles
  - High-temperature Operating Life (HTOL): ~95 °C, >500 hrs
    - Lifetime acceleration factor of 54-78 with Xilinx recommended activation energy of 0.7 eV



# EOS acceleration?








- As a cross-check, HTOL carried out also with FC7 R1 without white-wire fix
- Failure observed after approx. 300 hrs
- Same failure signature as observed in CMS



- Acceleration factor found to be lower than expected for 0.7 eV activation energy
- Calculated 0.5-0.6 eV, compatible with literature


***Had we done this kind of QA up-front, would not have suffered a nail-biting six months waiting for everything to fail...***

# FC7 R2 Validated




- No significant changes observed in either T-cycling or HTOL tests
- Accumulated 25 device-years of effective operation
- FC7 declared ready for deployment in Feb. 2016
- 17 months after TCDS installation...

# Summary






- CMS TCDS system installed during LS1
  - based upon  $\mu$ TCA system with FC7 AMC
- Suffered high-level of in-situ failures after a few months of operation
- AMC Sensor monitoring data very useful to track problems
- Full device Failure Analysis needed to solve problem
  - We do not have such facilities within the community, must rely on good relationships with vendors
- QA programme like the one typically required of the front-end electronics put in place to validate final board revision
  - Should foresee such tests for all custom electronics
  - Even if they are accessible, facing a complete failure of a central system critical to the operation of an experiment is very uncomfortable! Diagnosis always takes time...
  - Must allow time in development plans for this step, which can take several months (longer in case of problems)



# Backup



# HTOL Acceleration Factor



- Device temperature measured in-situ in CMS, take 35 °C as conservative maximum value
- Acceleration factor 90 °C w.r.t. to operation is  $\times 54$