
## SPS Status – week 36 so far

- Availability for the last 5 days: 95.7 %
  - Main faults from the injector complex
- Occasional trip of transverse damper still to be understood
  - At the end of the ramp for fixed target beams in the horizontal plane
  - At the start of the ramp: related to tune kicker (MKQH) pulsing in the wrong cycle
- AWAKE run



## Miscellaneous

- Need ~ 2 h to debug issue with tune kicker MKQH
  - No fixed target beam during that time
  - No time scheduled yet need to discuss
- Plan to switch to COSE (constant optics slow extraction) after technical step
  - Loss reduction in extraction region expected
  - Automatic measurement of momentum distribution
  - Will automatically know beam momentum for given time slice and can adjust TT20 momentum accordingly