



W. Kalbreier, D. Smekens, T. Zickler AT-MEL-MI

I PS EAST HALL MAGNETS

1. Overall magnet status
 - Breakdowns
 - Installed magnets & spares
 - Details MNP23 → ANNEX 1
2. Status of 'weak' magnets
3. Proposal for an improved East Hall layout
4. Missing documentation → ANNEX 3



II SPS NORTH EXP. AREA MAGNETS

1. Overall magnet status
 - Layout SPS NEA
 - Breakdowns
 - Installed magnets & spares
2. Status of 'weak' magnets

III INSUFFICIENT STAFF

IV CONCLUSIONS


Acknowledgement: D. Bodart + P. Ziegler
have contributed effectively to compile
information on the East Hall magnets.



EAST HALL MAGNETS: BREAKDOWNS DURING OPERATION




PS+SPS days 24-1-2007 W.Kalbreier, D.Smekens, T.Zickler AT-MEL, CERN, 1211 Geneva 23




Access via PS Main Ring → for any magnet replacement PS must be stopped

SPLITTER-MEP35



SEPTUM BHZ01-MNP23



After installation → Access via PS Main Ring
→ for replacement PS must be stopped


- High DC power 400 kW
- High current 1300 A



F61S. BHZ01.MNP23 10-2006 breakdown 3rd coil SEF



PS+SPS days 24-1-2007 W.Kalbreier, D.Smekens, T.Zickler AT-MEL, CERN, 1211 Geneva 23






East Hall Magnets: in operation & spares as per January 2007



PS+SPS days 24-1-2007 W.Kalbreier, D.Smekens, T.Zickler AT-MEL, CERN, 1211 Geneva 23



'weak' magnet definition:

- ➔ high risk for operation:
 - failure is likely to happen in the coming years
 - mainly because of the bad state of the coil insulation due to severe radiation damage
- ➔ low or zero operational spare number
- ➔ long down-time when replaced during operation:
 - long cooling-down due to high induced radiation level or
 - requires the opening + closing of the top shielding = 2 weeks or PS stop.

high impact for whole East Hall:

Operates in primary lines: F61, F61S, F61N

High priority

- for **revision** and/or
- **new fabrication** shall be given for:


'weak' magnets of

- **high impact** for the
- **operation of the whole East Hall.**

East hall primary zone: Access possible during PS operation

Extremely densely packed + covered with concrete shielding roof → for any magnet replacement an opening + closing takes 2 weeks + cool-down + magnet exchange period

PS+SPS days 24-1-2007 W.Kalbreier, D.Smekens, T.Zickler AT-MEL, CERN, 1211 Geneva 23





As MNP23 problems have been presented in several ATC sessions in 2006 I skip it here + leave it for questions.

→ For full story → see Annex 1.

→ February 2007: install C-shaped MCB magnet to replace MNP23 for 2007 operation.






'weak' magnets

Q74



PS+SPS days 24-1-2007 W.Kalbreier, D.Smekens, T.Zickler AT-MEL, CERN, 1211 Geneva 23

	NEW	OK	RISKY	SUM
OPERATING	0	1	1	2
	NEW	OK	UNKNOWN	SUM
SPARES	0	1	0	1
Importance issues	Risky magnet is in T9 line at QDE01.Q74.02 for AMS/T2K-KEK.			
2007	Replace risky magnet in 2007 if feasible. If high priority → ask budget for 1 new magnet.			
2008	If budget + additional staff obtained, 1 new magnet could be fabricated.			
2009	1 spare available			





'weak' magnets

Q 600



PS+SPS days 24-1-2007 W.Kalbreier, D.Smekens, T.Zickler AT-MEL, CERN, 1211 Geneva 23

	NEW	OK	RISKY	SUM
OPERATING	0	1	4	5
	NEW	OK	UNKNOWN	SUM
SPARES	0	3	2	5
Importance issues	<p>T7.QFO01.Q606+QDE02.Q607 for OPERA. T7 Beam energy reduced: 10 → 9 GeV T11.QDE01.Q604 + QFO02.Q602 for CLOUD</p>			
2007	<p>3 risky magnets will be replaced. The 2 spare units (unknown) must be revised in order to obtain 2 operational spares. If successful, replace 4th risky magnet in 2008. If unsuccessful + priority → budget for 1-2 new magnets.</p>			
2008	<p>If budget + additional staff obtained, 1-2 new magnets could be fabricated.</p>			
2009	<p>risky magnet could be replaced + 1 spare left</p>			

'weak' magnets Q800

PS+SPS days 24-1-2007 W.Kalbreier, D.Smekens, T.Zickler AT-MEL, CERN, 1211 Geneva 23





'weak' magnets

Q 800



PS+SPS days 24-1-2007 W.Kalbreier, D.Smekens, T.Zickler AT-MEL, CERN, 1211 Geneva 23

	NEW	OK	RISKY	SUM
OPERATING	0	0	2	2
	NEW	OK	UNKNOWN	SUM
SPARES	0	0	1	1
Importance issues	<p>2 operating magnets are overheating.</p> <p>T10 beam energy reduced: 7 → 6 GeV ALICE</p> <p>T10.QDE01.Q804 + QFO02.Q803</p> <p>Already 3 broken non-repairable units.</p>			
2007	<p>1 (highly radio-active) spare must be revised in order to obtain 1 operational spare.</p> <p>If successful, keep it as spare.</p> <p>If unsuccessful + high priority → ask budget for 3 new magnets.</p>			
2008	<p>If budget + additional staff obtained, 3 new magnets could be fabricated.</p>			
2009	<p>risky magnets could be replaced + 1 spare</p>			






'weak' magnets

M105



PS+SPS days 24-1-2007 W.Kalbreier, D.Smekens, T.Zickler AT-MEL, CERN, 1211 Geneva 23

	NEW	OK	RISKY	SUM
OPERATING	0	3	0	3
	NEW	OK	UNKNOWN	SUM
SPARES	0	0	0	0
Importance issues	<p>No spare for primary lines</p> <p>F61N.DHZ01.M105.02+F61S.DHZ01.M105.03</p> <p>T8.DHZ01.M105.01</p>			
2007	No spare unit → Define priority → If high, ask budget for 1 new magnet.			
2008-9	If budget + additional staff obtained, 1 new magnet could be fabricated.			
2010	spare status ok			





'weak' magnets MEP19



PS+SPS days 24-1-2007 W.Kalbreier, D.Smekens, T.Zickler AT-MEL, CERN, 1211 Geneva 23

	NEW	OK	RISKY	SUM
OPERATING	0	0	1	1
	NEW	OK	UNKNOWN	SUM
SPARES	0	0	0	0
Importance issues	<p>No spare</p> <p>F61N.BVT01.MEP19 with high induced radiation level.</p>			
2007	<p>No spare unit → Define priority → If high, ask budget for 1 new magnet.</p>			
2008	<p>If budget + additional staff obtained, 1 new magnet could be fabricated.</p>			
2009	<p>spare status ok</p>			






'weak' magnets

Q120



PS+SPS days 24-1-2007 W.Kalbreier, D.Smekens, T.Zickler AT-MEL, CERN, 1211 Geneva 23

	NEW	OK	RISKY	SUM
OPERATING	2	0	3	5
	NEW	OK	UNKNOWN	SUM
SPARES	1	0	0	1
Importance issues	<p>F61S.QFO01.Q120.04+QDE02.Q120.06 T9.QFO02.Q120.02 AMS/T2K-KEK</p>			
2007	<p>Consolidation budget obtained. M. Karppinen AT-MEL-MI will launch + follow-up the fabrication. 3 Magnets will be fabricated.</p>			
2008	<p>3 risky magnets could be replaced, leaving 1 new spare.</p>			





'weak' magnets

MEP 35



PS+SPS days 24-1-2007 W.Kalbreier, D.Smekens, T.Zickler AT-MEL, CERN, 1211 Geneva 23


	NEW	OK	RISKY	SUM
OPERATING	0	0	1	1
	NEW	OK	UNKNOWN	SUM
SPARES	0	0	2	0
2007	<p style="text-align: center;">Splitter Magnet in primary line F61.SMH01 producing the beam intensity sharing between North and South branch.</p> <p>Magnet fully enclosed in vacuum container + motorized yoke.</p> <p style="text-align: center;">Maintenance of motorization shall be done by AB as AT-MEL-MI has no staff in this professional category.</p> <p>1 spare unit shall be revised; if unsuccessful + high priority → ask budget for 1 magnet.</p>			
2008-2009	If budget + additional staff obtained, 1 new magnet could be fabricated.			
2010	spare status ok			



- Magnets installed 63
- Risky Magnets (now: 11) at start-up of 2007: 8
- Magnet types 22
- Installed per type 2.9

Maintenance of such a high number of different types is:

- expensive and
- with increasing number of breakdowns
- cannot be managed with available staff.



The **East Hall magnets** after about 40 years of service have mostly arrived the **end of their lifetime**.

East Hall magnets: **8% of NEA but same FTE** →
12 times more expensive !

Therefore, it seems the right moment for **redesign of the East Hall with fewer magnet types and more space**.


Keeping in mind the **savings** in


- **Manpower**
- **Radiation budget**


combined with **less down-time for physics**
this could even be the **more economic solution**.




SPS towards North Exp. Area







Magnets for BT to NEA 18 Magnet Families






Magnet status for the NEA & secondary Beams



PS+SPS days 24-1-2007 W.Kalbreier, D.Smekens, T.Zickler AT-MEL, CERN, 1211 Geneva 23



OK: 10 spares available from SPS stocks





Potential Risks identified ('weak' magnets)



PS+SPS days 24-1-2007 W.Kalbreier, D.Smekens, T.Zickler AT-MEL, CERN, 1211 Geneva 23

	Magnet Type	Risk	Rating Risk*Impact	Proposed action
TT20 / TDC2	QTA/L (48 magnets in use in TT20/TDC2/NEA)	Failure of the Coil Water manifold	High (~20 risky magnets) (several repairs every year)	2007: supply of new manifolds for repairs. Next Shutdown: Replacement of weak parts on 20 magnets
	MSSB (6 magnets in use)	Failure of vacuum tank or magnet coil due to corrosion	Medium to high (unpredictable) <i>Risk of breakdown in series</i>	2008: Conversion of 1 (or 2) West Area splitter(s) into NEA splitter
TCC2	MBN (83 magnets in use in TCC2/NEA)	Vacuum Leak due to corrosion in radioactive areas (PVC covers)	High	<i>PVC covers replaced on magnet in radioactive environment last years.</i> Vacuum related problem. But it uses spare magnets.
	MSN (8 in use in TCC2)	Failure of the Coil Water manifold	Medium (probable within 5y)	2007: supply of new manifolds for repairs. 2008-2010: refurbishment of the 3 damaged MSN
	MTR/MTS/QLNRB/ QNLB	Lifetime elapsed. Probably coil failure	Low to medium (unpredictable)	1 spare MTS coil available. Consolidation proposal not yet assessed.





Weak Magnets: QTA/L/R/S




PS+SPS days 24-1-2007 W.Kalbreier, D.Smekens, T.Zickler AT-MEL, CERN, 1211 Geneva 23

	Situation	RISKY	SUM
OPERATING	<u>EA standard:</u> QTA:0 / QTL: 1 / QTR: 0 / QTS: 14 <u>BT standard:</u> in TT20/TDC2 :QTA:19 / QTL: 11 / QTR: 0 / QTS: 2 in other BT lines: QTA:0 / QTL: 14 / QTR: 2 / QTS: 2 TOTAL: 65	> 20 magnets	65 magnets in operation. 30% of them risky
SPARES	<u>EA standard:</u> QTA:0 / QTL: 19 / QTR: 4 / QTS: 36 <u>BT standard:</u> QTA:4 / QTL: 5 / QTR: 2 / QTS: 8	Not assessed	78 magnets spare ! Mostly QTS
Importance issues	Main BT quadrupoles for primary beamline TT20/TDC2. Mainly QTA magnets in TDC2, few spare QTA		
since 2006	Assembly Tool + workshop + spare coils to reconstruct QTA/QTL/QTR/QWL		
2007	Small consolidation budget available. Manufacture of new parts for 25 magnets (targeting repairs of QTA and QTL in TDC2 – 24 magnets)		
2008	Replacement of weak parts in situ (TDC2).		





- ➔ **MSSB Splitter Magnet Situation**
 - 1 spare magnet for North Area
 - Corrosion problem on all 6 North Area MSSB magnets
- ➔ **Risk of several failures in a row**
- ➔ **Availability of 3 West Area MSSB magnets (different septum profile)**
 - Conversion WEA MSSB into NEA MSSB seems possible

Replacement of 1 complete upper yoke+vacuum tank: ~115kCHF




North Area Version






AT-MEL-MI TASK LIST

PS+SPS days 24-1-2007 W.Kalbreier, D.Smekens, T.Zickler AT-MEL, CERN, 1211 Geneva 23



AT-MEL-MI STAFF EVOLUTION



Severe reliability problems due to

- About 40 years old magnets
- Coils heavily radiation damaged
- Yokes often with high induced radio-activity → high irradiation of staff at maintenance + repair
- Low or zero operational spares for several types
- Too many (22) types for 63 magnets
- Some of too delicate design + expensive in production

The **East Hall magnets** have mostly arrived at the **end of their lifetime**.

Therefore, it seems the right moment for a

- **redesign of the East Hall** with
- **fewer magnet types and more space**.

Otherwise a considerable effort in P+M must be invested to:

- Replace risky magnets
- Improve the current spare situation

Status is less critical than for the PS East Hall.

Magnets are about 30 years old.

Primary lines: 240 magnets, magnets/type 6-7

Secondary lines: 540 magnets, magnets/type 19

→ TDC2/TCC2 concentrate most of the problems.

→ Expected improvements by 2008:

- QTA/QTL water manifold problem solved in TT20/TDC2

- 2 to 3 Spare MSSB magnets available in case of breakdowns

→ by 2010 : Additional spare MSN magnets

Remaining Issues:

- No spares for 1 QM + 3 MTS + 4 MTRV + 4QNRB
- Only 1 MSN spare unit
- Few MBNV spare units
- Obsolete Magnet Interlock System



The staff is declining dramatically due to:

- Ending LD contracts end 2007 to mid 2008.
- Already 4 staff Cat 2xC, D, E have left to AB.
- Retiring staff
- Replacements inside MEL done 9-2006.

➔ Huge loss in expertise + effectiveness

Already for the basic programme we do just have

- sufficient staff for 2007,
- But NOT for the following years.



We need already in the **current of 2007 strong influx of experienced staff (cat C + D) to be trained in magnet manufacture, testing and maintenance.**

Without this input of experienced staff :

→ We cannot fulfill for >2007 our tasks for the basic programme : PS+ SPS + LHC (nc magnets)

→ Consequently beyond the basic programme we have to decline all tasks for:

- PS + SPS Experimental Areas + CNGS
- CTF3 + CLIC
- PS-MTE + LINAC4 + SPL + PS2



→ Start of Annex 1 below.

→ 1st generation (3 different designs) showed coil insulation + water cooling + short circuit leading to completely burnt coil insulations) problems starting already in the 1990^s.

Status in 2001. → No more spares from 1st generation + F61S-BHZ01 needed to be replaced.

→ 3 new magnets were built in 2001 at OSWALD/DE by T. Zickler (2nd generation).

→ Damaged unit in F61S was replaced the 1st unit of the new septum in March 2002 & operated until November 2003 (→ water leak + cooling channels blocked due to corrosion).



- July 2004: high leakage current + cooling channels blocked by a deposit stemming from corrosion. → required the replacement of the 2nd unit operating since March 2004.
- November 2004: same problems with the 3rd unit operating since September 2004.



ANNEX 1 F61S BHZ01-MNP23



PS+SPS days 24-1-2007 W.Kalbreier, D.Smekens, T.Zickler AT-MEL, CERN, 1211 Geneva 23







ANNEX 1 F61S.BHZ01.MNP23




PS+SPS days 24-1-2007 W.Kalbreier, D.Smekens, T.Zickler AT-MEL, CERN, 1211 Geneva 23



- ➔ An analysis by V. da Silva AT/MEL/MI in 2005 showed that corrosion problems were due to insufficient quality of the demineralized water:
 - too high conductivity (up to 15 microS/cm, nominal 0.5 microS/cm),
 - resin cartridges not regularly exchanged and problems of monitoring the conductivity.
 - As a consequence of the low water quality the inner walls of the cooling channel were corroded resulting in a deposit of $\text{CuO} + \text{Cu}_2\text{O}$ blocking the water circulation of the coils .
- ➔ In close collaboration with TS/CV we purchased + installed new devices to monitor the water quality online (operational since 3-2006).





- ➔ 2005: Fabrication of 5 new coil sets (3rd generation) to be mounted in the existing yokes at SEF/FR. The coils had improved cooling features (cooling per half-turn instead per full-turn) in order to reduce the very high water speed and the maximum coil temperature.
- ➔ March 2006: Installation of MNP23 with 1st new coil set from SEF.
- ➔ April 2006: a short circuit required the replacement of the MNP23 just before beam operation.
- ➔ July 2006: an electrical breakdown in the 2nd coil set required the replacement of the magnet.
- ➔ October 2006: an electrical breakdown in the 3rd coil set ended its operation after 4 weeks only.

- ➔ As the origin of the breakdown was fully unclear, it had been decided to use the 4th coil set in order to launch a study including simulations and measurements under true operating conditions (except beam).
- ➔ A study started in November 2006 by M. Zerlauth AB-CO & J. Kozak AT-MTM, D. Bodart AT-MEL & A. Beuret AB-PO using the 4th coil set. .
- ➔ The preliminary results after about 4 weeks were as follows:
 - no convincing fault explanation yet
 - the max over-voltage spikes from the power converter are only about 50% above the nominal max of 400 V.
 - several kV are required for causing the severe damage observed!




- ➔ Mid-February 2007: The study will continue when cooling water is again available until the origin is found.
- ➔ Results will be used for an improved fabrication of the 5th new coil set followed by long-term testing before an eventual re-installation in 2008.
- ➔ February 2007: install C-shaped MCB magnet to replace MNP23 for 2007 operation.



➔ SPARE SLIDES BELOW

COMPARISON PS EAST HALL - SPS NEA




Insufficient space required the design of **too delicate magnets** like the **MNP23 & Q120**.


Many of the installed magnets are

- About 40 years old + have radiation-damaged coil insulation
- unreliable for operation
- expensive in production
- result in too high radiation doses to people
- and too high costs for :
 - Interventions
 - Maintenance
 - replacements

Access via PS Main Ring → for any magnet replacement PS must be stopped



PS EAST EXTRACTION



EHNL 5 N-9
 18.03.98
 JP.VENTURINI 46393
 0 10m
 East Hall of PS
 MODIFICATION
 SCHEFFRE C. 74076
 20 MAI 1999






	NEW	OK	RISKY	SUM
OPERATING	0	1	0	1
	NEW	OK	UNKNOWN	SUM
SPARES	0	0	(5)	(5)
2007	<p style="text-align: center;">T7.DVT01.MNPA 38.02</p> <p style="text-align: center;">No spare unit, but could be replaced by MNPA 30 (5 spares of unknown state).</p> <p style="text-align: center;">➔ Do revision of MNPA 30 to get 1 spare magnet.</p>			





East Hall magnets: start of service




PS+SPS days 24-1-2007 W.Kalbreier, D.Smekens, T.Zickler AT-MEL, CERN, 1211 Geneva 23







Survey measurement
 18/10/06 15:30h
 PS, eject.EST stopped since 18/10 8:00h North and
 since 28/09 South.
 Measurements AD6 at 40cm in microSv/h






East hall T7 T8 secondary zone: access via experiment




PS+SPS days 24-1-2007 W.Kalbreier, D.Smekens, T.Zickler AT-MEL, CERN, 1211 Geneva 23



→ Beam line layout for F61 + F61S+N + line T10:


- Insufficient space for interventions
- In high dose level zones insufficient transversal space
 - one can only move along the lines and
 - thus it takes too long to escape rapidly from the radiation field.



Access via PS Main
Ring → for
replacement PS must
be stopped

High DC power 400 kW

High current 1300 A





ANNEX 3



→ BELOW



ANNEX 3 EAST HALL MAGNET RESPONSIBILITY



PS+SPS days 24-1-2007 W.Kalbreier, D.Smekens, T.Zickler AT-MEL, CERN, 1211 Geneva 23

	Magnet ownership	Magnet maintenance	Co-ordination Magnet installation, book-keeping, alignment, vacuum
1996-2004	PS → AB- ATB	SL-MS → AT- MEL	PS → AB-ATB
11-2004	AT-MEL	AT-MEL	AB-ATB

see Memo dated 18 August 2004 about the responsibility for normal-conducting magnets (ref. OUT-2004-058-annex Rev.1).

- Up to now AT-MEL (with exception of a magnet listing + X-section layout) has not received the required documentation needed for a proper maintenance or rebuilding of the magnets.
- This 'electronic' documentation for each type shall consist of:
- Scanned specifications
 - Drawings in CDD


This task is really urgent + shall be done by AB-ATB, as they have the documents + were the owners. AT-MEL has no manpower for this.

Per type it will take at least 1 week.


So for 22 types it is 6 months work of a good Cat 3 person.



➔ SPARE SLIDES BELOW



→ 2 recent breakdowns on MSN manifolds (1 during 2005 shutdown, 1 during 2006 run)





Weak Magnets: splitters MSSB




PS+SPS days 24-1-2007 W.Kalbreier, D.Smekens, T.Zickler AT-MEL, CERN, 1211 Geneva 23

	Situation	RISKY	SUM
OPERATING	<u>NEA standard:</u> MSSB Type 2: 6 magnets in use in TDC2 <u>WEA standard:</u> MSSB Type 1: 0 in use	All MSSBs in TDC2	6
SPARES	<u>NEA standard:</u> MSSB Type 2: 1 spare new magnet <u>WEA standard:</u> MSSB Type 1: 4 spares (recuperated magnets)	None	5 spares (4 not compatible with NEA)
Importance issues	2 triplets of MSSB used to split the primary beam toward T2/T4/T6 targets		
2007	No consolidation budget available. Study feasibility to convert WEA MSSB into NEA MSSB (NEW UPPER YOKE + VACUUM TANK REQUIRED)		
2008-09	If consolidation money available, conversion of 1 to 2 WEA to NEA MSSB		



MSSB Splitter magnet: Cross Section

PS+SPS days 24-1-2007 W.Kalbreier, D.Smekens, T.Zickler AT-MEL, CERN, 1211 Geneva 23



- ➔ Vacuum leaks. Due to corrosion of the stainless steel in contact with the PVC material used for the covers (made in the 70's).
- ➔ Not repairable in situ. Leaky Magnets have to be replaced





Conclusions: NEA



- ➔ TDC2/TCC2 concentrate most of the problems.
- ➔ Expected improvements by 2008:
 - QTA/QTL water manifold problem solved in TT20/TDC2
 - 2 to 3 Spare MSSB magnets available in case of breakdowns
- ➔ by 2010 : Additional spare MSN magnets

→ Remaining Issues:

- No spares for 1 QM + 3 MTS + 4 MTRV + 4QNRB (all these magnets are installed in hot places of TDC2/TCC2)
- Only one MSN spare unit (MSNs are installed in hot places of TDC2/TCC2)
- Few MBNV spare units
- Obsolete Magnet Interlock System