



W. Kalbreier, D. Smekens, T. Zickler AT-MEL-MI

## I PS EAST HALL MAGNETS

1. Overall magnet status
  - Interventions
  - Installed magnets & spares
  - Details MNP23 → ANNEX 1
2. Status of 'weak' magnets
3. Proposal for an improved East Hall layout  
Missing documentation → ANNEX 2



## II SPS NORTH EXP. AREA MAGNETS


1. Overall magnet status
  - Interventions
  - Installed magnets & spares
2. Status of 'weak' magnets

## III INSUFFICIENT STAFF

## IV CONCLUSIONS

Acknowledgement: D. Bodart + P. Ziegler  
have contributed effectively to compile  
information on the East Hall magnets.

## PS EAST EXTRACTION




EHNL 5 N-9  
 18.03.98  
 JP.VENTURINI 46393  
 0 10m  
 East Hall of PS  
 MODIFICATION  
 SCHEFFRE C. 74076  
 20 MAI 1999



# I.1 EAST HALL MAGNETS: BREAKDOWNS DURING OPERATION




ATC-ABOC days 24-1-2007 PS+SPS EA magnets W.Kalbreier, D.Smekens, T.Zickler AT-MEL




Access via PS Main Ring → for any magnet replacement PS must be stopped

**SPLITTER-MEP35**



**SEPTUM BHZ01-MNP23**





**After installation → Access via PS Main Ring**  
**→ for replacement PS must be stopped**


- High DC power 400 kW
- High current 1300 A



# F61S. BHZ01.MNP23 10-2006 breakdown 3<sup>rd</sup> coil SEF



ATC-ABOC days 24-1-2007 PS+SPS EA magnets W.Kalbreier, D.Smekens, T.Zickler AT-MEL






# East Hall Magnets: in operation & spares as per January 2007



ATC-ABOC days 24-1-2007 PS+SPS EA magnets W.Kalbreier, D.Smekens, T.Zickler AT-MEL





### 'weak' magnet definition:

- ➔ high risk for operation:
  - failure is likely to happen in the coming years
  - mainly because of the bad state of the coil insulation due to severe radiation damage
- ➔ low or zero operational spare number
- ➔ long down-time when replaced during operation:
  - long cooling-down due to high induced radiation level or
  - requires the opening + closing of the top shielding = 2 weeks or PS stop.

### high impact for whole East Hall:

Operates in primary lines: F61, F61S, F61N

## High priority

- for **revision** and/or
- **new fabrication** shall be given for:


## 'weak' magnets of

- **high impact** for the
- **operation of the whole East Hall.**

# East hall primary zone: Access possible during PS operation

Extremely densely packed + covered with concrete shielding roof → for any magnet replacement an opening + closing takes 2 weeks + cool-down + magnet exchange period

ATC-ABOC days 24-1-2007 PS+SPS EA magnets W.Kalbreier, D.Smekens, T.Zickler AT-MEL






**As MNP23 problems have been presented in several ATC sessions in 2006 I skip it here + leave it for questions.**

**→ For full story → see Annex 1.**

**→ February 2007: install C-shaped MCB magnet to replace MNP23 for 2007 operation.**









# 'weak' magnets

## Q74



ATC-ABOC days 24-1-2007 PS+SPS EA magnets W.Kalbreier, D.Smekens, T.Zickler AT-MEL

	NEW	OK	RISKY	SUM
<b>OPERATING</b>	0	1	1	2
	NEW	OK	UNKNOWN	SUM
<b>SPARES</b>	0	1	0	1
<b>Importance issues</b>	Risky magnet is in <b>T9 line at QDE01.Q74.02</b> for AMS/T2K-KEK.			
<b>2007</b>	Replace risky magnet in 2007 if feasible. If high priority → ask budget for 1 new magnet.			
<b>2008</b>	If budget + additional staff obtained, 1 new magnet could be fabricated.			
<b>2009</b>	1 spare available			





# 'weak' magnets

## Q 600



ATC-ABOC days 24-1-2007 PS+SPS EA magnets W.Kalbreier, D.Smekens, T.Zickler AT-MEL

	NEW	OK	RISKY	SUM
<b>OPERATING</b>	0	1	4	5
	NEW	OK	UNKNOWN	SUM
<b>SPARES</b>	0	3	2	5
<b>Importance issues</b>	<p>T7.QFO01.Q606+QDE02.Q607 for OPERA.  T7 Beam energy reduced: 10 → 9 GeV  T11.QDE01.Q604 + QFO02.Q602 for CLOUD</p>			
<b>2007</b>	<p>2 risky magnets will be replaced; 1 OK-spare kept.  The 2 spare units (unknown) must be revised in order to obtain 2 operational spares.  If successful, replace 3<sup>rd</sup> + 4<sup>th</sup> risky magnet in 2008.  If unsuccessful + priority → budget for 1-2 new magnets.</p>			
<b>2008</b>	<p>If budget + additional staff obtained, 1-2 new magnets could be fabricated.</p>			
<b>2009</b>	<p>risky magnet could be replaced + 1 spare left</p>			



# 'weak' magnets Q800

ATC-ABOC days 24-1-2007 PS+SPS EA magnets W.Kalbreier, D.Smekens, T.Zickler AT-MEL





# 'weak' magnets


## Q 800



ATC-ABOC days 24-1-2007 PS+SPS EA magnets W.Kalbreier, D.Smekens, T.Zickler AT-MEL

	NEW	OK	RISKY	SUM
<b>OPERATING</b>	0	0	2	2
	NEW	OK	UNKNOWN	SUM
<b>SPARES</b>	0	0	1	1
<b>Importance issues</b>	<p>2 operating magnets are overheating.</p> <p>T10 beam energy reduced: 7 → 6 GeV ALICE</p> <p>T10.QDE01.Q804 + QFO02.Q803</p> <p>Already 3 broken non-repairable units.</p>			
<b>2007</b>	<p>1 (highly radio-active) spare must be revised in order to obtain 1 operational spare.</p> <p>If successful, keep it as spare.</p> <p>If unsuccessful + high priority → ask budget for 3 new magnets.</p>			
<b>2008</b>	<p>If budget + additional staff obtained, 3 new magnets could be fabricated.</p>			
<b>2009</b>	<p>risky magnets could be replaced + 1 spare</p>			







# 'weak' magnets


# M105



ATC-ABOC days 24-1-2007 PS+SPS EA magnets W.Kalbreier, D.Smekens, T.Zickler AT-MEL

	NEW	OK	RISKY	SUM
<b>OPERATING</b>	0	3	0	3
	NEW	OK	UNKNOWN	SUM
<b>SPARES</b>	0	0	0	0
<b>Importance issues</b>	<p style="text-align: center;">No spare for primary lines  F61N.DHZ01.M105.02+F61S.DHZ01.M105.03  T8.DHZ01.M105.01</p>			
<b>2007</b>	<p style="text-align: center;">No spare unit → Define priority → If high, ask budget for 1 new magnet.</p>			
<b>2008-9</b>	<p style="text-align: center;">If budget + additional staff obtained, 1 new magnet could be fabricated.</p>			
<b>2010</b>	<p style="text-align: center;">spare status ok</p>			







# 'weak' magnets MEP19



ATC-ABOC days 24-1-2007 PS+SPS EA magnets W.Kalbreier, D.Smekens, T.Zickler AT-MEL

	NEW	OK	RISKY	SUM
<b>OPERATING</b>	0	0	1	1
	NEW	OK	UNKNOWN	SUM
<b>SPARES</b>	0	0	0	0
<b>Importance issues</b>	<p>No spare</p> <p>F61N.BVT01.MEP19 with high induced radiation level.</p>			
<b>2007</b>	<p>No spare unit → Define priority → If high, ask budget for 1 new magnet.</p>			
<b>2008</b>	<p>If budget + additional staff obtained, 2 new magnets could be fabricated.</p>			
<b>2009</b>	<p>spare status ok</p>			










# 'weak' magnets

# Q120



ATC-ABOC days 24-1-2007 PS+SPS EA magnets W.Kalbreier, D.Smekens, T.Zickler AT-MEL

	NEW	OK	RISKY	SUM
<b>OPERATING</b>	2	0	3	5
	NEW	OK	UNKNOWN	SUM
<b>SPARES</b>	1	0	0	1
<b>Importance issues</b>	<p>F61S.QFO01.Q120.04+QDE02.Q120.06 T9.QFO02.Q120.02 AMS/T2K-KEK</p>			
<b>2007</b>	<p>Consolidation budget obtained. M. Karppinen AT-MEL-MI will launch + follow-up the fabrication. 3 Magnets will be fabricated.</p>			
<b>2008</b>	<p>3 risky magnets could be replaced, leaving 1 new spare.</p>			





# 'weak' magnets

# MEP 35



ATC-ABOC days 24-1-2007 PS+SPS EA magnets W.Kalbreier, D.Smekens, T.Zickler AT-MEL

	NEW	OK	RISKY	SUM
<b>OPERATING</b>	0	1	0	1
	NEW	OK	UNKNOWN	SUM
<b>SPARES</b>	0	0	2	0
<b>2007</b>	<p style="text-align: center;">Splitter Magnet in primary line F61.SMH01 producing the beam intensity sharing between North and South branch.</p> <p>Magnet fully enclosed in vacuum container + motorized yoke.</p> <p style="text-align: center;">Maintenance of motorization shall be done by AB as AT-MEL-MI has no staff in this professional category.</p> <p>1 spare unit shall be revised; if unsuccessful + high priority → ask budget for 1 magnet.</p>			
<b>2008-2009</b>	If budget + additional staff obtained, 1 new magnet could be fabricated.			
<b>2010</b>	spare status ok			



ATC-ABOC days 24-1-2007 PS+SPS EA magnets W.Kalbreier, D.Smekens, T.Zickler AT-MEL





# 'weak' magnets

# MNPA 38



ATC-ABOC days 24-1-2007 PS+SPS EA magnets W.Kalbreier, D.Smekens, T.Zickler AT-MEL

	NEW	OK	RISKY	SUM
OPERATING	0	1	0	1
	NEW	OK	UNKNOWN	SUM
SPARES	0	0	(5)	(5)
2007	<p style="text-align: center;"><b>T7.DVT01.MNPA 38.02</b></p> <p style="text-align: center;">No spare unit, but could be replaced by MNPA 30 (5 spares of unknown state).</p> <p style="text-align: center;">➔ Do revision of MNPA 30 to get 1 spare magnet.</p>			





## 1.3 Proposal for an improved East Hall layout



- Magnets installed 63
- Risky Magnets (now: 11) at start-up of 2007: 8
- Magnet types 22
- Installed per type 2.9


**Maintenance** of such a high number of different types is:

- expensive and
- with increasing number of breakdowns
- cannot be managed with available staff.

Insufficient space required the design of **too delicate magnets** like the **MNP23 & Q120**.

Many of the installed magnets are

- **have radiation-damaged coil insulation**
- **unreliable for operation**
- **expensive in production**
- **result in too high radiation doses to people**
- **and too high costs for :**
  - Interventions
  - Maintenance
  - replacements






# East Hall magnets: start of service



ATC-ABOC days 24-1-2007 PS+SPS EA magnets W.Kalbreier, D.Smekens, T.Zickler AT-MEL





The **East Hall magnets** after about 40 years of service have mostly arrived the **end of their lifetime**.

East Hall magnets: **8% of NEA but same FTE** →  
12 times more expensive !

Therefore, it seems the right moment to think about a **redesign of the East Hall with fewer magnet types and more space + less lines**.

Keeping in mind the **savings** in


- **Manpower**
- **Radiation budget**


combined with **less down-time for physics**

this could even be the **more economic solution**.



## II SPS North Exp. Area Magnets NEA















**Magnets for BT to NEA** 18 Magnet Families

■ in use BT->NEA 
 ■ in use other BT 
 ■ spares 
 ■ damaged spares






# Magnet status for the NEA & secondary Beams



ATC-ABOC days 24-1-2007 PS+SPS EA magnets W.Kalbreier, D.Smekens, T.Zickler AT-MEL



OK: 10 spares available from SPS stocks





## II.2 Status 'weak' magnets + Potential Risks



ATC-ABOC days 24-1-2007 PS+SPS EA magnets W.Kalbreier, D.Smekens, T.Zickler AT-MEL

	Magnet Type	Risk	Rating Risk*Impact	Proposed action
TT20 / TDC2	<b>QTA/L</b> (48 magnets in use in TT20/TDC2/NEA)	<b>Failure of the Coil Water manifold</b>	<b>High</b> (~20 risky magnets ) (several repairs every year)	<b>2007: supply of new manifolds for repairs. Next Shutdown: Replacement of weak parts on 20 magnets</b>
	<b>MSSB</b> (6 magnets in use)	<b>Failure of vacuum tank or magnet coil due to corrosion</b>	<b>Medium to high</b> (unpredictable) <i>Risk of breakdown in series</i>	<b>2008: Conversion of 1 (or 2) West Area splitter(s) into NEA splitter</b>
TCC2	<b>MBN</b> (83 magnets in use in TCC2/NEA)	<b>Vacuum Leak due to corrosion in radioactive areas (PVC covers)</b>	<b>High</b>	<i>PVC covers replaced on magnet in radioactive environment last years.</i> <b>Vacuum related problem. But it uses spare magnets.</b>
	<b>MSN</b> (8 in use in TCC2)	<b>Failure of the Coil Water manifold</b>	<b>Medium</b> (probable within 5y)	<b>2007: supply of new manifolds for repairs.</b> <b>2008-2010: refurbishment of the 3 damaged MSN</b>
	<b>MTR/MTS/QLNRB/ QNLB</b>	<b>Lifetime elapsed. Probably coil failure</b>	<b>Low to medium</b> (unpredictable)	<b>1 spare MTS coil available. Consolidation proposal not yet assessed.</b>







# Weak Magnets: QTA/L/R/S



ATC-ABOC days 24-1-2007 PS+SPS EA magnets W.Kalbreier, D.Smekens, T.Zickler AT-MEL


	Situation	RISKY	SUM
<b>OPERATING</b>	<u>EA standard:</u> QTA:0 / QTL: 1 / QTR: 0 / QTS: 14 <u>BT standard:</u> in TT20/TDC2 :QTA:19 / QTL: 11 / QTR: 0 / QTS: 2 in other BT lines: QTA:0 / QTL: 14 / QTR: 2 / QTS: 2 TOTAL: 65	<b>&gt; 20 magnets</b>	65 magnets in operation. 30% of them risky
<b>SPARES</b>	<u>EA standard:</u> QTA:0 / QTL: 19 / QTR: 4 / QTS: 36 <u>BT standard:</u> QTA:4 / QTL: 5 / QTR: 2 / QTS: 8	<b>Not assessed</b>	78 magnets spare ! Mostly QTS
<b>Importance issues</b>	Main BT quadrupoles for primary beamline TT20/TDC2. Mainly QTA magnets in TDC2, few spare QTA		
<b>since 2006</b>	Assembly Tool + workshop + spare coils to reconstruct QTA/QTL/QTR/QWL		
<b>2007</b>	Small consolidation budget available. Manufacture of new parts for 25 magnets (targeting repairs of QTA and QTL in TDC2 – 24 magnets)		
<b>2008</b>	Replacement of weak parts in situ (TDC2).		







- ➔ **MSSB Splitter Magnet Situation**
  - 1 spare magnet for North Area
  - Corrosion problem on all 6 North Area MSSB magnets
- ➔ **Risk of several failures in a row**
- ➔ **Availability of 3 West Area MSSB magnets (different septum profile)**
  - Conversion WEA MSSB into NEA MSSB seems possible

**Replacement of 1 complete upper yoke+vacuum tank: ~115kCHF**



**North Area Version**








# MSSB Splitter magnet: Cross Section

ATC-ABOC days 24-1-2007 PS+SPS EA magnets W.Kalbreier, D.Smekens, T.Zickler AT-MEL





# Weak Magnets: splitters MSSB




ATC-ABOC days 24-1-2007 PS+SPS EA magnets W.Kalbreier, D.Smekens, T.Zickler AT-MEL

	Situation	RISKY	SUM
<b>OPERATING</b>	<u>NEA standard:</u> MSSB Type 2: 6 magnets in use in TDC2 <u>WEA standard:</u> MSSB Type 1: 0 in use	<b>All MSSBs in TDC2</b>	6
<b>SPARES</b>	<u>NEA standard:</u> MSSB Type 2: 1 spare new magnet <u>WEA standard:</u> MSSB Type 1: 4 spares (recuperated magnets)	None	5 spares (4 not compatible with NEA)
<b>Importance issues</b>	2 triplets of MSSB used to split the primary beam toward T2/T4/T6 targets		
<b>2007</b>	No consolidation budget available. Study feasibility to convert WEA MSSB into NEA MSSB (NEW UPPER YOKE + VACUUM TANK REQUIRED)		
<b>2008-09</b>	If consolidation money available, conversion of 1 to 2 WEA to NEA MSSB		


- ➔ Vacuum leaks. Due to corrosion of the stainless steel in contact with the PVC material used for the covers (made in the 70's).
- ➔ Not repairable in situ. Leaky Magnets have to be replaced







## AT-MEL-MI STAFF EVOLUTION



## Severe reliability problems due to

- About 40 years old magnets
- Coils heavily radiation damaged
- Yokes often with high induced radio-activity → high irradiation of staff at maintenance + repair
- Low or zero operational spares for several types
- Too many (22) types for 63 magnets
- Some of too delicate design + expensive in production

The **East Hall magnets** have mostly arrived at the **end of their lifetime**.

Therefore, it seems the right moment for a

- **redesign of the East Hall** with
- **fewer magnet types and more space**.

Otherwise a considerable effort in P+M must be invested to:

- Replace risky magnets
- Improve the current spare situation

Status is less critical than for the PS East Hall.

Magnets are about 30 years old.

Primary lines: 240 magnets, magnets/type 6-7

Secondary lines: 540 magnets, magnets/type 19

→ TDC2/TCC2 concentrate most of the problems.

→ Expected improvements by 2008:

- QTA/QTL water manifold problem solved in TT20/TDC2

- 2 to 3 Spare MSSB magnets available in case of breakdowns

→ by 2010 : Additional spare MSN magnets





## Remaining Issues:

- No spares for 1 QM + 3 MTS + 4 MTRV + 4QNRB
- Only 1 MSN spare unit
- Few MBNV spare units
- Obsolete Magnet Interlock System

The staff is declining dramatically due to:

- Ending LD contracts end 2007 to mid 2008.
- Already 4 staff Cat 2xC, D, E have left to AB.
- Retiring staff
- Replacements inside MEL done 9-2006.

➔ Huge loss in expertise + effectiveness

Already for the **basic programme** we do just have

- **sufficient staff for 2007,**
- **But NOT for the following years.**



We need already in the **current of 2007 strong influx of experienced staff (cat C + D) to be trained in magnet manufacture, testing and maintenance.**

Without this input of experienced staff :

→ We cannot fulfill for >2007 our tasks for the basic programme : PS+ SPS + LHC (nc magnets)

→ Consequently beyond the basic programme we have to decline all tasks for:

- PS + SPS Experimental Areas + CNGS
- CTF3 + CLIC
- PS-MTE + LINAC4 + SPL + PS2


→ 1<sup>st</sup> generation (3 different designs) showed coil insulation + water cooling + short circuit leading to completely burnt coil insulations) problems starting already in the 1990<sup>s</sup>.

Status in 2001. → No more spares from 1<sup>st</sup> generation + F61S-BHZ01 needed to be replaced.


→ 3 new magnets were built in 2001 at OSWALD/DE by T. Zickler (2nd generation).

→ Damaged unit in F61S was replaced the 1<sup>st</sup> unit of the new septum in March 2002 & operated until November 2003 (→ water leak + cooling channels blocked due to corrosion).





High DC power 400 kW  
High current 1300 A






- July 2004: high leakage current + cooling channels blocked by a deposit stemming from corrosion. → required the replacement of the 2<sup>nd</sup> unit operating since March 2004.
- November 2004: same problems with the 3<sup>rd</sup> unit operating since September 2004.


- An analysis by V. da Silva AT/MEL/MI in 2005 showed that corrosion problems were due to insufficient quality of the demineralized water:
- too high conductivity (up to 15 microS/cm, nominal 0.5 microS/cm),
  - resin cartridges not regularly exchanged and problems of monitoring the conductivity.
  - As a consequence of the low water quality the inner walls of the cooling channel were corroded resulting in a deposit of  $\text{CuO} + \text{Cu}_2\text{O}$  blocking the water circulation of the coils .
- In close collaboration with TS/CV we purchased + installed new devices to monitor the water quality online (operational since 3-2006).




CuO + Cu<sub>2</sub>O deposit blocking the cooling channels



CuO + Cu<sub>2</sub>O deposit blocking the cooling channels




- ➔ 2005: Fabrication of 5 new coil sets (3<sup>rd</sup> generation) to be mounted in the existing yokes at SEF/FR. The coils had improved cooling features (cooling per half-turn instead per full-turn) in order to reduce the very high water speed and the maximum coil temperature.
- ➔ March 2006: Installation of MNP23 with 1<sup>st</sup> new coil set from SEF.
- ➔ April 2006: a short circuit required the replacement of the MNP23 just before beam operation.
- ➔ July 2006: an electrical breakdown in the 2<sup>nd</sup> coil set required the replacement of the magnet.
- ➔ October 2006: an electrical breakdown in the 3<sup>rd</sup> coil set ended its operation after 4 weeks only.



Electrical breakdown  
between pancakes





Electrical breakdown  
between pancakes

- ➔ As the origin of the breakdown was fully unclear, it had been decided to use the 4<sup>th</sup> coil set in order to launch a study including simulations and measurements under true operating conditions (except beam).
- ➔ A study started in November 2006 by M. Zerlauth AB-CO & J. Kozak AT-MTM, D. Bodart AT-MEL & A. Beuret AB-PO using the 4<sup>th</sup> coil set. .
- ➔ The preliminary results after about 4 weeks were as follows:
  - no convincing fault explanation yet
  - the max over-voltage spikes from the power converter are only about 50% above the nominal max of 400 V.
  - several kV are required for causing the severe damage observed!



- ➔ Mid-February 2007: The study will continue when cooling water is again available until the origin is found.
- ➔ Results will be used for an improved fabrication of the 5<sup>th</sup> new coil set followed by long-term testing before an eventual re-installation in 2008.
- ➔ February 2007: install C-shaped MCB magnet to replace MNP23 for 2007 operation.



## ANNEX 2 EAST HALL MAGNET RESPONSIBILITY



	Magnet ownership	Magnet maintenance	Co-ordination Magnet installation, book-keeping, alignment, vacuum
1996-2004	PS → AB- ATB	SL-MS → AT- MEL	PS → AB-ATB
11-2004	AT-MEL	AT-MEL	AB-ATB

see Memo dated 18 August 2004 about the responsibility for normal-conducting magnets (ref. OUT-2004-058-annex Rev.1).

- Up to now AT-MEL (with exception of a magnet listing + X-section layout) has **not received the required documentation needed for a proper maintenance or rebuilding of the magnets.**
- This 'electronic' documentation for each type shall consist of:
  - Scanned specifications
  - Drawings in CDD

This task is really urgent + shall be done **by AB-ATB**, as they have the **documents + were the owners. AT-MEL has no manpower for this.**

Per type it will take at least 1 week.

So for 22 types it is 6 months work of a good Cat 3 person.