


Analysis of Booster and Storage Ring RF System Reliability at the Advanced Photon Source

Doug Horan – Advanced Photon Source RF Group
2010 – Sixth CW and High Average Power RF Workshop
ALBA, Barcelona, Spain

2008 APS Reliability Statistics By System

FY 2008 Downtime by System
Data through Run 2008-2

- Overall APS reliability was 97.6% with 91.4 hours mean time to beam loss
- Overall RF downtime was 1.04% with 319.9 hours mean time to beam loss
- 2.75% rf downtime in 2008 was due to booster coupler failure



Updated 8/18/8




2009 APS Reliability Statistics By System

- Overall APS reliability was 97.7% with 77.5 hours mean time to beam loss

- Overall RF downtime was .87% with 271.3 hours mean time to beam loss

- High rf downtime in 2009-2 due primarily to HVPS failures

FY 2009 Downtime by System
Data through Run 2009-2



2010 APS Reliability Statistics By System

- As of April 20th




...Overall APS reliability is 98.9% with 139.6 hours mean time to beam loss

...RF downtime is 0.48% with 383.9 hours mean time to beam loss

- **Biggest problem in present run: klystron arc detector tripsnot real?**

FY 2010 Downtime by System
Data through Run 2009-3



RF System Events Resulting in Beam Interruption - March 2008 to Present:

- High voltage power supply failures → 23
- Waveguide arc detector trips → 13
- LLRF hardware failures → 6
- Cavity input coupler failures → 4
- Klystron instabilities and failures → 4
- Cavity tuners problems → 1
- Controls malfunction affecting rf systems → 1
- Broken coupler blower hose in tunnel due to radiation damage causing trip of wg air PSS system → 1
- Human error – loose waveguide air hose in test stand → 1
- Human error – opening test stand waveguide shutters with coupler blowers off causing trip of wg air PSS system → 1

HVPS is biggest cause of downtime!

RF System High-Voltage Power Supplies

- Installed new in 1992-94.....*approximately 90,000 average operating hours per system since 1995*
 - Conventional design, 95kV@20A maximum output:
 - *Transformer-Rectifier*
 - *SCR voltage control*
 - *Ignitron crowbar*
 - *Tetrode mod-anode modulator*
- *Most frequent cause of downtime in the last two years*




HVPS Sub-System Problem Areas

- **Transformer-rectifier set capacitor bank**
- **Mod-anode regulator**
- **Pantak cable connectors and sockets**
- **Control system**
- **Cathode voltage regulator (SCR's)**
- **13.2kV Fused Disconnect Switch**




Transformer-Rectifier Set Capacitor Failures

- T-R set capacitor bank consists of eight 2x2uF capacitors arranged in series/parallel:
→ $C_t = 8\mu\text{F}$ at 95kV max
- Routine inspection of the RF5 T-R set in May 2008 revealed several failed capacitors – predicted lifetime was 20 years
- Original capacitors were obsolete and out of production by manufacturer
- Replacement capacitors were second-sourced to another manufacturer, hipot tested twice, and installed in the RF4 T-R set in May of 2009



Transformer-Rectifier Set Capacitor Failures

- **Most of the new caps failed after approximately one week service!**
- **The cause of the failures was determined to be incomplete oil impregnation to all sections of the capacitor:**




Transformer-Rectifier Set Capacitor Failures

- The original caps were re-installed in the RF4 T-R set so operation could resume
- A search for a second vendor was started
- New caps were ordered from Vendor #2 and were installed in RF4 during the August 2009 maintenance shutdown
- No further problems with caps from vendor #2
- Lessons learned:
 - *“old-school” high-voltage components may not be so easy to get nowadays*
 - *try to secure two vendors for such parts, and maintain adequate spares*

Mod-Anode Regulator Failures



- Many component failures resulting in significant downtime:



Mod-Anode Tetrode Socket Failures

- Over-heating of center pin tetrode contact due to trapped oil, causing intermittent loss of heater power
- 2-watt carbon composition resistors cracking


→ *temperature?.....old age?*



Solution: Drill oil escape hole in center of socket cover, and replace all carbon composition resistors with 3-watt metal film

Mod-Anode Fiber Optic Cables

- X-rays from tetrodes degrade fast glass fiber optic cables, impeding analog communication with tetrode control electronics cages and resulting in loss of anode regulation



Solution: Convert to radiation-resistant plastic fiber cables with larger active area

Tetrode Failures

- Two Thales TH5188 tetrodes are used as an active voltage divider in mod-anode regulator
- Production of TH5188 ceased approximately five years ago – *we made bulk purchase for spares*
- *Approximately 5 verified failures in the last ten years*

Solution: A tetrode test set was constructed to evaluate and test new and used tetrodes and other mod-anode electronics modules under high-voltage operation conditions




Problems with Pantak Cable Connections Between HVPS and Klystron

- Numerous HVPS system failures have occurred due to:

→ *cable failures due to high voltage breakdown*



→ *Intermittent socket connections*



Improved Pantak Socket Tip Connector

- Original tri-axial tip connector was sensitive to insertion force and would result in intermittent filament contact

Solution: Re-designed one-piece tip contact with fingerstock provided positive contact to tip and ring bushings on plug



TESTED AT 50A!



Pantak Cable High Voltage Failures

- Suspect causes include defects in connector or plug molding, potting, or material, incorrect plug insertion force, insufficient grease, undetected HV damage to the mating socket



Solution: Increased awareness of proper insertion force, improved technician training on Pantak connector inspection and maintenance

Failures in HVPS Control System


- Original control system, circa 1990:

→ *many obsolete parts*


→ *PC computer interface program written in Windows 3.1, running on Windows 95 OS!*

→ *many intermittents on board connectors*


Solution: Replace entire control system with a modern PLC.....*project currently underway*




Cathode Voltage Regulator - SCR Cabinet Failures



1996 EVENT



2007 EVENT



2007 EVENT

- Three catastrophic events have occurred: 1996, 2003, 2007
- Root cause in 1996 and 2007 events was traced to failure of SCR snubber capacitors

Solution: Replace original capacitors, and re-configure wiring between SCR stacks to reduce possibility of phase-to-phase shorts when components fail

13.2kV Fused-Disconnect Switches

- Original switches *notoriously* unreliable
 - Failure rate as high as once every 10 operations!
 - Would stick in both open and closed positions!
 - Switch was obsolete at time of installation....1992!

- Replaced by new switch that is more robust and easier to maintain, with improved personnel safety features



Waveguide Arc Detector Trips

- Typically occur once every 2 months per rf system, roughly 5-6 total per year.....are they real or false?
- Typical causes when arcs are considered real:
 - Humid air from storage ring tunnel blown into waveguides by coupler blowers -- *common when weather is wet, rainy..... tunnel air is not controlled for humidity or temperature*
 - Arcing between ferrites in circulators coming out of a shutdown.....*dust settling on ferrites?*
- Typical causes when arcs are considered false:
 - Radiated electrical noise coupling into arc detector electronics
- Number of arc detector trips since January 2010 is very high....7 total!
 - Radiated noise suspected.....*arc detector trips occurred on klystrons that were in standby diode mode!*


Solution: Find noise source.....*investigation ongoing!*

Cavity Input Coupler Failures

- **Four coupler failures in the last two years:**
 - 3/22/08 – Booster C1 -- sudden pinhole leak in ceramic
 - 4/25/08 – S40/C2 – intermittent vacuum trips
 - 6/04/08 – S40/C2 – new coupler destroyed by overpower accident during beam studies
 - 6/17/09 – S40/C2 – sudden pinhole leak in ceramic
- **Operating data before failure and post-mortem analysis did not find a definite cause for ceramic pinhole leaks**



FAILED BOOSTER C1 COUPLER



STORAGE RING COUPLER DESIGN

Klystron Trips and Instabilities

- Only two *verified* klystron-related beam losses in the last two years:

→ klystron vacuum trip (1)

→ sideband instability (1)

.....a relatively low number considering the accumulated operating hours:

RF1 → EEV s/n 01 = 73,409 hr

RF2 → Thales s/n 089041 = 56,231 hr

RF3 → EEV s/n 089041 = 57,548 hr

RF4 → Thales s/n 089030 = 29,757 hr

RF5 → Thales s/n 089026 = 48,073 hr




EEV K3513A → most reliable, free of instabilities

Thales TH2089A → reliable, but can become unstable at certain operating points

Klystron Instabilities

- The common sideband instability seen in the TH2089A results in very strong sidebands spaced $\sim 2\text{MHz}$ from the carrier:



- Typical remedies:
 - change cathode voltage by 1-3kV
 - adjust circulator bias to increase reflected power in the direction of *slightly lower efficiency*
- In most cases sidebands can be suppressed



Klystron sidebands can occur without warning and typically result in beam loss during a fill

Recent Failure of a Klystron


- TH2089A, s/n 089043, failed after approximately 1,850 hours of operation
- Purchased new in 2001, sat in storage for eight years
- Was installed at RF2 in January of 2010 and ran normally in storage ring service for approximately three months
- On April 6th it suddenly developed severe sideband instability that could not be corrected by normal means
- Preliminary investigation indicates severe dc leakage across mod-anode/cathode ceramic ($\sim 2.5\text{mA}$ at 60kV)
- No crowbar or HV breakdown events were logged



Investigation is ongoing.....

Klystron Instabilities

- Suspected multipactor losses in klystron C1 and/or C2 can result in sudden loss of efficiency and erratic rf power output, and have produced 800kHz sidebands:



- Typical remedy:
 - Adjust rf drive power to avoid multipactor region -- penalty: *loss of efficiency*
- In most cases the instability can be avoided without excessive loss of efficiency



C1/C2 multipactor can severely limit useful operating parameter range

Upgrade of Legacy RF System Hardware to Improve Reliability

- Replacement of original process meter-relay logic interlock systems with modern PLC hardware:



**ORIGINAL SYSTEM WITH
INDIVIDUAL PROCESS
METERS**




NEW PLC INTERLOCK SYSTEM INSTALLATION




Upgrade of Legacy RF System Hardware to Improve Reliability

- Upgrade of original low-level rf boards (circa 1990) with new data acquisition hardware:



LLRF BOARD WITH ORIGINAL DATA ACQUISITION HARDWARE



NEW LLRF BOARD WITH UPDATED ACQUISITION HARDWARE

Ongoing Effort to Maintain and Improve RF System Reliability

- Maintain adequate spares and avoid reliance on obsolete hardware wherever possible
- Implement design improvements on input couplers
 - Work underway; see D. Bromberek talk
- Increased attention paid to HVPS systems
 - Routine close visual inspection of system components to detect age-related defects.....replace anything suspect!
- Investigate every fault to determine the root cause.....
then implement change to prevent a future occurrence

THE PLACE IS GETTING OLD!.....THE FIGHT NEVER ENDS!